

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen Date: 09 Apr 2019

Preliminary Advice

Vehicle No	: SLD6155J	Accident Date	: 28/02/2019
Make	: HONDA VEZEL	Policy No.	: DMHCSN1904101900
Assignment Date	: 05/03/2019	Excess	: S\$3,000.00
Date of Inspection	: 05/03/2019	Est. Duration of Repair	: 12 days
Inspection At	: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	: \$	12,239.99 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	: \$	10,884.99 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	: \$	1,300.00
Total	: \$	12,184.99
Lump Sum Repair	: \$	

Total Loss Consideration

New for Old Value	: \$	
Pre-Accident Value	: \$	62,000.00
COE / PARF Rebate	: \$	42,520.00
Salvage Value	: \$	
Margin for Repair	: \$	19,480.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 362.00