

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd
3 Anson Road 51 Ubi Ave 1 #01-25
#16-00 Springleaf Tower Paya Ubi Industrial Park
Singapore 079909 Singapore 408933

Attn: Chong Boon Sen Date: 06 Mar 2019

Preliminary Advice

Vehicle No	: SLD6155J	Accident Date	: 28/02/2019
Make	: HONDA VEZEL	Policy No.	: DMHCSN1904101900
Assignment Date	: 05/03/2019	Excess	: S\$3,000.00
Date of Inspection	: 05/03/2019	Est. Duration of Repair	: 12 days
Inspection At	: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 11,827.99
Revised Amount	:S\$ 10,422.99
Check Items (Estimated)	:S\$ 1,300.00
Total	:S\$ 11,722.99
 Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 62,000.00
COE / PARF Rebate	:S\$ 42,520.00
Salvage Value	:S\$
Margin for Repair	:S\$ 19,480.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :