

INS. CASE OWNER:

CC3, MG 1900

4064, T. 803 4

LKK:

IDAC:

Surveyor:

MH

DOI:

ASSIGNMENT

2/13/19

Date / Time:

5/3/19

Registered in Merimen:

8/3/19

Pre-assign / CCU / FTE

SM 6 4264m



Insured Vehicle No.:

Name of Insured:

BU MOTORHILL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

2/3/19

Is driver the owner?

( YES / NO )

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

B-TM AT exit to C70

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKT 3308 H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/1/19  
hmv

SKT 3308 H. X: SM 6 4264m. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation to Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lit:

Repair Cost:

S\$

O-D REPAIR WORKED BY

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

WP

3) Survey fee:

\$320

290

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

MH 2/1/19

4064 (110)

--	--

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/0288/2019/KN  
Date : 06-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Fang Chao Yin  
Address : Blk 701 Tampines St 71  
#06-08  
Singapore 520701  
Telephone : 92266618  
Type of Claim : Third Party Claims  
Policy No. : 5080682350  
Vehicle No : **SKT 3308 H**  
Model Code : A3 SEDAN 1.4 TFSI  
Model / Year : 29-05-15  
Engine No : CZC 253659  
Chassis No : WAUZZZ8V1F1127213  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 02-Mar-19  
Place of Accident : CAVENAGH ROAD CTE BUKIT TIMAH EXIT

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKT 3308 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed	\$ 900.00 500	
3	To respray rear bumper.	\$ 800.00 550.	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,172.00</u>	

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKT 3308 H

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	REAR BUMPER COVER	\$	1,708.00	Kp
2	FIXING PARTS FOR BUMPER	\$	175.00	X
3	GUIDE SECTION - RH	\$	15.00	X
4	LOCKING MECHNISM	\$	27.00	X
5	REAR BUMPER SPOILER - LH	\$	216.00	X
6	SIDE REINFORCEMENT	\$	522.00	X
7	BRACKET - RH	\$	12.00	X
8	GUIDE SECTION - RH	\$	60.00	X
9	REAR PARKING SENSORS - INNER / OUTER	2 \$	462.00	?
10	PARKING SENSOR SEAL RING	4 \$	12.00	na
11	REAR LIGHT REFLECTOR - RH	\$	38.00	X MV
12	SUNDRIES	\$	300.00	2
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 3,547.00</b>	
<b>TOTAL LABOUR CHARGES</b>			<b>\$ 2,172.00</b>	
<b>GRAND TOTAL</b>			<b>\$ 5,719.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

Tan Hin 92445749  
WP.  
11/3/19 & 195  
Ready after repair  
3 days  
Sur@PremiumAuto.com

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

## Jia Le (LKK Auto)

---

**From:** Jia Le (LKK Auto)  
**Sent:** Wednesday, 28 August 2019 3:28 PM  
**To:** Foo, Chityan  
**Subject:** [Your ref: 7664572588SG] ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019  
**Attachments:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK REF: CC3/AIG19004064/ea3

Dear Jimmy,

Third Party claimant decided to withdraw the claim, we will submit WP report as soonest possible.

Thank you.

Best Regards,

**Carlør Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Jia Le (LKK Auto)**

---

**From:** PAL Claim <claims@premiumauto.com.sg>  
**Sent:** Tuesday, 30 July 2019 2:20 PM  
**To:** Asher Sng (LKKAuto) <AsherSng@lkkauto.com>  
**Cc:** Claims <claims@premiumauto.com.sg>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>  
**Subject:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK  
**REF:** CC3/AIG19004064/ea3

Dear Asher ,

Owner have decided to withdraw claims. I have attach the addendum for your kind reference.

Thank You.

Aside to Carrine ,

Please take note of the withdrawal.

Many thanks !

Best Regards,  
**Sheila M Ismail**  
Claims Advisor

**Premium Automobiles Pte Ltd** (Reg No 199902271W)  
55 Ubi Road 1 Road Singapore 408699  
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183  
e. claims@premiumauto.com.sg w. www.audi.com.sg  
**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 p. +65 6836 2223

---

**From:** Claims Dept <claims@premiumauto.com.sg>  
**Sent:** Wednesday, 13 March 2019 9:46 AM  
**To:** 'Asher Sng (LKKAuto)' <AsherSng@lkkauto.com>  
**Cc:** 'Claims' <claims@premiumauto.com.sg>  
**Subject:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK  
**REF:** CC3/AIG19004064/ea3

Dear Asher ,

Thank for your prompt reply. We will accept your offer on direct settlement with 100% liability in our client's favour. To avoid dispute on the LOU/LOR rate during final settlement we will follow the benchmark rate for 1800cc and below accordingly.

The LOU rate \$60/DAY or LOR rate \$100/DAY. Our client is driving a A3 1.4 cc.

Thank You.

Best Regards,  
**Sheila M Ismail**  
Claims Advisor

**Premium Automobiles Pte Ltd** (Reg No 199902271W)



55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

---

**From:** Asher Sng (LKKAuto) [<mailto:AsherSng@lkkauto.com>]

**Sent:** Monday, 11 March 2019 9:34 AM

**To:** Claims

**Subject:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK  
REF: CC3/AIG19004064/ea3

**'WITHOUT PREJUDICE'**

**SAVE AS TO COSTS**

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Dear Sirs,

We refer to the above matter.

Please be informed that liability is unclear for this matter. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims Dept <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>

**Sent:** Thursday, 7 March 2019 8:40 PM

**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

**Cc:** 'Claims Dept' <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>

**Subject:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK

REF: CC3/AIG19004064/ea3

Dear Asher,

Kindly assist to follow up liability clearance and direct settlement.

Thank you.

Best regards,

**Kelvin Khoo**

**Premium Automobiles Pte Ltd** (Reg No 109902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 p. +65 6836 2223



**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Tuesday, 5 March, 2019 6:55 PM  
**To:** Claims <claims@premiumauto.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>; CS A Team <cs-a@lkkauto.com>  
**Subject:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK  
**REF:** CC3/AIG19004064/ea3

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending for our principal to release OI GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

**Meanwhile, please arrange appointment for survey.**

**To check availability of the case handler, you may contact the undersigned.**

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims <claims@premiumauto.com.sg>  
**Sent:** Tuesday, 5 March, 2019 2:29 PM  
**To:** Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Cc:** 'Claims' <claims@premiumauto.com.sg>  
**Subject:** ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

We will forward you the estimate once is available.

TP is insured with **AIG**.

Do take note, Kindly arrange the survey on 11/03/2019, Monday, 10 AM.

Thank you

**Best regards,**  
**George Wong**  
Claims Advisor

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6388 2223 d. +65 66900293 f. +65 64751023

e.claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

**From:** Claims <claims@premiumauto.com.sg>  
**Sent:** Monday, 11 March 2019 9:24 AM  
**To:** Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>  
**Cc:** 'Claims' <claims@premiumauto.com.sg>  
**Subject:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK  
REF: CC3/AIG19004064/ea3

Dear Asher,

We are not agreeable that the liability is unclear, Enclosed herewith in this email is a copy of BOLA guideline for your reference.

As we can see from the Scenario 15 " If point of impact of the front vehicle is found on the rear bumper, the driver of rear vehicle will be 100 % liable for losses incurred by the front vehicle.

We appreciate if you could revert back to us with your offer as soon as possible.

Thank you.

**Best regards,**  
**George Wong**  
Claims Advisor

**Premium Automobiles Pte Ltd** (Reg No 199902271W)  
281 Alexandra Road Singapore 159938  
p. +65 6388 2223 d. +65 66900293 f. +65 64751023  
e. claims@premiumauto.com.sg w. www.audi.com.sg  
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

**From:** Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>  
**Sent:** Friday, March 8, 2019 9:11 AM  
**To:** Claims Dept <claims@premiumauto.com.sg>  
**Subject:** RE: ACCIDENT INVOLVING SKT 3308 H AND YOUR INSURED SMG 4264 M DATED ON 02/03/2019 \*\*\* LKK  
REF: CC3/AIG19004064/ea3

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2019 <a href="#">Edit Reg</a>		11 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,534.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,534.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	<b>BIS MOTORING PTE LTD</b> , Co. Reg. No.: 2017935055D		
Main Claimant:	<b>FANG CHAO YIN</b> , ID: S8274971C		
Vehicle Reg. No.:	<b>SKT3308H</b>	Date of Loss:	02/03/2019 16:00 ~ :59 [45 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 7664572588SG</b>	Policy/Cover Note No.:	0999994322 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SMG4264M</b>	Policy No. (Claimant):	5080682350
		Excess:	
Repairer:	<b>Premium Automobiles Pte Ltd (UBI)</b> 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com		
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 14/03/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKT3308H (7664572588SG)  
[SMG4264M]  
TP  
FANG CHAO YIN  
Mar 2 2019 4:00PM  
[BIS MOTORING PTE LTD]  
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <span style="float: right;">View in Browser</span>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print	
1	06/03/19 14:50	<b>Accident Statement</b> <small>From: SC - Reg. No: SMG4264M, Claimant: BIS MOTORING PTE LTD</small>			Load HTM		
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	28/08/19 15:45	Odometer Reading			Load JPG	<input checked="" type="checkbox"/>	
2	28/08/19 15:45	Chassis Number			Load JPG	<input checked="" type="checkbox"/>	
3	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
4	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
5	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
6	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
7	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
8	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
9	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
10	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
11	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
12	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
13	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
14	28/08/19 15:45	General View			Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	05/03/19 18:52	TP GIA REPORT			Load PDF		
2	17/03/19 20:25	TP ESTIMATE - MARKED			Load PDF		
3	28/08/19 15:44	WITHDRAW CLAIM EMAIL FROM TP			Load PDF		
4	28/08/19 15:44	EMAIL TO AIG TO WITHDRAW CLAIM			Load PDF		

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19004064/T1DA3Q2

Date: 13/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322  
**Claimant**  
**Vehicle No :** SKT3308H **Insured Vehicle No :** SMG4264M  
**Date of Loss:** 02/03/2019 **Nature of Claim:** TP **Claim No:** 7664572588SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

**Reg No:** SKT3308H  
**Make & Model:** AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A) **Engine No:** CZC253659  
**Reg. Date:** 29/05/2015 (Man. Year: 2015) **Chassis No:** WAUZZZ8V1F1127213  
**Colour:** Bronze **Odometer:** 64460 km  
**Engine Capacity:** 1395 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

## CONDITION OF TYRES

**Front Tyre Size:** 225/45 R18 **Rear Tyre Size:** 225/45 R18  
**Front Left Side:** Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm  
**Front Right Side:** Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,547.00	12.00	3,535.00	99.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,172.00	1,522.00	650.00	29.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,719.00</b>	<b>1,534.00</b>	<b>4,185.00</b>	<b>73.18</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>400.33</b>	<b>107.38</b>	<b>292.95</b>	<b>73.18</b>
<b>Nett Amount (S\$)</b>	<b>6,119.33</b>	<b>1,641.38</b>	<b>4,477.95</b>	<b>73.18</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

**Date of Assignment:** 11/03/2019  
**Date Inspected:** 11/03/2019 **Inspected At:** Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
**Estimated Period of Repair:** 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	1,708.00 FS	*- FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	175.00 FS	*- FS
3	1		*GUIDE SECTION -RH	Not Necessary	15.00 FS	*- FS
4	1		*LOCKING MECHNISM	Not Necessary	27.00 FS	*- FS
5	1		*REAR BUMPER SPOILER -LH	Not Necessary	216.00 FS	*- FS
6	1		*SIDE REINFORCEMENT	Not Necessary	522.00 FS	*- FS
7	1		*BRACKET -RH	Not Necessary	12.00 FS	*- FS
8	1		*GUIDE SECTION -RH	Not Necessary	60.00 FS	*- FS
9	2		*REAR PARKING SENSOR -INNER /OUTER	*Check	462.00 FS	*- FS
10	4		*PARKING SENSOR SEAL RING	Necessary	12.00 FS	*12.00 FS
11	1		*REAR LIGHT REFLECTOR -RH	Not Necessary	38.00 FS	*- FS
12	1		*SUNDRIES	*Check	300.00 FS	*- FS
Total Parts (S\$)					3,547.00	12.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY REAR BUMPER	New	800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>2,172.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >