

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004074/Evd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 15-04-2019 Code: FCI2		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 3362E	Veh. Inspected	SLQ 9887S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D19001543MFSH	Excess (\$)	0.00	
	Assign From	MERINA CHIA	Assign Date	04/03/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA JAZZ	c.c	1498	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JHMGK5850FX202582	Colour	SILVER	
	Odometer	105052	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/55 R16	CONTINENTAL	7 mm	
	L/H Front Tyre	185/55 R16	CONTINENTAL	7 mm	
	R/H Rear Tyre	185/55 R16	CONTINENTAL	7 mm	
	L/H Rear Tyre	185/55 R16	CONTINENTAL	7 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	01/03/2019	Inspection Date	05/03/2019	
	Survey held at	KAH MOTOR CO SDN BERHAD			
		NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a.	a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	7 Working Days		