

ASS. REP. BY:

REF:

CS/INC19004124/Jvd302

Special Instruction

Surveyor

ASSIGNMENT (Office)

From (Person):

Cynthia Ang

of

INC

Date/Time:

5/3/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / C3

To Inspect Vehicle No:

SLK4378J

Insured:

SHD1446A

at Workshop info:

World Auto

Tel:

63621776

of

Kranji Loop

Policy No:

Claim No:

MT/1034177-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate

SLK4378J-CCH/ASM1801RES25/Neaz DOA: 4/10/18

SHD1446A-X

7/6/19

Final fig \$28,107.36 confirmed by email (Ref 10,63408, 2799)

Huse Jie

REF:

INC

ASSIGNMENT

From:

Date:

Veh No SLK4378J

Yr From 17 Jan 2017

Estimated Cost:

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SLK 4378 J

Make: Honda Vezel

CC 1496

or Workshop m/s:

World Auto

Colour: white

A/C Insured / Std / Nil / NA

or 1 Kravji Loop

Sp Reading: 254506

T/B Radio: Insured / Std / Nil / NA

Insured:

Eng/No:

Policy No:

ChNo:

RU31216992

Claims No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ Harder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ Harder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)

Tyre Size F: 225/50 R18

R: -

Remarks: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIRO / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? Yes or No

R/Bal. 6 mm

R/Bal. 6 mm

QA / PR Seen:

Consistent? Yes or No

L/Bal. 6 mm

L/Bal. 6 mm

Est Repairs:

days Res: Yes or No

D.O.A. 28/2/19

D.O.I. 5/3/19 0225pm

Est Sum:

% 3 Val: Yes or No

Survey held at World Auto

CA / REV / REP. / 24 HRS

Des. of Damages: ☒ Front / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV - \$84,000

PV - \$48,952

NV - \$35,048

Pls confirm M.V.

RECEIVED 7 JUN 2019

Date/Time File Path to?

☐

Prel. Report

Days Of Repair: 15

to

☐

Final Report

Resurvey No. of Trip: 2

Survey Fee:

290

Date/Time File Return to?

Transportation

7/6 - typist

Add Fee:

☐

Late Ins. 15

☐

Interview 15

☐

Tech Ins. 15

☐

Ref. of Ins. 15

TOTAL:

Report Format:

TP

Temp Sum / LUT:

28,107.36

290

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 5 March 2019 11:48 AM
To: assignments@lkkauto.com
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/03/2019

Dear Veron / Nivitha,

Resend with the following details.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 5 March 2019 9:37 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Daniel Koh <daniel.koh@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/03/2019

Dear Veron / Nivitha,

Please assist to survey the vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Type	Survey Time	OI Veh	DOA	Ad Re
1	Rajeswary	MT/1034327-002	SMA668P	CHENG AUTO BODYWORKS	5 SOON LEE STREET #01-62 PIONEER POINT	/ 8666 7775	Physical Survey		SLQ199D	01/03/2019	
2	Wo Jessie	MT/1034312-002	SHA9591B	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	Guang / 94669828	Physical Survey		GBC6202E	02/03/2019	
3	Muhammad Airwan	MT/1033391-	XE2208U	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595	Physical Survey		XE2810E	15/02/2019	
4	Muhammad Airwan	MT/1034432-001	SLD3960X	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031	Physical Survey		SHC6854C	03/03/2019	

5	Thio Tse Kiat	MT/1034310-002	5LL9051M	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031	Physical Survey		SMF1784D	01/03/2019
6	Azhari	MT/1034201-002	PC1981G	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 62660555	Physical Survey	09:30-13:00	SJC6682H	28/02/2019
7	Rajeswary	MT/1034177-002	5LK4378J	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776	Physical Survey		SHD1446A	28/02/2019

Please contact workshops.

Please ack.

Thank You

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLK4378J
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5RS AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	LEB5917012
Chassis No.:	RU31216992
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$28,802.00
Original Registration Date:	17 Jan 2017
First Registration Date:	17 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,508.00
COE Rebate Amount:	\$45,202.00
Total Rebate Amount:	\$48,952.00

The information contained herein is correct as at 06 Mar 2019

OK

SUPREME

NEW CARS | PRE-LOVED CARS | INSURANCE | FI

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan Trade In And
Warranty 100% Depreciated Around
The Unapproved Loan,
Classic Credit StarAd



Browse by Category

1 vehicles

Vezel Hybrid 1.5A RS

Sort by Date Posted

Advanced Search

Search Selection

Vezel Hybrid 1.5A RS

Any

Any

2017

Any

Any

Any



Honda Vezel Hybrid 1.5A RS

\$89,600

\$10,770 /yr

07-Apr-2017

1,496 cc

38,000 km

SUV

Fuel Type: Petrol-Electric

100% Accident Free. 5 Years Warranty With Optima Werks. Tuned By Honda Hybrid Specialist. Full Car Sound Proof Worth \$3000. Pioneer 585i
Original Leather Seats With Alcantara Fixtures, V-Kool Solar F...

Monster Motors Pte Ltd

Posted: 12-Jan-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Home

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

For old advertisements, view Expired ads

Home

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article

Forum

Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedans or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car insurance. Find buy used Vezel Hybrid 1.5A RS, Vezel Hybrid 1.5A RS Singapore, used Vezel Hybrid 1.5A RS Singapore, used Vezel Hybrid 1.5A RS, used vehicles Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price list new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of the information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement
©2004-2019 sgCarMart. All rights reserved.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/03/2019 17:13
Date Of Accident	28/02/2019 16:20
Exact Location Of Accident	AYER RAJAH EXPRESSWAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLK4378J
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000194-R00
Cover Note Number	
Driver	
Name of Driver	GOH BENG CHIAN
NRIC No	S1723045Z
Date Of Birth	26/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	10/12/1986
Driving Experience	32 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90845567
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD1446A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJT9650R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE HIRE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHC2J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GOH BENG CHIAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN



- A. SLK 4378J
- B. SHD 1446A
- C. STJ 9650 R
- D. SHL 2J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

(Witnesses and/or reporting parties are true and correct)

Witness's Signature
Date & Time

Driver's Signature
(If driver is not the police officer)
Date & Time

Reporting Officer's Signature
Name
Police No.

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may give insurance companies the **right to dispute policy liability.**
4. The use and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers at the GIA Accidents Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I, under/NAME, acknowledge, agree and consent that:

- (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions in responding to any enquiry by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports to insurers to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as the internal cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (ii) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (iii) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
- (iv) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (v) the information so collected under (i) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, conducting or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NIC/PRN No.

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20190226/2165

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20190226/2165

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/02/2019 21:14	Video Report No.:	Station Diary No.:
--	-------------------	--------------------

Informant's Particulars

Name of Informant: GOH BENG CHIAN	Address: APT BLK 364 WOODLANDS AVENUE 5 #05-468 SINGAPORE 730364		
ID Type / ID No.: NRIC NO / S1723045Z	Contact No.: Home/Office: Mobile: 90845567		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 54	Date of Birth: 26/02/1965	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: OTHERS	Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 28/02/2019 16:20	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY TWDS JURONG				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow:	Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision:	Anyone conveyed by ambulance: Yes			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC2J	Car					0
SHD1446A	Car					0
SJT9650R	Car					0
SLK4378J	Car				Seriously Damaged	0

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20190228/2165

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190228/2165

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GOH BENG CHIAN	ID No.	S1723045Z
Related Vehicle	NIL	Contact No.	90845567
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/02/2019	Date Discharge	28/02/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE & LOCATION.

I WAS DRIVING ALONG THE STRAIGHT ROAD OF THE EXPRESSWAY ON THE LANE 1 OF 3. ALL THE VEHICLES INVOLVED WERE TRAVELING IN A STRAIGHT ROW. V1 (SHC2J) AND V2 (SJT9650R) COLLIDED IN FRONT OF ME. I WAS THE THIRD CAR BEHIND. DUE TO THE COLLISION, I COULDN'T STOP IN TIME AND I HIT THE BACK OF V2 (SJT9650R).

UNFORTUNATELY, I GOT HIT BY AN TAXI (SHD1446A) FROM THE BACK OF MY VEHICLE. IT WAS A CHAIN COLLISION INVOLVING FOUR VEHICLES.

I WAS UNWELL AFTER THE ACCIDENT AND WAS BROUGHT OVER TO THE HOSPITAL.

THATS ALL.

Sketch Plan #5



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190228/2165

3 of 3

Report No: T/20190228/2165

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
YOGENDRAN S/O RAJASAKARAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt NOR FAIZAL BIN YAHYA
Contact No.: 65476202

Authentication Stamp
1P108

Signature Of Informant:

Date/Time:
28/02/2019 21:14

Classification Of Case:



SINGAPORE
POLICE FORCE

Signature:

Sketch Plan #6



Individual Statement

This receipt is not valid unless amount paid is recognised by active police officers

RENEWAL NOTICE FOR VOCATIONAL LICENCE

Name: GOH HENG CHUAN

License No: S1723045Z

License Group: 02

Next Expiry Date: 3/9/2020

Land Transport Authority

DR-02-2017-0001 14425
N0321 000223
L T A QR 040520

Please see overleaf for renewal instructions



Reg No: 52977287 J

CASH SALE/WORK ORDER
迅速拖車服務
SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: C 23746

Date: 1/3/19

Name/Company

World Auto

Vehicle No.

SLK 4378 J

Model

Vezel

From

517 Air Port

To

1 karaji loop

Remarks

Time:

: : - : - :

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed.

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment

☐ Trips

Amount \$

60k

Tow Truck

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
 Email: speedwaytowing@gmail.com

Received By

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BONNET BUC /		819.00
2.	2	FRONT BONNET HINGE ?	95.60	191.20
3.	1	FRONT BONNET INSULATOR BUC /		140.00
4.	1	FRONT BONNET LOCK BT /		185.50
5.	1	FRONT BUMPER BUC /		620.80
6.	2	FRONT BUMPER SIDE RETAINER CRA /	38.50	77.00
7.	1	FRONT BUMPER REINFORCEMENT DD /		580.00
8.	1	FRONT BUMPER LOWER GRILLE SCR /		185.00
9.	1	FRONT BUMPER TOW COVER CUT /		40.00
10.	1	FRONT LOWER BUMPER DEF /		495.60
11.	1	FRONT GRILLE BASE CRA /		380.00
12.	1	FRONT GRILLE MOULDING LENS CRA /		360.00
13.	2	FRONT GRILLE LOWER CHROME MOULDING SCR /	98.00	196.00
14.	1	FRONT GRILLE EMBLEM NEC /		80.00
15.	1	FRONT GRILLE CENTRE LOCK BRACKET CRA /		42.00
16.	2	HEADLAMP ASSY CRA /	1,850.00	3,700.00
17.	2	HEADLAMP TOP BRACKET ?	32.00	64.00
18.	2	HEADLAMP LOWER BRACKET ?	78.80	157.60
19.	1	FRONT FENDER WHEEL ARCH MOULDING RH SCR /		145.00
20.	1	FRONT SUPPORT PANEL ?		790.00
21.	1	FRONT SUPPORT PANEL TOP GARNISH CUT /		95.00
22.	1	RADIATOR ?		1,311.90
23.	1	RADIATOR FAN COWLING ?		125.00
24.	1	RADIATOR FAN MOTOR ?		225.00
25.	1	RADIATOR FAN BLADE ?		122.00
26.	1	RADIATOR SPARE TANK ?		92.00
27.	1	RADIATOR SPARE TANK CAP ?		30.00
28.	1	AIRCON CONDENSOR ?		1,160.00
29.	1	AIRCON CONDENSOR FAN COWLING ?		168.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	AIRCON CONDENSOR FAN MOTOR ?		238.00
31.	1	AIRCON CONDENSOR FAN BLADE ?		95.00
32.	1	AIRCON RECEIVER PIPE ?		280.00
33.	1	AIR INTAKE AIR DUCT ?		132.00
34.	1	AIR INTAKE AIR DUCT TUBE ?		70.00
35.	1	REAR TAILGATE BUC /		1,100.00
36.	1	REAR TAILGATE INNER TRIM BOARD ?		278.00
37.	1	REAR TAILGATE INNER HANDGRIP COVER BT /		55.00
38.	1	REAR TAILGATE INNER LOCK ?		211.90
39.	1	REAR TAILGATE VEZEL EMBLEM NEC /		84.60
40.	1	REAR TAILGATE HYBRID EMBLEM NEC /		88.60
41.	1	REAR TAILGATE RS EMBLEM NEC /		85.50
42.	2	REAR TAILGATE REFLECTOR LAMP SCR-RH /	580.00	1,160.00
43.	1	REAR BUMPER DEF /		865.00
44.	2	REAR SIDE BUMPER CUT-RH /	210.00	420.00
45.	2	REAR BUMPER REFLECTOR LENS ? SCR-RH /	132.80	265.60
46.	2	REAR BUMPER SIDE RETAINER RH ?	78.00	156.00
47.	1	REAR BUMPER UNDERDUST COVER BUC /		155.00
48.	2	REAR TAIL LAMP SCR-RH /	550.00	1,100.00
49.	1	REAR END PANEL BUC /		830.00
50.	1	REAR END PANEL TOP GARNISH DEF /		138.50
51.	1	REAR BOOT WEATHER STRIP CUT /		155.00
52.	1	REAR BOOT FLOOR BOARD NM X		345.00
53.	1	REAR BOOT COMPARTMENT BOX CRA /		320.00
54.	1	REAR FLOOR PANEL BUC /		790.00
55.	1	REAR FLOOR PANEL STIFFENER ?		130.00
56.	1	REAR WINDSCREEN GLASS MOULDING NEC /		198.00
57.	1	SMART BUZZER SENSOR ?		155.00
58.	1	DASHBOARD NEC /		1,300.00
59.	1	DRIVER AIRBAG Activated /		1,580.00
60.	1	FRONT PASSENGER AIRBAG Activated /		2,340.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
 75 BRAS BASAH ROAD NTUC INCOME CENTRE
 189557

Attention : Motor Claim Department
 Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019
 Vehicle Num. : SLK 4378J (LCR)
 Make/Model : HONDA VEZEL HYBRID RS
 Chassis/Eng# :
 Accident Date : 28/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
61.	1	STEERING WHEEL AIR BAG SLIP RING <i>nec / nec /</i>		330.00
62.	1	STEERING ANGLE SENSOR <i>nec /</i>		250.00
63.	1	AIRBAG CONTROL MODULE <i>nec /</i>		1,100.00
64.	2	FRONT AIRBAG IMPACT SENSOR <i>Activated /</i>	150.00	300.00
65.	2	FRONT SEATBELT <i>Damaged /</i>	670.00	1,340.00
66.	2	FRONT SEATBELT BUCKLE <i>SVC X</i>	210.00	420.00
List TotalS\$:				31,439.30
20.00% Discount S\$:				6,287.86
				25,151.44
SPECIAL NETT ITEMS :				
1.	1SET	FRONT BONNET INSULATOR CLIP <i>nec /</i>		20 30.00
2.	1SET	FRONT BUMPER CLIP <i>nec /</i>		30 30.00
3.	1SET	FRONT FENDER WHEEL ARCH MOULDING CLIPS <i>nec /</i>		15 30.00
4.	1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>nec /</i>		15 30.00
5.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>?</i>		30.00
6.	1SET	REAR BUMPER CLIP <i>nec /</i>		30.00
7.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>nec /</i>		30.00
8.	1	WINDSCREEN SEALANT <i>nec /</i>	60	80.00
9.	1SET	REVERSE SENSOR <i>Shorted</i>	200	280.00
10.	1	TOWING CHARGE		60.00
Special Nett Total S\$:				630.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				100 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				50 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
 75 BRAS BASAH ROAD NTUC INCOME CENTRE
 189557

Attention : Motor Claim Department
 Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019
 Vehicle Num. : SLK 4378J (LCR)
 Make/Model : HONDA VEZEL HYBRID RS
 Chassis/Eng# :
 Accident Date : 28/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY	50	180.00
		REMOVE RADIATOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL COOLANT AND PERFORM ENGINE COOLING SYSTEM PRESSURE TEST		180.00 ?
		REMOVE AIRCON CONDENSOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL AIRCON GAS AND PERFORM AIRCON SYSTEM LEAK TEST		180.00 ?
		HOIST OUT ENGINE IN ORDER TO FACILITATE REPAIRS TO FRONT CHASSIS AND REFIT BACK SAME	120	480.00
		REMOVE FRONT UNDERCARRIAGE COMPONENTS IN ORDER TO FACILITATE REPAIRS TO FRONT CHASSIS AND REFIT BACK SAME	100	380.00
		REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1400	2,200.00
		REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1500	2,400.00
		REMOVE EXHAUST MUFFLER IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	40	180.00
		COMPUTERISED ALIGNMENT	100	180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

75 BRAS BASAH ROAD NTUC INCOME CENTRE

189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	250	480.00
		REMOVE DASHBOARD AND DAMAGED SRS COMPONENTS AND REPLACE WITH NEW	350	680.00
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES, REINITIALISE HV HYBRID SYSTEM AND PERFORM SRS FUNCTIONALITY CHECK	120	480.00
		PUTTY AND SPRAY PAINT FRONT ACCIDENT DAMAGED AREAS	1000	1,300.00
		PUTTY AND SPRAY PAINT REAR ACCIDENT DAMAGED AREAS	1000	1,600.00
		NOTE: PEARL WHITE		
		Labour Total S\$:		11,260.00


E. & O.E.**Total S\$: 37,041.44****for WORLD AUTO PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jin - LKK
5/3/19
P/P 15 days



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BONNET BUC ✓		819.00
2.	2	FRONT BONNET HINGE BT ✓	95.60	191.20
3.	1	FRONT BONNET INSULATOR BUC ✓		140.00
4.	1	FRONT BONNET LOCK BT ✓		185.50
5.	1	FRONT BUMPER BUC ✓		620.80
6.	2	FRONT BUMPER SIDE RETAINER CRA ✓	38.50	77.00
7.	1	FRONT BUMPER REINFORCEMENT DD ✓		580.00
8.	1	FRONT BUMPER LOWER GRILLE SCR ✓		185.00
9.	1	FRONT BUMPER TOW COVER CUT ✓		40.00
10.	1	FRONT LOWER BUMPER DEF ✓		495.60
11.	1	FRONT GRILLE BASE CRA ✓		380.00
12.	1	FRONT GRILLE MOULDING LENS CRA ✓		360.00
13.	2	FRONT GRILLE LOWER CHROME MOULDING SCR ✓	98.00	196.00
14.	1	FRONT GRILLE EMBLEM NR ✓		50 80.00
15.	1	FRONT GRILLE CENTRE LOCK BRACKET CRA ✓		42.00
16.	2	HEADLAMP ASSY CRA ✓	1,850.00	3,700.00
17.	2	HEADLAMP TOP BRACKET CRA ✓	32.00	64.00
18.	2	HEADLAMP LOWER BRACKET CRA ✓	78.80	157.60
19.	1	FRONT FENDER WHEEL ARCH MOULDING RH SCR ✓		145.00
20.	1	FRONT SUPPORT PANEL BT ✓		790.00
21.	1	FRONT SUPPORT PANEL TOP GARNISH CUT ✓		95.00
22.	1	RADIATOR DD ✓		1100 1,311.90
23.	1	RADIATOR FAN COWLING CRA ✓		125.00
24.	1	RADIATOR FAN MOTOR SVC X		225.00
25.	1	RADIATOR FAN BLADE SVC X		122.00
26.	1	RADIATOR SPARE TANK NR X		92.00
27.	1	RADIATOR SPARE TANK CAP NR X		30.00
28.	1	AIRCON CONDENSOR BT ✓		650 1,160.00
29.	1	AIRCON CONDENSOR FAN COWLING CRA ✓		168.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	AIRCON CONDENSOR FAN MOTOR <i>DD-</i>		238.00
31.	1	AIRCON CONDENSOR FAN BLADE <i>CRA-</i>		95.00
32.	1	AIRCON RECEIVER PIPE <i>DD-</i>		280.00
33.	1	AIR INTAKE AIR DUCT <i>max</i>		132.00
34.	1	AIR INTAKE AIR DUCT TUBE <i>max</i>		70.00
35.	1	REAR TAILGATE <i>BUC-</i>		1,100.00
36.	1	REAR TAILGATE INNER TRIM BOARD <i>max</i>		278.00
37.	1	REAR TAILGATE INNER HANDGRIP COVER <i>BT-</i>		55.00
38.	1	REAR TAILGATE INNER LOCK <i>SUCX</i>		211.90
39.	1	REAR TAILGATE VEZEL EMBLEM <i>NEC-</i>	30	84.60
40.	1	REAR TAILGATE HYBRID EMBLEM <i>NEC-</i>	30	88.60
41.	1	REAR TAILGATE RS EMBLEM <i>NEC-</i>	30	85.60
42.	2	REAR TAILGATE REFLECTOR LAMP <i>SCR-RH-</i>	580.00	420 4,160.00
43.	1	REAR BUMPER <i>DEF-</i>		865.00
44.	2	REAR SIDE BUMPER <i>CUT-RH-</i>	210.00	190 420.00
45.	2	REAR BUMPER REFLECTOR LENS <i>SCR-RH-</i>	132.80	120 265.60
46.	2	REAR BUMPER SIDE RETAINER RH <i>max</i>	78.00	156.00
47.	1	REAR BUMPER UNDERDUST COVER <i>BUC-</i>		155.00
48.	2	REAR TAIL LAMP <i>SCR-RH-</i>	550.00	470 4,400.00
49.	1	REAR END PANEL <i>BUC-</i>		830.00
50.	1	REAR END PANEL TOP GARNISH <i>DEF-</i>		138.50
51.	1	REAR BOOT WEATHER STRIP <i>CUT-</i>		155.00
52.	1	REAR BOOT FLOOR BOARD <i>max</i>		345.00
53.	1	REAR BOOT COMPARTMENT BOX <i>CRA-</i>		320.00
54.	1	REAR FLOOR PANEL <i>BUC-</i>		790.00
55.	1	REAR FLOOR PANEL STIFFENER <i>BT-</i>		130.00
56.	1	REAR WINDSCREEN GLASS MOULDING <i>NEC-</i>		198.00
57.	1	SMART BUZZER SENSOR <i>max</i>		155.00
58.	1	DASHBOARD <i>NEC-</i>	1050	1,300.00
59.	1	DRIVER AIRBAG <i>Activated</i>	1300	4,580.00
60.	1	FRONT PASSENGER AIRBAG <i>Activated</i>	2000	2,340.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
61.	1	STEERING WHEEL AIR BAG SLIP RING <i>nec / nec /</i>		330.00
62.	1	STEERING ANGLE SENSOR <i>nec /</i>		250.00
63.	1	AIRBAG CONTROL MODULE <i>nec /</i>		900 4,100.00
64.	2	FRONT AIRBAG IMPACT SENSOR <i>Activated /</i>	150.00	300.00
65.	2	FRONT SEATBELT <i>damaged /</i>	670.00	1,340.00
66.	2	FRONT SEATBELT BUCKLE <i>SVC X</i>	210.00	420.00
List TotalS\$:				31,439.30
20.00% Discount S\$:				6,287.86
				25,151.44
SPECIAL NETT ITEMS :				
1.	1SET	FRONT BONNET INSULATOR CLIP <i>nec /</i>		20 30.00
2.	1SET	FRONT BUMPER CLIP <i>nec /</i>		30 30.00
3.	1SET	FRONT FENDER WHEEL ARCH MOULDING CLIPS <i>nec /</i>		15 30.00
4.	1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>nec /</i>		15 30.00
5.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>nec /</i>		30.00
6.	1SET	REAR BUMPER CLIP <i>nec /</i>		30.00
7.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>nec /</i>		30.00
8.	1	WINDSCREEN SEALANT <i>nec /</i>		60 80.00
9.	1SET	REVERSE SENSOR <i>shorted</i>		200 280.00
10.	1	TOWING CHARGE		60.00
Special Nett Total S\$:				630.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				120 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				50 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY	50	180.00
		REMOVE RADIATOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL COOLANT AND PERFORM ENGINE COOLING SYSTEM PRESSURE TEST	60	180.00 3
		REMOVE AIRCON CONDENSOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL AIRCON GAS AND PERFORM AIRCON SYSTEM LEAK TEST	60	180.00 3
		HOIST OUT ENGINE IN ORDER TO FACILITATE REPAIRS TO FRONT CHASSIS AND REFIT BACK SAME	120	480.00
		REMOVE FRONT UNDERCARRIAGE COMPONENTS IN ORDER TO FACILITATE REPAIRS TO FRONT CHASSIS AND REFIT BACK SAME	100	380.00
		REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1400	2,200.00
		REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1500	2,400.00
		REMOVE EXHAUST MUFFLER IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	40	180.00
		COMPUTERISED ALIGNMENT	100	180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190004

Date : 01/03/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	250	480.00
		REMOVE DASHBOARD AND DAMAGED SRS COMPONENTS AND REPLACE WITH NEW	350	680.00
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES, REINITIALISE HV HYBRID SYSTEM AND PERFORM SRS FUNCTIONALITY CHECK	120	480.00
		PUTTY AND SPRAY PAINT FRONT ACCIDENT DAMAGED AREAS	1000	1,300.00
		PUTTY AND SPRAY PAINT REAR ACCIDENT DAMAGED AREAS	1000	1,600.00
		NOTE: PEARL WHITE		
		Labour Total S\$:		11,260.00

38,741.44

E. & O.E.

Total S\$: 37,041.44

Total - \$28,107.36/-

Huse In - LKK

5/3/19

P/P 15 days

for WORLD AUTO PTE LTD

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED Supplementary Estimate : SE190004

75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Date : 28/02/2019

Vehicle Num. : SLK 4378J (LCR)

Make/Model : HONDA VEZEL HYBRID RS

Chassis/Eng# :

Accident Date : 28/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	INTAKE MANIFOLD <i>SLK</i>	360	482.00
2.	1	INTAKE MANIFOLD BREATHER HOSE <i>CUT</i>		50.00
3.	1	THERMOSTAT HOUSING <i>CRA</i>		130.00
4.	1	WIPER WASHER TANK <i>BT</i>		130.00
5.	1	FOG LAMP ASSY - RH <i>CRA</i>	320	480.00
6.	1	FOG LAMP COVER RH <i>CRA</i>		55.00
7.	1	REAR FENDER WHEEL ARCH MOULDING - RH <i>CRA</i>		198.00
8.	1	EXHAUST MUFFLER <i>BT</i>		550.00

List TotalS\$:

2,075.00

20.00% Discount S\$:

415.00

1,660.00

SPECIAL NETT ITEMS :

1.	1	FRONT NUMBER PLATE WITH CASING <i>CRA</i>	30	40.00
----	---	---	----	------------------

Special Nett Total S\$:

40.00

E. & O.E.

Total S\$:

1,700.00

=====

for WORLD AUTO PTE LTD

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 7 June 2019 3:52 PM
To: tggtan@worldauto.com.sg; SUR
Cc: Hwee Jie (LKK Auto) (hweejie@lkkauto.com)
Subject: RE: SLK 4378J Our ref: TP/2495/19

Dear Sophia,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Friday, 7 June 2019 3:35 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SLK 4378J Our ref: TP/2495/19

Veron

Confirmed finalised COR \$28,107.36 and 15 working days.

Rdgs
Sophia

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Friday, 7 June 2019 2:30 PM
To: tggtan@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>; Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Subject: RE: SLK 4378J Our ref: TP/2495/19

Dear Sophia,

WITHOUT PREJUDICE

Finalize amount \$28,107.36 @ 15 working days.

- (1) Spare parts (page 1)-\$10,756.70
 - Spare parts (page 2)-\$10,989.50
 - Spare parts (page 3)-\$3120
 - Spare parts (supp)- \$1793
 - Total -\$26,659.20 (less 20%) =\$ 21,327.36

- (2) SN \$460 (incl.supplementary \$30)

(3) Labour -\$6320

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>

Sent: Friday, 7 June 2019 12:05 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: FW: SLK 4378J Our ref: TP/2495/19

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>

Sent: Wednesday, 29 May 2019 3:14 PM

To: 'Hwee Jie (LKK Auto)' <hweejie@lkkauto.com>

Subject: FW: SLK 4378J Our ref: TP/2495/19

Hwee Jie

I have recalculated as follows:-

Items 1 to 15	:	\$4362.10	
Items 16 to 29	:	\$6394.60	
Items 30 to 46	:	\$3329.00	
Items 47 to 60	:	\$8036.50	
Items 61 to 66	:	<u>\$3120.00</u>	
		\$25242.20	
20%		<u>\$5048.44</u>	
		\$20,193.76	
SN		\$ 490.00	
Labour		\$6320.00	
Supp list		\$1434.40	(\$1793.00/20%(\$358.60)
Supp list – SN		<u>\$ 30.00</u>	
		<u>\$28,468.16</u>	
Your figure	:	\$28107.36	
Our figure		<u>\$28468.16</u>	
		\$ 360.80	
Difference		\$360.80	

Can you verify and revert.

Thanks
Sophia

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Wednesday, 8 May 2019 4:30 PM
To: 'Hwee Jie (LKK Auto)' <hweejie@lkkauto.com>
Subject: FW: SLK 4378J Our ref: TP/2495/19

Hi Hwee Jie

Please revert urgently.

Rdgs
Sophia

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Monday, 22 April 2019 5:26 PM
To: 'Hwee Jie (LKK Auto)' <hweejie@lkkauto.com>
Subject: RE: SLK 4378J Our ref: TP/2495/19

Hwee Jie

Attach our estimate markings.

Our figure is \$29084.16.

Yours is \$28107.36

Diff : \$976.80

Kindly revert.

Rdgs
Sophia

From: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Sent: Thursday, 18 April 2019 1:48 PM
To: tggtan@worldauto.com.sg
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SLK 4378J Our ref: TP/2495/19

Hi Sophia,

Finalized amount P/P \$28,107.36/- 15days.

Please let me know if you're agree with the amount so I can proceed with finalize, thank you.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315

From: tggtan@worldauto.com.sg [mailto:tggtan@worldauto.com.sg]
Sent: Monday, 8 April, 2019 3:59 PM
To: Hwee Jie (LKK Auto)
Subject: SLK 4378J Our ref: TP/2495/19

Hi Hwee Jie

Can we finalise?

Thanks & Rgds
Sophia Tan
Claims Manager

WORLD AUTO PTE LTD

1 Kranji Loop
Singapore 739535
Tel : 63621776





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19004124/Jvd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date : 25-06-2019	
ATTN : RAJESWARY			Code : INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 1446A	Veh. Inspected	SLK 4378J	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1034177-002	Excess (\$)	0.00	
Assign From	CYNTHIA ANG	Assign Date	05/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31216992	Colour	WHITE	
Odometer	254506	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	PIRELLI	6 mm	
L/H Front Tyre	225/50 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2019	Inspection Date	05/03/2019	
Survey held at	1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 4378J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BUCKLED	819.00	819.00
2	FRONT BONNET HINGE @\$95.60	BENT	191.20	191.20
1	FRONT BONNET INSULATOR	BUCKLED	140.00	140.00
1	FRONT BONNET LOCK	BENT	185.50	185.50
1	FRONT BUMPER	BUCKLED	620.80	620.80
2	FRONT BUMPER SIDE RETAINER @\$38.50	CRACKED	77.00	77.00
1	FRONT BUMPER REINFORCEMENT	DENTED	580.00	580.00
1	FRONT BUMPER LOWER GRILLE	SCRATCHED	185.00	185.00
1	FRONT BUMPER TOW COVER	CUT	40.00	40.00
1	FRONT LOWER BUMPER	DEFORMED	495.60	495.60
1	FRONT GRILLE BASE	CRACKED	380.00	380.00
1	FRONT GRILLE MOULDING LENS	CRACKED	360.00	360.00
2	FRONT GRILLE LOWER CHROME MOULDING @\$98.00	SCRATCHED	196.00	196.00
1	FRONT GRILLE EMBLEM	NECESSARY	80.00	50.00
1	FRONT GRILLE CENTRE LOCK BRACKET	CRACKED	42.00	42.00
2	HEADLAMP ASSY @\$1850.00	CRACKED	3,700.00	3,100.00
2	HEADLAMP TOP BRACKET @\$32.00	CRACKED	64.00	64.00
2	HEADLAMP LOWER BRACKET @\$78.80	CRACKED	157.60	157.60
1	FRONT FENDER WHEEL ARCH MOULDING RH	SCRATCHED	145.00	145.00
1	FRONT SUPPORT PANEL	BENT	790.00	790.00
1	FRONT SUPPORT PANEL TOP GARNISH	CUT	95.00	95.00
1	RADIATOR	DENTED	1,311.90	1,100.00
1	RADIATOR FAN COWLING	CRACKED	125.00	125.00
1	RADIATOR FAN MOTOR	SERVICEABLE	225.00	-
1	RADIATOR FAN BLADE	SERVICEABLE	122.00	-
1	RADIATOR SPARE TANK	NOT NECESSARY	92.00	-
1	RADIATOR SPARE TANK CAP	NOT NECESSARY	30.00	-
1	AIRCON CONDENSOR	BUCKLED	1,160.00	650.00
1	AIRCON CONDENSOR FAN COWLING	CRACKED	168.00	168.00
1	AIRCON CONDENSOR FAN MOTOR	DENTED	238.00	238.00
1	AIRCON CONDENSOR FAN BLADE	CRACKED	95.00	95.00

Report Ref No. CS/INC19004124/Jvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON RECEIVER PIPE	DENTED	280.00	280.00
1	AIR INTAKE AIR DUCT	NOT NECESSARY	132.00	-
1	AIR INTAKE AIR DUCT TUBE	NOT NECESSARY	70.00	-
1	REAR TAILGATE	BUCKLED	1,100.00	1,100.00
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	278.00	-
1	REAR TAILGATE INNER HANDGRIP COVER	BENT	55.00	55.00
1	REAR TAILGATE INNER LOCK	SERVICEABLE	211.90	-
1	REAR TAILGATE VEZEL EMBLEM	NECESSARY	84.60	30.00
1	REAR TAILGATE HYBRID EMBLEM	NECESSARY	88.60	30.00
1	REAR TAILGATE RS EMBLEM	NECESSARY	85.50	30.00
2	REAR TAILGATE REFLECTOR LAMP @\$580.00	O/S SCRATCHED	1,160.00	420.00
1	REAR BUMPER	DEFORMED	865.00	865.00
2	REAR SIDE BUMPER @\$210.00	O/S CUT	420.00	190.00
2	REAR BUMPER REFLECTOR LENS @\$132.80	O/S SCRATCHED	265.60	120.00
2	REAR BUMPER SIDE RETAINER RH @\$78.00	NOT NECESSARY	156.00	-
1	REAR BUMPER UNDERDUST COVER	BUCKLED	155.00	155.00
2	REAR TAIL LAMP @\$550.00	O/S SCRATCHED	1,100.00	470.00
1	REAR END PANEL	BUCKLED	830.00	830.00
1	REAR END PANEL TOP GARNISH	DEFORMED	138.50	138.50
1	REAR BOOT WEATHERSTRIP	CUT	155.00	155.00
1	REAR BOOT FLOOR BOARD	NOT NECESSARY	345.00	-
1	REAR BOOT COMPARTMENT BOX	CRACKED	320.00	320.00
1	REAR FLOOR PANEL	BUCKLED	790.00	790.00
1	REAR FLOOR PANEL STIFFENER	BENT	130.00	130.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	198.00	198.00
1	SMART BUZZER SENSOR	NOT NECESSARY	155.00	-
1	DASHBOARD	NECESSARY	1,300.00	1,050.00
1	DRIVER AIRBAG	ACTIVATED	1,580.00	1,300.00
1	FRONT PASSENGER AIRBAG	ACTIVATED	2,340.00	2,000.00
1	STEERING WHEEL AIR BAG SLIP RING	NECESSARY	330.00	330.00
1	STEERING ANGLE SENSOR	NECESSARY	250.00	250.00
1	AIRBAG CONTROL MODULE	NECESSARY	1,100.00	900.00
2	FRONT AIRBAG IMPACT SENSOR @\$150.00	ACTIVATED	300.00	300.00

Report Ref No. CS/INC19004124/Jvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT SEATBELT @\$670.00	JAMMED	1,340.00	1,340.00
2	FRONT SEATBELT BUCKLE @\$210.00	SERVICEABLE	420.00	-
1	INTAKE MANIFOLD (ADDITIONAL)	SCRATCHED	482.00	360.00
1	INTAKE MANIFOLD BREATHER HOSE (ADDITIONAL)	CUT	50.00	50.00
1	THERMOSTAT HOUSING (ADDITIONAL)	CRACKED	130.00	130.00
1	WIPER WASHER TANK (ADDITIONAL)	DENTED	130.00	130.00
1	FOG LAMP ASSY - RH (ADDITIONAL)	CRACKED	480.00	320.00
1	FOG LAMP COVER RH (ADDITIONAL)	CRACKED	55.00	55.00
1	REAR FENDER WHEEL ARCH MOULDING - RH (ADDITIONAL)	CRACKED	198.00	198.00
1	EXHAUST MUFFLER (ADDITIONAL)	BENT	550.00	550.00
	LESS 20% DISCOUNT		-6,702.86	-5,331.84
			26,811.44	21,327.36
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BONNET INSULATOR CLIP (SN)	NECESSARY	30.00	20.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT FENDER WHEEL ARCH MOULDING CLIPS (SN)	NECESSARY	30.00	15.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	15.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	FRONT NUMBER PLATE WITH CASING (SN) (ADDITIONAL)	CRACKED	40.00	30.00
			610.00	400.00
	<u>LABOUR</u>			
	TOWING CHARGE.		60.00	60.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	50.00
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	50.00

Report Ref No. CS/INC19004124/Jvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE RADIATOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL COOLANT AND PERFORM ENGINE COOLING SYSTEM PRESSURE TEST.		180.00	60.00
	REMOVE AIRCON CONDENSOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL AIRCON GAS AND PERFORM AIRCON SYSTEM LEAK TEST.		180.00	60.00
	HOIST OUT ENGINE IN ORDER TO FACILITATE REPAIRS TO FRONT CHASSIS AND REFIT BACK SAME.		480.00	120.00
	REMOVE FRONT UNDERCARRIAGE COMPONENTS IN ORDER TO FACILITATE REPAIRS TO FRONT CHASSIS AND REFIT BACK SAME.		380.00	100.00
	REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		2,200.00	1,400.00
	REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		2,400.00	1,500.00
	REMOVE EXHAUST MUFFLER IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME.		180.00	40.00
	COMPUTERISED ALIGNMENT.		180.00	100.00
	DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		480.00	250.00
	REMOVE DASHBOARD AND DAMAGED SRS COMPONENTS AND REPLACE WITH NEW.		680.00	350.00
	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES, REINITIALISE HV HYBRID SYSTEM AND PERFORM SRS FUNCTIONALITY CHECK.		480.00	120.00
	PUTTY AND SPRAY PAINT FRONT ACCIDENT DAMAGED AREAS.		1,300.00	1,000.00
	PUTTY AND SPRAY PAINT REAR ACCIDENT DAMAGED AREAS.		1,600.00	1,000.00
			-	-
			-	-
			-	-
			11,320.00	6,380.00

Report Ref No. CS/INC19004124/Jvd3e2



GRAND TOTAL		38,741.44	28,107.36
RECOMMENDED COST OF REPAIRS (CONFIRMED)			28,107.36

Report Ref No. CS/INC19004124/Jvd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.