



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Goh Choon Leng
100 Gerald Drive #04-88
Singapore 798592

Not Authorized
U/Sing B?
Resurvey After Paint
12days

Dear sir

Estimate cost of repair to vehicle no. SKT 6822U

To supply

1. Rear door right	R R	950.00	✓
2. Rear door inner lock	Red	285.00	✓?
3. Rear door protector	Red	98.00	✓
4. Rear fender	Blue	980.00	✓
5. Rear fender inner garish cover	Blue	220.00	✓
6. Tail boot cover	Red	860.00	✓
7. Tail boot hinge x2	ots R	160.00	✓
8. Tail boot inner lock	Red	245.00	✓
9. Tail boot outer switch	.	98.00	?
10. Tail boot logo	Red	52.00	✓
11. Tail boot badge Camry	Red	46.60	✓
12. Tail boot badge 2.4	Red	45.80	✓
13. Tail boot outer handle	CM	281.90	✓
14. Number plate lamp x2	ols cm	80.00	✓
15. Tail boot number plate garish	CM	280.00	✓
16. Tail boot reflector x2	ols cm	422.60	✓
17. Tail boot rubber	CM	198.00	506.00
18. Tail boot cable	Red	102.00	X
19. Tail boot inner cover garish	Red	260.00	X
20. Tail lamp x2	ols CM	872.40	✓
21. Tail lamp panel right	R	108.00	✓
22. Rear bumper	R	863.80	✓
23. Rear bumper reinforcement	R	369.40	✓
24. Rear bumper sensor	Red	350.00	200.00
25. Rear bumper retainer side x2	ols m	111.40	✓
26. Rear bumper retainer centre x2	ols cm	90.80	✓
27. Rear bumper sponge		168.70	?
28. Rear bumper reflector x2	ols cm	106.00	✓
29. Rear panel	R	515.80	✓
30. Rear panel top garish	Red	188.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



方 商 昭 噴 漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Pg2

31. Rear exhaust box		965.70	7
32. Spare tyre panel	Bz	990.00	✓
33. Spare tyre board		234.00	?
34. Rear chassis cross member		658.00	7
35. Rear bumper cover x2	old rd	75.60	4x
36. Rear w/s moulding	na	311.40	✓
37. Sealant	na	150.00	405m
38. Chip s x15	259 na	15.00	✓
Labour charges			
Rust proofing		100.00	✓
Panel beating		2,500.00	2000
Spray painting		1,500.00	1400
To remove and refit w/s glass and cushion		250.00	220

Total

Your faithfully

ALBERT POON