

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 23 Mar 2019

Preliminary Advice

Insured Vehicle No	: SGK9835H		
TP Vehicle No	: SKD6650H	Accident Date	: 04/03/2019
Make	: FIAT BRAVO	Assignment Date	: 06/03/2019
Date of Inspection	: 06/03/2019	Est. Duration of Repair	6 days
Inspection At	Carz Auto Services Pte Ltd (HQ) 1 KAKI BUKIT AVE 6 #02-35 AUTOBAY @ KAKI BUKIT Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear N/S... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,738.88
Revised Amount	:S\$	3,740.90
Check Items (Estimated)	:S\$	3,723.30
Total	:S\$	7,464.20

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.