

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0293/2019/KN
Date : 6-Mar-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Glenn Koh Si Jie
Address : 329 River Valley Road
#02-02
Singapore 238361
Telephone : 97561296
Type of Claim : Own Damage Claims
Policy No. : 2100491595-02
Vehicle No : **SLJ 2668 R**
Model Code : A4 SEDAN 1.4 TFSI
Model / Year : 28/11/2016
Engine No : CVN 023992
Chassis No : WAUZZZF40HA067048
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Mar-19
Place of Accident : GIVE WAY JUNCTION OPPOSITE JURONG HEALTH

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 2668 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper. Re-organize front crash management components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray front bumper. , Bonnet	\$ 1600 1100	
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLJ 2668 R**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER COVER <i>del</i>	\$ 1,946.00	✓
2	FIXING PARTS FOR FRONT BUMPER <i>new</i>	\$ 258.00	✗
3	SECURING STRIP <i>torn</i>	2 \$ 64.00	✓
4	CENTER GRILLE <i>crackd</i>	\$ 178.00	✓
5	CENTER GRILLE CLOSING ELEMENT ?	\$ 191.00	?
6	AIR GUIDE - LH <i>new</i>	\$ 56.00	✗
7	AIR GUIDE - RH	\$ 56.00	✗
8	RADIATOR GRILLE <i>crackd</i>	\$ 1,666.00	✓
9	AIR GUIDE GRILLE - LH <i>new</i>	\$ 333.00	✗
10	AI GUIDE GRILLE - RH	\$ 333.00	✗
11	FOAM FILLER PIECE ?	\$ 113.00	?
12	BUMPER CARRIER ?	\$ 733.00	?
13	BUMPER COVER <i>del</i>	\$ 116.00	✓
14	GUIDE SECTION - LH <i>new</i>	\$ 33.00	✗
15	GUIDE SECTION - RH	\$ 34.00	✗
16	CAUTION' SIGN <i>new</i>	\$ 13.00	✓
17	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 7.00	✓
18	BRACKET FOR LOCK CARRIER ?	\$ 125.00	?
19	SUPPORT FOR LOCK CARRIER - LH ?	\$ 26.00	?
20	SUPPORT FOR LOCK CARRIER - RH ?	\$ 26.00	?

SUB TOTAL SPARE PARTS: **\$ 6,307.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLJ 8668 R**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
21	AIR GUIDE - LH <i>green</i>	\$ 25.00	<i>+</i>
22	AIR GUIDE - RH	\$ 25.00	<i>+</i>
23	FRONT NUMBER PLATE <i>Best</i>	\$ 25.00	<i>✓</i>
24	SUNDRIES <i>?</i>	\$ 300.00	<i>?</i>
TOTAL SPARE PARTS		\$ 6,682.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 8,934.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim.
Surveyed Date : 07/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repair, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant