

1 FENDER, FRONT / CUT	1WD-XF151-30-P1	\$	245.30 185/
2 EMBLEM, YAMAHA / NEC	1WD-F153E-00	\$	15.00/
3 WINDSHIELD x NN	1WD-F8381-00	\$	185.30x
4 COVER, METER x NN	1WD-H3559-00	\$	96.30x
5 BODY, FRONT UPPER 1 x NN	1WD-F835G-00	\$	212.60x
6 BODY COWLING SUB ASSY H/upper cover /	1WD-XF83F-20-P1 CUT	\$	276.20/
7 REAR VIEW MIRROR ASSY (LEFT) /	1WD-F6280-10 CUT	\$	103.50 80/
8 REAR VIEW MIRROR ASSY (RIGHT) /	1WD-F6290-10 CUT	\$	103.50 80/
9 PANEL, INNER 4 LHCH/back side cover	1WD-F836N-00 CUT	\$	141.69/
10 PANEL, INNER 5 RH "	1WD-F836R-00 CUT	\$	141.69/
11 BODY, FR. UNDER 1 SUB ASSY LH /	1WD-XF83L-20-P1 B fairing CUT	\$	296.45 250/
12 BODY, FR. UNDER 2 SUB ASSY RH /	1WD-XF83M-20-P1 " CUT	\$	296.45 250/
13 PANEL 1 refer page 48 x NN	1WD-F835U-00-P0	\$	185.60x
14 PANEL 2 refer page 48 (LH) (RH) end CUT	1WD-F835V-00-P0 Fading small	\$	185.60/
15 COVER 7 refer page 48 (LH) BEL BR	1WD-XF11W-10-P0 Fading inner	\$	143.90/
16 FRONT FLASHER LIGHT ASSY 1 / LH	1WD-H3310-10 CUT	\$	95.00/
17 FRONT FLASHER LIGHT ASSY 2 / RH	1WD-H3320-10 BR	\$	95.00/
18 HEADLIGHT ASSY / CUT	1WD-H4300-00	\$	496.30 380/
19 LEVER 2 / RH BT	1WD-H3922-00	\$	45.00 30/
20 REAR FOOTREST ASSY 1 / gear	1WD-F7430-00 BR	\$	95.00/
(Inkton for Pt.) (gear)	TOTAL	\$	3,455.38
	-10%	\$	3,109.84

SPECIAL NETT ITEMS

1 REAR MUFFLER AKRA FULL SYSTEM / DO	\$	2,000.00 1300/
2 STICKERS / NEC	\$	50.00 /
3 FRONT SIDE STAND (SET) / Engine Supp (LH) BT	\$	75.00 /
4 REAR SIDE STAND (SET) / Slip supd RH rear CUT	\$	75.00 /

LABOUR

1 TO RENEW, REMOVE AND REFIT ACCIDENT DAMAGED PARTS	\$	500.00 250
2 TO SPRAY PAINTING	\$	600.00 200
3 TO CHECK WIRING	\$	50.00 20
4 TO REMOVE AND REPAIR FORK ASSY	\$	400.00 100 200
5 TOWING CHARGES (1 x \$30) max 2 trips.	\$	60/ 250.00 30?

GOLD AUTOWORKS PTE LTD

48, TOH GUAN RD EAST, ENTERPRISE HUB #01-119 S(608586)

TEL: 62640995 HP: 81999149 Claims@goldautoworks.com.sg

Simon

VEHICLE NO: JSM4318 MODEL: YAMAHA R-25

CHASSIS NO: PMYRG1510H0012268/G401E-0075863

Simon
13/3/19

Steno (LKK) with Prevalve
8322 8813
11/3/19 5-45 pm
3 days
L/S
R- AF spray

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: