

ASS. REC. BY:

REF: 05/07119004259/Rmd307

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Merimen

From (Person): Cheryl Boon Sen of CTI Date/Time: 02/13/19

Estimate # Cont: Bill to:

OD/IT/AWS/IT RES / OD RES / EYA / INV / MYTCS

To inspect Vehicle No. GBE 3828J Insured:

at Workshop n/a: Sng Ah Tee Tel: 6268 6183

of 171K 3 Pioneer Rd North #01-18

Policy No: DACVSN 3079271803 Claim No:

Sum Insured: Amount: 500

Make of Vch: D.O.A. 02/13/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: Person Contacted: Vehicle: INT/DIT

Date/Time	Action/Instruction () Estimate
	GBE 3828J
11/3/19	Revert via merimen
12/3/19	Rece approved \$3055 from Elaine via merimen
12/3/19	Informed Sharon / Janice c/A ex \$500 by email
25/7/19	@ 215pm Sharon will email us finalised

From: *John*

REF:

CT

2142W

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *GBE 3828J*

at Workshop m/s: *Sky Air Re*

at

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

49K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / *REV* / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBE 3828J

Yr Regn: *2015 / NOV*

Type: M.Car / M.Cycle / Bus / Van / *Cony* / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA DYNA 3.0M

2982

Colour:

WHITE

AC Insured / Std / NI / NA

Sp. Reading:

82169

T/Radio: Insured / Std / NI / NA

Eng/No:

C/Nr:

K04 2318021241

Gen. Cond: Good / *Fair* / Poor / Burnt

Steering: *Order* / Jammed / Leaked / Burnt or

Brake: *Order* / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15C

R:

165 R13C

BS / DUN / EXNOVA / GY / FS / LIZA / *MC* / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

6/6

mm

L/Bal:

7

mm

L/Bal:

6/6

mm

D.O.A:

02/03/19

D.O.I:

08/03/19

Survey held at

Sky Air Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

6/1 R/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/7/19

Final fig \$2185 (Rad 1540, 41/0) (No IS)

RECEIVED 30 JUL 2019

[Signature]

30/7/2019

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

30/7- typist

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

1. S + PS: \$

1. Photo:

1. Other:

1. Other:

1. Other:

Add Fee:



Site Insp: \$



Interview: \$



Tech. Inv: \$



Week-end: \$

Report Format:

merimen

Lump Sum / I.B.I: \$

2185

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Received	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2019 Sendback Est	06 Mar 2019 14:37 S\$3,640.00	07 Mar 2019 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	MEYER HOUSEWARE (SINGAPORE) PTE LTD, Co. Reg. No.: 199402142W		
Vehicle Reg. No.:	GBE3828J	Date of Loss:	02/03/2019 16:00 - :59 [39 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / GBE3828J	Policy/Cover Note No.:	DMCVSN3079271803 (Comprehensive) Coverage: 11/11/2018 - 10/11/2019
		Excess:	S\$500.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/03/2019]		
Driver/Custodian:	CHAN GEEN WAI (56 / Male), NRIC: S1601726D, Tel: +6594488833 Email: NOEMAIL		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

in

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 12 March 2019 12:09 PM
To: 'Sharon Sng'; Janice Chang (janice@sngahtee.com); SUR
Subject: GBE 3828J-DOA: 2/3/2019 (CHINA TAIPING OD)

Dear Sharon/Janice,

As instructed by our client , please proceed to repair the **insured vehicle GBE 3828J (Excess S500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

GBE3828J (SNM19D201046C01)

OD

Mar 2 2019 4:00PM

[MEYER HOUSEWARE (SINGAPORE) PTE LTD]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 12/03/2019 11:20 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3055.00) - GBE3828J - Claim Handler: Chong Boon Sen

Approved:3055.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Chong Boon Sen	Date:	11 Mar 2019
Preliminary Advice			

Vehicle No	: GBE3828J	Accident Date	: 02/03/2019
Make	: TOYOTA DYNA	Policy No.	: DMCVSN3079271803
Assignment Date	: 07/03/2019	Excess	: S\$500.00
Date of Inspection	: 08/03/2019	Est. Duration of Repair	: 6.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,640.00
Revised Amount	:S\$	3,000.00
Check Items (Estimated)	:S\$	55.00
Total	:S\$	3,055.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	14,948.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,052.00

Brake System : In Order
Steering System : In Order
Tyre Condition (Front) : 7/7 mm
Tyre Condition (Rear) : 6/6 (D)

Remarks

☒ (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ (X) Other comments : Vehicle repair on part by part.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 2142W

Vehicle Details

Vehicle No.: GBE3828J
Vehicle to be Exported: No
Intended Deregistration Date: 06 Mar 2019
Vehicle Make: TOYOTA
Vehicle Model: DYNA 3.0 M
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 1KD2549523
Chassis No.: KDY2318021241
Maximum Power Output: -
Open Market Value: \$29,469.00
Original Registration Date: 11 Nov 2015
First Registration Date: 11 Nov 2015
Transfer Count: 0
Actual ARF Paid: \$1,474.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Nov 2025
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$22,385.00
COE Rebate Amount: \$14,948.00
Total Rebate Amount: \$14,948.00

The information contained herein is correct as at 04 Mar 2019.

OK

49,000
14,948

34,052

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/03/2019 11:04
Date Of Accident	02/03/2019 16:25
Exact Location Of Accident	DEFU LANE 1 & DEFU AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE3828J
Insured/Policyholder	
Name Of Registered Owner	MEYER HOUSEWARE (SINGAPORE) PTE LTD
Co Reg No	199402142W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64678108

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? ☒ YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3079271803
Cover Note Number	

Driver

Name of Driver	CHAN GEEN WAI
NRIC No	S1601726D
Date Of Birth	06/01/1963
Occupation	OUTDOOR
Date Of Driving Pass	21/05/1984
Driving Experience	34 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94488833
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	172A LORONG 1 TOA PAYOH #02-1162
Postcode	311172
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO: T/20190302/2137

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK7169B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN DRIVER

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLK7169B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



(A) 6BE382FJ

(B) 2K7169B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report No.: T20190302/2137

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other works hop
☐ For record purpose

Policy No. 0MVCUS32A271873
Insurer China Veh. No. 6BE382FJ

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190302/2137

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190302/2137

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/03/2019 19:14	Vide Report No.: F/20190302/0141	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: CHAN GEEN WAI			Address: APT BLK 172A LORONG 1 TOA PAYOH #02-1162 SINGAPORE 311172	
ID Type / ID No.: NRIC NO / S1601726D			Contact No.: Home/Office: Mobile: 94488833	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 56	Date of Birth: 06/01/1963	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/03/2019 16:25	Type of Location: Straight Road
Location: Along Road 1 DEFU LANE 1 DEFU LANE 1 AND DEFU AVE 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE3828J	Lorry				Slightly Damaged	0
SLK7169B	Car					1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE
POLICE FORCE



T/20190302/2137

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190302/2137

CONTINUATION OF REPORT

Driver			
Name	CHAN GEEN WAI		ID No. S1601728D
Related Vehicle	GBE3828J (Lorry)		Contact No. 94488833
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 02/03/2019 at about 1625hrs, I was travelling along Defu Lane going straight towards Defu Lane 1. I stopped at the stop line and make sure that the traffic is clear. I had check and the traffic clear I started to move off. When I was in the middle of the road, out of a sudden one vehicle come from my right hit on to the middle of my vehicle.

I alighted from my vehicle and the driver that hit me complain of giddy. I called for ambulance and shortly traffic police arrive. My vehicle in car camera was spoilt therefore did not capture anything. I was issue with a case card and told to make a police report.



SINGAPORE
POLICE FORCE



T/20190302/2137

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190302/2137

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E/

Sgt 2 LIM JIAN HONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

02/03/2019 19:14

Officer In Charge Of Case:

TP/GIT/ 10 11011

Classification Of Case:

Contact No.: 65476131

Authentication Stamp
NP168



SINGAPORE
POLICE FORCE

SN 168

SIGNATURE

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No 200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3079271803	Date of Loss:	02/03/2019
Vehicle Reg. No.:	GBE3828J	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	MEYER HOUSEWARE (SINGAPORE) PTE LTD		
Driver:	CHAN GEEN WAI		

Make/Model:	TOYOTA DYNA, 3.0 D (M)	Vehicle Reg. Date:	11/11/2015
Vehicle Colour:	WHITE		
Engine No:	1KD2549523	Chassis No:	KDY2318021241
Odometer:	5 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Description of Accident/Loss	AS PER POLICE REPORT NO: T/20190302/2137
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	2,090.00
Miscellaneous Items	0.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00
	3705
Gross Total (S\$)	3,640.00
+ GST 7.00% (S\$)	254.80
Nett Amount (S\$)	3,894.80

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Mar 2019)
Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBE3828J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT TYRE MUDGUARD RH <i>DE</i>	0.00	0.00	*170.00 F <i>50</i>
2	1		*FRT TYRE MUDFLAP RH <i>BE</i>	0.00	0.00	*120.00 F <i>70</i>
3	1		*FRT TYRE MUDGUARD BRACKET RH <i>DIS</i> <i>X SVC</i>	0.00	0.00	*55.00 F
4	1		*FRT AIR INTAKE DUCT <i>DE</i> <i>X SVC</i>	0.00	0.00	*75.00 F
5	1		*FRT AIR INTAKE JOINT <i>Red</i>	0.00	0.00	*75.00 F <i>50</i>
6	1		*FRT AIR INTAKE CLEANER BOX <i>Pro</i>	0.00	0.00	*340.00 F <i>280</i>
7	1		*FRT AIR INTAKE FILTER <i>RA</i> <i>X SVC</i>	0.00	0.00	*35.00 F
8	1		*DIESEL TANK <i>RA</i> <i>2A-7A/RH-RA</i>	0.00	0.00	*450.00 F <i>450</i>
9	2		*DIESEL TANK BRACKET	0.00	0.00	*110.00 F <i>55</i>
10	<i>1 pc</i>		*DIESEL TANK HOLDER <i>RA</i> <i>SS</i>	0.00	0.00	*110.00 F <i>75</i>
11	<i>1 pc</i>		*DIESEL TANK RUBBER <i>RA</i> <i>X SVC</i>	0.00	0.00	*100.00 F
12	1		*REAR BOX SLIDING DOOR LOWER PANEL <i>RA</i> <i>X SVC</i>	0	0.00	*450.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

2,090.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK,WELD FRT DOOR PILLAR RH,RR BOX STEP (SIDE) RH,REMOVE & FIX ON ABOVE PARTS	New	600 850.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	350 500.00
3	TO REMOVE & FIX DIESEL TANK	New	120 200.00
Gross Labour Cost (\$\$)			1,550.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FASUL

HP 90010068

6 days

P/P

[Signature]
12/3/19

EXCER: SUV

REGR

08/03/19 P1650

Reswry before paint

UK Auto Consultants hence notify
the Repairer of the following:

- To recover *[initials]* after spray painting
- To display damaged part(s) during recovery
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- If a legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Mar 2019)
 Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for GBE3828J)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT TYRE MUDGUARD RH <i>DE/</i>	0.00	0.00	*170.00 F <i>\$50</i>
2	1		*FRT TYRE MUDFLAP RH <i>DE/</i>	0.00	0.00	*120.00 F <i>\$70</i>
3	1		*FRT TYRE MUDGUARD BRACKET RH <i>BIS/</i>	0.00	0.00	*55.00 F
4	1		*FRT AIR INTAKE DUCT <i>DE/</i>	0.00	0.00	*75.00 F
5	1		*FRT AIR INTAKE JOINT <i>DE/</i>	0.00	0.00	*75.00 F <i>\$50</i>
6	1		*FRT AIR INTAKE CLEANER BOX <i>PRE/</i>	0.00	0.00	*340.00 F <i>\$280</i>
7	1		*FRT AIR INTAKE FILTER <i>RI/</i>	0.00	0.00	*35.00 F
8	1		*DIESEL TANK <i>BI/</i> <i>LH-7. / RH-RA/</i>	0.00	0.00	*450.00 F
9	2		*DIESEL TANK BRACKET	0.00	0.00	*110.00 F <i>\$50</i>
10	<i>1 pc</i>		*DIESEL TANK HOLDER <i>BI/</i>	0.00	0.00	*110.00 F <i>\$50</i>
11	<i>1 pc</i>		*DIESEL TANK RUBBER <i>REC/</i>	0.00	0.00	*100.00 F <i>\$50</i>
12	1		*REAR BOX SLIDING DOOR LOWER PANEL <i>RA/</i>	0	0.00	*450.00 F <i>\$50</i>

F=Franchise part, S=SpccNett.

Total Parts (\$\$) *4115* 2,090.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

* *Supplementary*
 ① Bumper Gate Rubber - \$15/-
 ② coolant Tank - \$70/-

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK,WELD FRT DOOR PILLAR RH,RR BOX STEP (SIDE) RH,REMOVE & FIX ON ABOVE PARTS	New	600 850.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	350 500.00
3	TO REMOVE & FIX DIESEL TANK	New	120 200.00
Gross Labour Cost (\$5)			\$1070 1,550.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$ 7185

before exam \$500
ok? 16/10/19
Sham 21/11/2019

RASUL

HP 90010068

6 days

P/P

EXCESS: 500

RECEIPT

08/03/19 P1650

Resurvey before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 29 Jul 2019)
Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3828J/29/07/2019 17:43
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Supplementary

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BUMPER GATE RUBBER <i>is rec</i>	0.00	0.00	*15.00 F
2	1		*COOLANT TANK <i>70 de</i>	0.00	0.00	*70.00 F
Total Parts (S\$)						85.00

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3828J/29/07/2019 17:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3828J/29/07/2019 17:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : SHARON / JOYCE/JANICE/ SAMANTHA

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9530

Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201903-06271
DATE : 13/03/2019
CUSTOMER ID : SNG001
VEH REG. NO. : GBE3828J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID

DESCRIPTION

StkLoc

QTY

U/PRICE

AMOUNT

T77601-25120
KDY231BAND SUB ASSY
Pisef tatic holder.U1
SUPPLIER

1

75.00

75.00

SUB-TOTAL : 75.00

ADD GST 7.00 % 5.25

E. & O.E

TOTAL AMOUNT SGD : 80.25

[P] 13/03/2019 11:57:00AM

[E] 13/03/2019 11:56:37AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



* AR201903-06271 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
S'PORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : SHARON / JOYCE/JANICE/ SAMANTHA

WIPER BLADES (S) SGT
Dept Direct: 6417 9791 / 6745 9891



Dept Direct: 6200 3610

Dept Direct: 6200 3611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blades, Silper (Made in Korea),
Forch (Made in Germany))

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201903-06308
DATE : 13/03/2019
CUSTOMER ID : SNG001
VEH REG. NO. : GBE3828J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID

1 T53715-25020

KDY231

DESCRIPTION

FRT MUDFLAP RH

StkLoc

UI

SUPPLIER

QTY

1

U/PRICE

70.00

AMOUNT

70.00

SUB-TOTAL : 70.00

ADD GST 7.00 % 4.90

E. & O.E

TOTAL AMOUNT SGD : 74.90

[P] 13/03/2019 12:47:06PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 13/03/2019 12:42:44PM

JAE Auto Pte. Ltd.

Sales Executive : JASON



* A R 2 0 1 9 0 3 - 0 6 3 0 8 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 0291 / 6746 0500



Dept Direct: 6201 0610

Dept Direct: 6205 9611

Dept Direct: 6417 0192



Dept Direct: 6417 0794

Dept Direct: 6417 0795

Dept Direct: 6417 0796

Dept Direct: 6417 0797

Wiper blade: NWB (Nippon Wiper blades), Silber (Made in Korea),
Forch (Made in Germany),
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : SHARON / JOYCE/JANICE/ SAMANTHA

TAX INVOICE : AR201903-08292
DATE : 18/03/2019
CUSTOMER ID : SNG001
VEH REG. NO. : GBE3828J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T16470-54410 LY235 DYNA '02	RAD TANK	CC CC12-O-10A2	1	70.00	70.00
2. T52811-25030 KDY231	AIR DUCT	CC CC12-O-05A3	1	50.00	50.00

SUB-TOTAL : 120.00
ADD GST 7.00 % 8.40

E. & OE TOTAL AMOUNT SGD : 128.40

[P] 18/03/2019 9:43:24AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 18/03/2019 9:31:10AM

JAE Auto Pte. Ltd.

Sales Executive : JASON

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6745 9931



Dept Direct: 6208 9010

Dept Direct: 6208 9811

Dept Direct: 6417 8730



Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : SHARON / JOYCE/JANICE/ SAMANTHA

TAX INVOICE : AR201903-08306
DATE : 18/03/2019
CUSTOMER ID : SNG001
VEH REG. NO. : GBE3828J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	166331-95010 KDY231	BUMPER,GATE RUBBER (FRT)	PA PL2-K1-09V	1	15.00	15.00

SUB-TOTAL : 15.00
ADD GST 7.00 % 1.05

E. & O.E TOTAL AMOUNT SGD : 16.05

[P] 18/03/2019 5:56:29PM

[E] 18/03/2019 9:39:43AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
S'PORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : SHARON / JOYCE/JANICE/ SAMANTHA

WIPACORIN GLASS
Dept Direct: 6417 9791 / 6745 9426



Dept Direct: 6205 9610

Dept Direct: 6205 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9791

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade, Sliper I Made in Korea).
Forch (Made in Germany)

Spark plug: Nippon, Denso, NGK (Made in Japan)

TAX INVOICE : AR201903-06243
DATE : 13/03/2019
CUSTOMER ID : SNG001
VEH REG. NO. : GBE3828J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID

1. T7700/-25441

KDY231

DESCRIPTION

FUEL TANK

StkLoc

U1

SUPPLIER

QTY

1

U/PRICE

450.00

AMOUNT

450.00

SUB-TOTAL : 450.00

ADD GST 7.00 % 31.50

E & OE

TOTAL AMOUNT SGD : 481.50

[P] 13/03/2019 11:42:13AM

[E] 13/03/2019 11:30:35AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



* A R 2 0 1 9 0 3 - 0 6 2 4 3 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jeeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 9745 9020



Dept Direct: 6417 9790

Dept Direct: 6417 9790

Dept Direct: 6417 9790

Dept Direct: 6417 9790

Wiper blade: NNB (Nippon Wiper blades, Silper (Made in Korea))

Ford (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 03 #01-18 PIONEER ROAD NOR

SPORE 628457

CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : SHARON / JOYCE/JANICE/ SAMANTHA

TAX INVOICE : AR201903-06232

DATE : 13/03/2019

CUSTOMER ID : SNG001

VEH REG. NO. : GBE3828J

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1.	T53881-25030 LY235	MUDGUARD R+L	CC CC12-O-01B8	1	50.00	50.00
2.	T77501-25160 KDY231	BRACKET SUB ASSY Disc disk bracket	CC CC12-I-10B	1	55.00	55.00

SUB-TOTAL : 105.00

ADD GST 7.00 % 7.35

E. & O.E

TOTAL AMOUNT SGD : 112.35

[P] 13/03/2019 12:47:18PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 13/03/2019 11:25:13AM

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 8791 / 6745 9626



Dept Direct: 6417 8796

Dept Direct: 6417 8796

Dept Direct: 6417 8796

Dept Direct: 6417 8796

Wiper blade: NWB (Nippon Wiper blades, Silber (Made in Korea))

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 03 #01-18 PIONEER ROAD NOR

SPORE 628457

CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : SHARON / JOYCE/JANICE/ SAMANTHA

TAX INVOICE : AR201903-06233

DATE : 13/03/2019

CUSTOMER ID : SNG001

VEH REG. NO. : GBE3828J

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T17700-30241 KDY231	AIR CLEANER ASSY	PA PL2-M1-100	1	280.00	280.00

SUB-TOTAL : 280.00

ADD GST 7.00 % 19.60

E & O E

TOTAL AMOUNT SGD : 299.60

[P] 13/03/2019 12:43:38PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 13/03/2019 11:25:21AM

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 30 July 2019 2:06 PM
To: Sharon Sng; Rasul (LKKAuto); SUR
Subject: RE: GBE3828J - BEFORE PAINT & ITEMS

Dear Sharon,

Confirmed final amount \$2185 before excess \$500

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Tuesday, 30 July 2019 10:46 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: GBE3828J - BEFORE PAINT & ITEMS

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2019 Sendback Est	06 Mar 2019 14:37 S\$3,640.00	07 Mar 2019 16:35 Edit Adj Rpt	S\$2,185.00 Edit Estimates	S\$2,185.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	29 Jul 2019 17:43	29 Jul 2019 17:43 S\$85.00	29 Jul 2019 17:43			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	MEYER HOUSEWARE (SINGAPORE) PTE LTD , Co. Reg. No.: 199402142W								
Vehicle Reg. No.:	GBE3828J	Date of Loss:	02/03/2019 16:00 - :59 [39 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D201046C01	Policy/Cover Note No.:	DMCVSN3079271803 (Comprehensive) Coverage: 11/11/2018 - 10/11/2019						
		Excess:	S\$500.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/03/2019]								
Driver/Custodian:	CHAN GEEN WAI (56 / Male), NRIC: S1601726D, Tel: +6594488833 Email: NOEMAIL								
Adj Asg. Remarks:	SURVEY REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (12/03/2019): Alert - Adj Mandate Approved (S\$3055.00) - GBE3828J - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBE3828J (SNM19D201046C01)
 OD
 Mar 2 2019 4:00PM
 [MEYER HOUSEWARE (SINGAPORE) PTE LTD]
 Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	04/03/19 16:58	Accident Statement		Load HTM	
2	06/03/19 14:37	Repairer Estimates		Load HTM	
3	29/07/19 17:43	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 14:14	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	04/03/19 16:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 14:15	General View		Load PDF	
2	30/07/19 11:03	Reinspection Photo		Load PDF	
Documentation				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	04/03/19 16:57	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	04/03/19 16:58	POLICE REPORT [Linked Accident Report Documents]		Load TIF	
3	04/03/19 16:58	CI,IC,DL [Linked Accident Report Documents]		Load TIF	
4	06/03/19 14:37	E-filed GIA report		Load PDF	
5	29/07/19 17:54	Copy of Supplier's Invoice		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 14:15	MARK ESTIMATE		Load PDF	
2	08/08/19 17:08	Parts Invoice		Load PDF	
3	08/08/19 17:08	Supplementary		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	04/03/19 16:58	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	04/03/19 16:50	Accident Photo	Load JPG	☒
2	04/03/19 16:50	Accident Photo	Load JPG	☒
3	04/03/19 16:50	Accident Photo	Load JPG	☒
4	04/03/19 16:50	Accident Photo	Load JPG	☒
5	04/03/19 16:50	Accident Photo	Load JPG	☒
6	04/03/19 16:50	Accident Photo	Load JPG	☒
7	04/03/19 16:50	Accident Photo	Load JPG	☒
8	04/03/19 16:50	Accident Photo	Load JPG	☒
9	04/03/19 16:50	Accident Photo	Load JPG	☒
10	04/03/19 16:50	Accident Photo	Load JPG	☒
11	04/03/19 16:50	Accident Photo	Load JPG	☒
12	04/03/19 16:50	Accident Photo	Load JPG	☒
13	04/03/19 16:50	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	04/03/19 16:57	Sketch Plan	Load TIF	
2	04/03/19 16:58	POLICE REPORT	Load TIF	
3	04/03/19 16:58	CI,IC,DL	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19004259/R1VD3E2

Date: 13/08/2019

REFERENCE

Insured/Claimant: MEYER HOUSEWARE (SINGAPORE) PTE LTD Policy No: DMCVSN3079271803
Date of Loss: 02/03/2019 Nature of Claim: OD Claim No: SNM19D201046C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE3828J Engine No: 1KD2549523
Make & Model: TOYOTA DYNA, 3.0 D (M) Chassis No: KDY2318021241
Reg. Date: 11/11/2015 (Man. Year: 2015) Odometer: 87769 km
Colour: White
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$49,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 165 R13C (D)
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 6/6 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,175.00	1,115.00	1,060.00	48.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,070.00	480.00	30.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,725.00	2,185.00	1,540.00	41.34
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	3,725.00	1,685.00	2,040.00	54.77
+ GST 7.00/7.00% (S\$)	260.75	117.95	142.80	54.77
Nett Amount (S\$)	3,985.75	1,802.95	2,182.80	54.77

INSPECTION

Date of Assignment: 07/03/2019 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected: 08/03/2019 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457
Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Aug 2019)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE3828.J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT TYRE MUDGUARD RH	Deformed	170.00 F	*50.00 F
2	1		*FRT TYRE MUDFLAP RH	Deformed	120.00 F	*70.00 F
3	1		*FRT TYRE MUDGUARD BRACKET RH	Serviceable	55.00 F	*- F
4	1		*FRT AIR INTAKE DUCT	Serviceable	75.00 F	*- F
5	1		*FRT AIR INTAKE JOINT	Cut	75.00 F	*50.00 F
6	1		*FRT AIR INTAKE CLEANER BOX	Broken	340.00 F	*280.00 F
7	1		*FRT AIR INTAKE FILTER	Serviceable	35.00 F	*- F
8	1		*DIESEL TANK	Bent	450.00 F	*450.00 F
9	1		*DIESEL TANK BRACKET	N/S Serviceable / O/S Bent	110.00 F	*55.00 F
10	1		*DIESEL TANK HOLDER (2PCS)	Bent-1pc only	110.00 F	*75.00 F
11	2		*DIESEL TANK RUBBER	Serviceable	100.00 F	*- F
12	1		*REAR BOX SLIDING DOOR LOWER PANEL	Serviceable	450.00 FS	*- FS
Supplementary #1						
13	1		*BUMPER GATE RUBBER	Necessary	15.00 F	*15.00 F
14	1		*COOLANT TANK	Deformed	70.00 F	*70.00 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,175.00** **1,115.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD FRT DOOR PILLAR RH,RR BOX STEP (SIDE) RH,REMOVE & FIX ON ABOVE PARTS	New	850.00	800.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	500.00	350.00
3	TO REMOVE & FIX DIESEL TANK	New	200.00	120.00
Gross Labour Cost (\$\$)			1,550.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >