# **MOVA Automotive Pte Ltd** Blk 1008, Bukit Merah Lane 3, #01-04/06/08. Singapore 159722

Claim Reference:

Assessment number: ck134276

Version: 1810

Date calculated: 03/08/2019 10:06 AM

**Full Report** Registration: SMJ2599U Printed: 08/03/2019 10:06 AM

### **Summary Information**

#### Claim

Location:

Printed by: Claim Reference:

Estimated Repair Time: Actual Repair Days:

GOH CHAI HOCK

Singapore (SG)

Work Provider: Currency: Date of Incident:

Hire Car Start: Hire Car End:

AXA Insurance Pte Ltd

SGD

2019-03-05

### **Vehicle Details**

#### Vehicle

Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration: VIN number:

Odometer:

**HYUNDAI** AVANTE (HD) **BASIS** 

30 22 50 SMJ2599U

## **Vehicle Condition**


#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

#### **Damage Areas**

All

Underbody



# MOVA Automotive Pte Ltd Blk 1008, Bukit Merah Lane 3, #01-04/06/08. Singapore 159722

Claim Reference:

Assessment number: ck134276

Version: 1810

Date calculated: 03/08/2019 10:06 AM

Full Report Registration: SMJ2599U Printed: 08/03/2019 10:06 AM

| Labour       | Time Base 10 W  | U/h         | Pric              | e = 45. | 00 SGD/h       |
|--------------|---|-------------|-------------------|---------|----------------|
| Code         | Description   | o,          |                   |         | Price SGD      |
| 86512R00     | RENEW FRONT BUMPER INCLUDES: BUMPER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: REINFORCEMENT BUMPER REMOVE AND REFIT |             |                   | 8.0     | 36.00          |
| 0561         | LEFT HEADLAMP ASSY CHECK  |             |                   |         |                |
|              | Labour Cost   |             | Hrs               | wu      |                |
|              | Panel / Mechanical Labour   |             | 0.80              | 8.0     | 36.00          |
|              | Total of Labour   |             |                   |         | 36.00          |
| Paint        |   |             |                   |         |                |
| Paint Work   | SYSTEM AZT  |             | Time Basis 10WU/h |         |                |
| Code         | Description   |             |                   | wu      | Price SGD      |
|              | FRONT BUMPER NEW PART PAINT K1R   |             |                   | 9,0     |                |
| Paint Materi | al Per Part   |             |                   |         |                |
| Code         | Description   |             |                   |         | Price SGD      |
| 0283         | FRONT BUMPER NEW PART PAINT K1R   |             |                   |         | 33.50          |
|              |   |             |                   |         |                |
|              | Labour Cost - Paint<br>Factor   | 45.00 SGD/h | Hrs               | WU      | Price SGD      |
|              | Time Paint  |             |                   | 9.0     |                |
|              | Preparation Comp. Work Plastic  |             | 0.70              | 7.0     | 31.50          |
|              | Total   | 10 WU/h     | 1.60              | 16.0    | 72.00          |
|              | *   |             |                   |         |                |
|              | Material Cost - Paint   |             |                   |         | Price SGD      |
|              | New Part Painting - Plastic K1R   |             |                   |         | 33.50          |
|              | Material-constant Plastic <b>Total</b>  |             |                   |         | 16.20<br>49.70 |
| Spare Par    | ts  |             |                   |         |                |