COMFORTDELGRO ENGINEERING PTE LTD **REPAIR ESTIMATE***

VEHICLE NO: SH 8372G

MAKE

China Taiping-LIS

DATE 7/3/2019

LKK-Kalvin.

Qty	: MERCEDES BENZ Parts Description/ Labour	Type	Unit Price		Amount
	Rear Bumper			\$	1,510.00
	Rear Bumper Retainer Mounting (LH) Rear Tyre Rim (LH) hourd			\$	115.00
	Rear Tyre Rim (LH) - horand			\$	1,250.00
	Rear Westlake Tyre LH x > 2				480 1
	SUB TOTAL			\$	2,875.00
	LESS 20%			\$	575.00
	DISCOUNTED TOTAL			\$	2,300.00
	DISCOUNTED TOTAL			9	2,300.00
		`			
	Labour Charge				11
	Panel Beating-Repair Rear LH Fender			\$	500.00
	Spray Painting Charge			\$	600.00
	Wiring Charge			\$	50.00
	Tuff Kote	-		\$	50.00
	Remove/Refix Reverse Sensor			\$	120.00
	Rear Wheel Alignment			\$	120.00
	Rear wheel Anglillient			D.	140.00
	TOTAL LABOUR			\$	1,440.00
	ESTIMATE TOTAL			\$	3,740.00
	7/3/19 12 45 hs med bedy sur	me following a great part of the following and part of the month of the following and the month of the month	g: einting ng resurvey rmation out Prejudice" basis		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.