

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 7 March, 2019 6:25 PM
To: rozi@bcclaw.com.sg; Admin-D (LKKAuto)
Cc: Admin A
Subject: RE: Our Ref : BCC.rz.11441.1218.N.DCPI - ACCIDENT INVOLVING FBC 8027G & SHC 8745X ALONG PIE ON 21.9.18

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Hi Team,

For your necessary action please,

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rozi <rozi@bcclaw.com.sg>
Sent: Thursday, 7 March, 2019 4:56 PM
To: Admin A <admin-a@lkkauto.com>
Subject: Our Ref : BCC.rz.11441.1218.N.DCPI - ACCIDENT INVOLVING FBC 8027G & SHC 8745X ALONG PIE ON 21.9.18

Dear Sirs,

We write to confirm the re-inspection of our client's vehicle FBC 8027G as follows :-

Date: 12 March 2019 (Tuesday)
Time: 1.00 pm
Venue: 2 Kaki Bukit Ave 2
#01-18 Kaki Bukit Autohub
Singapore 417921

Please confirm as soon as possible the above arrangement is agreeable and advise the name of your surveyor who will be attending the re-inspection. Please attend without fail.

Regards

Rozi

BENEDICT CHAN & COMPANY

14 Fort Road

Singapore 439075
Tel : 6220 6088 Fax : 6220 6087



Virus-free. www.avast.com

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 7 March, 2019 6:39 PM
To: Admin-D (LKKAuto)
Cc: Admin A
Subject: FW: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Hi

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Manivel Priyadarshini <manivel@iii.com.sg>
Sent: Thursday, 7 March, 2019 3:22 PM
To: 'Rozi' <rozi@bcclaw.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Without Prejudice – Save as to Cost

Dear Rozi,

We refer to the letter dated 06.03.19,

We are agreeable to the proposed downtime fee at \$50.00, Please provide the appointment date for the re-inspection to our surveyor (Admin A <admin-a@lkkauto.com>).

Thank You

With Regard's

Priya Manivel

Motor Claims Department

India International Insurance Pte Ltd

From: Rozi [<mailto:rozi@bcclaw.com.sg>]
Sent: Wednesday, 6 March, 2019 2:26 PM
To: Manivel Priyadarshini
Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee
Importance: High

Dear Sirs,

Please see our enclosed reply.

Regards

Rozi

BENEDICT CHAN & COMPANY

14 Fort Road

Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

From: Manivel Priyadarshini [mailto:manivel@iii.com.sg]

Sent: Thursday, 28 February, 2019 9:51 AM

To: 'Rozi'

Cc: Admin A

Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Without Prejudice – Save as to Cost

Dear Rozi,

We refer to the letter dated 26.02.19,

Since the re-appraisal report and your counter proposal had a difference in COR , So we request to arrange physical re-inspection for your client Veh no: **FBC8027G** Please provide the appointment date for the re-inspection to our surveyor (Admin A <admin-a@lkkauto.com>).

In meanwhile we maintain our offer as per our email dated 23.01.19.

Thank You

With regards

Priya Manivel

Motor Claims Department

India International Insurance Pte Ltd

Tel : 63476100, Ext-284

Email : manivel@iii.com.sg

From: Rozi [mailto:rozi@bcclaw.com.sg]

Sent: Tuesday, 26 February, 2019 3:05 PM

To: Manivel Priyadarshini

Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Dear Sirs,

Please see our enclosed reply.

Regards

Rozi

BENEDICT CHAN & COMPANY

14 Fort Road

Singapore 439075

From: Manivel Priyadarshini [<mailto:manivel@iii.com.sg>]

Sent: Wednesday, 23 January, 2019 2:36 PM

To: 'Rozi'

Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Without Prejudice – Save as to Cost

Dear Rozi,

We refer to the above matter.

According to the re-appraisal report the cost of repair is \$2,400.00 only , more than 13 items was not recommended by our surveyor.

Strictly without any admission of liability, We are revising our offers to global lump sum S\$4,500.00 (all in) to wrap up this matter.

Thank You

With regards

Priya Manivel

Motor Claims Department

India International Insurance Pte Ltd

Tel : 63476100, Ext-284

Email : manivel@iii.com.sg

From: Rozi [<mailto:rozi@bcclaw.com.sg>]

Sent: Tuesday, 22 January, 2019 11:49 AM

To: Manivel Priyadarshini

Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Dear Sirs,

Please see our enclosed reply.

Regards

Rozi

BENEDICT CHAN & COMPANY

14 Fort Road

Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

From: Manivel Priyadarshini [<mailto:manivel@iii.com.sg>]

Sent: Tuesday, 8 January, 2019 5:32 PM

To: 'Rozi'

Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Involving SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Without Prejudice Save as to Cost

Dear Rozi,

We refer to your below email,

We had conducted paper survey for your client vehicle FBC8027G. Herewith enclosed re-appraisal report for your perusal.

Strictly without any admission of liability, we are offering settlement as follows:

| | | |
|----------------------------------|------------|-----------------|
| Cost of Repair | - \$ | 2,400.00 |
| Loss of Use | - \$ | 210.00 |
| Pre-Repair Inspection | - \$ | 100.00 |
| LTA /GIA fees | - \$ | 36.49 |
| Towing Fee | -\$ | 90.00 |
| Survey report | - \$ | 642.00 |
| <u>Cost Inclusive of Disburs</u> | <u>-\$</u> | <u>400.00</u> |
| Total | -\$ | 3,878.49 |

Please confirm acceptance .

Thank You
With Regard's
Priya Manivel
Motor Claims Department
India International Insurance Pte Ltd
Tel : 63476100, Ext-284

From: Rozi [<mailto:rozi@bcclaw.com.sg>]
Sent: Monday, 7 January, 2019 11:46 AM
To: Manivel Priyadarshini
Subject: RE: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Invovling SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Dear Sirs,

Please see our enclosed reply.

Regards
Rozi
BENEDICT CHAN & COMPANY
14 Fort Road
Singapore 439075
Tel : 6220 6088 Fax : 6220 6087

From: Manivel Priyadarshini [<mailto:manivel@iii.com.sg>]
Sent: Wednesday, 2 January, 2019 3:16 PM
To: 'Rozi'
Subject: India ref: MCT18090602/001/MP- Your ref: BCC.11441.1218.N.DC.PI-Accident Invovling SHC8745X & FBC8027G on 21.09.18 Claimant Lim Hock Ghee

Without Prejudice Save as to Cost

Dear Rozi,

We refer to your LOD dated 17.12.18,

Why your client vehicle was not called for PRI ? .As per state courts there is a breach of pre-repair inspection protocol.

Please let us have your clarification.

Thank you
Best Regards's
Priya Manivel
Motor Claims Department
India International Insurance Pte Ltd
Tel : 63476100, Ext-284
Email : manivel@iii.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.


If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Virus-free. www.avast.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|---|-------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 1808F |
| Vehicle Details | |
| Vehicle No.: | FBC8027G |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 14 Mar 2019 |
| Vehicle Make: | SUZUKI |
| Vehicle Model: | FU150SCD |
| Primary Colour: | Blue |
| Manufacturing Year: | 2005 |
| Engine No.: | G419TH200434 |
| Chassis No.: | BG41BTH200434 |
| Maximum Power Output: | - |
| Open Market Value: | \$1,955.00 |
| Original Registration Date: | 11 Jul 2008 |
| First Registration Date: | 11 Jul 2008 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$294.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 10 Jul 2023 |
| COE Category: | D - Motorcycle |
| COE Period(Years): | 5 |
| PQP Paid: | \$3,537.00 |
| COE Rebate Amount: | \$3,056.00 |
| Total Rebate Amount: | \$3,056.00 |
| Message | |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 14 Mar 2019

OK

DOK: 211 9/18
 PARF = NIL
 COE = PQP ^{bal with} _{COE Expiry}
 = 3537 x $\frac{58}{60}$
 = 3419.00
 LTA = PARF + COE = 3419.00 ^{1/2}

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

| To: Lim Hock Ghee Blk 23 Chai Chee Road #12-488 Singapore 461023 | Date : 21/11/2018 Reference No : CAS/18-11/027 | | | | | | | | | | | | |
|--|--|--------|---------|------|---------|------------|----------|--------|-----|-----------|----------|--------|-----|
| <u>General Information</u> | | | | | | | | | | | | | |
| Registration No. : FBC 8027G Accident Date : 21/09/2018 | | | | | | | | | | | | | |
| <u>Particulars of Damaged Vehicle</u> | | | | | | | | | | | | | |
| Colour : Blue Engine Capacity : 147 cc Mileage (KM) : 95268 Chassis No. : BG41BTH200434 Registration Date : 11/07/2008 | Make & Model : Suzuki FU150SCD Pre-Accident Condition : Good Engine No. : G419TH200434 Steering : Affected Brake : In Order | | | | | | | | | | | | |
| <u>Tyre Condition</u> | | | | | | | | | | | | | |
| | <table><thead><tr><th></th><th>Size</th><th>Make</th><th>Balance</th></tr></thead><tbody><tr><td>Front Tyre</td><td>70/90R17</td><td>DUNLOP</td><td>70%</td></tr><tr><td>Rear Tyre</td><td>90/80R17</td><td>DUNLOP</td><td>50%</td></tr></tbody></table> | | Size | Make | Balance | Front Tyre | 70/90R17 | DUNLOP | 70% | Rear Tyre | 90/80R17 | DUNLOP | 50% |
| | Size | Make | Balance | | | | | | | | | | |
| Front Tyre | 70/90R17 | DUNLOP | 70% | | | | | | | | | | |
| Rear Tyre | 90/80R17 | DUNLOP | 50% | | | | | | | | | | |
| <u>Inspection</u> | | | | | | | | | | | | | |
| Repairer : Moto 51 Pte Ltd 2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921 | | | | | | | | | | | | | |
| <u>Adjustment And Recommendation Cost Of Repair</u> | | | | | | | | | | | | | |
| Repairer's Estimate : \$7,424.60 Revised Amount : \$5,600.00 Less Excess : - Nett Total : \$5,600.00 | | | | | | | | | | | | | |
| <u>Remarks</u> | | | | | | | | | | | | | |
| (A) Survey was done on 26/09/2018 (B) Re-survey was done on 12/11/2018 (C) Re-survey after repair was done on 16/11/2018 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle. | | | | | | | | | | | | | |

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : FBC 8027G

Our ref : CAS/IS-11/027

Adjustment On Repair Costs And Replacement Of Parts:

| S/No | Qty | Descriptions | Assessed Condition | Estimate by Workshop (\$) | Revised Amount (\$) |
|---|------|---------------------------------|--------------------|---------------------------|---------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u> | | | | | |
| 1 | 1pc | Brake lever | Grazed | 55.00 | 30.00 55.00 |
| 2 | 1pc | Brake pedal | Grazed/Bent | 65.00 | 33.00 65.00 |
| 3 | 1pc | Clutch lever | Broken | 55.00 | 30.00 55.00 |
| 4 | 1pc | Exhaust muffler | Dented/Grazed | 415.00 | MH 415.00 |
| 5 | 2pcs | Fork assy R/L @ \$455.00 | Bent/Twisted | 910.00 | 910.00 |
| 6 | 1pc | Fork under bracket | Bent | 185.00 | 185.00 |
| 7 | 1pc | Front brake disc | Bent/Warped | 195.00 | 195.00 |
| 8 | 1pc | Front fairing RH | Grazed/Broken | 160.00 | 160.00 |
| 9 | 1pc | Front fender | Twisted | 89.00 | 89.00 |
| 10 | 1pc | Front footrest stay RH | Bent | 65.00 | 65.00 |
| 11 | 1pc | Front inner cover | Broken | 165.00 | 165.00 |
| 12 | 1pc | Front wheel rim | Dented/Warped | 485.00 | 485.00 |
| 13 | 1pc | Front wheel rim shaft | Bent | 45.00 | 45.00 |
| 14 | 1pc | Gear pedal | Serviceable | 85.00 | - |
| 15 | 2pcs | Handle bar R/L @ \$115.00 60.00 | Bent | 230.00 | 120.00 230.00 |
| 16 | 1pc | Headlamp assy | Broken | 185.00 | 185.00 |
| 17 | 1pc | Headlamp cowling | Grazed/Broken | 105.00 | 68.00 105.00 |
| 18 | 1pc | Headlamp stay | Bent | 95.00 | 30.00 95.00 |
| 19 | 2pcs | Mirror R/L @ \$89.00 50.00 | Grazed/Broken | 178.00 | 100.00 178.00 |
| 20 | 2pcs | Rear side board R/L @ \$145.00 | Repair | 290.00 | - |
| 21 | 1pc | Signal switch | Broken | 162.00 | 162.00 |
| 22 | 1pc | Steering stem | Bent | 225.00 | 225.00 |
| | | | | 1286.2 | |
| | | | | 4,444.00 | 4,069.00 |
| Less 10% | | | | 10% 1157.58 | (406.90) |
| Sub total | | | | 3,999.60 | 3,662.10 |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> | | | | | |
| 1 | 1set | Body sticker set | Necessary | 180.00 | 180.00 |
| 2 | 2pcs | Fork oil seal R/L @ \$24.00 | Necessary | 48.00 | 48.00 |
| 3 | 1set | Front footrest rubber set | Grazed | 84.00 | 84.00 |
| 4 | 1pc | Front no plate (sticker) | Necessary | 20.00 | 12.00 20.00 |
| 5 | 1pc | Front tyre | Serviceable | 160.00 | - |

Constant Appraiser Services

Vehicle No : FBC 8027G

Our ref : CAS/18-11/027

| S/No | Qty | Descriptions | Assessed Condition | Estimate by Workshop (\$) | Revised Amount (\$) |
|---|------|--|--------------------|---------------------------|---------------------|
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS (CONT'D)</u> | | | | | |
| 6 | 1set | Handle bar balancer set | Grazed | 62.00 | 62.00 |
| 7 | 1set | Handle bar grip set | Grazed | 76.00 | 76.00 |
| 8 | 1pc | Rear box | Grazed | 280.00 | 280.00 |
| 9 | 1pc | Rear box stay | Bent | 160.00 | 160.00 |
| 10 | 1pc | Rear side box LH | Grazed | 220.00 | 220.00 |
| 11 | 1pc | Rear side box RH | Grazed | 220.00 | 220.00 |
| 12 | 1pc | Rear side box stay LH | Bent | 155.00 | 155.00 |
| 13 | 1pc | Rear side box stay RH | Bent | 155.00 | 155.00 |
| 14 | 1pc | Steering corn/bearing | Necessary | 95.00 | 95.00 |
| Sub total | | | | 5,914.60 | 5,417.10 |
| <u>LABOUR & MISC. CHARGES</u> | | | | | |
| 1 | | To remove, reinstall electrical wiring harness, check lighting. (to FR) | | 60.00 | 30.00 |
| 2 | | To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident | | 600.00 | 450.00 |
| 3 | | To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident | | 500.00 | 400.00 |
| 4 | | To Straighten body frame to the original position | 450 | 350.00 | 250.00 |
| Grand total | | | | 7,424.60 | 6,547.10 |
| Recommended cost of lump sum repair (To its pre-accident condition) | | | | | 5,600.00 |

Repair days 34

2459.58
29%: 1950

TGIM
LIM
7/1/19

Constant Appraiser Services

Vehicle No : FBC 8027G

Our ref : CAS/18-11/027

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$5,600.00** on a contractual basis. Under normal circumstances, the repair period would be about **7 (Seven)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS1/III19000308/Gqd3s2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 14-03-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

| | | | |
|--------------|-------------|----------------|------------|
| Insured Veh. | SHC 8745X | Veh. Inspected | FBC 8027G |
| Policy No. | MCOM0015 | Coverage (\$) | 0.00 |
| Claim No. | MCT18090602 | Excess (\$) | 0.00 |
| Assign From | PRIYA | Assign Date | 07/03/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-----------------|--------------|----------|
| Make & Model | SUZUKI FU150SCD | c.c | 147 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | BG41BTH200434 | Colour | BLUE |
| Odometer | 98980 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|----------|--------|---------|
| R/H Front Tyre | 70/90-17 | DUNLOP | 4 mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | 90/80-17 | DUNLOP | 4 mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 21/09/2018 | Inspection Date | 12/03/2019 |
| Survey held at | MOTOR 51 PTE LTD 2 KAKI BUKIT AVE 2 #01-18 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|-----------------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 8027G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|----------------------------------|---------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | BRAKE LEVER | REPLACED | 55.00 | 30.00 |
| 1 | BRAKE PEDAL | REPLACED | 65.00 | 38.00 |
| 1 | CLUTCH LEVER | REPLACED | 55.00 | 30.00 |
| 1 | EXHAUST MUFFLER | NOT CHANGED | 415.00 | - |
| 2 | FORK ASSY R/L @ \$455.00 | NOT NECESSARY | 910.00 | - |
| 1 | FORK UNDER BRACKET | NOT NECESSARY | 185.00 | - |
| 1 | FRONT BRAKE DISC | NOT NECESSARY | 195.00 | - |
| 1 | FRONT FAIRING RH | REPLACED | 160.00 | 160.00 |
| 1 | FRONT FENDER | REPLACED | 89.00 | 89.00 |
| 1 | FRONT FOOTREST STAY RH | REPLACED | 65.00 | 65.00 |
| 1 | FRONT INNER COVER | REPLACED | 165.00 | 165.00 |
| 1 | FRONT WHEEL RIM | NOT NECESSARY | 485.00 | - |
| 1 | FRONT WHEEL RIM SHAFT | REPLACED | 45.00 | 45.00 |
| 1 | GEAR PEDAL | SERVICEABLE | 85.00 | - |
| 2 | HANDLE BAR R/L @ \$115.00 | REPLACED | 230.00 | 120.00 |
| 1 | HEADLAMP ASSY | REPLACED | 185.00 | 185.00 |
| 1 | HEADLAMP COWLILNG | REPLACED | 105.00 | 68.00 |
| 1 | HEADLAMP STAY | REPLACED | 95.00 | 30.00 |
| 2 | MIRROR R/L @ \$89.00 | REPLACED | 178.00 | 100.00 |
| 2 | REAR SIDE BOARD R/L @ \$145.00 | REPAIRED SEE LABOUR | 290.00 | - |
| 1 | SIGNAL SWITCH | REPLACED | 162.00 | 162.00 |
| 1 | STEERING STEM | NOT NECESSARY | 225.00 | - |
| | LESS 10% DISCOUNT | | -444.40 | -128.70 |
| | | | 3,999.60 | 1,158.30 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET BODY STICKER (SN) | REPLACED | 180.00 | 120.00 |
| 2 | FORK OIL SEAL R/L @ \$24.00 (SN) | NOT NECESSARY | 48.00 | - |
| 1 | SET FRONT FOOTREST RUBBER (SN) | REPLACED | 84.00 | 60.00 |
| 1 | FRONT NO PLATE (STICKER) (SN) | REPLACED | 20.00 | 12.00 |
| 1 | FRONT TYRE (SN) | SERVICEABLE | 160.00 | - |
| 1 | SET HANDLE BAR BALANCER (SN) | REPLACED | 62.00 | 40.00 |
| 1 | SET HANDLE BAR GRIP (SN) | REPLACED | 76.00 | 45.00 |
| 1 | REAR BOX (SN) | REPLACED | 280.00 | 180.00 |

Report Ref No. CS1/III19000308/Gqd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| 1 | REAR BOX STAY (SN) | SERVICEABLE | 160.00 | - |
| 1 | REAR SIDE BOX LH (SN) | REPLACED | 220.00 | 150.00 |
| 1 | REAR SIDE BOX RH (SN) | REPLACED | 220.00 | 150.00 |
| 1 | REAR SIDE BOX STAY LH (SN) | SERVICEABLE | 155.00 | - |
| 1 | REAR SIDE BOX STAY RH (SN) | SERVICEABLE | 155.00 | - |
| 1 | STEERING CORN / BEARING (SN) | REPLACED | 95.00 | 95.00 |
| | | | 1,915.00 | 852.00 |
| | LABOUR | | | |
| | TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR) | NOT NECESSARY | 60.00 | - |
| | TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT. | | 600.00 | 250.00 |
| | TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR SIDE BOARD R/L. | | 500.00 | 200.00 |
| | TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION. | NOT NECESSARY | 350.00 | - |
| | | | 1,510.00 | 450.00 |
| | GRAND TOTAL | | 7,424.60 | 2,460.30 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,950.00 |

Report Ref No. CS1/III19000308/Gqd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.