

00000000

ASS. REC. BY:

REF:

01TPD19004307/PC

Special Instructions:

CITY/STATE

ASSIGNMENT (Office)

From (Person): Kamaliah Karis

or

SPF

Date/Time:

20/2/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

PC391FE

Insured:

at Workshop m/s:

Tel:

of

Policy No:

MHASPF06000014051

Claim No:

TP/IP/05309/2019

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/1/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time:

Action/Instruction ( ) Estimate

PC391FE-X

8/2/19

## Celine Fong (LKKAUTO)

---

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Wednesday, 20 February 2019 12:30 PM  
**To:** Rohaizal (LKKAUTO)  
**Cc:** Bryan Ang (LKKAUTO); Jackson MU (SPF); Guang Hui LEE (SPF); SPF-TP FAIT  
**Subject:** Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **10 vehicles** below:

**a) Case IAFP-IB-20190201 - Mechanical Inspection of Motor Car, SCK1726P (TP/IP/01847/2019)**

On 10 January 2019 at about 10.49 am, Police incident was created regarding an accident along Bukit Batok Road by Bukit Batok West Avenue 6. The motor car, SCK1726P, was travelling on the right of 2-lanes along Bukit Batok Street 21 making a right turn into Bukit Batok West Ave 6 when traffic light was green only. While making a right turn, the motor car collided onto a pedestrian (deceased) who was crossing at the pedestrian crossing from the motor car's left to right view. The pedestrian was conveyed to NTFGH by ambulance. On the same day, at 12.06 pm, the pedestrian succumbed to her injuries and was pronounced dead by Doctor at NTFGH.

**Vehicle to be inspected:** SCK1726P (Potential Defendant)

IO In-Charge: Si Dzul Hairie

**b) Case: IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBE8770H (TP/IP/69903/2018)**

On 20 December 2018 at 12.21 pm, the deceased was riding FBE 8770 H on the left lane of 3 lanes when his motorcycle hit the side kerb and skidded. The deceased was sent to National University Hospital (NUH) and succumbed to her injuries on the same day and was pronounced dead at NUH.

**Vehicles to be inspected:** FBE8770H (Deceased)

IO In-Charge: SIO Yazid

**c) Case: IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, JSC2795 (TP/IP/00599/2019)**

**d) Case: IAFP-IB-20190201 - Mechanical Inspection of Police Motor Car, QX327E (TP/IP/00599/2019)**

On 3<sup>rd</sup> January 2019 at 8.43 am, the rider with pillion (deceased) was riding JSC 2795 along Woodlands Road entering into BKE when the rider collided onto the rear of the police car QX 327 E which was stationary on the chevron. As a result the rider and deceased was flung off the motorcycle. The rider and pillion of the motorcycle was then sent to KTPH and the pillion was pronounced dead in hospital.

**Vehicles to be inspected:** JSC2795 (Potential Defendant)

**Vehicles to be inspected:** QX327E (Involved Party)

IO In-Charge: SIO Yazid

**e) Case: IAFP-IB-20190201 - Mechanical Inspection of Motor Car, SLL3915K (TP/IP/62683/2018)**

On 10 November 2018 at 1.00 am, the accused was driving a motor car, SLL 3915 K along AYE (Tuas) 12.4 km when he claimed there are mechanical faults to the brakes and gear of the said motor car which resulted in him to lose control of his car on a straight road.

**Vehicles to be inspected: SLL3915K (Accused)**

IO In-Charge: SIO Jackson Mu

- f) **Case IAFP-IB-20190201 - Mechanical Inspection of Tipper Truck, XD3396H (TP/IP/03829/2019)**
- g) **Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBB8585S (TP/IP/03829/2019)**

On 22 January 2019, sometime before 5.23 p.m., the Involved Party (XD3396H) was travelling along Old Choa Chu Kang Road towards the direction of Jalan Sungei Poyan on a single lane, 2-way direction (divided by a continuous white), when the Deceased (FBB8585S) riding on the opposite direction lost control of the motor cycle and fell on the opposite direction, in front of the tipper truck. The involved Party was unable to brake in time and run over the Deceased. As a result, the motorcyclist (Deceased) sustained fatal injuries and passed away at the accident scene.

**Vehicles to be inspected: FBB8585S (Deceased)**  
**XD3396H (Involved Party)**

IO In-Charge: SIO Farhan

- h) **Case IAFP-IB-20190201 - Mechanical Inspection of Motor Bus, PC3917E (TP/IP/05309/2019)**

On 28 January 2019 (Monday) at about 5.32 p.m., the Involved Party was driving his motor bus, PC3917E, along the single lane, two-way traffic along Gul Road towards Pioneer Road when he suddenly felt an impact at the left rear wheel of his motor bus and ran over an object. He immediately stopped his motor bus and realised that he was involved in an accident with the Deceased. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene by paramedic SSgt Hong Bin at 5.54 p.m.

**Vehicle to be inspected: PC3917E (Involved party)**

IO In-Charge: DOC Saleha

- i) **Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBJ1912K (TP/IP/05309/2019)**

On 28 January 2019 (Monday) at about 5.32 p.m., the Involved Party was driving his motor bus, PC3917E, along the single lane, two-way traffic along Gul Road towards Pioneer Road when he suddenly felt an impact at the left rear wheel of his motor bus and ran over an object. He immediately stopped his motor bus and realised that he was involved in an accident with the Deceased (Motor cycle FBJ1912K). As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene by paramedic SSgt Hong Bin at 5.54 p.m.

**Vehicle to be inspected: FBJ1912K (Deceased)**

IO In-Charge: DOC Saleha

- j) **Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, SFR65Y (TP/IP/03061/2019)**

On 19 January 2019 at about 9.38 a.m., the Involved Party was driving her motor car, SFR65Y along Yio Chu Kang Road junction of Ang Mo Kio Street 64 and collided onto a traffic light pole. She was initially conscious and refused to be conveyed to hospital. Her daughter then insisted to send the Involved Party to Gleneagles Hospital.

Subsequently after, the Involved Party's condition deteriorated and she is currently under close observation in ICU.

**Vehicle to be inspected:** SFR65Y (Involved Party)

IO In-Charge: SIO Ken Lee

2. These request has been approved by my management.
3. Thank you Sirs.

Cc: Bryan, FAIT Team, SIO Jackson Mu & SIO Ken Lee, fyip

Best regards,

**Kamaliah Kamis (Miss)**  
Senior Investigation Officer | Fatal Accident Investigation Team  
Traffic Police Department | Singapore Police Force  
DID: (65) 6547 6435 | FAX: (65) 6547 6352



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

⑧ PC3917E

On 10 November 2018 at 1.00 am, the accused was driving a motor car, SLL 3915 K along AYE (Tuas) 12.4 km when he claimed there are mechanical faults to the brakes and gear of the said motor car which resulted in him to lose control of his car on a straight road.

Vehicles to be inspected: SLL3915K (Accused)

IO In-Charge: SIO Jackson Mu

- f) Case IAFP-IB-20190201 - Mechanical Inspection of Tipper Truck, XD3396H (TP/IP/03829/2019)
- g) Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBB8585S (TP/IP/03829/2019)

On 22 January 2019, sometime before 5.23 p.m., the Involved Party (XD3396H) was travelling along Old Choa Chu Kang Road towards the direction of Jalan Sungei Poyan on a single lane, 2-way direction (divided by a continuous white), when the Deceased (FBB8585S) riding on the opposite direction lost control of the motor cycle and fell on the opposite direction, in front of the tipper truck. The Involved Party was unable to brake in time and run over the Deceased. As a result, the motorcyclist (Deceased) sustained fatal injuries and passed away at the accident scene.

Vehicles to be inspected: FBB8585S (Deceased)  
XD3396H (Involved Party)

IO In-Charge: SIO Farhan

- h) Case IAFP-IB-20190201 - Mechanical Inspection of Motor Bus, PC3917E (TP/IP/05309/2019)

On 28 January 2019 (Monday) at about 5.32 p.m., the Involved Party was driving his motor bus, PC3917E, along the single lane, two-way traffic along Gul Road towards Pioneer Road when he suddenly felt an impact at the left rear wheel of his motor bus and ran over an object. He immediately stopped his motor bus and realised that he was involved in an accident with the Deceased. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene by paramedic SSgt Hong Bin at 5.54 p.m.

Vehicle to be inspected: PC3917E (Involved party)

IO In-Charge: DOC Saleha

- i) Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FB11912K (TP/IP/05309/2019)

On 28 January 2019 (Monday) at about 5.32 p.m., the Involved Party was driving his motor bus, PC3917E, along the single lane, two-way traffic along Gul Road towards Pioneer Road when he suddenly felt an impact at the left rear wheel of his motor bus and ran over an object. He immediately stopped his motor bus and realised that he was involved in an accident with the Deceased (Motor cycle FB11912K). As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene by paramedic SSgt Hong Bin at 5.54 p.m.

Vehicle to be inspected: FB11912K (Deceased)

IO In-Charge: DOC Saleha

- j) Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, SFR65Y (TP/IP/03061/2019)