

LKK Joy



Co. Reg: 200922097K GST Reg.No: 200922097K
Auto Bay @ Kaki Bukit Bldg 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883
Tel: (65) 6555 2909 Fax: (65) 6841 7181 Web: www.autoncars.com.sg

Date: 11/3/2019

TO: AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 Chartis Building
Singapore 079120

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: Total Pages: 1

Our Customer: LIM HENG YONG, DARYL DA
Vehicle No: SKJ9011B

Model: NISSAN MURANO 2.5

Manufacture Year: 2012

Date of Accident: 1/3/2019

Total Estimate Repair Days: 6

Attn: Motor Claim Department
Fax:

Re: Repair Estimate For Third Party Claim against SJL6187Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper	1	\$995.50	\$995.50	Re/78m ✓
2	Rear bumper clips	10	\$3.50	\$35.00	12m ✓
3	Rear bumper retainer	2	\$82.10	\$164.20	47 X
4	Rear bumper 3rd brake light	1	\$130.50	\$130.50	20m 10X
5	Rear bumper 3rd brake light cover	1	\$95.10	\$95.10	20m ✓
6	Rear bumper parking sensor	1	\$280.00	\$280.00	shift ✓
7	Rear bumper sponge	1	\$195.20	\$195.20	47 X
8	Rear bumper reinforcement	1	\$28.20	\$28.20	17 X
9	X Tronic CVT badge	1	\$85.20	\$85.20	17 X
10	"MURANO" emblem	1	\$80.10	\$80.10	17 X
11	Tailgate logo	1	\$85.10	\$85.10	17 X
	Sub Total			\$2,174.10	
	Less 30%			\$652.23	
	Sub Total 1			\$1,521.87	
	Total Spare Parts			\$1,521.87	
B.	Labour				
1	To knock and straighten rear end panel and rear damaged panel. Adjust and realign the same			\$800.00	200
2	To putty and spray tailgate outer, end panel and rear bumper			\$800.00	300
3	To install rear parking sensor			\$60.00	10
4	To check wiring and all lighting			\$60.00	20
	Total Labour			\$1,720.00	
	(* The above quoted are exclusive of GST.) Total Repair Cost			\$3,241.87	

P-1406.6
983.92
1553.92
1243

To be phd. After repair
1/5/2020
2 day.

Yours faithfully,

Daria
Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	Mercus LKK
Contact	90096608
Survey Date	11/3/19
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	1/5

DATE	Remark From MR CHOO
11/3/2019	Please arrange for survey asap