



SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

<b>1. GENERAL INFORMATION</b>			
INCIDENT NO. : /20190307/0803		LOCATION OF FIRE:  Along Worthing Road Outside 35, Worthing Road Singapore 554969	
FIRE REPORTED ON : 07 March 2019			
TIME OF CALL : 20:46:45 hrs			
STATION COVERAGE : Sengkang Fire Station			
<b>2. INCIDENT INFORMATION</b>			
FIRE INVOLVED: The engine of a Nissan car (SGC2494X)			
METHOD OF EXTINGUISHMENT: By SCDF crew using a domestic water hose and a dry powder fire extinguisher from a fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine of the car was damaged. The front part of the car, including the windscreen and interior of the car, sustained varying degrees of heat and smoke damage.			
<b>3. FATALITY/INJURY INFORMATION</b>			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
<b>REPORT CERTIFIED TRUE AND CORRECT BY:</b>			
          HUANG WEI KANG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

*This is a computer generated Fire Report. No signature is required.*