

Surveyor

Taufik

DOI:

ASSIGNMENT

K

Date / Time:

11/03/19

Registered in Merimen:

11/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKM 9640 U

Name of Insured:

Goldbell car rental o/c

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

8/3/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

OI GIA REPORT (YES / NO) : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

Sou 9696 A



INSRS:

WSP:

Tel:

Liability:

RMKS:

pmc



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

Sou 9696 A - x

SKM 9640 U - 11/03/19 10:00 AM

(13) 0111 111 111 111

21/03/19

- MTR KOUKOUO, OLO RANG KOUKOUO TP.
- 11/03/19 TO OI TO KOUKOUO TP. CEN
- 11/03/19 KOUKOUO.
- 11/03/19 KOUKOUO

14/10/19

Khancha

File pass to type mandate

24/10/19

Khancha

File pass to close to mei turn

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 010111-3L

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P SS 8,054.65 (5 days) Reduction: 42 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Caroline

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.:

27

IF NO or B 28, Ass. Lia:

Repair Cost: (w/ GST)

SS 8,618.48

0111 111 111 111

Loss of Rental (LOR) (w/ GST)

SS 342.40 (4 days) x \$80

Loss of Use (LOU):

SS - (\$ - x - days)

Loss of Income (LOI):

SS - (\$ - x - days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

Legal Cost

SS -

Total:

SS 8,968.33

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 8,625.93

Name 1:

PERFORMANCE MOTORS PTE LTD

Payee 2: (Strike if N.A.)

SS 342.40

Name 2:

BEW RENT-A-CAR PTE LTD

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

Tang

ALB

4298/TIB

Vehicle No.

Location

Estimated Cost

QVE / TP / WS / TP RES / OD RES / EVA / INV / MV

Vehicle / Vehicle No.

at Motor Insurance

at

Insured

Policy No.

Claims No.

Amount Insured

Excess

(Clearly Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value

WAC: Accident Report Consistent? Yes or No

QDA: PP Seen Consistent? Yes or No

Est. Repair: 5 days Res: Yes or No

Est. Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted

Gary

Date / Time Action / Instruction

98054.65, 5 days

Vehicle

SD49696A

2018 June

Type: M/Cat / T/Cycle / Bus / Van / Lorry / Taxi / Crane / Motor

Truck / Trailer or

Make

BMW 216E GT

1499

Colour

Grey

Insured / Std / NI / NA

Sp Reading

7983

Tiffalo: Insured / Std / NI / NA

Eng/No

WBA2D920905K 81214

C/N

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/R / STD ARin or

Tyre Size

F: 205/60R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Continental

Front

Rear

R/Bal

6 mm

R/Bal

6 mm

L/Bal

6 mm

L/Bal

6 mm

D.O.A

D.O.A

01/07/19

Survey held at

PMU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Expiry Date / For Parts



Preli. Report

at



Final Report

Expiry Date / For Parts

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

at 10000

at 10000

at 10000

Report Format

Lump Sum / LB /

Add Fee:



date trip



1 day trip



1 day trip



1 day trip



- (Red \$ 5,809.81 / 421.)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



105, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190228 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

08 MAR 2019

ESTIMATE

Estimate No. : b1 50428
Date Estimated : 08/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Neo Chye Yong (Liang CaiRong)
Blk 301 Clementi Avenue 4
#06-559

Singapore 120301

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDU9696A	5K81214	29/06/2018	216i GT	0

DESCRIPTION

To replace rear bumper and bootlid and attachment include knocking cause by the accident

1700 2,975.00

Painting rear bumper, bootlid, tail panel

1730 2,666.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To remove and install rear windscreen glass to facilitate the repair job.

450 574.00

Sandries WA

Total Labour 1: 6,510.00

DESCRIPTION

BOOTLID
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE
RR BUMPER RH INNER SIDE GUIDE
REAR BUMPER PANEL PRIMED (PDC)
SET MOUNTS PDC SENSOR REAR
REAR BUMPER TOWING FLAP EYE PRIMED
LETTERING 216 I
GROMMET
PLAQUE 74MM
REAR WINDOW
REAR BUMPER HEAT INSULATION
BOOTLID SEALING
DECOUPING RING PDC TORQUE CONVERTER
ULTRASONIC SENSOR MINERALGRAU B39
(DG) CLEANER R1 (100ML)

QTY PRICE

1 1,204.35
1 61.50
1 61.50
1 458.10
1 45.30
1 67.55
1 67.55
1 1,029.50
1 60.35
1 42.85
1 64.10
2 0.75
1 71.25
1 654.35
1 63.20
1 143.00
4 5.05
4 380.65
1 26.15

VALUE

del 1,204.35
un X 61.50
un X 61.50
ht X 458.10
de X 45.30
de X 67.55
un X 67.55
de 1,029.50
ne X 60.35
ne X 42.85
ne X 64.10
ne 1.50
ne 71.25
X 654.35
X 63.20
X 143.00
X 20.20
X 1,522.60
ne 26.15

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401359W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

288, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63443773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190518 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50428
Date Estimated : 08/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDU9696A	5K81214	29/06/2018	216i GT	0

DESCRIPTION

(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) GLASS PRIMER 30ML (VP205)

QTY	PRIC	VALUE
2	131.55	263.10
1	27.85	27.85

Total Parts : 5,955.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Reg No. _____ Claim No. _____

Date/Time 01/04/19 Excess \$5

Surveyor's Name Tanpin Sign [Signature]

Surveyor's Tel 9749 5219 Authorised Yes / No

Authorized Date 01/04/19 Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No

Surveyor's E-mail tanpin@lkk.com

No. of Working Days Recommended 5 days - body

Labour 1	:	6,510.00
Parts	:	5,955.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	872.61
Grand Total	:	13,338.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401589W, GST Reg. No. M2-0000081-X



FINAL REPORT

Estimate No. : b1 50428
Date Estimated : 08/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Neo Chye Yong (Liang CaiRong)
Blk 301 Clementi Avenue 4
#06-559

Singapore 120301

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SDU9696A	5K81214	29/06/2018	216i GT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid include knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint rear bumper and boot lid	1730.00		1,730.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
* To remove and install rear windscreen glass to facilitate repairs	574.00		574.00	
# To conduct water leak tests *	75.00		75.00	
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function *	451.00		451.00	
Sundries	80.00		80.00	✓nd✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,204.35	1.00		1,204.35
REAR BUMPER CARRIER	458.10	1.00		458.10
SUPPORT	45.30	1.00		45.30
RR BUMPER LH INNER SIDE GUIDE	67.55	1.00		67.55
REAR BUMPER PANEL PRIMED (PDC)	1,029.50	1.00		1,029.50
GROMMET	0.75	2.00		1.50
PLAQUE 74MM	71.25	1.00		71.25
(DG) CLEANER R1 (100ML)	26.15	1.00		26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85

SUPPLEMENTARY ITEMS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Total Labour :	4,860.00
Total Parts :	3,194.65
Total Labour & Parts :	8,054.65
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,054.65
GST @7%:	563.83
Grand Total :	8,618.48

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 50428
Date Estimated : 08/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Neo Chye Yong (Liang CaiRong)
Blk 301 Clementi Avenue 4
#06-559

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 120301

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDU9696A	5K81214	29/06/2018	2161 GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To conduct water leak tests *	75.00		75.00 <i>ndc</i>
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function *	451.00		451.00 <i>ndc</i>

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	526.00
Total Parts :	
Total Labour & Parts :	526.00

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 23 October 2019 9:23 AM
To: PBSP
Cc: Admin A
Subject: RE: URGENT REMINDER: LOD REMINDER - SDU9696A & SKM9640U ON 08/03/2019

Tracking:	Recipient	Delivery
	PBSP	
	Admin A	
	olivialau@lkkauto.com	Delivered: 23/10/2019 9:23 AM
	Meikwan@lkkauto.com	Delivered: 23/10/2019 9:23 AM
	shupei@lkkauto.com	Delivered: 23/10/2019 9:23 AM

Without Prejudice
(save as to costs)

Dear Caroline,

The above matter and your e-mail below refers.

We confirm settlement for Cost of repair (w/GST) and LTA fee as per your payment breakdown form for **\$8,625.93 (all in)** and will proceed to do the necessary.

Please note that BKW has been activated for rental claim.

We will proceed to do the necessary promptly.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khanchna (LKK Auto)
Sent: Monday, 14 October 2019 9:12 AM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: URGENT REMINDER: LOD REMINDER - SDU9696A & SKM9640U ON 08/03/2019

View Received Message

This mail is associated with :

***SDU9696A (8418220201SG)**
[SKM9640U]

TP
NEO CHYE YONG
Mar 8 2019 11:00AM
[GOLDBELL CAR RENTAL PTE LTD]
Performance Motors Limited

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/03/2019 11:39 AM.
To LKK_HQ
Subject No OI GIA Report

Hi,

Please be informed that no OI GIA report received till date.

Please find OI details below for your further action.

OI name: GOLDBELL CAR RENTAL PTE LTD

Address:
10 RAEBURN PARK
#02-01
Singapore 088702

Contact No: 6838 6300

Regards,
Sheng Yang

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19004398/ha3

13 March, 2019

GOLDBELL CAR RENTAL PTE LTD
10 RAEBURN PARK
#02-01
SINGAPORE 088702

Dear Sirs,

**ACCIDENT INVOLVING SKM 9640U AND SDU 9696A ON 08/03/2019 ALONG/
AT DEMPSEY**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Print Received Message

This mail is associated with :

***SDU9696A (8418220201SG)
[SKM9640U]**

TP

NEO CHYE YONG

Mar 8 2019 10:00AM

[GOLDBELL CAR RENTAL PTE LTD]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 22/10/2019 19:46 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8968.33) - SDU9696A - Claim Handler: Loh, Chee-Heng

Approved:8968.33.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____


**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	5049696A	Model:	BMW 216
Date of Accident:	8 Mar 19		


Global Sum Settlement	☐ Yes	☒ No	
Repair Estimate	\$	13,338.46	
Final Repair Cost	\$	8,618.48	
Loss of Use	\$	-	days at \$ per day
Rental (if any)	\$	- BkW	days
LTA / GIA Search Fee	\$	7.45	
Others:	\$	-	
	\$	-	
Final Settlement Sum	\$	8,625.93	

Is Third Party Workshop GIA Registered? ☐ YES ☐ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	\$	8,618.48
2)	Performance Motors Ltd	\$	7.45
3)	BkW	\$	342.40



Signed by appointed surveyor



Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19004398/T1ha3

5 APRIL 2019

GOLDBELL CAR RENTAL PTE LTD

10 RAEBURN PARK,
#02-01, SINGAPORE 088702
Attn: The Management

Dear Sir/Madam,

**ACCIDENT INVOLVING SKM 9640U & SDU 9696A ALONG/AT HOLLAND ROAD
(NEAR BOTANICAL GARDEN) ON 08/03/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SDU 9696A against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, NEO CHYE NONG (the third party claimant) of BLK 301 CLEMENTI
AVE 4 S 120301 (address), owner of SDU 9696A (vehicle no.)
hereby authorize PERFORMANCE MOTORS LIMITED ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SDU 9696A that was damaged pursuant to the accident which occurred on 8/3/19
(date) along DENMARK (location) involving vehicle no/s
SDU 9696A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 05 (day) of 04 (month) 2019 (year)


Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 8,618.48 (Repair Cost), S\$ 342.40 (Loss of rental/loss), S\$ 7.45 (Disbursement), for vehicle no. SOU9696A that was damaged pursuant to the accident which occurred on 8/3/19 (date) along Demoan (location) involving vehicle no/s SOU9640U. This is pursuant to the inspection conducted on 1 Apr 19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Neo Chye Yong ("the third party claimant") of vehicle no. SOU9696A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SOU9696A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of 10 (month) 2019 (year)



Signed by appointed surveyor

GARY POH CHAI HOON
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 119941

Signed by "the workshop" (with chop)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401589W GST Reg. No. M2-0020281-K

(branch)



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438190
Tel. 63190688 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1349754
Date IN : 01/04/2019
Motor Claim Advisor: Gary Poh Chai Hoon

Page No. : 1 of 2
Invoice Number : 2116097 / WSB
Invoice Date : 26/06/2019
Payment Terms : 30 Days From Invoice
Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Mr Neo Chye Yong (Liang CaiRong)
Blk 301 Clementi Avenue 4
#06-559

Singapore 120301

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDU9696A /	5K81214	29/06/2018	216I GT	7983

- - - - LABOUR 1 - - - -

	NETT
To replace rear bumper and attachments, bootlid including knock out dented area caused by the accident.	1,700.00
To respray rear bumper and bootlid.	1,730.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To carry out body cavity preservation. (Per panel).	100.00
To remove and install rear windscreen glass to facilitate repairs.	574.00
To conduct water leak tests.	75.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 08.03.2019. 3RD PARTY CAR : SKM9640U.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 01.04.2019 AT 11AM. AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK AUTO ON 27.03.2019 VIA EMAIL.	
LTA SEARCH FEE = \$7.45.	0.00
COURTESY CAR PROVIDED BY BKW.	0.00

Total Labour 1: **4,860.00**

- - - - PARTS - - - -

	Qty	Retail Price	NETT
REAR BUMPER CARRIER	1	458.10	458.10
SUPPORT	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE	1	67.55	67.55
REAR BUMPER PANEL PRIMED (PDC)	1	1,029.50	1,029.50
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. SG-0020081-X



363, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 478185
Tel: 63190888 (AfterSales)
Fax: 63445773

313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64786601 (AfterSales)
64786624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1349754	Page No. : 2 of 2
Date IN : 01/04/2019	Invoice Number : 2116097 / WSB
Motor Claim Advisor: Gary Poh Chai Hoon	Invoice Date : 26/06/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
BOOTLID	1	1,204.35	1,204.35
Total Parts :			3,194.65

Labour Charges :	4,780.00	Total Labour & Parts Charges :	S\$ 8,054.65
Parts Charges :	3,194.65	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 8,054.65
		GST @ 7% :	S\$ 563.83
		Invoice Total Amount Include GST :	S\$ 8,618.48

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 8,618.48**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
AIG ASIA PACIFIC INSURANCE PTE. LTD. 78 SHENTON WAY #07-16 SINGAPORE 079120 ATTN: CLAIMS DEPARTMENT C/O LKK AUTO CONSULTANT PTE LTD

DATE	INVOICE NO.
08-Apr-2019	P 1712

	VHA NO.	DUE DATE	VEH. NO.
	P 1712	08-Apr-2019	SJS 8438 A
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 01 APRIL 2019 TO 05 APRIL 2019 YOUR REF: SDU9696A & SKM9640U (PERFOMANCE)	4	80.00	320.00
GST @ 7%			\$22.40
TOTAL			\$342.40

*All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.*

VEHICLE HIRING AGREEMENT
HIRER'S PARTICULARS

Name (as in I/C): **NEO CHYE YONG**
 NRIC/Passport No: **S8227109J** Date of Birth: **24/8/1982**
 Address: **APT BIK 301 Clementi Ave 4** Age: **36**
#06-559 S: **120301**
 Name & Address of Employer: _____
 Occupation: _____ Driving Exp: **10**
 Driving Licence No: **S8227109J** Passed Date: **22/7/2002**
 D/L Type: Local/Int'l/Others: _____
 Tel(O): _____ (R): _____ HP: **9873 9696**

DRIVER'S PARTICULARS

Name (as in I/C): _____
 NRIC/Passport No: _____ Date of Birth: _____
 Address: _____ Age: _____
 S: _____
 Occupation: _____ Driving Exp: _____ Yrs
 Driving Licence No: _____ Passed / Expiry Date: _____
 D/L Type: Local/Int'l/Others: _____ Contact No: _____


Hirer's Own Vehicle No: ~~S8227109J~~ **S04964** Replace Veh No: _____
 Loan Vehicle No: **SJS 8488A** VR No: _____
 Make & Model: **H. CRV** Auto/Manual Group: **Auto**

CHARGES		\$	cts
Daily	4 day @ \$ 80	Per day	320 00
Weekly/Monthly	week @ \$	Per week/Monthly	
Others			
CDW/PAI	@ \$	Per day/Monthly	
Delivery/Collection Svc			
GST			
OR No: _____		(A) SUB-TOTAL	
Petrol Level	OUT	E	1/4 1/2 3/4 F
Surcharge	IN		
First	_____ km FREE per day	GST	7% 22 40
Excess mileage is chargeable at _____ cents per km		TOTAL CHARGES	342 40

Security Deposit : \$ _____ Bank: **OCEB**
 CASH/NETS/VISA/MC/AMEX/CHO No: **S100 1261 0041 1717**
 Expiry Date: **05/12** Card ID No: **984**
 Name as in Card: **TOM NEO**

NON WAIVER EXCESS (Subject to GST): \$ **3000**
ACCESSORIES CHECK
☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: _____ Additional Driver's Signature: _____
SINGAPORE Use Only



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given BKW Rent A Car Pte Ltd in connection with this agreement is true.

IMPORTANT

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hiree/Authorized Driver.
- All vehicles are supplied with petrol and should be returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance, in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace an replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Smoking or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair, between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to each occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claims. Full excess amount have to be paid immediately in the event of an accident.
- The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.


Date Out	Time Out	Mileage	Check By	Remarks
1/4/19	1030	162199	Axx6	
Return Of Vehicle: The Hirer Driver Is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)"				
Date In	Time In	Mileage	Check By	Remarks
05.04.19	1100	162311	henny	

VEHICLE HIRING AGREEMENT
HIRER'S PARTICULARS

Name (as in IC): **NEO CHYE YONG**
 NRIC/Passport No: **58227109J** Date of Birth: **24/8/1982**
 Address: **APT BIK 301 Clementi Ave 4** Age: **36**
#06-559 S(**120301**)
 Name & Address of Employer: _____
 Occupation: _____ Driving Exp: **10**
 Driving Licence No: **S8227109J** Passed Date: **22/7/2002**
 D/L Type: Local/Int'l/Others: _____
 Tel(O) _____ (R) _____ HP **9873 9696**

DRIVER'S PARTICULARS

Name (as in IC): _____
 NRIC/Passport No: _____ Date of Birth: _____
 Address: _____ Age: _____
 S()
 Occupation: _____ Driving Exp: _____ Yrs
 Driving Licence No: _____ Passed / Expiry Date: _____
 D/L Type: Local/Int'l/Others: _____ Contact No: _____



INDICATE:
 A - Accidents
 B - Dents
 C - Scratches
 X - Crack

Hirer's Own Vehicle No: ~~S8227109J~~ SDA 9016 Replace Veh No: _____
 Loan Vehicle No: **SJS 8488A** VR No: _____
 Make & Model: **H. CRV** Auto/Manual Group: **Auto**

CHARGES		\$	cts
Daily	4 day @ \$ 80	Per day	320 00
Weekly/Monthly	week @ \$ _____	Per week/Monthly	
Others			
CDW/PAI	@ \$ _____	Per day/Monthly	
Delivery/Collection Svc			
GST			
OR No: _____		(A) SUB-TOTAL	
Petrol Level & Surcharge	OUT E 1/4 1/2 3/4 F		
First _____ km FREE per day	GST 7%	22	40
Excess mileage is chargeable at _____ cents per km	TOTAL CHARGES	342	40

Security Deposit : \$ _____ Bank: **OCL**
 CASH/NETS/VISA/MC/AMEX/CHO No: **5400 1261 0041 1717**
 Expiry Date: **05/12** Card ID No: **984**
 Name as in Card: **TOM NEO**

NON WAIVER EXCESS (Subject to GST): \$ **3000**

ACCESSORIES CHECK

☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: _____
 Additional Driver's Signature: _____

SINGAPORE Use Only

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given BKW Rent A Car Pte Ltd in connection with this agreement is true.

IMPORTANT

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorized Driver.
- All vehicles are supplied with petrol and should returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PIW where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance, in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserves the right not to replace an replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Strike or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to bear all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The hirer/driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
1/4/19	1030	162199	Abul	

Return Of Vehicle: The Hirer Driver is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)"

Date In	Time In	Mileage	Check By	Remarks
05-04-19	1100	162311	Lowry	



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 08 Mar 2019 / 17:12:04

Receipt Date/Time : 08 Mar 2019 / 17:12:04

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190308-003059

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SKM9640U				
As at 08 Mar 2019/11:00:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SKM9640U Enquiry Fee 20190308171058418089	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - SMG653A				
As at 06 Mar 2019/20:45:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
2	Insurance Enquiry - SMG653A Enquiry Fee 20190308171058473610	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		14.00	0.98	14.98
Rounding Difference				0.03
Total Amount Payable				14.95
Paid By				
	xxxxxxxxxxxx5164	Credit Card: Visa/MasterCard		14.95
Total				14.95
Cash Change				0.00
Tendered Amount				14.95
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2019 Edit Reg		01 Apr 2019 00:00 Edit Adj Rpt	\$58,054.65 Edit Estimates	\$58,054.65 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Main Claimant:	NEO CHYE YONG, ID: S8227109J		
Vehicle Reg. No.:	SDU9696A	Date of Loss:	08/03/2019 10:00 - :59 [8 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8418220201SG	Policy/Cover Note No.:	0999994306 (Comprehensive)
Vehicle Reg. No. (Insured):	SKM9640U	Policy No. (Claimant):	A29109845APO
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 20/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG_EXPRESS (22/10/2019): Alert - Adj Mandate Approved (\$58968.33) - SDU9696A - Claim Handler: Loh, Chee-H...
- AIG_SG (22/03/2019): Re: Fw: No OI GIA Report
- AIG_SG (12/03/2019): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDU9696A (8418220201SG)
[SKM9640U]
TP
NEO CHYE YONG
Mar 8 2019 10:00AM
[GOLDBELL CAR RENTAL PTE LTD]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On		Thumbnail	Print
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ)		
		Third Party Express Settlement – Payment Breakdown		Edit

Assessment Reports

1 per page

No	Finalized On		Thumbnail	Print
		AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	22/03/19 13:01	Accident Statement From: SC - Reg. No: SKM9640U, Claimant: GOLDBELL CAR RENTAL PTE LTD		Load HTM

Photos/Images

3 per page

No	Relabel/Reorder		Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)		
	22/10/19 13:41	General View		Load JPG
2	22/10/19 13:41	General View		Load JPG
3	22/10/19 13:41	General View		Load JPG
4	22/10/19 13:41	General View		Load JPG
5	22/10/19 13:41	General View		Load JPG
6	22/10/19 13:41	General View		Load JPG
7	22/10/19 13:41	General View		Load JPG
8	22/10/19 13:41	General View		Load JPG
9	22/10/19 13:41	General View		Load JPG
10	22/10/19 13:41	General View		Load JPG
11	22/10/19 13:41	General View		Load JPG
12	22/10/19 13:41	General View		Load JPG
13	22/10/19 13:41	General View		Load JPG
14	22/10/19 13:41	General View		Load JPG
15	22/10/19 13:41	General View		Load JPG
16	22/10/19 13:41	General View		Load JPG
17	22/10/19 13:41	General View		Load JPG
18	22/10/19 13:41	General View		Load JPG
19	22/10/19 13:41	General View		Load JPG
20	22/10/19 13:41	General View		Load JPG
21	22/10/19 13:41	General View		Load JPG
22	22/10/19 13:42	General View		Load JPG
23	22/10/19 13:42	General View		Load JPG
24	22/10/19 13:42	General View		Load JPG
25	22/10/19 13:42	Reinspection Photo		Load JPG
26	22/10/19 13:42	Reinspection Photo		Load JPG
27	22/10/19 13:42	Reinspection Photo		Load JPG
28	22/10/19 13:42	Reinspection Photo		Load JPG
29	22/10/19 13:42	Reinspection Photo		Load JPG
30	22/10/19 13:42	Reinspection Photo		Load JPG
31	22/10/19 13:42	Reinspection Photo		Load JPG
32	22/10/19 13:42	Reinspection Photo		Load JPG
33	22/10/19 13:42	Reinspection Photo		Load JPG
34	22/10/19 13:42	Reinspection Photo		Load JPG
35	22/10/19 13:42	Reinspection Photo		Load JPG
36	22/10/19 13:42	Reinspection Photo		Load JPG

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
37	22/10/19 13:42	Reinspection Photo	 Load JPG	☒
38	22/10/19 13:42	Reinspection Photo	 Load JPG	☒
39	22/10/19 13:42	Reinspection Photo	 Load JPG	☒
40	22/10/19 13:42	Reinspection Photo	 Load JPG	☒
41	22/10/19 13:42	Reinspection Photo	 Load JPG	☒
42	22/10/19 13:42	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/03/19 19:31	TP ESTIMATE + DOCS	 Load PDF	
2	11/03/19 19:31	TP GIA REPORT	 Load PDF	
3	13/03/19 13:41	Non reporting letter	 Load PDF	
4	05/04/19 20:42	TP ESTIMATE - MARKED	 Load PDF	
5	08/04/19 10:11	LETTER TO OI	 Load PDF	
6	08/04/19 18:12	RENTAL RECEIPT	 Load PDF	
7	21/10/19 10:22	LTA SEARCH	 Load PDF	
8	30/10/19 10:14	WORKSHOP INVOICE	 Load PDF	
9	30/10/19 10:14	AUTHORISATION TO ACT FORM	 Load PDF	
10	30/10/19 10:14	Release Voucher	 Load PDF	
11	30/10/19 10:14	LOD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKM9640U (Insd veh)	Model:	BMW 216i 1.5 D GT LED (A)
	SDU9696A (TP veh)		
Date of Accident:	08/03/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	13,986.88
Final Repair Cost	:	\$	8,618.48
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	342.40 4 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,968.33

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 8,625.93
2)	BKW Rent-A-Car Pte Ltd	:	\$ 342.40
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

30 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19004398/T1KA3Q2

Date: 30/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994306
Claimant
Vehicle No : SDU9696A **Insured Vehicle No :** SKM9640U
Date of Loss: 08/03/2019 **Nature of Claim:** TP **Claim No:** 8418220201SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDU9696A
Make & Model: BMW 216I, 1.5 D GT LED (A) **Engine No:** 31385260B38A15A
Reg. Date: 29/06/2018 (Man. Year: 2018) **Chassis No:** WBA2D920905K81214
Colour: Grey **Odometer:** 7983 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 **Rear Tyre Size:** 205/60 R16
Front Left Side: Continental 6 mm **Rear Left Side:** Continental 6 mm
Front Right Side: Continental 6 mm **Rear Right Side:** Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,035.85	3,274.65	2,761.20	45.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,036.00	4,780.00	2,256.00	32.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,071.85	8,054.65	5,017.20	38.38
+ GST 7.00/7.00% (\$\$)	915.03	563.83	351.20	38.38
Nett Amount (\$\$)	13,986.88	8,618.48	5,368.40	38.38
+ Car Rental (4.0 x S\$80.00/day + 7.00% GST) (\$\$)		342.40		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,968.33		

INSPECTION

Date of Assignment: 01/04/2019

Date Inspected: 01/04/2019 Inspected At:

Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*BOOTLID	Dented	1,204.35 FS	*1,204.35 FS
3	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	61.50 FS	*- FS
4	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	61.50 FS	*- FS
5	1		*REAR BUMPER CARRIER	Bent	458.10 FS	*458.10 FS
6	1		*SUPPORT	Deformed	45.30 FS	*45.30 FS
7	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	67.55 FS	*67.55 FS
8	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	67.55 FS	*- FS
9	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	1,029.50 FS	*1,029.50 FS
10	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	60.35 FS	*- FS
11	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	42.85 FS	*- FS
12	1		*LETTERING 216 I	Not Necessary	64.10 FS	*- FS
13	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
14	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
15	1		*REAR WINDOW	Not Necessary	654.35 FS	*- FS
16	1		*REAR BUMPER HEAT INSULATION	Not Necessary	63.20 FS	*- FS
17	1		*BOOTLID SEALING	Not Necessary	143.00 FS	*- FS
18	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
19	4		*ULTRASONIC SENSOR MINERALGRAU B39	Not Necessary	1,522.60 FS	*- FS
20	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
21	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
22	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,035.85	3,274.65
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND BOOTLID AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	2,975.00	1,700.00
2	PAINTING REAR BUMPER ,BOOTLID ,TAIL PANEL	New	2,666.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
5	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR JOB	New	574.00	574.00
6	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
7	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	451.00	451.00
Gross Labour Cost (S\$)			7,036.00	4,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >