

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

08 MAR 2019

ESTIMATE

Estimate No. : b1 50428
Date Estimated : 08/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Neo Chye Yong (Liang CaiRong)
Blk 301 Clementi Avenue 4
#06-559

Singapore 120301

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDU9696A	5K81214	29/06/2018	216i GT	0

DESCRIPTION

To replace rear bumper and bootlid and attachment include knocking cause by the accident

1700 2,975.00

Painting rear bumper, bootlid, tail panel.

1730 2,666.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To remove and install rear windscreen glass to facilitate the repair job.

488 574.00

Total Labour 1: 6,510.00

DESCRIPTION

BOOTLID
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE
RR BUMPER RH INNER SIDE GUIDE
REAR BUMPER PANEL PRIMED (PDC)
SET MOUNTS PDC SENSOR REAR
REAR BUMPER TOWING FLAP EYE PRIMED
LETTERING 216 I
GROMMET
PLAQUE 74MM
REAR WINDOW
REAR BUMPER HEAT INSULATION
BOOTLID SEALING
DECOUPING RING PDC TORQUE CONVERTER
ULTRASONIC SENSOR MINERALGRAU B39
(DG) CLEANER R1 (100ML)

QTY PRIC

1 1,204.35
1 61.50
1 61.50
1 458.10
1 45.30
1 67.55
1 67.55
1 1,029.50
1 60.35
1 42.85
1 64.10
2 0.75
1 71.25
1 654.35
1 63.20
1 143.00
4 5.05
4 380.65
1 26.15

VALUE

del 1,204.35
? 61.50
? 61.50
? 458.10
? 45.30
? 67.55
? 67.55
del 1,029.50
del 60.35
del 42.85
del 64.10
del 1.50
del 71.25
? 654.35
? 63.20
? 143.00
del 20.20
? 1,522.60
del 26.15

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50428
Date Estimated : 08/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDU9696A	5K81214	29/06/2018	216i GT	0

DESCRIPTION

(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) GLASS PRIMER 30ML (VP206)

QTY	PRIC	VALUE
2	131.55	263.10
1	27.85	27.85

Total Parts : 5,955.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date&Time 01/04/19 Excess \$5

Surveyor's Name Tanpin Sign [Signature]

Surveyor's Tel 97495219 Authorised Yes / No

Authorised Date wp' Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanpin@lkkauto.com

No. of Working Days Recommend 5 days - body

Labour 1	:	6,510.00
Parts	:	5,955.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	872.61
Grand Total	:	13,338.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **