

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 14 Mar 2019

Preliminary Advice

Insured Vehicle No	: XE2977H	Accident Date	: 26/02/2019
TP Vehicle No	: SMF3469B	Assignment Date	: 12/03/2019
Make	: HONDA CIVIC	Est. Duration of Repair	: 12.00
Date of Inspection	: 12/03/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and undercarriage and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	10,845.04
Revised Amount	:S\$	6,853.59
Check Items (Estimated)	:S\$	2,866.95
Total	:S\$	9,720.54

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.