

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SMF3469B / TP

Version: 1810

Date calculated: 04/08/2019 10:52 AM

Full Report

Registration: SMF3469B

Printed: 20/04/2019 11:14 AM

Material Cost - Paint

New Part Painting	97.01
Repair Painting	32.95
Surface-/Blend Paint	40.59
Surface Painting Plastic	45.39
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	253.54

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier		Price SGD
0283	FRONT BUMPER	04711TECN00ZZ			300.00
0320	R/F BUMPER BRACKET	71140TEAT00			9.00
0346	R/BUMPER GRILLE	71103TEAT00			15.00
0352	CLIP FASTENING	91505TM8003			15.00
0417	GRILLE	72121TEAT01			60.00
0562	R/F HEADLAMP CPL	33100TEAT11			410.00
0742	R/F WING	60211TBAA00ZZ			160.00
0770	R/F WING BRACKET FRT	60263TBAA00ZZ	(A)	Di	18.00
0842	R/F WHEELHOUSE COVER	74101TEAT10			40.00
0848	R/FASTENING CLIP	91505TM8003			15.00
1435	WASHER RESERVOIR	76841TBAA01	(A)	Di	25.00
1482	RIGHT FRONT DOOR	67010TECQ00ZZ			500.00
1664	R/F UPP DOOR MLDG	72425TBAA01	(A)	Di	23.00
1738	R/DOOR MIRROR ASSY	76208TECE02			195.00
1746	R/DOOR MIRROR HSG	76201TBAA11ZN			30.00
1782	R/R DOOR	67510TECQ00ZZ			510.00
1796	R/R LOWER DOOR HINGE	67920T2MT02ZZ			30.00
4614	R/F AIRBAG SENSOR	77930TEAB11	(A)	Me	68.00
4661	L/F SEAT BELT	04818TBAA01ZA	(A)	Ju	580.00
4662	R/F SEAT BELT	04814TBAA01ZA	(A)	Ju	580.00
7053	L/F LWR CONTROL ARM	51360TEAT10			145.00
7054	R/F LWR CONTROL ARM	51350TEAT10			145.00
7201	L/F WHEEL	42700TEXY11			290.00
7440	AIRBAG CONTROL UNIT	77960TEAN82	(A)	Me	550.00
9386	R/R LOWER AXLE LINK	52350TEAT00	(A)	Di	60.00
9388	R/F UPP CNTRL ARM RR	52360TEAT00	(A)	R	60.00
9552	R/R WHEEL	42700TEXY11			290.00
1002	R/Sill Panel Clips	Clips			30.00
1005	R/F Wing S-Lamp	R/F Wing Lamp			25.00

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: SMF3469B / TP

Version: 1810

Date calculated: 04/08/2019 10:52 AM

Full Report

Registration: SMF3469B

Printed: 20/04/2019 11:14 AM

Code	Description	Part Number	Supplier	Price SGD
1010	F/BUMPER LWR GRILLE	71102TBAA10	} (A)	CM 45.00
1011	R/F H-LAMP LWR BRKT	71140TEAT00		CM 18.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			5,241.00
u: Used parts	Addition(+15.00%)			786.15
	Total			6,027.15

Extras

Code	Description	Price SGD
1003	L/F Tyre L/F Tyre	288 320.00* 9081a
1006	Wheel Alignment Wheel Alignment	60.00* ✓
1007	Sealant Sealant X	40.00* ✓
1008	Inner Seal Inn Seal	30.00* ✓
1009	R/R Tyre R/R Tyre	288 PM 320.00* John
1012	RE-PROGRAM AIR BAG RE-PROGRAM	Bill attached ✓ 300.00* 2881
Total Extras		1,070.00