

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19004446/T1ga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG		Date: 05-08-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLS 3129B	Veh. Inspected	FBJ 6230L
	Policy No.	GA268600/1	Coverage (\$)	0.00
	Claim No.	S9M01EX6	Excess (\$)	0.00
	Assign From	LYNN KHONG	Assign Date	12/03/2019
2. Vehicle Particulars & Condition				
	Make & Model	DUCATI HYPERSTRADA	c.c	821
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	ZDMB200AADB002693	Colour	RED
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70 R17	PIRELLI	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	180/55 R17	PIRELLI	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	23/02/2019	Inspection Date	13/03/2019
	Survey held at	WEARNES AUTOMOTIVE PTE LTD		
		45 LENG KEE ROAD SINGAPORE 159103.		
5a.				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			