

10/10/2019
 10/10/2019
 10/10/2019
 10/10/2019
 10/10/2019

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5934G

AAD1903-047

Not Authorised

Return B4 point

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5934G

JTDKB3FU503079209

RENAULT

LATITUDE

7.3.2019

CHINA TAIPING

25/1/2019

PART

LIST

1	1 FRONT BUMPER	\$	CMS 499.90 ✓
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	SL 101.20 X
3	1 REINFORCEMENT, FRONT BUMPER	\$	R 696.40 X
4	1 ABSORBER, FRONT BUMPER, LOWER	\$	SL 130.20 X
5	1 ABSORBER, FRONT BUMPER ENERGY	\$	SL 78.10 X
6	1 FRONT BUMPER SIDE RETAINER RH	\$	SL 78.00 ✓
7	1 FRONT BUMPER SIDE RETAINER LH	\$	SL 78.00 X
8	1 FRONT BUMPER SUPPORT	\$	SL 81.70 X
9	1 EXTENSION, FRONT BUMPER, RH	\$	SL 117.80 X
10	1 EXTENSION, FRONT BUMPER, LH	\$	SL 117.80 X
11	1 FRONT LED LAMP (LOWER) RH	\$	907.75 ✓
12	1 FRONT LED LAMP (LOWER) LH	\$	SL 907.75 X
13	1 FRONT HEADLAMP RH	\$	2,909.04 ✓
14	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	SL 492.30
15	1 MOTOR, HEADLAMP LEVELING, RH	\$	SL 413.10
16	1 FRONT HEADLAMP LH	\$	SL 2,909.04
17	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	SL 492.30
18	1 MOTOR, HEADLAMP LEVELING, RH	\$	SL 413.10
19	1 FRONT FENDER RH	\$	R 945.30 X
20	1 EXTENSION, FRONT FENDER, RH	\$	SL 48.80
21	1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	SL 98.30
22	1 LINER, FRONT FENDER, RH	\$	SL 200.70
23	1 FRONT FENDER EMBLEM RH	\$	SL 86.50
24	1 SEAL, FENDER APRON MUDGUARD, RH	\$	SL 50.90
25	1 FRONT BONNET	\$	R 950.50
26	1 FRONT LOWER ARM	\$	SL 631.90
27	1 FRONT SHOCK ABSORBER	\$	SL 398.20
28	1 SHAFT ASSY, FRONT DRIVE, RH	\$	R 1,186.20
29	1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	SL 637.50

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5934G**AAD1903-047**

30	1 KNUCKLE, STEERING, RH	\$	562.30	} X
31	1 LINK ASSY, FRONT STABILIZER, RH	\$	199.00	
32	1 BAR, STABILIZER, FRONT	\$	360.30	
33	1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	200.60	
34	1 ABSORBER ASSY, SHOCK, FRONT RH	\$	401.80	
35	1 COCK ASSY, RESERVE TANK	\$	117.80	
		\$	18,500.08	
25%		\$	4,625.02	
		\$	13,875.06	

Special Nett

1	1 FRONT WHEEL RIM	\$	1,570.55	X
2	1 FRONT WHEEL RIM COVER	\$	175.80	X
3	1 CLIP, FRONT FENDER LINER	\$	22.00	X
TOTAL		\$	1,768.35	
TOTAL PARTS		\$	15,643.41	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	3001
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5934G

AAD1903-047

To transfer of front windscreen fittings and conduct water seepage test.	\$	un	170.00	X
To check steering geometry and computer wheel alignment	\$	un	220.00	X
To vacuum, replace, refix and recharge air condenser	\$	un	380.00	X
To replace, refix and top up coolant for radiator	\$	un	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	un	170.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	un	380.00	X

TOTAL \$ 10,400.00

Over All Total \$ 39,918.47

26043.41

(PART-BY-PART) Repair Days

~~14~~ days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: