

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019 Edit Reg		12 Mar 2019 00:00 Edit Adj Rpt	S\$35,000.00 Edit Estimates	S\$35,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: JESLINE KWEK SIEW LEE , Co. Reg. No.: -									
Main Claimant: KWOK YU YING JADE , ID: S9335375G									
Vehicle Reg. No.:	SME3715X	Date of Loss:	09/03/2019 00:00 - :59 [5 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4458530808SG	Policy/Cover Note No.:	2100502051 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK9999J	Policy No. (Claimant):	5104046376						
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (23/04/2020): Alert - Adj Mandate Maintained - SME3715X - Claim Handler: Tan, Bennie-WZ - AIG_SG_EXPRESS (06/03/2020): Alert - Adj Mandate Maintained - SME3715X - Claim Handler: Tan, Bennie-WZ - AIG_SG_EXPRESS (29/02/2020): Alert - Adj Mandate Approved (S\$36000.00) - SME3715X - Claim Handler: Tan, Bennie... - AIG_SG_EXPRESS (17/02/2020): Alert - Adj Mandate Approved (S\$34800.00) - SME3715X - Claim Handler: Tan, Bennie... - AIG_SG_EXPRESS (03/12/2019): Alert - Adj Mandate Maintained - SME3715X - Claim Handler: Tan, Bennie-WZ									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME3715X (4458530808SG)**
[SLK9999J]

TP

KWOK YU YING JADE
Mar 9 2019 12:00AM
[JESLINE KWEK SIEW LEE]
Fastech Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Video

1 per page ▼ ☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/09/19 12:28	Video - Accident (SLS1841R)		Load MP4	
2	23/09/19 09:56	Video - Accident		Load MP4	
3	23/09/19 09:56	Video - Accident SFA819D - rear		Load MP4	

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports

1 per page ▼ ☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/03/19 16:39	Accident Statement From:SC - Reg. No: SLK9999J, Claimant: JESLINE KWEK SIEW LEE		Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/03/19 18:22	Chassis Number		Load JPG	☒
2	12/03/19 18:22	Odometer Reading		Load JPG	☒
3	12/03/19 18:23	General View		Load JPG	☒
4	12/03/19 18:23	General View		Load JPG	☒
5	12/03/19 18:23	General View		Load JPG	☒
6	12/03/19 18:23	General View		Load JPG	☒
7	12/03/19 18:23	General View		Load JPG	☒
8	12/03/19 18:23	General View		Load JPG	☒
9	12/03/19 18:23	General View		Load JPG	☒
10	12/03/19 18:23	General View		Load JPG	☒
11	12/03/19 18:23	General View		Load JPG	☒
12	12/03/19 18:23	General View		Load JPG	☒
13	12/03/19 18:23	General View		Load JPG	☒
14	12/03/19 18:23	General View		Load JPG	☒
15	12/03/19 18:23	General View		Load JPG	☒
16	12/03/19 18:23	General View		Load JPG	☒
17	12/03/19 18:23	General View		Load JPG	☒
18	12/03/19 18:23	General View		Load JPG	☒
19	12/03/19 18:23	General View		Load JPG	☒
20	12/03/19 18:23	General View		Load JPG	☒
21	12/03/19 18:23	General View		Load JPG	☒
22	12/03/19 18:23	General View		Load JPG	☒
23	12/03/19 18:23	General View		Load JPG	☒
24	12/03/19 18:23	General View		Load JPG	☒
25	12/03/19 18:23	General View		Load JPG	☒
26	12/03/19 18:23	General View		Load JPG	☒
27	12/03/19 18:23	General View		Load JPG	☒
28	12/03/19 18:23	General View		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
29	12/03/19 18:23	General View		Load JPG	☒
30	12/03/19 18:23	General View		Load JPG	☒
31	12/03/19 18:23	General View		Load JPG	☒
32	12/03/19 18:23	General View		Load JPG	☒
33	12/03/19 18:23	General View		Load JPG	☒
34	12/03/19 18:23	General View		Load JPG	☒
35	12/03/19 18:23	General View		Load JPG	☒
36	12/03/19 18:23	General View		Load JPG	☒
37	12/03/19 18:23	General View		Load JPG	☒
38	12/03/19 18:23	General View		Load JPG	☒
39	12/03/19 18:23	General View		Load JPG	☒
40	12/03/19 18:23	General View		Load JPG	☒
41	12/03/19 18:23	General View		Load JPG	☒
42	12/03/19 18:23	General View		Load JPG	☒
43	12/03/19 18:23	General View		Load JPG	☒
44	12/03/19 18:23	General View		Load JPG	☒
45	12/03/19 18:23	General View		Load JPG	☒
46	12/03/19 18:23	General View		Load JPG	☒
47	12/03/19 18:23	General View		Load JPG	☒
48	12/03/19 18:23	General View		Load JPG	☒
49	12/03/19 18:23	General View		Load JPG	☒
50	12/03/19 18:23	General View		Load JPG	☒
51	12/03/19 18:23	General View		Load JPG	☒
52	12/03/19 18:23	General View		Load JPG	☒
53	12/03/19 18:23	General View		Load JPG	☒
54	12/03/19 18:23	General View		Load JPG	☒
55	12/03/19 18:23	General View		Load JPG	☒
56	12/03/19 18:23	General View		Load JPG	☒
57	12/03/19 18:23	General View		Load JPG	☒
58	12/03/19 18:23	General View		Load JPG	☒
59	12/03/19 18:23	General View		Load JPG	☒
60	12/03/19 18:23	General View		Load JPG	☒
61	12/03/19 18:23	General View		Load JPG	☒
62	12/03/19 18:23	General View		Load JPG	☒
63	12/03/19 18:23	General View		Load JPG	☒
64	12/03/19 18:23	General View		Load JPG	☒
65	12/03/19 18:23	General View		Load JPG	☒
66	12/03/19 18:23	General View		Load JPG	☒
67	12/03/19 18:23	General View		Load JPG	☒
68	12/03/19 18:23	General View		Load JPG	☒
69	12/03/19 18:23	General View		Load JPG	☒
70	12/03/19 18:23	General View		Load JPG	☒
71	12/03/19 18:23	General View		Load JPG	☒
72	12/03/19 18:23	General View		Load JPG	☒
73	12/03/19 18:23	General View		Load JPG	☒
74	12/03/19 18:23	General View		Load JPG	☒
75	12/03/19 18:23	General View		Load JPG	☒
76	12/03/19 18:23	General View		Load JPG	☒
77	12/03/19 18:23	General View		Load JPG	☒
78	12/03/19 18:23	General View		Load JPG	☒
79	12/03/19 18:23	General View		Load JPG	☒
80	12/03/19 18:23	General View		Load JPG	☒
81	12/03/19 18:23	General View		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
82	12/03/19 18:23	General View		Load JPG	☒
83	12/03/19 18:23	General View		Load JPG	☒
84	12/03/19 18:23	General View		Load JPG	☒
85	12/03/19 18:23	General View		Load JPG	☒
86	12/03/19 18:23	General View		Load JPG	☒
87	12/03/19 18:23	General View		Load JPG	☒
88	12/03/19 18:23	General View		Load JPG	☒
89	12/03/19 18:23	General View		Load JPG	☒
90	12/03/19 18:23	General View		Load JPG	☒
91	12/03/19 18:23	General View		Load JPG	☒
92	12/03/19 18:23	General View		Load JPG	☒
93	12/03/19 18:23	General View		Load JPG	☒
94	12/03/19 18:23	General View		Load JPG	☒
95	12/03/19 18:23	General View		Load JPG	☒
96	12/03/19 18:23	General View		Load JPG	☒
97	12/03/19 18:23	General View		Load JPG	☒
98	12/03/19 18:23	General View		Load JPG	☒
99	12/03/19 18:23	General View		Load JPG	☒
100	12/03/19 18:23	General View		Load JPG	☒
101	12/03/19 18:23	General View		Load JPG	☒
102	12/03/19 18:23	General View		Load JPG	☒
103	12/03/19 18:23	General View		Load JPG	☒
104	12/03/19 18:23	General View		Load JPG	☒
105	07/05/19 08:56	Reinspection Photo		Load JPG	☒
106	07/05/19 08:56	Reinspection Photo		Load JPG	☒
107	07/05/19 08:56	Reinspection Photo		Load JPG	☒
108	07/05/19 08:56	Reinspection Photo		Load JPG	☒
109	07/05/19 08:57	Reinspection Photo		Load JPG	☒
110	07/05/19 08:57	Reinspection Photo		Load JPG	☒
111	07/05/19 08:57	Reinspection Photo		Load JPG	☒
112	07/05/19 08:57	Reinspection Photo		Load JPG	☒
113	07/05/19 08:57	Reinspection Photo		Load JPG	☒
114	07/05/19 08:57	Reinspection Photo		Load JPG	☒
115	07/05/19 08:57	Reinspection Photo		Load JPG	☒
116	07/05/19 08:57	Reinspection Photo		Load JPG	☒
117	07/05/19 08:57	Reinspection Photo		Load JPG	☒
118	07/05/19 08:57	Reinspection Photo		Load JPG	☒
119	07/05/19 08:57	Reinspection Photo		Load JPG	☒
120	07/05/19 08:57	Reinspection Photo		Load JPG	☒
121	07/05/19 08:57	Reinspection Photo		Load JPG	☒
122	07/05/19 08:58	Reinspection Photo		Load JPG	☒
123	07/05/19 08:58	Reinspection Photo		Load JPG	☒
124	07/05/19 08:58	Reinspection Photo		Load JPG	☒
125	07/05/19 08:58	Reinspection Photo		Load JPG	☒
126	07/05/19 08:58	Reinspection Photo		Load JPG	☒
127	07/05/19 08:58	Reinspection Photo		Load JPG	☒
128	07/05/19 08:58	Reinspection Photo		Load JPG	☒
129	07/05/19 08:58	Reinspection Photo		Load JPG	☒
130	07/05/19 08:58	Reinspection Photo		Load JPG	☒
131	07/05/19 08:58	Reinspection Photo		Load JPG	☒
132	07/05/19 08:58	Reinspection Photo		Load JPG	☒
133	07/05/19 08:58	Reinspection Photo		Load JPG	☒
134	07/05/19 08:58	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
135	07/05/19 08:58	Reinspection Photo		Load JPG	☒
136	07/05/19 08:58	Reinspection Photo		Load JPG	☒
137	07/05/19 08:58	Reinspection Photo		Load JPG	☒
138	07/05/19 08:58	Reinspection Photo		Load JPG	☒
139	07/05/19 08:58	Reinspection Photo		Load JPG	☒
140	07/05/19 08:58	Reinspection Photo		Load JPG	☒
141	07/05/19 08:58	Reinspection Photo		Load JPG	☒
142	07/05/19 08:58	Reinspection Photo		Load JPG	☒
143	07/05/19 08:58	Reinspection Photo		Load JPG	☒
144	07/05/19 08:58	Reinspection Photo		Load JPG	☒
145	07/05/19 08:58	Reinspection Photo		Load JPG	☒
146	07/05/19 08:58	Reinspection Photo		Load JPG	☒
147	07/05/19 08:58	Reinspection Photo		Load JPG	☒
148	07/05/19 08:58	Reinspection Photo		Load JPG	☒
149	07/05/19 08:58	Reinspection Photo		Load JPG	☒
150	07/05/19 08:58	Reinspection Photo		Load JPG	☒
151	07/05/19 08:58	Reinspection Photo		Load JPG	☒
152	07/05/19 08:58	Reinspection Photo		Load JPG	☒
153	07/05/19 08:58	Reinspection Photo		Load JPG	☒
154	07/05/19 08:58	Reinspection Photo		Load JPG	☒
155	07/05/19 08:58	Reinspection Photo		Load JPG	☒
156	07/05/19 08:58	Reinspection Photo		Load JPG	☒
157	07/05/19 08:58	Reinspection Photo		Load JPG	☒
158	07/05/19 08:58	Reinspection Photo		Load JPG	☒
159	07/05/19 08:58	Reinspection Photo		Load JPG	☒
160	07/05/19 08:58	Reinspection Photo		Load JPG	☒
161	07/05/19 08:58	Reinspection Photo		Load JPG	☒
162	07/05/19 08:59	Reinspection Photo		Load JPG	☒
163	07/05/19 08:59	Reinspection Photo		Load JPG	☒
164	07/05/19 08:59	Reinspection Photo		Load JPG	☒
165	07/05/19 08:59	Reinspection Photo		Load JPG	☒
166	07/05/19 08:59	Reinspection Photo		Load JPG	☒
167	07/05/19 08:59	Reinspection Photo		Load JPG	☒
168	07/05/19 08:59	Reinspection Photo		Load JPG	☒
169	07/05/19 08:59	Reinspection Photo		Load JPG	☒
170	07/05/19 08:59	Reinspection Photo		Load JPG	☒
171	07/05/19 08:59	Reinspection Photo		Load JPG	☒
172	07/05/19 08:59	Reinspection Photo		Load JPG	☒
173	07/05/19 08:59	Reinspection Photo		Load JPG	☒
174	07/05/19 08:59	Reinspection Photo		Load JPG	☒
175	07/05/19 08:59	Reinspection Photo		Load JPG	☒
176	07/05/19 08:59	Reinspection Photo		Load JPG	☒
177	07/05/19 08:59	Reinspection Photo		Load JPG	☒
178	07/05/19 08:59	Reinspection Photo		Load JPG	☒
179	07/05/19 08:59	Reinspection Photo		Load JPG	☒
180	07/05/19 08:59	Reinspection Photo		Load JPG	☒
181	07/05/19 08:59	Reinspection Photo		Load JPG	☒
182	07/05/19 08:59	Reinspection Photo		Load JPG	☒
183	07/05/19 08:59	Reinspection Photo		Load JPG	☒
184	07/05/19 08:59	Reinspection Photo		Load JPG	☒
185	07/05/19 08:59	Reinspection Photo		Load JPG	☒
186	07/05/19 08:59	Reinspection Photo		Load JPG	☒
187	07/05/19 08:59	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
188	07/05/19 08:59	Reinspection Photo		Load JPG	☒
189	07/05/19 08:59	Reinspection Photo		Load JPG	☒
190	07/05/19 08:59	Reinspection Photo		Load JPG	☒
191	07/05/19 08:59	Reinspection Photo		Load JPG	☒
192	07/05/19 08:59	Reinspection Photo		Load JPG	☒
193	07/05/19 08:59	Reinspection Photo		Load JPG	☒
194	07/05/19 08:59	Reinspection Photo		Load JPG	☒
195	07/05/19 08:59	Reinspection Photo		Load JPG	☒
196	07/05/19 08:59	Reinspection Photo		Load JPG	☒
197	07/05/19 08:59	Reinspection Photo		Load JPG	☒
198	07/05/19 08:59	Reinspection Photo		Load JPG	☒
199	07/05/19 08:59	Reinspection Photo		Load JPG	☒
200	07/05/19 08:59	Reinspection Photo		Load JPG	☒
201	07/05/19 08:59	Reinspection Photo		Load JPG	☒
202	07/05/19 08:59	Reinspection Photo		Load JPG	☒
203	07/05/19 08:59	Reinspection Photo		Load JPG	☒
204	07/05/19 08:59	Reinspection Photo		Load JPG	☒
205	07/05/19 08:59	Reinspection Photo		Load JPG	☒
206	07/05/19 08:59	Reinspection Photo		Load JPG	☒
207	07/05/19 08:59	Reinspection Photo		Load JPG	☒
208	07/05/19 08:59	Reinspection Photo		Load JPG	☒
209	07/05/19 08:59	Reinspection Photo		Load JPG	☒
210	07/05/19 08:59	Reinspection Photo		Load JPG	☒
211	07/05/19 08:59	Reinspection Photo		Load JPG	☒
212	07/05/19 08:59	Reinspection Photo		Load JPG	☒
213	07/05/19 08:59	Reinspection Photo		Load JPG	☒
214	07/05/19 08:59	Reinspection Photo		Load JPG	☒
215	07/05/19 08:59	Reinspection Photo		Load JPG	☒
216	07/05/19 08:59	Reinspection Photo		Load JPG	☒
217	07/05/19 08:59	Reinspection Photo		Load JPG	☒
218	07/05/19 08:59	Reinspection Photo		Load JPG	☒
219	07/05/19 08:59	Reinspection Photo		Load JPG	☒
220	07/05/19 08:59	Reinspection Photo		Load JPG	☒
221	07/05/19 08:59	Reinspection Photo		Load JPG	☒
222	07/05/19 08:59	Reinspection Photo		Load JPG	☒
223	07/05/19 08:59	Reinspection Photo		Load JPG	☒
224	07/05/19 08:59	Reinspection Photo		Load JPG	☒
225	07/05/19 08:59	Reinspection Photo		Load JPG	☒
226	07/05/19 08:59	Reinspection Photo		Load JPG	☒
227	07/05/19 08:59	Reinspection Photo		Load JPG	☒
228	07/05/19 08:59	Reinspection Photo		Load JPG	☒
229	07/05/19 08:59	Reinspection Photo		Load JPG	☒
230	07/05/19 08:59	Reinspection Photo		Load JPG	☒
231	07/05/19 08:59	Reinspection Photo		Load JPG	☒
232	07/05/19 08:59	Reinspection Photo		Load JPG	☒
233	07/05/19 08:59	Reinspection Photo		Load JPG	☒
234	07/05/19 08:59	Reinspection Photo		Load JPG	☒
235	07/05/19 08:59	Reinspection Photo		Load JPG	☒
236	07/05/19 08:59	Reinspection Photo		Load JPG	☒
237	07/05/19 08:59	Reinspection Photo		Load JPG	☒
238	07/05/19 08:59	Reinspection Photo		Load JPG	☒
239	07/05/19 08:59	Reinspection Photo		Load JPG	☒
240	07/05/19 08:59	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
241	07/05/19 08:59	Reinspection Photo		Load JPG	☒
242	07/05/19 08:59	Reinspection Photo		Load JPG	☒
243	07/05/19 08:59	Reinspection Photo		Load JPG	☒
244	07/05/19 08:59	Reinspection Photo		Load JPG	☒
245	07/05/19 08:59	Reinspection Photo		Load JPG	☒
246	07/05/19 08:59	Reinspection Photo		Load JPG	☒
247	07/05/19 08:59	Reinspection Photo		Load JPG	☒
248	07/05/19 08:59	Reinspection Photo		Load JPG	☒
249	07/05/19 08:59	Reinspection Photo		Load JPG	☒
250	07/05/19 08:59	Reinspection Photo		Load JPG	☒
251	07/05/19 08:59	Reinspection Photo		Load JPG	☒
252	07/05/19 08:59	Reinspection Photo		Load JPG	☒
253	07/05/19 08:59	Reinspection Photo		Load JPG	☒
254	07/05/19 08:59	Reinspection Photo		Load JPG	☒
255	07/05/19 08:59	Reinspection Photo		Load JPG	☒
256	07/05/19 08:59	Reinspection Photo		Load JPG	☒
257	07/05/19 08:59	Reinspection Photo		Load JPG	☒
258	07/05/19 08:59	Reinspection Photo		Load JPG	☒
259	07/05/19 08:59	Reinspection Photo		Load JPG	☒
260	07/05/19 08:59	Reinspection Photo		Load JPG	☒
261	07/05/19 08:59	Reinspection Photo		Load JPG	☒
262	07/05/19 08:59	Reinspection Photo		Load JPG	☒
263	07/05/19 08:59	Reinspection Photo		Load JPG	☒
264	07/05/19 08:59	Reinspection Photo		Load JPG	☒
265	07/05/19 08:59	Reinspection Photo		Load JPG	☒
266	07/05/19 08:59	Reinspection Photo		Load JPG	☒
267	07/05/19 08:59	Reinspection Photo		Load JPG	☒
268	07/05/19 08:59	Reinspection Photo		Load JPG	☒
269	07/05/19 08:59	Reinspection Photo		Load JPG	☒
270	07/05/19 08:59	Reinspection Photo		Load JPG	☒
271	07/05/19 08:59	Reinspection Photo		Load JPG	☒
272	07/05/19 08:59	Reinspection Photo		Load JPG	☒
273	07/05/19 08:59	Reinspection Photo		Load JPG	☒
274	07/05/19 08:59	Reinspection Photo		Load JPG	☒
275	07/05/19 08:59	Reinspection Photo		Load JPG	☒
276	07/05/19 08:59	Reinspection Photo		Load JPG	☒
277	07/05/19 08:59	Reinspection Photo		Load JPG	☒
278	07/05/19 08:59	Reinspection Photo		Load JPG	☒
279	07/05/19 08:59	Reinspection Photo		Load JPG	☒
280	07/05/19 08:59	Reinspection Photo		Load JPG	☒
281	07/05/19 08:59	Reinspection Photo		Load JPG	☒
282	07/05/19 08:59	Reinspection Photo		Load JPG	☒
283	07/05/19 08:59	Reinspection Photo		Load JPG	☒
284	07/05/19 08:59	Reinspection Photo		Load JPG	☒
285	07/05/19 08:59	Reinspection Photo		Load JPG	☒
286	07/05/19 08:59	Reinspection Photo		Load JPG	☒
287	07/05/19 08:59	Reinspection Photo		Load JPG	☒
288	07/05/19 08:59	Reinspection Photo		Load JPG	☒
289	07/05/19 08:59	Reinspection Photo		Load JPG	☒
290	07/05/19 08:59	Reinspection Photo		Load JPG	☒
291	07/05/19 08:59	Reinspection Photo		Load JPG	☒
292	07/05/19 08:59	Reinspection Photo		Load JPG	☒
293	07/05/19 08:59	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
294	07/05/19 08:59	Reinspection Photo		Load JPG	☒
295	07/05/19 08:59	Reinspection Photo		Load JPG	☒
296	07/05/19 08:59	Reinspection Photo		Load JPG	☒
297	07/05/19 08:59	Reinspection Photo		Load JPG	☒
298	07/05/19 08:59	Reinspection Photo		Load JPG	☒
299	07/05/19 08:59	Reinspection Photo		Load JPG	☒
300	07/05/19 08:59	Reinspection Photo		Load JPG	☒
301	07/05/19 08:59	Reinspection Photo		Load JPG	☒
302	07/05/19 08:59	Reinspection Photo		Load JPG	☒
303	07/05/19 08:59	Reinspection Photo		Load JPG	☒
304	07/05/19 08:59	Reinspection Photo		Load JPG	☒
305	07/05/19 08:59	Reinspection Photo		Load JPG	☒
306	07/05/19 08:59	Reinspection Photo		Load JPG	☒
307	07/05/19 08:59	Reinspection Photo		Load JPG	☒
308	07/05/19 08:59	Reinspection Photo		Load JPG	☒
309	07/05/19 08:59	Reinspection Photo		Load JPG	☒
310	07/05/19 08:59	Reinspection Photo		Load JPG	☒
311	07/05/19 08:59	Reinspection Photo		Load JPG	☒
312	07/05/19 08:59	Reinspection Photo		Load JPG	☒
313	07/05/19 08:59	Reinspection Photo		Load JPG	☒
314	07/05/19 08:59	Reinspection Photo		Load JPG	☒
315	07/05/19 08:59	Reinspection Photo		Load JPG	☒
316	07/05/19 08:59	Reinspection Photo		Load JPG	☒
317	07/05/19 08:59	Reinspection Photo		Load JPG	☒
318	07/05/19 08:59	Reinspection Photo		Load JPG	☒
319	07/05/19 08:59	Reinspection Photo		Load JPG	☒
320	07/05/19 08:59	Reinspection Photo		Load JPG	☒
321	07/05/19 08:59	Reinspection Photo		Load JPG	☒
322	07/05/19 08:59	Reinspection Photo		Load JPG	☒
323	07/05/19 08:59	Reinspection Photo		Load JPG	☒
324	07/05/19 08:59	Reinspection Photo		Load JPG	☒
325	07/05/19 08:59	Reinspection Photo		Load JPG	☒
326	07/05/19 08:59	Reinspection Photo		Load JPG	☒
327	07/05/19 08:59	Reinspection Photo		Load JPG	☒
328	07/05/19 08:59	Reinspection Photo		Load JPG	☒
329	07/05/19 08:59	Reinspection Photo		Load JPG	☒
330	07/05/19 08:59	Reinspection Photo		Load JPG	☒
331	07/05/19 08:59	Reinspection Photo		Load JPG	☒
332	07/05/19 08:59	Reinspection Photo		Load JPG	☒
333	07/05/19 08:59	Reinspection Photo		Load JPG	☒
334	07/05/19 08:59	Reinspection Photo		Load JPG	☒
335	07/05/19 08:59	Reinspection Photo		Load JPG	☒
336	07/05/19 08:59	Reinspection Photo		Load JPG	☒
337	07/05/19 08:59	Reinspection Photo		Load JPG	☒
338	07/05/19 08:59	Reinspection Photo		Load JPG	☒
339	07/05/19 08:59	Reinspection Photo		Load JPG	☒
340	07/05/19 08:59	Reinspection Photo		Load JPG	☒
341	07/05/19 08:59	Reinspection Photo		Load JPG	☒
342	07/05/19 09:00	Reinspection Photo		Load JPG	☒
343	07/05/19 09:00	Reinspection Photo		Load JPG	☒
344	07/05/19 09:00	Reinspection Photo		Load JPG	☒
345	07/05/19 09:00	Reinspection Photo		Load JPG	☒
346	07/05/19 09:00	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
347	07/05/19 09:00	Reinspection Photo		Load JPG	☒
348	07/05/19 09:00	Reinspection Photo		Load JPG	☒
349	07/05/19 09:00	Reinspection Photo		Load JPG	☒
350	07/05/19 09:00	Reinspection Photo		Load JPG	☒
351	07/05/19 09:00	Reinspection Photo		Load JPG	☒
352	07/05/19 09:00	Reinspection Photo		Load JPG	☒
353	07/05/19 09:00	Reinspection Photo		Load JPG	☒
354	07/05/19 09:00	Reinspection Photo		Load JPG	☒
355	07/05/19 09:00	Reinspection Photo		Load JPG	☒
356	07/05/19 09:00	Reinspection Photo		Load JPG	☒
357	07/05/19 09:00	Reinspection Photo		Load JPG	☒
358	07/05/19 09:00	Reinspection Photo		Load JPG	☒
359	07/05/19 09:00	Reinspection Photo		Load JPG	☒
360	07/05/19 09:00	Reinspection Photo		Load JPG	☒
361	07/05/19 09:00	Reinspection Photo		Load JPG	☒
362	07/05/19 09:00	Reinspection Photo		Load JPG	☒
363	07/05/19 09:00	Reinspection Photo		Load JPG	☒
364	07/05/19 09:00	Reinspection Photo		Load JPG	☒
365	07/05/19 09:00	Reinspection Photo		Load JPG	☒
366	07/05/19 09:00	Reinspection Photo		Load JPG	☒
367	07/05/19 09:00	Reinspection Photo		Load JPG	☒
368	07/05/19 09:00	Reinspection Photo		Load JPG	☒
369	07/05/19 09:00	Reinspection Photo		Load JPG	☒
370	07/05/19 09:00	Reinspection Photo		Load JPG	☒
371	07/05/19 09:00	Reinspection Photo		Load JPG	☒
372	07/05/19 09:00	Reinspection Photo		Load JPG	☒
373	07/05/19 09:00	Reinspection Photo		Load JPG	☒
374	07/05/19 09:00	Reinspection Photo		Load JPG	☒
375	07/05/19 09:00	Reinspection Photo		Load JPG	☒
376	07/05/19 09:00	Reinspection Photo		Load JPG	☒
377	07/05/19 09:00	Reinspection Photo		Load JPG	☒
378	07/05/19 09:00	Reinspection Photo		Load JPG	☒
379	07/05/19 09:00	Reinspection Photo		Load JPG	☒
380	07/05/19 09:00	Reinspection Photo		Load JPG	☒
381	07/05/19 09:00	Reinspection Photo		Load JPG	☒
382	07/05/19 09:00	Reinspection Photo		Load JPG	☒
383	07/05/19 09:00	Reinspection Photo		Load JPG	☒
384	07/05/19 09:00	Reinspection Photo		Load JPG	☒
385	07/05/19 09:00	Reinspection Photo		Load JPG	☒
386	07/05/19 09:00	Reinspection Photo		Load JPG	☒
387	07/05/19 09:00	Reinspection Photo		Load JPG	☒
388	07/05/19 09:00	Reinspection Photo		Load JPG	☒
389	07/05/19 09:00	Reinspection Photo		Load JPG	☒
390	07/05/19 09:00	Reinspection Photo		Load JPG	☒
391	07/05/19 09:00	Reinspection Photo		Load JPG	☒
392	07/05/19 09:00	Reinspection Photo		Load JPG	☒
393	07/05/19 09:00	Reinspection Photo		Load JPG	☒
394	07/05/19 09:00	Reinspection Photo		Load JPG	☒
395	07/05/19 09:00	Reinspection Photo		Load JPG	☒
396	07/05/19 09:00	Reinspection Photo		Load JPG	☒
397	07/05/19 09:00	Reinspection Photo		Load JPG	☒
398	07/05/19 09:00	Reinspection Photo		Load JPG	☒
399	07/05/19 09:00	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
400	07/05/19 09:00	Reinspection Photo		Load JPG	☒
401	07/05/19 09:00	Reinspection Photo		Load JPG	☒
402	07/05/19 09:00	Reinspection Photo		Load JPG	☒
403	07/05/19 09:00	Reinspection Photo		Load JPG	☒
404	07/05/19 09:00	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/03/19 12:09	TP GIA REPORT		Load PDF	
2	22/07/19 09:39	EMAIL TO OI		Load PDF	
3	02/09/19 17:47	GIA SEARCH		Load PDF	
4	02/09/19 17:47	LOD		Load PDF	
5	02/09/19 17:47	RENTAL MILEAGE		Load PDF	
6	02/09/19 17:47	RENTAL RECEIPT		Load PDF	
7	21/10/19 11:17	PARF COE REBATE		Load PDF	
8	24/02/20 13:17	Email from TP reject offer		Load PDF	
9	26/03/20 16:29	Email from TP reject offer		Load PDF	
10	30/06/20 09:29	Authorisation to Act		Load PDF	
11	30/06/20 09:29	Release Voucher		Load PDF	
12	30/06/20 09:29	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/11/19 11:51	Interim CLEAR		Load XLSX	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK9999J (Insd veh)	Model:	SEAT IBIZA 999CC 5DR 1.0
	SME3715X (TP veh)		ECOTSI 110 FR 7 (A)
Date of Accident:	09/03/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:\$	73,185.86	
Final Repair Cost	:\$	36,000.00	
Loss of Use	:\$	days at \$0.00 per day	
Rental (if any)	:\$	32 days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$	36,000.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:\$	36,000.00
2)		:\$	
3)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

30 Jun
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19004504/UKA3S2**Date:** 30/06/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100502051
Claimant Vehicle No :	SME3715X	Insured Vehicle No :	SLK9999J
Date of Loss:	09/03/2019	Nature of Claim:	TP
		Claim No:	4458530808SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME3715X		
Make & Model:	SEAT IBIZA, 999cc 5DR 1.0 ECOTSI 110 FR 7 (A)	Engine No:	DKJ016322
Reg. Date:	27/09/2018 (Man. Year: 2018)	Chassis No:	VSSZZKJZR133983
Colour:	Orange	Odometer:	6031 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	57,398.00	31,655.30	25,742.70	44.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,000.00	5,670.00	5,330.00	48.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	68,398.00	37,325.30	31,072.70	45.43
Approved Total (Overridden) (S\$)		35,000.00		
(S\$)	68,398.00	35,000.00	33,398.00	48.83
+ GST 7.00/7.00% (S\$)	4,787.86	2,450.00	2,337.86	48.83
Nett Amount (S\$)	73,185.86	37,450.00	35,735.86	48.83
+ Car Rental (32.0 x S\$100.00/day) (S\$)		3,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		40,652.00		
Global Sum Settlement (S\$)		36,000.00		

INSPECTION

Date of Assignment:	12/03/2019	
Date Inspected:	12/03/2019	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	25.0 days	

Adjuster: MARCUS CHUA**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$75,000

LTA REBATE: \$39,892

NETT VALUE: \$35,108

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	125.00 F	*125.00 FL
2	1		*TAILGATE	Badly Dented	1,450.00 F	*1,450.00 FL
3	1		*TAILGATE INNER LOCK	Twisted / Jammed	325.00 F	*315.00 FL
4	1		*TAILGATE REAR LOGO	Necessary	85.00 F	*75.00 FL
5	1		*TAILGATE IBIZA EMBLEM	Necessary	90.00 F	*90.00 FL
6	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	488.00 F	*395.00 FL
7	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*TAILGATE WEATHERSTRIP	Twisted	311.00 F	*311.00 FL
9	2		*TAILGATE DAMPERS	Serviceable	500.00 F	*- FL
10	1		*REAR BUMPER	Distorted	1,250.00 F	*1,250.00 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
12	1		*REAR BUMPER TOW COVER	Twisted	25.00 F	*25.00 FL
13	1		*REAR BUMPER LOWER SKIRTING	Distorted	685.00 F	*685.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Distorted	711.00 F	*550.00 FL
15	1		*REAR BUMPER SPONGE	Not fitted	285.00 F	*- FL
16	1		*REAR BUMPER INNER RETAINER	Not Necessary	215.00 F	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
18	1		*REAR BUMPER LICENCE LAMP	Serviceable	150.00 F	*- FL
19	1		*REAR BUMPER REFLECTORS	O/s Broken	170.00 F	*85.00 FL
20	4		*REAR BUMPER PDC SENSORS	Shorted 2pcs Only	740.00 F	*370.00 FL
21	1		*REAR END PANEL	Badly Dented	699.00 F	*699.00 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	288.00 F	*288.00 FL
23	1		*REAR FLOOR PANEL	Repair	1,125.00 F	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	645.00 F	*- FL
25	2		*REAR FENDERS	Repair	2,300.00 F	*- FL
26	1		*REAR FENDER INNER TRIMS	O/s Torn	970.00 F	*485.00 FL
27	2		*TAILLAMPS	Cracked	1,840.00 F	*1,650.00 FL
28	2		*TAILLAMP HOUSING PANELS	Repair	850.00 F	*- FL
29	1		*REAR EXHAUST	Repair	688.00 F	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Bent	199.00 F	*199.00 FL
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	120.00 F	*- FL
32	2		*REAR FENDER INNER TOP SIDE GARNISHS	Serviceable	630.00 F	*- FL
33	1		*REAR SPARE TYRE TOOLS SPONGE	Torn	699.00 F	*488.00 FL
34	1		*REAR SPARE TYRE LOCK NUT	Cracked	60.00 F	*60.00 FL
35	1		*REAR AXLE BEAM	Serviceable	1,885.00 F	*- FL
36	2		*REAR SHOCK ABSORBERS	Not Necessary	500.00 F	*- FL
37	1		*REAR FENDER UNDER SHIELDS	O/s Torn	370.00 F	*185.00 FL
38	1		*BONNET	Buckled	1,685.00 F	*1,685.00 FL
39	2		*BONNET HINGES	Bent	220.00 F	*220.00 FL
40	1		*BONNET INNER RUBBER	Necessary	60.00 F	*60.00 FL
41	2		*BONNET LOCKS	Twisted	390.00 F	*390.00 FL
42	1		*FRONT BUMPER	Distorted	1,250.00 F	*1,250.00 FL
43	1		*FRONT BUMPER TOW COVER	Not Necessary	45.00 F	*- FL
44	1		*FRONT BUMPER CENTRE GARNISH	Distorted	392.00 F	*392.00 FL
45	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	430.00 F	*- FL
46	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	120.00 F	*- FL
47	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
48	1		*FRONT BUMPER SPONGE	Torn	199.00 F	*199.00 FL
49	1		*FRONT BUMPER REINFORCEMENT	Bent	715.00 F	*715.00 FL
50	1		*FRONT GRILLE	Cracked	688.00 F	*688.00 FL
51	1		*FRONT GRILLE LOGO	Necessary	95.00 F	*95.00 FL
52	1		*SET FRONT GRILLE CLIPS	Not Necessary	20.00 F	*- FL
53	2		*HEADLAMPS	Cracked	2,200.00 F	*2,200.00 FL
54	2		*HEADLAMP MOUNTINGS	Not Necessary	50.00 F	*- FL
55	2		*HEADLAMP TOP PANELS	Buckled	210.00 F	*210.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT SUPPORT PANEL	Bent / Cracked	799.00 F	*799.00 FL
57	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	311.00 F	*311.00 FL
58	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	30.00 F	*30.00 FL
59	1		*AIR CON CONDENSER	Bent / Punctured	1,285.00 F	*1,285.00 FL
60	1		*AIR CON SUCTION HOSE	Not Necessary	319.00 F	*- FL
61	1		*AIR CON DISCHARGE HOSE	Not Necessary	366.00 F	*- FL
62	2		*AIR CON SIDE GARNISHS	Torn	190.00 F	*190.00 FL
63	1		*RADIATOR	Bent / Punctured	1,485.00 F	*1,485.00 FL
64	1		*RADIATOR FAN ASSY	Cracked / Jammed	815.00 F	*815.00 FL
65	1		*WIPER WASHER TANK	Deformed	220.00 F	*220.00 FL
66	2		*FRONT FENDERS	Buckled	1,238.00 F	*1,238.00 FL
67	2		*FRONT FENDER INNER SHIELDS	Not Necessary	290.00 F	*- FL
68	1		*HORN UNIT	Not Necessary	60.00 F	*- FL
69	2		*FRONT DOORS	Repair	2,398.00 F	*- FL
70	1		*ALTERNATOR	Not Necessary	1,200.00 F	*- FL
71	2		*FRONT BUMPER SENSORS	Shorted	390.00 F	*390.00 FL
72	1		*FRONT BUMPER LOWER TRAY	Torn	366.00 F	*366.00 FL
73	1		*SET FRONT BUMPER TRAY CLIPS	Necessary	30.00 F	*30.00 FL
74	1		*AIR BAG PASSENGER	Activated	2,400.00 F	*2,400.00 FL
75	1		*AIR BAG DRIVER	Activated	1,885.00 F	*1,885.00 FL
76	1		*DASHBOARD	Burst	1,655.00 F	*1,655.00 FL
77	1		*AIR BAG SPIRAL SENSOR	Activated	225.00 F	*225.00 FL
78	1		*AIR BAG CONTROL UNIT	Activated	1,050.00 F	*1,050.00 FL
79	2		*SAFETY BELTS	Activated	1,830.00 F	*1,830.00 FL
80	1		*FRONT STEERING RACK ASSY	Not Necessary	4,880.00 F	*- FL
81	1		*AIR DUCT	Cracked	199.00 F	*199.00 FL
82	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
83	1		*REAR LICENCE PLATE W/HOLDER	Broken	50.00 FS	*40.00 FS
84	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
85	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	250.00 FS	*100.00 FS
86	1		*SET REAR REVERSE CAMERA	Shorted	480.00 FS	*380.00 FS
87	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
88	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	57,398.00	35,097.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	3,441.70
Total Parts (\$\$)	57,398.00	31,655.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOEING CHARGE KING ROLLER.	New	150.00	120.00
2	TO CHECK WIRING.	New	80.00	30.00
3	TO DISMANTLE & REPLACING REVERSE SENSOR.	New	80.00	50.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN.	New	150.00	120.00
5	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	New	150.00	100.00
6	TO DISMANTLE & REFIX REAR UNDERCARRIAGE.	New	500.00	0.00
7	TO DISMANTLE & REFIX FUEL TANK.	New	100.00	60.00
8	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
9	TO REFILL AIRCON GAS.	New	150.00	100.00
10	TO SPRAY RUST PROOFING.	New	250.00	150.00
11	TO DISMANTLE & REPLACING FRONT DASHBOARD.	New	480.00	300.00
12	TO DISMANTLE & REPLACING AIR BAG.	New	480.00	200.00
13	TO REPROGRAMME & RESET AIRBAG SYSTEM.	New	450.00	380.00
14	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE.	New	500.00	0.00
15	TO DISMANTLE & REPLACING REAR EXHAUST.	New	100.00	60.00
16	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.	New	4,000.00	2,000.00
17	TO PUTTY & SPRAY PAINTING.	New	3,000.00	2,000.00
Gross Labour Cost (\$\$)			11,000.00	5,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >