

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 7620Y

DATE 12/3/2019 11:22

MAKE :

MODEL : HYUNDAI i40

L/Sum  
AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Wheel Hub Cap (RH) ✓			\$ 107.10	
	Front Fender (RH) X repair				
	Front Door (RH) X repair				
	Rear Door (RH) X repair				
	SUB TOTAL			\$ 107.10	
	LESS 20%			\$ 21.42	
	DISCOUNTED TOTAL			\$ 85.68	
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00	Nett
	Front Door Comfort Logo (RH) ✓			\$ 75.00	Nett
	Front Door Advertisement Logo (RH) ✓			\$ 100.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) ✓			\$ 80.00	Nett
	Rear Door Advertisement Logo (RH) ✓			\$ 100.00	Nett
				\$ 455.00	
	Labour Charge				
	Panel Beating			\$ 200	
	Spray Painting Charge-Fender/Door X2/Rocker Panel			\$ 400.00	
	Tuff Kote			\$ 800.00	600
	FRT Wheel Alignment			\$ 50.00	X
				\$ 80.00	X
	TOTAL LABOUR			\$ 1,330.00	
	ESTIMATE TOTAL			\$ 1,870.68	
	<div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul>Acknowledged by Repairer Signature: Date:</div> <div>Kahin Uley 12/3/19 1505h 2 By 1 L/S After Repair p/h</div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					