



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd
(Co. Reg. No. 201006949C)
Blk 3022A Ubi Road 1 #01-45/ 46 S408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
RAMLI BIN ANI

Singapore

Claimant Insurer: FWD Singapore Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0319-5428
Policy No:		Date of Loss:	06/03/2019
Vehicle Reg. No.:	SLM5500E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHUA CHOON YEN		
Make/Model:	LEXUS IS200T, 2.0 EXECUTIVE (A)	Vehicle Reg. Date:	25/03/2017
Vehicle Colour:	WHITE	Chassis No:	JTHBA1D2405048867
Engine No:	8ARZ072039		
Odometer:	4019 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	STATEMENT RECORDED BY SOO - PROGRESSIVE CAR CARE PTE LTD (6741 5336)		
Remarks:	VEHICLE IS NOT IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	2,615.13
Miscellaneous Items	10.00
Labour	715.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (\$\$)	3,940.13
+ GST 7.00% (\$\$)	275.81
Nett Amount (\$\$)	4,215.94

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Acknowledged
Date
15/3/19
Take photo before painting
3 day.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2019)**Parts:** 143 LEXUS IS200T 2.0 EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Car Care Pte Ltd/SLM5500E/09/03/2019 14:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT FENDER - RH	0.00	0.00	*1,063.10 F
2	1	NA	*FRONT DOOR - RH	0.00	0.00	*1,465.80 F
3	1	NA	*FRONT DOOR RUBBER - RH	0.00	0.00	*240.10 F
4	1	NA	*FRONT DOOR STICKER - RH	0.00	0.00	*136.70 F
5	1	NA	*TYRE RIM R/F	0.00	0.00	*- F
				Sub Total (S\$)		2,905.70
				- Add. Disc. on L,N Items 10.00% (S\$)		290.57
				Total Parts (S\$)		2,615.13

Progressive Car Care Pte Ltd/SLM5500E/09/03/2019 14:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	600.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; REMOVE; REPLACE ACCIDENT PARTS	New	450.00
3	TO CHECK WIRING	New	20.00
4	TO REMOVE; REPLACE R/F TYRE RIM AND BALANCING TYRE	New	45.00
5	TO 4 WHEEL ALIGNMENT	New	120.00
6	TO TRANSFER DOOR AND DOOR FITTING	New	80.00
Gross Labour Cost (S\$)			1,315.00

Progressive Car Care Pte Ltd/SLM5500E/09/03/2019 14:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.