

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:33

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013892 Date : 12/06/2019 Order : SMD7509D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SMD7509D (V 38275)	Regn Date: 31/08/2018	Mileage: 16471	WIP No.: 44877
Model: Q2 1.0 TFSI S tronic GABANG	Chassis: WAUZZZGA6JA089386	Engine: CHZ 461193	Dept: U
You have been assisted by :- UB-Jiayee (43)			


		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.TO INSPECT FRONT LOCK CARRIER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A81A853651 MX3	(A) (SK)GRILLE 14/03/	Less 020%	1.00	1301.00
X	A81A941774A	HEADLIGHT	Less 020%	1.00	4491.00
X	A81A807107 GRU	COVER	Less 020%	1.00	785.50
X	A81A807108 GRU	COVER	Less 020%	1.00	785.50
X	A81A853718 4W3	COVER	Less 020%	1.00	293.50
X	A81A807110 4W3	SPOILER	Less 020%	1.00	272.50
X	A81A805608C	007181/(V) (GER)MOUNT	Less 020%	1.00	107.00
X	A81A807663 GRU	CONN PIECE	Less 020%	1.00	134.00
X	A81A807672 4W3	GRILL	Less 020%	1.00	153.50
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	A81A807081	COVER	Less 020%	1.00	90.70
X	A81A853717 4W3	COVER	Less 020%	1.00	293.50

Parts 6,981.04
Labour 0.00
Sublet 2,427.00
Menus 0.00
Lubricant 0.00

Sub-Total 8,608.04

7% GST 602.56

Grand Total 9,210.60



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMD 7509 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0314/2019/KK
16 April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi Q2 1.0 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZGA6JA089386
Vehicle Regn No. : **SMD 7509 D**
Vehicle Mileage : 16471 KM
Vehicle Owner : Mr. Fong Yu Jun
Certificate No : 1800104565
Own Damage Excess : \$856.00 (Inclusive 7%GST)
Accident Date : 1/3/2019
Place : Along Chao Chu Kang Way
Repair Cost : \$ 9,210.60
WIP No. : 44877
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



16/4
