

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Md Ishak, Mohd Imran

Date: 10 Apr 2019

Preliminary Advice

Vehicle No	: SLW3344A	Accident Date	: 04/03/2019
Make	: AUDI A5	Policy No.	: 1800012970-01
Assignment Date	: 13/03/2019	Excess	: S\$1,600.00
Date of Inspection	: 13/13/2019	Est. Duration of Repair	: 4 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	: \$	19,496.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	: \$	14,244.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	: \$	735.00
Total	: \$	14,979.00
Lump Sum Repair	: \$	

Total Loss Consideration

New for Old Value	: \$	
Pre-Accident Value	: \$	165,000.00
COE / PARF Rebate	: \$	73,497.00
Salvage Value	: \$	
Margin for Repair	: \$	91,503.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 7,696.00.