



KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08, Sin Ming AutoCare
Singapore 575721

Tel: 64556268 Fax: 64555166

TO: FWD INSURANCE

DATE: 20/07/2019

ATTN: MOTOR CLAIM DEPT

REF: 1201900006308/LT

RE: LETTER OF DEMAND FOR SKJ 2266 D

Please find below breakdown claim of the vehicle no: SKJ 2266 D


Repair cost: \$ 3,716.11 (INCL GST)

Loss of used: 3 days x \$120.00 = \$360.00

LTA Search Fees \$7.49

Total amount: \$4,083.60

Your kind assistance on above matter would be appreciated



Thanks & Regards,

Wendy Siew – Mobile: 91786498

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

FWD INSURANCE

Attention : Motor Claim Department

Estimate : ES000482

Date : 13/03/2019

Vehicle Num. : SKJ 2266 D

Make/Model : PORSCHE MACAN

Chassis/Eng# :

Accident Date : 13/03/2019

Claim No. :

Reference :

Policy No. :

S/N Quantity Particular Unit Price Amount S\$

- LIST ITEMS :
- 1 REAR BUMPER
 - 1 REAR BUMPER LOWER SPOILER
 - 1 REAR BUMPER NUMBER PLATE PANEL CENTRE
 - 1 REAR BUMPER REINFORCEMENT
 - 2 REAR BUMPER BRACKET
 - 1 SET REAR BUMPER CLIPS
 - 1 SET REAR REVERSE SENSOR

List Total S\$:

- NETT ITEMS :
- 1 REAR NUMBER PLATE
 - 1 REAR BUMPER DECAL - 3M MATTE DARK GREY

Nett Total S\$:

LABOUR :

LABOUR FEES:

TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS

TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS

TO CHECK AND REPAIR ELECTRICAL WIRING

TO CHECK REVERSE SENSOR

Labour Total S\$:

108 -

95.00	1,460.00	✓
	455.00	✓
	420.00	✓
	395.00	X
	190.00	X
	85.00	✓

3,005.00

455.00
350.00

me	58.00
Bill	680.00

738.00

400.00
400.00
100.00

1,820.00

E. & O.E.

Total S\$: 5,563.00

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 Mar 2019 / 08:35:48

Receipt Date/Time : 12 Mar 2019 / 08:35:48

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190312-000233

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SJH995T

As at 07 Mar 2019/23:59:00

Insurance Co: FWD SINGAPORE PTE. LTD.

1 Insurance Enquiry - SJH995T

Enquiry Fee

20190312083314863330

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

7.00	0.49	7.49
------	------	------

Rounding Difference

		0.04
--	--	------

Total Amount Payable

		7.45
--	--	------

Paid By

xxxxxxxxxxxx7788

Credit Card:

Visa/MasterCard

		7.45
--	--	------

Total

		7.45
--	--	------

Cash Change

		0.00
--	--	------

Tendered Amount

		7.45
--	--	------

Excess Refundable Amount

		0.00
--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

Fwd pre-repair