

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)1 April 2019
Sung & repair2 April
Sung & repair

13 MAR 2019

GST REG. NO : M2 - 0020081 - X

E S T I M A T EEstimate No. : b1 50478
Date Estimated : 13/03/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Irene Er
4 Mimosa Road

Singapore 807971

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
ER183B	GA69107	30/10/2014	428IA GC	0

DESCRIPTION

Replace Front bumper and remove attachment etc include repair on the accident damage area

850 1,275.00

Spray painting front bumper

934 1,038.00

To replace right headlight. 408

? 481.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries.

? 80.00

Total Labour 1: **3,051.00**DESCRIPTION

FRT LH BOTTOM MOUNTING SIDE PANEL ✓
 FRT RH BOTTOM MOUNTING SIDE PANEL ✓ BR
 FRT LH TOP MOUNTING SIDE PANEL ✓
 FRT RH TOP MOUNTING SIDE PANEL ✓ Nec
 FRT BUMPER PANEL PRIMED (SRA) ✓ CN?
 RH COVER SPRAY NOZZLE PRIMED ?
 SET MOUNTING PDC/PMA SENSOR FRT ✓ Nec
 GROMMET ✓ Nec
 PLAQUE 82MM ✓ Nec
 HOSE LINE HEADLIGHT CLEANING SYSTEM ?
 RH TELESCOPING NOZZLE ?
 RH BI XENON HEADLIGHT ?
 DECOUPLING RING PDC TORQUE CONVERTER ✓ Nec
 PDC SENSOR IMPERIAL BLUE (A89) ?

QTY	PRIC	VALUE
1	19.20	19.20
1	19.20	19.20
1	19.20	19.20
1	19.20	19.20
1	1,078.65	1,078.65
1	43.25	43.25
1	77.55	77.55
2	0.75	1.50
1	71.25	71.25
1	87.00	87.00
1	159.85	159.85
1	2,119.70	2,119.70
4	5.05	20.20
1	368.80	368.80

Total Parts : **4,104.55**

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 50478**
Date Estimated : **13/03/2019**
Prepared By : **Chua Kee Sin**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
ER183B	GA69107	30/10/2014	428IA GC	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

Labour 1	:	3,051.00
Parts	:	4,104.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	500.89
Grand Total	:	7,656.44

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY******** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****