

LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE
HQ-TRANSPORT COMMAND
KRANJI CAMP 3
151 CHUA CHU KANG WAY
SINGAPORE 688248

REF No. CC2/MIDA19004613/p

REF Date 07/05/2019

Code MIDA

DISBURSEMENT FEE

Vehicle No. **MID 95104**
Insured
Claim No **FY 18/19/0035**
Policy No
Accident Date **7/8/2018**
Inspection Date

<u>LKK Cost of Claim paid to claimant on behalf of MINDEF</u>		
Repair Cost of SBS 8099P	\$	176.80
Loss of Use (\$275.00 x 1day)	\$	275.00
Total Fee	\$	451.80

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "LKK AUTO CONSULTANTS PTE LTD".

LKK AUTO CONSULTANTS PTE LTD

CHEW LIAN