

Registration No. QX 5249P

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	Buckled	\$180.00	\$180.00	
1.2	Front RH Bumper Retainer	1	Cracked	\$24.00	\$24.00	
1.3	Front LH Bumper Retainer	1	Cracked	\$24.00	\$24.00	
1.4	Radiator Grill	1	Missing	\$120.00	\$120.00	
1.5	Car Emblem	1	Necessary	\$18.00	\$18.00	
1.6	Front Number Plate	1	Deformed	\$50.00	\$50.00	
1.7	Front Bumper Reinforcement	1	Dented	\$138.00	\$138.00	
1.8	Front Bumper RH Reinforcement Bracket	1	Bent	\$12.00	\$12.00	
1.9	Front Bumper LH Reinforcement Bracket	1	Bent	\$12.00	\$12.00	
1.10	Lock Panel	1	Bent	\$60.00	\$60.00	
1.11	Front Support Panel	1	Bent	\$660.00	\$660.00	
1.12	RHS Head Lamp	1	Cracked	\$216.00	\$216.00	
1.13	LHS Head Lamp	1	Cracked	\$216.00	\$216.00	
1.14	RHS Fog Lamp	1	Scratched	\$84.00	\$84.00	
1.15	Air Con Compressor	1	Unconfirm	\$468.00	\$468.00	
1.16	Air Con Condenser	1	Bent	\$220.00	\$220.00	
1.17	Air Con Pipe (Discharge Hose)	1	Bent	\$180.00	\$180.00	
1.18	Air Con Pipe (Cooler Hose)	1	Bent	\$342.00	\$342.00	
1.19	Radiator	1	Dented	\$300.00	\$300.00	
1.20	Radiator Cowling	1	Cracked	\$96.00	\$96.00	
1.21	Radiator Fan Blade	1	Cracked	\$48.00	\$48.00	
1.22	Radiator Fan Motor	1	Dented	\$108.00	\$108.00	

1.23	Radiator Upper Hose	1	Bent	\$22.00	\$22.00	
1.24	Radiator Lower Hose	1	Cut	\$22.00	\$22.00	
1.25	Wiper Tank	1	Dented	\$48.00	\$48.00	
1.26	ABS Pump	1	Unconfirm	\$2,280.00	\$2,280.00	
1.27	Alternator	1	Unconfirm	\$384.00	\$384.00	
1.28	Front RH Fender	1	Buckled	\$120.00	\$120.00	
1.29	Front LH Fender	1	Buckled	\$120.00	\$120.00	
1.30	Bonnet Cover	1	Buckled	\$360.00	\$360.00	
1.31	Bonnet Cover RHS Hinges	1	Bent	\$33.00	\$33.00	
1.32	Bonnet Cover LHS Hinges	1	Bent	\$33.00	\$33.00	
1.33	Bonnet Cover Insulator	1	Deformed	\$108.00	\$108.00	
1.34	Bonnet Cover Inlet Rubber	1	Not Necessary	\$14.00		
1.35	Bonnet Cover Lock	1	Missing	\$30.00	\$30.00	
1.36	Bonnet Stand Holder	1	Necessary	\$8.00	\$8.00	
1.37	Bonnet Stand Stopper	1	Bent	\$8.00	\$8.00	
1.38	RHS Engine Mounting	1	Unconfirm	\$84.00	\$84.00	
1.39	LHS Engine Mounting	1	Unconfirm	\$54.00	\$54.00	
1.40	Front Engine Mounting	1	Unconfirm	\$48.00	\$48.00	
1.41	Gear Box Engine Mounting	1	Unconfirm	\$54.00	\$54.00	
1	Scope Of Repairs					
1.1	Front Bumper					5
	Remove & Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers					
	Putty & Spray Paint for Front Complete Bumper					
1.2	Radiator Grill & Front Number Plate					1
	Replace Radiator Grill					
	Replace Car Emblem					
	Replace Front Number Plate					
1.3	Front Bumper Reinforcement & Lock Panel					8

	Remove & Replace Front Bumper Reinforcement					
	Remove & Replace RHS Front Bumper Reinforcement Bracket					
	Remove & Replace LHS Front Bumper Reinforcement Bracket					
	Remove & Replace Lock Panel					
1.4	Front Support Panel					6
	Remove & Replace Front Support Panel					
1.5	Head Lamp & RHS Fog Lamp					1.5
	Remove & Replace RHS Head Lamp					
	Remove & Replace LHS Head Lamp					
	Replace RHS Fog Lamp					
	Wiring for RHS Head Lamp					
	Wiring for LHS Head Lamp					
	Wiring for RHS Fog Lamp					
1.6	Air Con Compressor & Air Con Condenser					8
	Remove & Replace Air Con Compressor					
	Remove & Replace Air Con Condenser					
	Remove & Replace Air Con Piping					
	Top Up Air Con Gas					
1.7	Radiator					6
	Remove & Replace Radiator					
	Remove & Replace Radiator Cowling					
	Remove & Replace Radiator Upper Hose					
	Remove & Replace Radiator Lower Hose					
	Remove & Replace Radiator Fan Blade					
	Remove & Replace Radiator Fan Motor					
	Top Up Coolant					
1.8	Wiper Tank & Battery					2
	Remove & Replace Wiper Tank					

	Remove & Replace Battery					
1.9	ABS Pump					16
	Remove & Replace ABS Pump					
1.10	Alternator					4
	Remove & Replace Alternator					
1.11	Front RH Fender					4
	Remove & Replace Front RH Fender					
	Putty & Spray Paint for Front RH Fender					
1.12	Front LH Fender					4
	Remove & Replace Front LH Fender					
	Putty & Spray paint for Front LH Fender					
1.13	Bonnet Cover					10.5
	Remove & Replace Bonnet Cover					
	Remove & Replace Both Side Bonnet Cover Hinges					
	Remove & Replace Bonnet Cover Insulator					
	Remove & Replace Bonnet Cover Inlet Rubber					
	Remove & Replace Bonnet Cover Lock					
	Replace Bonnet Stand Stopper					
	Replace Bonnet Stand Holder					
	Replace 'POLICE' Wording Sticker on Bonnet Cover (To be provided by AMED)					
	Putty & Spray Paint for Bonnet Cover					
1.14	Engine Mounting					10
	Remove & Replace all Engine Mounting (Front, RHS, LHS & Gear Box)					
		TOTAL PARTS COST			\$7,392.00	
		TOTAL MAN-HOUR				86