

Surveyor

Adnan

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 14 March 2019 8:27 AM

Estimated Cost:

Bill to:

OD (TP) WS / TP RRS / OD RRS / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 6469 U

Insured: GBC 6472 S

at Workshop info: Premium Automobiles

Tel: 63882323

of 55 Ubi Road 1 Road Singapore 408699

Policy No:

Claim No: SVM19D201087

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4/3/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 9.06 AM

Person Contacted: George

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 6469 U - X
	GBC 6472 S - X
3/6/19	final fig \$3783 (Red 18.370, 83%) confirmed by email

Adrian

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLT64694 Yr Regn: 2017 / NovType: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 C.C. 1395Colour: Grey AC: Insured / Std / NI / NASp. Reading: 44258 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222F48JA022526Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / SR / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

P/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 13/03/19Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Check

RECEIVED 3 JUN 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 3/6 - typist

2)

3)

4)

5)

6)

Pres. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 14 March 2019 8:37 AM
To: NORA ; 'Claims Dept'
Cc: 'claimstatusenquiry'; assignments
Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING SLT 6469 U AND YOUR INSURED GBC 6472 S DATED ON 04/03/2019 SNM19D201087 PRS
Attachments: SAftersales19031014340.pdf

Without Prejudice

Dear Nora,

We appoint LKK.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: NORA [mailto:nora.khai@premiumauto.com.sg]

Sent: Tuesday, 12 March, 2019 6:00 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; 'Claims Dept' <claims@premiumauto.com.sg>

Cc: 'claimstatusenquiry' <claimstatusenquiry@borneomotors.com.sg>

Subject: RE: ***SPAM*** RE: ACCIDENT INVOLVING SLT 6469 U AND YOUR INSURED GBC 6472 S DATED ON 04/03/2019 SNM19D201087 PRS

Dear Boon Sen,

We choose Adrian Ling.

Thank you.

Best Regards,

Norah Khai

Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Tuesday, 12 March 2019 9:16 AM

To: 'NORA'

Cc: claimstatusenquiry

Subject: ***SPAM*** RE: ACCIDENT INVOLVING SLT 6469 U AND YOUR INSURED GBC 6472 S DATED ON 04/03/2019 SNM19D201087 PRS

WITHOUT PREJUDICE

Dear Sir,

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: NORA [<mailto:nora.khai@premiumauto.com.sg>]

Sent: Sunday, March 10, 2019 2:38 PM

To: 'Claims' <claims@premiumauto.com.sg>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: ACCIDENT INVOLVING SLT 6469 U AND YOUR INSURED GBC 6472 S DATED ON 04/03/2019

Dear All,

Attached is the estimate for the survey arrangement this Wednesday 13/03 at 11am. Kindly advise who is the surveyor coming?

Thank you.

Best Regards,

Norah Khai

Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Thursday, 7 March 2019 10:50 AM

To: claimsdept@sg.cntaiping.com

Cc: 'Claims'

Subject: ACCIDENT INVOLVING SLT 6469 U AND YOUR INSURED GBC 6472 S DATED ON 04/03/2019

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

Please arrange the survey on 13/03/2019, Wednesday, 11AM.

Thank you

Best regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 66900293 f. +65 64751023

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 3 June 2019 9:30 AM
To: Shiau Chan (LKKAUTO); jiajee.yap@premiumauto.com.sg
Cc: Carrine Leong; Boo seng yak; claims@premiumauto.com.sg; SUR
Subject: RE: FINAL REVISION FOR SLT6469U - TP CHINA - SURVEYED ON 13 MAR 19

Dear Jia Yee,

Confirm repair cost of \$3783.00 before GST @ 4 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 31 May 2019 5:27 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: FINAL REVISION FOR SLT6469U - TP CHINA - SURVEYED ON 13 MAR 19

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>
Sent: Friday, 31 May 2019 4:29 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION FOR SLT6469U - TP CHINA - SURVEYED ON 13 MAR 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Kindly confirm repair cost of \$3783.00 @ 4 days.

Your early approval will be most appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 190902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiaYee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

ase do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2019 14:43
Date Of Accident	04/03/2019 20:00
Exact Location Of Accident	CAR PARK OPPOSITE OF BLK 348 BUKIT BATOK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT6469U
Insured/Policyholder	
Name Of Registered Owner	WONG TUCK SENG
NRIC No	S1154799J
Email Address	CRISTAL3@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96172003
Alternative Phone No	OFFICE-96172003

Vehicle Particulars

Manufacturer	AUDI
Model	AUDI A4 TFSI 1.4 1395CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10879497
Cover Note Number	

Driver

Name of Driver	WONG TUCK SENG
NRIC No	S1154799J
Date Of Birth	03/06/1956
Occupation	INDOOR
Date Of Driving Pass	18/10/1978
Driving Experience	40 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96172003
Fax Number	
Contact Number	OFFICE-96172003
Email Address	CRISTAL3@SINGNET.COM.SG

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE PARKING LOT, NO. 200, AT THE SAID LOCATION, WHEN IT WAS HIT BY A REVERSING VEHICLE B. MY VEHICLE WAS STATIONARY WHEN I SAW VEHICLE B REVERSING TOWARDS MY VEHICLE. I TRIED TO AVOID VEHICLE B FROM HITTING MY VEHICLE BY DRIVING FORWARD BUT IT WAS TOO LATE. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL UPLOAD TO FILEZILLA ONCE INSURED SEND
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC6472S
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TOH ENG HOY
NRIC/Passport Number	S1136203F
Contact Number	96273013
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA):**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal and/or personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyer-law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, receipts or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer-law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyer-law firms), which may be placed outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


Hashim

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE PARKING LOT, NO. 200, AT THE SAID LOCATION, WHEN IT WAS HIT BY A REVERSING VEHICLE B. MY VEHICLE WAS STATIONARY WHEN I SAW VEHICLE B REVERSING TOWARDS MY VEHICLE. I TRIED TO AVOID VEHICLE B FROM HITTING MY VEHICLE BY DRIVING FORWARD BUT IT WAS TOO LATE. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

5 March 2019 at 10:51 AM

Date/Time:

Accident Photo



Academy

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S1154799J

Name: WONG TUCK SENG

Birth Date: 03 Jun 1956

Issue Date: 30 Sep 2003

0008750380



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1154799J

Name: WONG TUCK SENG

黄德成

Race: CHINESE

Date of Birth: 03-06-1956

Sex: M

Country of Birth: SINGAPORE



Driving License



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0311/2019/GW (NK)
Date : 9-Mar-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : GBC 6472 S

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr. Wong Tuck Seng
Address : 29 Pavillion Street
Singapore 658709
Telephone : (HP)96172003
Type of Claim : Third Party Claims
Policy No. : 10879497
Vehicle No : **SLT 6469 U** ✓
Model Code : A4 Sedan 1.4 TFSI
Model / Year : Sep-15
Engine No : CVN 045275
Chassis No : WAUZZZF48JA022526
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Mar-19
Place of Accident : Car Park Opposite of Blk 348 Bukit Batok

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 6469 U

S/N	Nature of Jobs		Estimated Charges	
1	To remove and reinstall rear parking aid and rear lid kick sensor.	S/N \$	360.00	✓
2	To renew rear windscreen and rhs 1/4 glass to facillitate fender renewal.	S/N \$	600.00	✗
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, elctrical and audio equipment.	S/N \$	1,400.00	✗
4	To remove and reinstall rear seat , back rest, hat tray , abcd pillar trims, luggage compartment trims. Dislodge rood liner and disengage curtain air bag etc.	S/N \$	1,400.00	✗
5	To dismantle rear bumper and rear lid cut out and reweld rhs rear fender. To renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$	4,800.00 900	✓
6	To respray rear bumper, rhs rear fener, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	3,900.00 1400	✓

7 To carry out diagnostic check.

S/N \$ 192.00 ✓ ✓

TOTAL LABOUR CHARGES

: \$ 12,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No] SLT 6469 U

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	\$ 2,015.00	X
2	REAR BUMPER FIXING PARTS <i>all on</i>	\$ 66.00	+
3	REAR BUMPER SECURING STRIP <i>not on</i>	\$ 203.00	X
4	REAR BUMPER SPOILER <i>all on</i>	\$ 227.00	+
5	REAR LIGHT REFLECTOR-RH <i>not on</i>	\$ 38.00	+
6	REAR BUMPER GUIDE SECTION-RH <i>all on</i>	\$ 41.00	+
7	REAR BUMPER UPPPER GUIDE SECTION-RH <i>all on</i>	\$ 20.00	X
8	REAR FENDER-RH <i>Repair</i>	\$ 2,443.00	X
9	REAR WINDSCREEN <i>all on</i>	\$ 1,049.00	X
10	REAR SIDE WINDOW-RH <i>all on</i>	\$ 561.00	+
11	LED TAILLIGHT-RH <i>all on</i>	\$ 931.00	931
12	LED TAILLIGHT TRI-RH <i>all on</i>	\$ 27.00	+
13	ACRYLIC SEALANT	S/N \$ 180.00	+
14	CAVITY WAX	S/N \$ 140.00	+
15	STONE CHIP	S/N \$ 180.00	+
16	METAL FILLER POWDER	S/N \$ 280.00	+
17	REAR WINDSCREEN SEALANT	S/N \$ 200.00	+
18	1/4 GLASS SEALANT	S/N \$ 100.00	+
19	SUNDRIES <i>Not New</i>	\$ 800.00	? X
TOTAL SPARE PARTS		:	\$ 9,501.00
TOTAL LABOUR CHARGE		:	\$ 12,652.00
GRAND TOTAL		:	\$ 22,153.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name : Adrian King
Surveyed Date : 13/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0311/2019/GW
Date : 9-Mar-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : **GBC 6472 S**

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Adrian,
4 days - ok - 31 APR 19

Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr. Wong Tuck Seng
Address : 29 Pavillion Street
Singapore 658709
Telephone : (HP)96172003
Type of Claim : Third Party Claims
Policy No. : 10879497
Vehicle No : **SLT 6469 U**
Model Code : A4 Sedan 1.4 TFSI
Model / Year : Sep-15
Engine No : CVN 045275
Chassis No : WAUZZZF48JA022526
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Mar-19
Place of Accident : Car Park Opposite of Blk 348 Bukit Batok

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 6469 U

S/N	Nature of Jobs	Estimated Charges			
1	To remove and reinstall rear parking aid and rear lid kick sensor.	S/N	\$	360.00	\$ 360.00
2	To renew rear windscreen and rhs 1/4 glass to facillitate fender renewal.	S/N	\$	600.00	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, elctrical and audio equipment.	S/N	\$	1,400.00	
4	To remove and reinstall rear seat , back rest, hat tray , abcd pillar trims, luggage compartment trims. Dislodge rood liner and disengage curtain air bag etc.	S/N	\$	1,400.00	
5	To dismantle rear bumper and rear lid cut out and reweld rhs rear fender. To renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.		\$	4,800.00	\$ 900.00
6	To respray rear bumper, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$	3,900.00	\$ 1,400.00
7	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$	12,652.00	\$ 2,852.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn NoJ SLT 6469 U

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,015.00	
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	
4	REAR BUMPER SPOILER	\$ 227.00	
5	REAR LIGHT REFLECTOR-RH	\$ 38.00	
6	REAR BUMPER GUIDE SECTION-RH	\$ 41.00	
7	REAR BUMPER UPPPER GUIDE SECTION-RH	\$ 20.00	
8	REAR FENDER-RH	\$ 2,443.00	
9	REAR WINDSCREEN	\$ 1,049.00	
10	REAR SIDE WINDOW-RH	\$ 561.00	
11	LED TAILLIGHT-RH	\$ 931.00	\$ 931.00
12	LED TAILLIGHT TRI-RH	\$ 27.00	
13	ACRYLIC SEALANT	S/N \$ 180.00	
14	CAVITY WAX	S/N \$ 140.00	
15	STONE CHIP	S/N \$ 180.00	
16	METAL FILLER POWDER	S/N \$ 280.00	
17	REAR WINDSCREEN SEALANT	S/N \$ 200.00	
18	1/4 GLASS SEALANT	S/N \$ 100.00	
19	SUNDRIES	\$ 800.00	
TOTAL SPARE PARTS		: \$ 9,501.00	\$ 931.00
TOTAL LABOUR CHARGE		: \$ 12,652.00	\$ 2,852.00
GRAND TOTAL		: \$ 22,153.00	\$ 3,783.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19004634/AVD3N2

Date: 04/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN15211918033
Claimant Vehicle No :	SLT6469U	Insured Vehicle No :	GBC6472S
Date of Loss:	04/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201087C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6469U	Engine No:	CVN045275
Make & Model:	AUDI A4, 1.4 (A)	Chassis No:	WAUZZZF48JA022526
Reg. Date:	04/11/2017 (Man. Year: 2017)	Odometer:	44258 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,501.00	931.00	8,570.00	90.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,652.00	2,852.00	9,800.00	77.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,153.00	3,783.00	18,370.00	82.92
+ GST 7.00/7.00% (S\$)	1,550.71	264.81	1,285.90	82.92
Nett Amount (S\$)	23,703.71	4,047.81	19,655.90	82.92

INSPECTION

Date of Assignment:	25/03/2019	
Date Inspected:	13/03/2019	Inspected At: PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2019)
Parts:	143	AUDI A4 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT6469U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,015.00 FS	*-FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*-FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	203.00 FS	*-FS
4	1		*REAR BUMPER SPOILER	Not Necessary	227.00 FS	*-FS
5	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	38.00 FS	*-FS
6	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	41.00 FS	*-FS
7	1		*REAR BUMPER UPPER GUIDE SECTION-RH	Not Necessary	20.00 FS	*-FS
8	1		*REAR FENDER-RH	Repair	2,443.00 FS	*-FS
9	1		*REAR WINDSCREEN	Not Necessary	1,049.00 FS	*-FS
10	1		*REAR SIDE WINDOW-RH	Not Necessary	561.00 FS	*-FS
11	1		*LED TAILLIGHT-RH	Cut	931.00 FS	*931.00 FS
12	1		*LED TAILLIGHT TRI-RH	Not Necessary	27.00 FS	*-FS
13	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*-FS
14	1		*CAVITY WAX	Not Necessary	140.00 FS	*-FS
15	1		*STONE CHIP	Not Necessary	180.00 FS	*-FS
16	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*-FS
17	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*-FS
18	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*-FS
19	1		*SUNDRIES	Not Necessary	800.00 FS	*-FS
Total Parts (\$\$)					9,501.00	931.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
4	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOD LINER AND DISENGAGE CURTAIN AIR BAG ETC	New	1,400.00	0.00
5	TO DISMANTLE REAR BUMPER AND REAR LID CUT OUT AND REWELD RHS REAR FENDER.TO RENEW REAR BUMPER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,800.00	900.00
6	TO RESPRAY REAR BUMPER,RHS REAR FENDER,RHS SILL PANEL,DOOR ENTRANCES,ROOF CHANNEL,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	3,900.00	1,400.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,652.00	2,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >