

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: CPW/jc/1804009

Date: 18th March 2019

Our Ref: CS1/LAW19004651/Dtd3s2

## M/s Wong Thomas & Leong

21 Merchant Road #07-02 Singapore 058267

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBA 2510C INSURED VEHICLE: JJW 8710 ACCIDENT DATE: 26/08/2017

We thank you for your instruction on 28/02/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBA 2510C from M/s Prudent Adjustors Services.
- b) Police Report of Vehicles FBA 2510C and JJW 8710.
- c) Colour damaged vehicle photographs of FBA 2510C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: FBA 2510C

Make & Model

: Suzuki GSX1300RK5

Year of Registration

: 2005

Chassis Number

: JS1A1111200117612

**Engine Capacity** 

: 2510 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.