

ASS. REC. BY:

REF: CS/SPF/900462 / Rlyd302

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Hafizul Fuzon

of

SPF

Date/Time:

14/3/19 12:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

AJR 6178

Insured:

QX 1031B

at Workshop n/s

Moya Automotive

Tel:

62723892

of

Bik 1008 Bkt Merah lane 3 # 01-04

Policy No:

Claim No:

AEMD/105/009/2019/014

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:47pm 14/3/19

Person Contacted:

Nithen

Vehicle IN/OUT

Date/Time

Action/Instruction (-) Estimate

AJR 6178 - X

QX 1031 - X

Do Not Finalise

7/5/19

@501pm Suzanne said vehicle not repair, pending liability

29/5/19

@501pm Suzanne said vehicle not send in for repair, pending liability


Form

REP:

SIGNATURE

From: Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / LVA / RV / MV
To Inspect Vehicle No: **ASR 6178**
at Workshop no: **MOVA**
of: **BUKIT MEKOH**
Insured: **SPF**
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)
Remarks: The veh had commenced its
repair at the time of inspection.



Est. or Market Value:
IDAC Accident Report Consistent? : Yes or No
GIA / PR Seen Consistent? : Yes or No
Est. Repairs: days Res: Yes or No
Turn Time: % 3 Val: Yes or No
GA / REV / REP / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Veh No: **ASR 6178** at Reg: **2014 MAR**
Type: Motor Cycle / Bus / Van / Lorry / Taxi / Private Motor /
Truck / Trailer or
Make: **TOYOTA CAMRY 2.5 V A** CC: **2494**
Colour: **GREEN** A/C: Insured / STD / HI / HA
Cap Loading: **671/28** T/Radio: Insured / STD / HI / HA
Eng No:
Chassis: **PN153AKJ5007005938**
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Under / Jammed / Leaked / Burnt or
Brake: Under / Jammed / Leaked / Burnt or
Mod: HI / AIR / STD AIR / or
Tyre Size: F: **225/45R18**
R:
BS / DUN / EXHOVA / GY / ES / LIZA / MR / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: Rear:
R/Bal: **6** mm R/Bal: **6** mm
L/Bal: **6** mm L/Bal: **6** mm
D.O.A: **01/03/19** D.O.I: **20/03/19**
Survey held at: **MOVA (Bm)**
Pos. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

Range of repair cost - 2K - 4K (EST)

RECEIVED 03 JUN 2019

Date/Time, File Passed

0

Date/Time, File Returned

316 - typist

Report Form

Unrep. Sum / D.O.C.



Preli. Report

Final Report

Days Of Repair: **3**

Resurvey No. of Trip:

Add Fee: ☐ Side Imp. ☐
☐ Imp. Rep. ☐
☐ Tech. Imp. ☐
☐ Structural ☐

Survey Fee

Transportation

1. 1st Trip

2. 2nd

3. 3rd

4. 4th

200

200

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Thursday, 14 March 2019 12:31 PM
To: Admin-D (LKKAUTO); assignments
Cc: Olivia Lau (LKKAUTO); SUR; Frankie THAY (SPF)
Subject: Pre-repair inspection AJR6178

Hi,

Please conduct per-repair inspection on **AJR6178**. (Our veh: QX1031B)

The vehicle is currently at:

MOVA AUTOMOTIVE PTE LTD

Blk 1008 Bukit Merah Lane 3 #01-04/06/08

Singapore 159722

Tel: 6272 3892

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Notify Insurance Company to Conduct Inspection

Date: 11/03/219

From: GOH XJI YANG

To: SPF ACCIDENT CLAIM SECTION

Dear Sir / Madam

MOTOR ACCIDENT ON 01/03/2019 ALONG GOPENG STREET INVOLVING AJR6178 & QX1031B

I am registered owner of motor-vehicle registration no AJR6178 which was involved in an accident with motor-vehicle registration no QX1031B insured by you.

As the accident was cause solely by the negligence of your insured's driver, I am holding you full responsible for the damage to my vehicle.

Herewith, I enclose the estimate and GIA report from the repairer, M/s MOVA AUTOMOTIVE PTE LTD at Blk 1008 Bukit Merah Lane 3 #01-04/06/08 Singapore 159722 for your perusal and kindly arrange your surveyor to survey my vehicle at MOVA Automotive Pte Ltd. Any doubt or queries, please contact MOVA Automotive Pte Ltd at Tel: 6272 3892.

Kindly arrange to have my vehicle surveyed by your appointed motor assessor within 48 hours on receipt of my letter at the above mentioned workshop, failing which I will proceed to appoint my own independent motor assessor to inspect my vehicle and authorize the repair without further notice to you.

Please let me hear from you soon.

Date the 01 day of March 11, 2019

Signed by:



Name :NITHA



cc. MOVA Automotive Pte Ltd



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

JQS2SK7K

No. Pendaftaran : AJR6178
No. ID : 930901075351
Nama Pemunya Berdaftar : GOH XJI YANG
Alamat : B24-02 TWIN GALAXY JLN DATO ABDULLAH TAHIR
80300 JOHOR BAHRU JOHOR

No. Chasis/No. Enjin : PN153AK5007005938 / 2ARU105916
Buatan>Nama Model : TOYOTA / TOYOTA CAMRY 2.5V (A)
Keupayaan Enjin : 2494
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR / 2014
Tarikh Pendaftaran : 21/03/2014
B.D.M/B.G.K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

7936417

NOTA PENTING

1. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
2. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
3. Jika alamat anda bertukar, sila kemaskini dalam tempoh dua bulan dari tarikh pertukaran ini.



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

JQS2SK7K

No. Pendaftaran : AJR6178
No. ID : 930901075351
Nama Pemunya Berdaftar : GOH XJI YANG
Alamat : B24-02 TWIN GALAXY JLN DATO ABDULLAH TAHIR
80300 JOHOR BAHRU JOHOR

No. Chasis/No. Enjin : PN153AK5007005938 / 2ARU105916
Buatan>Nama Model : TOYOTA / TOYOTA CAMRY 2.5V (A)
Keupayaan Enjin : 2494
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR / 2014
Tarikh Pendaftaran : 21/03/2014
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

7936417

NOTA PENTING

1. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
2. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
3. Jika alamat anda bertukar, sila kemaskini dalam tempoh dua bulan dari tarikh pertukaran ini.



SINGAPORE POLICE FORCE



T/20190305/2090

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190305/2090

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/03/2019 14:41		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: GOH XJI YANG			Address: 6 TUAS BAY WALK #01-00 SINGAPORE 637752		
ID Type / ID No.: FIN NO / G2477636R			Contact No.: Home/Office: Mobile: 91211800		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 26	Date of Birth: 01/03/1993	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: SALES ASSISTANT		Driving Licence Information: Class: 2B,3 Date of Expiry:			

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 05/03/2019 00:00	Type of Location: T-Junction
Location: GOPENG STREET ALONG GOPENG STREET				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
AJR6178	Car					0
QX1031B	Car	HYUNDAI	ELANTRA 1.6 AT ABS D/AB 2WD 4DR			0



**SINGAPORE
POLICE FORCE**



T/20190305/2090

2 of 3

Report No. T/20190305/2090

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION,
I WAS DRIVING OF (AJR6178) AT THE SAID LOCATION. ALONG GOPENG ST TWDS ANSON ROAD
WHEN UPON APPROACHING THE UNCONTROLLED JUNCTION OF PECK SEAT ST. I WANTED TO
MAKE A LEFT TURN. SO I SIGNAL AND SLOWED DOWN AND SUDDENLY FELT AN IMPACT FROM
HIS REAR. THAT'S ALL



**SINGAPORE
POLICE FORCE**



T/20190305/2090

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190305/2090

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD HAZIQ BIN SAIFUDDIN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH
Contact No.: 65476204

Authentication Stamp
NP168

Signature Of Informant:

Yan

Date/Time:
05/03/2019 14:41

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: _____

Estimate

08/03/2019

SPF ACCIDENT CLAIM SECTION
No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Attention :- **XA066**

Page # :- 1

Veh # :- AJR6178

Veh Model :- TOYOTA CAMRY 2.5

Estimate# :- CK418833

Claim # :-

ACC. Date :- 01/03/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : **(65) 6272 3892**
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>DE</i>	1 PC	769.80	769.80
2.	REAR TAILLAMP LOWER BRACKET L+R <i>X500</i>	2 PC	85.70	171.40
3.	REAR BUMPER RETAINER L+R <i>X500</i>	2 PC	122.10	244.20
4.	PARKING SENSOR <i>?</i>	2 PC	418.80	837.60
5.	REAR REINFORCEMENT <i>?</i>	1 PC	491.80	491.80
6.	SPONGE <i>?</i>	1 PC	143.00	143.00
7.	KEYLESS SENSOR <i>?</i>	1 PC	190.80	190.80
8.	END PANEL - REPAIR <i>X</i>	1 PC		
9.	REAR BUMPER LOWER SKIRT - REPAIR <i>X</i>	1 PC		
10.	REAR BOOT - REPAIR <i>X</i>	1 PC		
LIST TOTAL S\$				2,848.60
25% DISCOUNT S\$				-712.15
				<u>2,136.45</u>
LABOUR :				
TO REPAIR REAR BOOT, REAR BUMPER LOWER SKIRTING, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ACCIDENT AFFECTED AREAS				<i>400</i> 600.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				<i>400</i> 600.00
TO REMOVE & REFIX REAR PARKING SENSOR & CHECK WIRING				<i>60</i> 120.00
TO REMOVE REAR BOOT TRIM, SPARE TYRE COVER AND OTHER ATTACHMENT PARTS				<i>60</i> 120.00
TO RUST PROOF ON ACCIDENT DAMAGED PARTS				<i>40</i> 80.00
TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST				<i>12 X</i> 60.00
LABOUR TOTAL S\$				<u>1,580.00</u>

Estimate

08/03/2019

SPF ACCIDENT CLAIM SECTION
No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Attention :- **XA066**

Page # :- 1 134313

Veh # :- AJR6178

Veh Model :- TOYOTA CAMRY 2.5

Estimate# :- CK418833

Claim # :-

ACC. Date :- 01/03/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: **(65) 6272 3892**
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,716.45

GST @ 7 % 260.15

AMOUNT DUE S\$ 3,976.60

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Resue
Hp 90010068
3 days
4/3
20/03/19 @ 1200hrs
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- Is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 7 May 2019 5:25 PM
To: SUR
Cc: Admin A
Subject: FW: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

CS/SPF19004662/R1vd3

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Suann <suann@mova.com.sg>
Sent: Tuesday, 7 May 2019 5:19 PM
To: Frankie_THAY@spf.gov.sg; Rosalyn_TAN@spf.gov.sg
Cc: Abdul_Rahman_Mohamad_Salim@spf.gov.sg; tanyw@mova.com.sg; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear sir / mdm

Please check outcome.

Best Regards

Suanne Chiu

Claims Asst. Manager

MOVA Automotive Pte Ltd

Tel: +65 6272 3892

Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential Information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

From: Suann [<mailto:suann@mova.com.sg>]
Sent: Wednesday, 3 April 2019 9:37
To: 'Frankie_THAY@spf.gov.sg'; 'Rosalyn_TAN@spf.gov.sg'
Cc: 'Abdul_Rahman_Mohamad_Salim@spf.gov.sg'; 'tanyw@mova.com.sg'; 'Hsiao Tong (LKKAUTO)'; 'Admin A'
Subject: RE: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear sir / Mdm

Please advise the liability for direct settlement.

Thank you

Best Regards

Suanne Chiu

Claims Asst. Manager

MOVA Automotive Pte Ltd

Tel: +65 6272 3892

Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential Information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

From: Nitha [<mailto:nitha@movacom.sg>]

Sent: Thursday, 21 March 2019 11:09

To: Frankie THAY@spf.gov.sg; Rosalyn TAN@spf.gov.sg

Cc: Abdul Rahman Mohamad Salim Abdul_Rahman_Mohamad_Salim@spf.gov.sg; 'Suann'; tanyw@movacom.sg

Subject: RE: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear Frankie & Rosalyn,

Please kindly advise on the liability for the this case.

Thank you,

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



From: Nitha [<mailto:nitha@movacom.sg>]

Sent: Tuesday, 12 March 2019 3:44 PM

To: 'Abdul_Rahman_Mohamad_Salim' Abdul_Rahman_Mohamad_Salim@spf.gov.sg

Cc: 'Suann'; tanyw@movacom.sg

Subject: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear Mr Rahman,

Kindly assist to advise on liability & assign surveyor for the above mention case.

Thank you

Best Regards,

Nitha

Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



Veron Chen (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 8 April 2019 6:07 PM
To: Admin-D (LKKAUTO)
Subject: FW: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019
Attachments: EST.PDF; POLICE REPORT.PDF

[CS/SPF19004662/R1vd3](#)

From: Suann <suann@movacom.sg>
Sent: Monday, 8 April, 2019 6:06 PM
To: Abdul_Rahman_Mohamad_Salim@spf.gov.sg
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear Mr. Abdul Rahman

Please advice the liability for direct settlement.

Thank you.

Best Regards
Suanne Chiu
Claims Asst. Manager
MOVA Automotive Pte Ltd
Tel: +65 6272 3892
Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential Information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

From: Suann [<mailto:suann@movacom.sg>]
Sent: Wednesday, 3 April 2019 9:37
To: 'Frankie_THAY@spf.gov.sg'; 'Rosalyn_TAN@spf.gov.sg'
Cc: 'Abdul_Rahman_Mohamad_Salim@spf.gov.sg'; 'tanyw@movacom.sg'; 'Hsiao Tong (LKKAUTO)'; 'Admin A'
Subject: RE: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear sir / Mdm

Please advice the liability for direct settlement.

Thank you

Best Regards
Suanne Chiu

Claims Asst. Manager
MOVA Automotive Pte Ltd
Tel: +65 6272 3892
Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential Information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

From: Nitha [<mailto:nitha@mov.com.sg>]
Sent: Thursday, 21 March 2019 11:09
To: Frankie THAY@spf.gov.sg; Rosalyn TAN@spf.gov.sg
Cc: Abdul Rahman Mohamad Salim Salim@spf.gov.sg; 'Suann'; tanyw@mov.com.sg
Subject: RE: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear Frankie & Rosalyn,

Please kindly advise on the liability for the this case.

Thank you,

Best Regards,

Nitha

Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



From: Nitha [<mailto:nitha@mov.com.sg>]
Sent: Tuesday, 12 March 2019 3:44 PM
To: 'Abdul_Rahman_Mohamad_Salim@spf.gov.sg'
Cc: 'Suann'; tanyw@mov.com.sg
Subject: TP CLAIMS - AJR6178 AGAINST QX1031B DOA 01/03/2019

Dear Mr Rahman,

Kindly assist to advise on liability & assign surveyor for the above mention case.

Thank you

Best Regards,

Nitha

Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19004662/R1vd3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 26-06-2019		
ATTN : HAFIZUL FARHAN		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 1031B	Veh. Inspected	AJR 6178	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/014	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	14/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.5V (A)	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	PN153AK5007005938	Colour	GREY	
Odometer	67728	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	MICHELIN	6 mm	
L/H Front Tyre	225/45 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2019	Inspection Date	20/03/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AJR 6178

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	769.80	769.80
2	REAR TAILLAMP LOWER BRACKET L+R @\$85.70	SERVICEABLE	171.40	-
2	REAR BUMPER RETAINER L+R @\$122.10	SERVICEABLE	244.20	-
2	PARKING SENSOR @\$418.80	* CHECK	837.60	-
1	REAR REINFORCEMENT	* CHECK	491.80	-
1	SPONGE	* CHECK	143.00	-
1	KEYLESS SENSOR	* CHECK	190.80	-
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER LOWER SKIRT (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOT (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-712.15	-192.45
			2,136.45	577.35
	<u>LABOUR</u>			
	TO REPAIR REAR BOOT, REAR BUMPER LOWER SKIRTING, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF END PANEL, REAR BUMPER LOWER SKIRT AND REAR BOOT.		600.00	400.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.		600.00	400.00
	TO REMOVE & REFIX REAR PARKING SENSOR & CHECK WIRING.		120.00	60.00
	TO REMOVE REAR BOOT TRIM, SPARE TYRE COVER AND OTHER ATTACHMENT PARTS.		120.00	60.00
	TO RUST PROOF ON ACCIDENT DAMAGED PARTS.		80.00	40.00
	TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST.	NOT NECESSARY	60.00	-
			-	-
			-	-
			-	-
			-	-
			-	-
			1,580.00	960.00
	GRAND TOTAL		3,716.45	1,537.35

Report Ref No. CS/SPF19004662/R1vd3e2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,247.40 NETT)				1,537.35
---	--	--	--	----------

Report Ref No. CS/SPF19004662/R1vd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$4,000

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.