

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 15 Mar 2019

Preliminary Advice

Insured Vehicle No : FBC4629X

TP Vehicle No : SHB1305J

Make : TOYOTA PRIUS TAXI

Date of Inspection : 13/03/2019

Inspection At : SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Accident Date : 12/03/2019

Assignment Date : 15/03/2019

Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,535.42
Revised Amount	:S\$	1,483.00
Check Items (Estimated)	:S\$	384.00
Total	:S\$	1,867.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.