

Adrian

ASSIGNMENT

From:

mmmm

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

at Workshop m/s:

of:

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess: \$300/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

115K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 888 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLP6347J.

Yr Regn:

2017, June.

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 Sedan.

c.c 1395

Colour:

Grey.

A/C:

Insured / Std / Nil / NA

Sp. Reading:

49645.

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

WAU222F42HA164591.

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/60R18.

R:

245/60R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/03/19.

Survey held at

Premium.

Des. of Damages:

Frt

Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OP AIG

SLP 6347 - CC3/AIG/19004678/Asd322

DOT: 1/1/2018

15/03/19 @ 10:14 a.m. received ZA to Noiseari via phone.

15/03/19 @ 10:14 a.m. mandate requested authorise repair to Noiseari.

MV:

PV:

Nett:

RECEIVED 17 MAY 2019

18/03/19 @ 4:42 p.m. mandate approved by Victor Koh.

18/03/19 @ 5:13 p.m. revert authorise repair to Tony (Graham) via email.

17/04/19 Confirmed P/P \$24,702.12 @ 10 days with Adrian. (\$24,702.88 Ad-50)

Date/Time, File Pass to?

Date/Time, File Return to?

1) 17/05/19

2)

3) Typist

4)

5)

6)

Pres. Report:

Final Report: \$24,702.12 P/P

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

200

11

211

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9668R
Vehicle Details	
Vehicle No.:	SLP6347J
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC (NAV)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CVN039040
Chassis No.:	WAUZZZF42HA164591
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,490.00
Original Registration Date:	13 Jun 2017
First Registration Date:	13 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$27,486.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2027
PARF Rebate Amount:	\$20,614.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$41,305.00
Total Rebate Amount:	\$61,919.00

The information contained herein is correct as at 15 Mar 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 17 April 2019 3:29 PM
To: 'Boo seng yak'
Cc: Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiajee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLP6347J - OD AIG - SURVEYED 14 MAR 19

Dear Mr Boo,

Confirmed final fig \$ 24,702.12 @ 10 days of repairs before excess \$ 300/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Monday, 15 April 2019 4:37 PM
To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLP6347J - OD AIG - SURVEYED 14 MAR 19

hi Adrian and all,

Revised estimate is attached. Photographs of damaged items was mailed to you on 21 Mar 19.

Please confirm repair cost of \$24,702.12 @ 10 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 18 March 2019 3:13 PM
To: 'Claims'
Cc: SUR
Subject: RE: OD CLAIM FOR SLP 6347 J
Attachments: ESTIMATE .pdf

Dear Tony,

As instructed by our client, please proceed to repair the insured vehicle **SLP 6347J** (Excess \$ 300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Thursday, 14 March 2019 3:47 PM
To: 'SUR' <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: OD CLAIM FOR SLP 6347 J

Dear all,

Kindly assist follow up repair approval.

Survey had carry out just now.

Thank you.

Best Regards,

Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902211W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

View Received Message

This mail is associated with :

***SLP6347J (7041495353SG)**

OD

Mar 13 2019 11:00AM

[THAT MARKETING GUY PTE LTD]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/03/2019 14:47 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$26348.00) - SLP6347J - Claim Handler: Mohd Zawaye, Norsazani

Approved:26348.00:Kindly justify why 6.5 labour needed? Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 15 Mar 2019

Preliminary Advice

Vehicle No	: SLP6347J	Accident Date	: 13/03/2019
Make	: AUDI A4	Policy No.	: 1700015312-01
Assignment Date	: 14/03/2019	Excess	: S\$0.00
Date of Inspection	:	Est. Duration of Repair	:
Inspection At	:		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,460.00
Revised Amount	:S\$	26,348.00
Check Items (Estimated)	:S\$	3,833.00
Total	:S\$	30,181.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	61,919.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,081.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/03/2019 09:57
Date Of Accident	13/03/2019 11:25
Exact Location Of Accident	CTE TOWARDS CITY MERGING TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6347J
Insured/Policyholder	
Name Of Registered Owner	THAT MARKETING GUY PTE LTD
Co Reg No	201409668R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96360813

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700015312-01
Cover Note Number	

Driver

Name of Driver	LEE YONG HENG, WILLIE
NRIC No	S8308246A
Date Of Birth	31/03/1983
Occupation	INDOOR
Date Of Driving Pass	02/09/2005
Driving Experience	13 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96360813
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	21 YISHUN STREET 51 #04-03
Postcode	768085
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE MERGING INTO PIE, THE VEHICLE STOPPED SUDDENLY AND I COULDN'T STOP IN TIME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV8360Z
Vehicle Make/Model/Colour	NISSAN / MURANO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/YIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While merging into PIE, the vehicle stopped suddenly and I couldn't stop in time

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No: _____

Accident Photo



IDENTITY CARD NO. S8308246A



Name

LEE YONG HENG, WILLIE
(LI YONGXING, WILLIE)

李永興

Race

CHINESE

Date of birth

31-03-1983

Country/Place of birth

SINGAPORE

Sex

M

S8308246A

License Number: S8308246A

Name:

LEE YONG HENG, WILLIE
(LI YONGXING, WILLIE)

Birth Date: 31 Mar 1983

Issue Date: 02 Sep 2006

0013662070

S83024



NRIC No. S8308246A



Date of issue

24-03-2014

21 YISHUN STREET 51 #04-03
SINGAPORE 788085

NRIC No: S8308246A

Date: 04/08/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers,
exclusive of the driver, and motor tractors
/ vehicles $\leq$ 2500 kg

02 Sep 2006

NP 428A



License No: S8308246A

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : THAT MARKETING GUY PTE LTD
 Period of Insurance : 13 Jun 2018 To 12 Jun 2019
 Engine No. : CVN039040
 Chassis No. : WAUZZZF42HA164591

Vehicle No. : SLP6347J
 Policy No. : 1700015312-01
 Endorsement No. :
 Issued Date : 18 May 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
 Engine Capacity/Tonnage : 1,395.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

Any person who is driving on the Policyholder's order or with their permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YONG HENG, WILLIE LEE - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125268

PREMIUM LEASING - MPL

261 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SICPNY

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Write/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0322/2019/GW
Date	:	14-Mar-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	That Marketing Guy Pte Ltd
Address	:	21 Yishun Street 51 #04-03 Singapore 768085
Telephone	:	HP +65 96360813
Type of Claim	:	Own Damage Claims
Policy No.	:	1700015312-01
Vehicle No	:	SLP 6347 J
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	13/6/2017
Engine No	:	CVN 039040
Chassis No	:	WAUZZZF42HA164591
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Mar-19
Place of Accident	:	CTE Towards City Merging Towards PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 6347 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and renew aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	
3	To dismantle both front door panel trim. To remove and reinstall both wing mirror assy.	S/N \$ 600.00 ✓	
4	To dismantle and renew front bumper, bonnet, both front fenders and both headlights. Renew front lock carrier and align to position. Re-organise rear crash management components. Reinstall all parts removed.	\$ 5,400.00	3250.
5	To respray front bumper, bonnet, both front fenders, both upper A-pillar and both front doors. ✓ ✓ RH ✓ ✓	\$ 5,600.00	3850
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 13,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLP 6347 J**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 1,946.00	<i>✓</i> 1556.80
2	FRONT BUMPER FIXING PARTS <i>Free</i>	\$ 258.00	<i>+</i>
3	FRONT BUMPER SECURING STRIP	\$ 64.00	<i>+</i>
4	FRONT BUMPER GRILLE-CENTER <i>new</i>	\$ 178.00	<i>+</i>
5	FRONT BUMPER CLOSING LEMENT-LOWER CENTRE <i>new</i>	\$ 191.00	<i>+</i>
6	FRONT BUMPER AIR GUIDE-LH <i>new</i>	\$ 56.00	<i>+</i> 244.40
7	FRONT BUMPER AIR GUDIE-RH <i>Delnd</i>	\$ 56.00	<i>✓</i> 44.40
8	RADIATOR GRILLE <i>Smashed</i>	\$ 1,053.00	<i>✓</i> 842.40
9	FRONT BUMPER AIR GUIDE GRILLE -LH/RH <i>new</i>	2 \$ 246.00	<i>+</i>
10	FRONT BUMPER CARRIER <i>Best</i>	\$ 733.00	<i>✓</i> 586.00
11	FRONT BUMPER BRACKET-LH/RH <i>Not Nec</i>	2 \$ 414.00	<i>?X</i>
12	FRONT BUMPER GUIDE SECTION-LH <i>Free new</i>	\$ 33.00	<i>+</i>
13	FRONT BUMPER GUIDE SECTION-RH <i>new</i>	\$ 34.00	<i>✓</i> 27.12
14	FRONT BUMPER COVER <i>Delnd</i>	\$ 116.00	<i>✓</i> 92.40
15	FRONT FOAM FILLER PIECE <i>Delnd</i>	\$ 113.00	<i>✓</i> 90.40
16	SIGN ' CAUTION ' <i>Free</i>	\$ 13.00	<i>✓</i> 9.76
17	AIR CONDITIONER STICKER	\$ 7.00	<i>✓</i> 5.12
18	FRONT LOCK CARRIER BRACKET <i>cracked</i>	\$ 125.00	<i>✓</i> 100
19	FRONT BUMPER SUPPORT-LH/RH <i>new</i>	2 \$ 52.00	<i>? ✓</i> 20.32
20	FAN FARE LOW TONE-RH <i>Not nec</i>	\$ 262.00	<i>?X</i>
SUB-TOTAL SPARE PARTS		\$ 5,950.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLP 6347 J**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	SPRING SHACKLE-RH <i>Not nec.</i>	\$ 26.00	?X
22	FRONT FENDER-LH/RH <i>RH Buckled</i>	2 \$ 1,400.00	700 559.60
23	FRONT FENDER ATTACHMENT PARTS-LH/RH <i>Not nec</i>	2 \$ 365.00	?X
24	FRONT FENDER CLOSING ELEMENT-LH/RH <i>nearby d</i>	2 \$ 90.00	✓ 36.00
25	FRONT FENDER BRACKET-LH/RH <i>3</i>	2 \$ 64.00	+
26	FRONT FENDER BRACE-LH/RH <i>near</i>	2 \$ 214.00	✓
27	FRONT WHEEL HOSUING LINER-RH	\$ 220.00	✓
28	FRONT WHEEL HOSING LINER ATTACHMENT PARTS-RH <i>Not nec</i>	\$ 82.00	+
29	FRONT WHEEL SPOILER-RH <i>Not nec</i>	\$ 66.00	+
30	FRONT FENDER MOLDING TRIM-RH <i>near</i>	\$ 33.00	✓ 25.54
31	FRONT STONE CHIP GUARD-RH <i>near</i>	\$ 46.00	✓ 36.64
32	FRONT FENDER LEDGE-RH/LH <i>RH 1st</i>	2 \$ 56.00	28 22.24
33	FRONT FENDER LEDGE COVER-RH/LH <i>RH 1st</i>	2 \$ 42.00	21 16.16
34	BONNET <i>Derbed</i>	\$ 2,554.00	2043.20
35	BONNET ATTACHMENT PARTS <i>Not nec</i>	\$ 111.00	?X
36	BONNET LID HINGE-LH/RH <i>near</i>	2 \$ 554.00	+
37	BONNET IMPACT PROTECTION -CENTER <i>3</i>	\$ 25.00	19.76
38	BONNET IMPACT PROTECTION-LH/RH <i>3</i>	2 \$ 50.00	39.68
39	BONNET GAS FILLED STRUT-LH/RH <i>near</i>	2 \$ 217.00	+
40	BONNET STRIKER-LH/RH <i>Not nec</i>	2 \$ 92.00	?X
SUB-TOTAL SPARE PARTS		\$ 6,307.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 6347 J

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remark
41	BONNET LID LOCK	Not Nec	2 S	391.00	?X
41	FLAT CONNECTOR HOUSING WITH CONTACT LOCKING MECHANISM	Not Nec	2 S	24.00	?X
42	CONNECTOR HOUSING BRACKET	Not Nec	2 S	18.00	?X
43	BONNET BOWDEN CABLE-CENTER	Not Nec	S	53.00	+
44	BONNET LOCK CABLE OVER	Not Nec	S	9.00	+
45	BONNET RELEASE CABLE	Not Nec	S	53.00	+
46	BONNET RELEASE LEVER	Not Nec	S	12.00	+
47	BONNET LID LOCK CABLE	Not Nec	S	67.00	+
48	LED HEALDIGHT-LH/RH	Rtl Cashed	2 S	14,174.00	7087 5669.60
49	LED HEALDIGHT POWER MODULE	Damaged	S	716.00	+ 572.80
50	LED HEADLIGHT CONTROL UNIT	Damaged.	S	685.00	+ 548.00
51	LED HEADLIGHT LIFT CYLINDER	Not Nec	S	192.00	?X
52	LED HEADLIGHT CORRUGATED PIPE FOR WASHING SYSTEM	Not Nec	S	83.00	+
53	LED HEADLIGHT WASHER TANK CONNECTOR PIPE	Not Nec	S	35.00	+
54	WASH WATER RESERVOIR	Not Nec	S	135.00	+
55	RADIATOR LOCK CARRIER WITH MOUNTING	Rehanded	S	928.00	✓ 742.00
56	A/C CONDENSER WITH DRYER	Dented	S	568.00	✓ 454.00
57	RADIATOR	Bent	S	603.00	✓ 482.40
58	RADIATOR LOWER RUBBER BUSH	Not Nec	2 S	17.00	?X
59	RADIATOR LOWER MOUNTING	Not Nec	2 S	24.00	?X
60	INTERCOOLER-LOWER CENTRE	Not Nec	S	470.00	+
SUB-TOTAL SPARE PARTS			:	\$ 19,257.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLP 6347]**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	READY MIX COOLANT 1.5 LTR <i>plan</i>	4 \$ 84.00	✓ 67.20
61	AIR DUCT-LH/RH <i>21st & 2nd</i>	2 \$ 50.00	25 19.84
61	INNER AIR DUCT-LH/RH <i>2x/2x Damaged</i>	2 \$ 22.00	+ ✓ 8.32
62	UPPER AIR DUCT <i>3 new</i>	\$ 15.00	+
63	LOWER AIR DUCT	\$ 19.00	+
64	FAN RING <i>2 new</i>	\$ 242.00	2x
65	RADIATOR FAN WITH CONTROL UNIT <i>1 new</i>	\$ 2,107.00	+
66	FRONT WINDOW GUIDE TRIM STRIP-LH/RH <i>4 new</i>	2 \$ 470.00	+
67	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH/RH <i>cut</i>	2 \$ 560.00	✓ 448
68	FRONT NO. PLATE <i>Best</i>	S/N \$ 25.00	✓
69	SUNDRIES <i>new</i>	\$ 1,000.00	? ✓ 39.12
TOTAL SPARE PARTS		\$ 36,108.00	
TOTAL LABOUR CHARGES		\$ 13,352.00	
GRAND TOTAL		\$ 49,460.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 14/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 Days.

LIAC Auto Consultants hence notify the Repairee of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairee

Signature

Date

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0322/2019/GW
Date : 14-Mar-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

10 days exclude 1 Sunday - jh

15-Apr-19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : That Marketing Guy Pte Ltd
Address : 21 Yishun Street 51 #04-03
Singapore 768085
Telephone : HP +65 96360813
Type of Claim : Own Damage Claims
Policy No. : 1700015312-01
Vehicle No : **SLP 6347 J**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : 13/6/2017
Engine No : CVN 039040
Chassis No : WAUZZZF42HA164591
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Mar-19
Place of Accident : CTE Towards City Merging Towards PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 6347 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To remove and renew aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
3	To dismantle both front door panel trim. To remove and reinstall both wing mirror assy.	S/N \$	600.00	\$ 600.00
4	To dismantle and renew front bumper, bonnet, both front fenders and both headlights. Renew front lock carrier and align to position. Re-organise rear crash management components. Reinstall all parts removed.	\$	5,400.00	\$ 3,250.00
5	To respray front bumper, bonnet, both front fenders, both upper A-pillar and both front doors.	\$	5,600.00	\$ 3,850.00
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 13,352.00	\$ 9,452.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLP 6347 J**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,946.00	\$ 1,556.80
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	FRONT BUMPER SECURING STRIP	\$ 64.00	
4	FRONT BUMPER GRILLE-CENTER	\$ 178.00	
5	FRONT BUMPER CLOSING LEMENT-LOWER CENTRE	\$ 191.00	
6	FRONT BUMPER AIR GUIDE-LH	\$ 56.00	
7	FRONT BUMPER AIR GUDIE-RH	\$ 56.00	\$ 44.40
8	RADIATOR GRILLE	\$ 1,053.00	\$ 842.40
9	FRONT BUMPER AIR GUIDE GRILLE -LH/RH	2 \$ 246.00	
10	FRONT BUMPER CARRIER	\$ 733.00	\$ 586.00
11	FRONT BUMPER BRACKET-LH/RH	2 \$ 414.00	
12	FRONT BUMPER GUIDE SECTION-LH	\$ 33.00	
13	FRONT BUMPER GUIDE SECTION-RH	\$ 34.00	\$ 27.12
14	FRONT BUMPER COVER	\$ 116.00	\$ 92.40
15	FRONT FOAM FILLER PIECE	\$ 113.00	\$ 90.40
16	SIGN ' CAUTION '	\$ 13.00	\$ 9.76
17	AIR CONDITIONER STICKER	\$ 7.00	\$ 5.12
18	FRONT LOCK CARRIER BRACKET	\$ 125.00	\$ 100.00
19	FRONT BUMPER SUPPORT-LH/RH	2 \$ 52.00	\$ 20.32
20	FAN FARE LOW TONE-RH	\$ 262.00	
SUB-TOTAL SPARE PARTS		\$ 5,950.00	\$ 3,374.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLP 6347 J**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 3,374.72
21	SPRING SHACKLE-RH		\$ 26.00	
22	FRONT FENDER-LH/RH	2	\$ 1,400.00	\$ 559.60
23	FRONT FENDER ATTACHMENT PARTS-LH/RH	2	\$ 365.00	
24	FRONT FENDER CLOSING ELEMENT-LH/RH	2	\$ 90.00	\$ 36.00
25	FRONT FENDER BRACKET-LH/RH	2	\$ 64.00	
26	FRONT FENDER BRACE-LH/RH	2	\$ 214.00	
27	FRONT WHEEL HOSUING LINER-RH		\$ 220.00	
28	FRONT WHEEL HOSING LINER ATTACHMENT PARTS-RH		\$ 82.00	
29	FRONT WHEEL SPOILER-RH		\$ 66.00	
30	FRONT FENDER MOLDING TRIM-RH		\$ 33.00	\$ 25.84
31	FRONT STONE CHIP GUARD-RH		\$ 46.00	\$ 36.64
32	FRONT FENDER LEDGE-RH/LH	2	\$ 56.00	\$ 22.24
33	FRONT FENDER LEDGE COVER-RH/LH	2	\$ 42.00	\$ 16.16
34	BONNET		\$ 2,554.00	\$ 2,043.20
35	BONNET ATTACHMENT PARTS		\$ 111.00	
36	BONNET LID HINGE-LH/RH	2	\$ 554.00	
37	BONNET IMPACT PROTECTION -CENTER		\$ 25.00	\$ 19.76
38	BONNET IMPACT PROTECTION-LH/RH	2	\$ 50.00	\$ 39.68
39	BONNET GAS FILLED STRUT-LH/RH	2	\$ 217.00	
40	BONNET STRIKER-LH/RH	2	\$ 92.00	
SUB-TOTAL SPARE PARTS			\$ 6,307.00	\$ 6,173.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLP 6347 J**

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>		Remark
			S/Nett	\$	
					6,173.84
41	BONNET LID LOCK	2	\$ 391.00		
41	FLAT CONNECTOR HOUSING WITH CONTACT LO	2	\$ 24.00		
42	CONNECTOR HOUSING BRACKET	2	\$ 18.00		
43	BONNET BOWDEN CABLE-CENTER		\$ 53.00		
44	BONNET LOCK CABLE OVER		\$ 9.00		
45	BONNET RELEASE CABLE		\$ 53.00		
46	BONNET RELEASE LEVER		\$ 12.00		
47	BONNET LID LOCK CABLE		\$ 67.00		
48	LED HEALDIGHT-LH/RH	2	\$ 14,174.00	\$ 5,669.60	
49	LED HEALDIGHT POWER MODULE		\$ 716.00	\$ 572.80	
50	LED HEADLIGHT CONTROL UNIT		\$ 685.00	\$ 548.00	
51	LED HEADLIGHT LIFT CYLINDER		\$ 192.00		
52	LED HEADLIGHT CORRUGATED PIPE FOR WASHING S		\$ 83.00		
53	LED HEADLIGHT WASHER TANK CONNECTOR PIPE		\$ 35.00		
54	WASH WATER RESERVOIR		\$ 135.00		
55	RADIATOR LOCK CARRIER WITH MOUNTING		\$ 928.00	\$ 742.00	
56	A/C CONDENSER WITH DRYER		\$ 568.00	\$ 454.00	
57	RADIATOR		\$ 603.00	\$ 482.40	
58	RADIATOR LOWER RUBBER BUSH	2	\$ 17.00		
59	RADIATOR LOWER MOUNTING	2	\$ 24.00		
60	INTERCOOLER-LOWER CENTRE		\$ 470.00		
SUB-TOTAL SPARE PARTS			\$ 19,257.00	\$ 14,642.64	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLP 6347 J**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 14,642.64
61	READY MIX COOLANT 1.5 LTR	4	\$ 84.00	\$ 67.20
61	AIR DUCT-LH/RH	2	\$ 50.00	\$ 19.84
61	INNER AIR DUCT-LH/RH	2	\$ 22.00	\$ 8.32
62	UPPER AIR DUCT		\$ 15.00	
63	LOWER AIR DUCT		\$ 19.00	
64	FAN RING		\$ 242.00	
65	RADIATOR FAN WITH CONTROL UNIT		\$ 2,107.00	
66	FRONT WINDOW GUIDE TRIM STRIP-LH/RH	2	\$ 470.00	
67	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-L	2	\$ 560.00	\$ 448.00
68	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
69	SUNDRIES		\$ 1,000.00	\$ 39.12
TOTAL SPARE PARTS			\$ 36,108.00	\$ 15,250.12
TOTAL LABOUR CHARGES			\$ 13,352.00	\$ 9,452.00
GRAND TOTAL			\$ 49,460.00	\$ 24,702.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLP 6347 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0322/2019/MAS

15 May 2019

from
Telephone +65-
Telefax +65-
Email
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLP 6347 J, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLP 6347 J**, claimant,
That Marketing Guy Pte Ltd, please find the related document per attached.

1. A copy of the Original invoice no. 85013741 – S\$26,110.27
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG -- SLP 6347 J

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6886 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6886 2222
Telefax: 6471 3733

UBI Service Centre
55 Ubi Road 1
Singapore 408723
Telephone: 6886 2222
Telefax: 6471 3733

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2222
9826 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 15:22

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013741 Date : 08/05/2019 Order : SLP6347J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLP6347J (V 33956)	Regn Date: 13/06/2017	Mileage: 49645	WIP No.: 46167
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF42HA164591	Engine: CVN 039040	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER AND RADIATOR, CHECK ELECTRICAL FANS, ADDITIONAL RADIATOR AND CONTROL UNIT, PRESSURISE COOLING SYSTEM, TO CARRY OUT VACUUM AND REGAS	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE BOTH FRONT DOOR PANEL TRIM, TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY	600.00	1.00	600.00
S	BODYWORK	M:	3250.00	1.00	3,250.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3723

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 2223

Customer Service
Service Appointment
Singapore Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2323
9826 1232

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 15:22

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013741 Date : 08/05/2019 Order : SLP6347J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLP6347J (V 33956)	Regn Date: 13/06/2017	Mileage: 49645	WIP No.: 46167
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF42HA164591	Engine: CON 039040	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee	(33)		

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED M:	3850.00	1.00	3,850.00
S	BODYWORK	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH UPPER A PILLAR AND BOTH FRONT DOOR M:	192.00	1.00	192.00
X	ABW0853651 3FZ	TO CARRY OUT DIAGNOSTIC CHECK			
X	ABW0941774A	GRILLE Less 020%	1.00	1053.00	842.40
X	ABW0821106A	HEADLIGHT Less 020%	1.00	7087.00	5,669.60
X	ABW0807771	FENDER Less 020%	1.00	699.50	559.60
X	ABW0807061	BRACKET Less 020%	1.00	125.00	100.00
X	ABW0816411L	COVER Less 020%	1.00	115.50	92.40
X	ABW0816411L	REFR. COND. Less 020%	1.00	567.50	454.00
X	ABW0121251K	RADIATOR Less 020%	1.00	603.00	482.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159538
Page 3
15:22

Alexandra Service Centre
281 Alexandra Road
Singapore 159538
Telephone: 6388 2223
Telefax: 6475 1023

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2223
8828 1233

Invoice: 85013741

Account: 00006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Date : 08/05/2019

Order : SLP6347J

Term : 30

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLP6347J (U 33956)

Regn Date: 13/06/2017

Mileage: 49645

WTP No.: 46167

Model: A4 SEDAN 1.4 TFSI S tronic

Chassis: WAUZZZF42HA164591

Engine: CVN 039040

Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
X	ABW0805594	CARRIER Less 020%	1.00	927.50	742.00
X	ABW0807558A	FOAM INSER Less 020%	1.00	113.00	90.40
X	ABW0807113	BRACKET Less 020%	1.00	732.50	586.00
X	AG A13040M2	PREMIX-COOLANT Less 020%	4.00	21.00	67.20
X	ABW0823029A	HOOD Less 020%	1.00	2554.00	2,043.20
X	ABW0807065C GRU	COVER Less 020%	1.00	1946.00	1,556.80
X	ABW0807334	SUPPORT Less 020%	1.00	25.40	20.32
X	ABW0807284	GUIDE Less 020%	1.00	33.90	27.12
X	ABW0821092	PLATE Less 020%	1.00	45.00	36.00
X	ABW0121674A	AIR DUCT Less 020%	1.00	10.40	8.32
X	ABW0121763	AIR DUCT Less 020%	1.00	55.50	44.40
X	ABW0823746	COVER Less 020%	1.00	20.20	16.16
X	ABW0853834	SPOILER Less 020%	1.00	32.30	25.84
X	ABW0823125	PROTECTION Less 020%	1.00	24.90	19.92
X	ABW0823126	PROTECTION Less 020%	1.00	24.70	19.76
X	A4E0260749A	WASHER Less 020%	1.00	3.60	2.88
X	A3D0260749C	WASHER Less 020%	1.00	4.00	3.20
X	A7H0820896	SEAL Less 020%	1.00	2.50	2.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Jurong Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6894 2223
Fax: 6894 3333

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6894 2223
Telefax: 6894 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408723

Customer Service
Service Appointment

6866 2323
6828 1233

INSURANCE TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Customer Care Email: customer.care@premiumauto.com.sg

Page 4 15:22

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013741 Date : 08/05/2019 Order : SLP6347J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLP6347J (V 33956)	Regn Date: 13/06/2017	Mileage: 49645	WIP No.: 46167
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF42HA164591	Engine: CVN 039040	Dept: U
VSD No.:			
You have been assisted by :- UB-Jiayee	(33)		

		Details	Qty	Unit Price	Amount
X	ABW0820582C	COVER Less 020%	1.00	27.80	22.24
X	ABW0853824B 989	STONEGUARD Less 020%	1.00	45.80	36.64
X	ABW0010515A	STICKER Less 020%	1.00	6.40	5.12
X	ABK0010520A	PLATE Less 020%	1.00	12.20	9.76
X	ABW0121284AL	AIR DUCT Less 020%	1.00	24.80	19.84
X	AAM0907397AD	CTRL UNIT Less 020%	1.00	685.00	548.00
X	A7PP941572AB200	POWER MOD Less 020%	1.00	716.00	572.80
X	AN 0161857	POP-RIVET Less 020%	12.00	3.00	28.80
X	AN 91093901	RIVET Less 020%	4.00	0.70	2.24
X	ABW0853284E 222	WINDOW SLD Less 020%	1.00	280.00	224.00
X	ABW0853283E 222	WINDOW SLD Less 020%	1.00	280.00	224.00
X	ABW0823124	PROTECTION Less 020%	1.00	24.70	19.76

Parts 15,225.12	Sub-Total	24,402.12
Labour 0.00	7% GST	1,708.15
Sublet 9,477.00	Grand Total	26,110.27
Menus 0.00		
Lubricant 0.00		



RF

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLP 6347 J

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0322/2019/DY
29 March 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI
Vehicle Chassis No. : WAUZZZF42HA164591
Vehicle Regn No. : SLP 6347 J
Vehicle Mileage : 49645 KM
Vehicle Owner : That Marketing Guy Pte Ltd
Certificate No : 1700015312-01
Own Damage Excess : \$321.00 (Inclusive 7% GST)
Accident Date : 13/03/2019
Place : CTE Towards City Merging Towards PIE
Repair Cost : \$ 26,110.27
WIP No. : 46167
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

THAT
MARKETING
GUY

That Marketing Guy Pte Ltd
GST Reg No. 2014/98680
89 Raffles Road #03-01
Singapore 208018

Owner / Insured Signature :

Time :

Date :

29/3

REPUBLIC OF SINGAPORE
NATIONAL IDENTITY CARD NO. S8308246A



Name

LEE YONG HENG, WILLIE
(LI YONGXING, WILLIE)

李 永 兴

Race

CHINESE

Date of birth

31-03-1983

Country/Place of birth

SINGAPORE

Sex

M

S8308246A



License Number S8308246A

Name

LEE YONG HENG, WILLIE
(LI YONGXING, WILLIE)

Birth Date: 31 Mar 1983

Issue Date: 02 Sep 2005



NRIC No. S8308246A



Date of issue

24-03-2014

21 YISHUN STREET 51 #04-03
SINGAPORE 788085

NRIC No. S8308246A

Date: 04/08/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor cars <= 3000 kg with <= 7 passengers,
exclusive of the driver; and motor tractors
/vehicles <= 2500 kg

02 Sep 2005

NP 428A



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : THAT MARKETING GUY PTE LTD
Period of Insurance : 13 Jun 2018 To 12 Jun 2019
Engine No. : CVN039040
Chassis No. : WAUZZZF42HA164591

Vehicle No. : SLP6347J
Policy No. : 1700015312-01
Endorsement No. :
Issued Date : 18 May 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

Any person who is driving on the Policyholder's order or with their permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YONG HENG, WILLIE LEE - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 406699-63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125268

PREMIUM LEASING - MPL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCHFY

R AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Mar 2019		14 Mar 2019 17:26 Edit Adj Rpt	S\$24,702.12 Edit Estimates	S\$24,702.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	THAT MARKETING GUY PTE LTD, Co. Reg. No.: 201409668R, Tel: +6596360813								
Vehicle Reg. No.:	SLP6347J	Date of Loss:	13/03/2019 12:00 - :59 [21 Months From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 7041495353SG	Policy/Cover Note No.:	1700015312 (Comprehensive) Coverage: 13/06/2018 - 12/06/2019						
		Excess:	S\$300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/03/2019]								
Driver/Custodian:	LEE YONG HENG, WILLIE (35 / Male), NRIC: S8308246A, Tel: +6596360813 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (18/03/2019): Alert - Adj Mandate Approved (S\$26348.00) - SLP6347J - Claim Handler: Mohd Zawaye... - AIG_SG (15/03/2019): SLP6347J / OD / 13/03/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP6347J (7041495353SG)
OD
Mar 13 2019 12:00PM
[THAT MARKETING GUY PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video											1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UB1)								Thumbnail	Print	
1	14/03/19 10:16	Video - Accident [Linked Accident Report Documents]							1	Load MP4		
Assessment Reports											1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	15/03/19 10:14	Adjuster Immediate Advice							1	Load HTML		
Photos/Images											3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	15/03/19 09:02	General View							1	Load JPG	☒	
2	15/03/19 09:02	Chassis Number							1	Load JPG	☒	
3	15/03/19 09:02	General View							1	Load JPG	☒	
4	15/03/19 09:02	General View							1	Load JPG	☒	
5	15/03/19 09:02	General View							1	Load JPG	☒	
6	15/03/19 09:02	General View							1	Load JPG	☒	
7	15/03/19 09:02	General View							1	Load JPG	☒	
8	15/03/19 09:02	General View							1	Load JPG	☒	
9	15/03/19 09:02	General View							1	Load JPG	☒	
10	15/03/19 09:02	General View							1	Load JPG	☒	
11	15/03/19 09:02	General View							1	Load JPG	☒	
12	15/03/19 09:02	General View							1	Load JPG	☒	
13	15/03/19 09:02	General View							1	Load JPG	☒	
14	15/03/19 09:02	General View							1	Load JPG	☒	
15	15/03/19 09:02	General View							1	Load JPG	☒	
16	15/03/19 09:02	General View							1	Load JPG	☒	
17	15/03/19 09:02	General View							1	Load JPG	☒	
18	15/03/19 09:02	General View							1	Load JPG	☒	
19	15/03/19 09:02	General View							1	Load JPG	☒	
20	15/03/19 09:02	General View							1	Load JPG	☒	
21	15/03/19 09:02	General View							1	Load JPG	☒	
22	15/03/19 09:02	General View							1	Load JPG	☒	
23	15/03/19 09:02	General View							1	Load JPG	☒	
24	15/03/19 09:02	General View							1	Load JPG	☒	
25	15/03/19 09:02	General View							1	Load JPG	☒	
26	15/03/19 09:02	General View							1	Load JPG	☒	
27	15/03/19 09:02	General View							1	Load JPG	☒	
28	15/03/19 09:02	General View							1	Load JPG	☒	
29	15/03/19 09:02	General View							1	Load JPG	☒	
30	15/03/19 09:02	General View							1	Load JPG	☒	
31	15/03/19 09:02	General View							1	Load JPG	☒	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
32	15/03/19 09:02	General View		☒
33	15/03/19 09:02	General View		☒
34	15/03/19 09:02	General View		☒
35	15/03/19 09:02	General View		☒
36	15/03/19 09:02	General View		☒
37	15/03/19 09:02	General View		☒
38	15/03/19 09:02	General View		☒
39	15/03/19 09:02	General View		☒
40	15/03/19 09:02	General View		☒
41	15/03/19 09:02	General View		☒
42	15/03/19 09:02	General View		☒
43	15/03/19 09:02	General View		☒
44	15/03/19 09:02	General View		☒
45	15/03/19 09:02	General View		☒
46	15/03/19 09:02	General View		☒
47	15/03/19 09:02	General View		☒
48	15/03/19 09:02	General View		☒
49	15/03/19 09:02	General View		☒
50	15/03/19 09:02	General View		☒
51	15/03/19 09:02	General View		☒
52	15/03/19 09:02	General View		☒
53	15/03/19 09:02	General View		☒
54	15/03/19 09:02	General View		☒
55	15/03/19 09:02	General View		☒
56	15/03/19 09:02	General View		☒
57	15/03/19 09:02	General View		☒
58	15/03/19 09:02	General View		☒
59	15/03/19 09:02	General View		☒
60	15/03/19 09:02	General View		☒
61	15/03/19 09:02	General View		☒
62	15/03/19 09:02	General View		☒
63	15/03/19 09:02	General View		☒
64	16/04/19 18:55	Reinspection Photo		☒
65	16/04/19 18:55	Reinspection Photo		☒
66	16/04/19 18:55	Reinspection Photo		☒
67	16/04/19 18:55	Reinspection Photo		☒
68	16/04/19 18:55	Reinspection Photo		☒
69	16/04/19 18:55	Reinspection Photo		☒
70	16/04/19 18:55	Reinspection Photo		☒
71	16/04/19 18:55	Reinspection Photo		☒
72	16/04/19 18:55	Reinspection Photo		☒
73	16/04/19 18:55	Reinspection Photo		☒
74	16/04/19 18:55	Reinspection Photo		☒
75	16/04/19 18:55	Reinspection Photo		☒
76	16/04/19 18:55	Reinspection Photo		☒
77	16/04/19 18:55	Reinspection Photo		☒
78	16/04/19 18:55	Reinspection Photo		☒
79	16/04/19 18:55	Reinspection Photo		☒
80	16/04/19 18:55	Reinspection Photo		☒
81	16/04/19 18:55	Reinspection Photo		☒

Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
82	16/04/19 18:55	Reinspection Photo		Load JPG	☒
83	16/04/19 18:55	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/19 09:01	SLP 63473.pdf		Load PDF	
2	15/03/19 09:01	DRIVING & CI.pdf		Load PDF	
3	15/03/19 09:01	ESTIMATE.pdf		Load PDF	
4	17/04/19 15:25	ESTIMATE MARKED.pdf		Load PDF	
5	13/06/19 11:30	Workshop Invoice		Load PDF	
6	13/06/19 11:30	Discharge Voucher		Load PDF	

Linked Accident Report Documents

Video				View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	14/03/19 10:16	Video - Accident		Load MP4	
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	14/03/19 10:18	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	14/03/19 10:12	Accident Photo		Load JPG	☒
2	14/03/19 10:12	Accident Photo		Load JPG	☒
3	14/03/19 10:12	Accident Photo		Load JPG	☒
4	14/03/19 10:12	Accident Photo		Load JPG	☒
5	14/03/19 10:12	Accident Photo		Load JPG	☒
6	14/03/19 10:12	Accident Photo		Load JPG	☒
7	14/03/19 10:12	Accident Photo		Load JPG	☒
8	14/03/19 10:12	Accident Photo		Load JPG	☒
9	14/03/19 10:12	Accident Photo		Load JPG	☒
10	14/03/19 10:12	Accident Photo		Load JPG	☒
11	14/03/19 10:12	Accident Photo		Load JPG	☒
12	14/03/19 10:12	Accident Photo		Load JPG	☒
13	14/03/19 10:12	Accident Photo		Load JPG	☒
14	14/03/19 10:12	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	14/03/19 10:09	Sketch Plan		Load JPG	☒
2	14/03/19 10:09	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19004678/ASD3E2

Date: 13/06/2019

REFERENCE

Insured/Claimant: THAT MARKETING GUY PTE LTD

Policy No: 1700015312

Date of Loss: 13/03/2019

Nature of Claim: OD

Claim No: 7041495353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP6347J

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No: CVN039040

Reg. Date: 13/06/2017 (Man. Year: 2017)

Chassis No: WAUZZZF42HA164591

Colour: Grey

Odometer: 49645 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$115,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/60 R18

Rear Tyre Size:

245/60 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,108.00	15,250.12	20,857.88	57.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,352.00	9,452.00	3,900.00	29.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,460.00	24,702.12	24,757.88	50.06
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	49,160.00	24,402.12	24,757.88	50.36
+ GST 7.00/7.00% (S\$)	3,441.20	1,708.15	1,733.05	50.36
Nett Amount (S\$)	52,601.20	26,110.27	26,490.93	50.36

INSPECTION

Date of Assignment: 14/03/2019

Date Inspected: 14/03/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,946.00 FS	*1,556.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	64.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	178.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING LEMENT - LOWER CENTRE	Not Necessary	191.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	56.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	56.00 FS	*44.40 FS
8	1		*RADIATOR GRILLE	Smashed	1,053.00 FS	*842.40 FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	246.00 FS	*- FS
10	1		*FRONT BUMPER CARRIER	Bent	733.00 FS	*586.00 FS
11	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	414.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	33.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	34.00 FS	*27.12 FS
14	1		*FRONT BUMPER COVER	Deformed	116.00 FS	*92.40 FS
15	1		*FRONT FOAM FILLER PIECE	Deformed	113.00 FS	*90.40 FS
16	1		*SIGN CAUTION	Necessary	13.00 FS	*9.76 FS
17	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*5.12 FS
18	1		*FRONT LOCK CARRIER BRACKET	Cracked	125.00 FS	*100.00 FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	52.00 FS	*20.32 FS
20	1		*FAN FARE LOW TONE - RH	Not Necessary	262.00 FS	*- FS
21	1		*SPRING SHACKLE - RH	Not Necessary	26.00 FS	*- FS
22	2		*FRONT FENDER - LH / RH	O/S Buckled	1,400.00 FS	*559.60 FS
23	2		*FRONT FENDER ATTACHMENT PARTS - LH / RH	Not Necessary	365.00 FS	*- FS
24	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Damaged	90.00 FS	*36.00 FS
25	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	64.00 FS	*- FS
26	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	214.00 FS	*- FS
27	1		*FRONT WHEEL HOSUING LINER - RH	Not Necessary	220.00 FS	*- FS
28	1		*FRONT WHEEL HOSING LINER ATTACHMENT PARTS - RH	Not Necessary	82.00 FS	*- FS
29	1		*FRONT WHEEL SPOILER - RH	Not Necessary	66.00 FS	*- FS
30	1		*FRONT FENDER MOLDING TRIM - RH	Necessary	33.00 FS	*25.84 FS
31	1		*FRONT STONE CHIP GUARD - RH	Necessary	46.00 FS	*36.64 FS
32	1		*FRONT FENDER LEDGE - RH / LH	O/S Necessary	56.00 FS	*22.24 FS
33	1		*FRONT FENDER LEDGE COVER - RH / LH		42.00 FS	*16.16 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*BONNET	O/S Necessary		
35	1		*BONNET ATTACHMENT PARTS	Dented	2,554.00 FS	*2,043.20 FS
36	2		*BONNET LID HINGE - LH / RH	Not Necessary	111.00 FS	*- FS
37	1		*BONNET IMPACT PROTECTION - CENTER	Not Necessary	554.00 FS	*- FS
38	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	25.00 FS	*19.76 FS
39	2		*BONNET GAS FILLED STRUT - LH / RH	Necessary	50.00 FS	*39.68 FS
40	2		*BONNET STRIKER - LH / RH	Not Necessary	217.00 FS	*- FS
41	2		*BONNET LID LOCK	Not Necessary	92.00 FS	*- FS
42	2		*FLAT CONNECTOR HOUSING WITH CONTACT LOCKING MECHANISM	Not Necessary	391.00 FS	*- FS
43	2		*CONNECTOR HOUSING BRACKET	Not Necessary	24.00 FS	*- FS
44	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	18.00 FS	*- FS
45	1		*BONNET RELEASE CABLE	Not Necessary	53.00 FS	*- FS
46	1		*BONNET RELEASE LEVER	Not Necessary	53.00 FS	*- FS
47	1		*BONNET LID LOCK CABLE	Not Necessary	12.00 FS	*- FS
48	2		*LED HEADLIGHT - LH / RH	Not Necessary	67.00 FS	*- FS
49	1		*LED HEADLIGHT POWER MODULE	O/S Cracked	14,174.00 FS	*5,669.60 FS
50	1		*LED HEADLIGHT CONTROL UNIT	Damaged	716.00 FS	*572.80 FS
51	1		*LED HEADLIGHT LIFT CYLINDER	Damaged	685.00 FS	*548.00 FS
52	1		*LED HEADLIGHT CORRUGATED PIPE FOR WASHING SYSTEM	Not Necessary	192.00 FS	*- FS
53	1		*LED HEADLIGHT WASHER TANK CONNECTOR PIPE	Not Necessary	83.00 FS	*- FS
54	1		*WASH WATER RESERVOIR	Not Necessary	35.00 FS	*- FS
55	1		*RADIATOR LOCK CARRIER WITH MOUNTING	Not Necessary	135.00 FS	*- FS
56	1		*A/C CONDENSER WITH DRYER	Deformed	928.00 FS	*742.00 FS
57	1		*RADIATOR	Dented	568.00 FS	*454.00 FS
58	2		*RADIATOR LOWER RUBBER BUSH	Bent	603.00 FS	*482.40 FS
59	2		*RADIATOR LOWER MOUNTING	Not Necessary	17.00 FS	*- FS
60	1		*INTERCOOLER - LOWER CENTRE	Not Necessary	24.00 FS	*- FS
61	4		*READY MIX COOLANT 1.5 LTR	Not Necessary	470.00 FS	*- FS
62	1		*AIR DUCT - LH / RH	Necessary	84.00 FS	*67.20 FS
63	2		*INNER AIR DUCT - LH / RH	O/S Deformed	50.00 FS	*19.84 FS
64	1		*LOWER AIR DUCT	Damaged	22.00 FS	*8.32 FS
65	1		*FAN RING	Not Necessary	19.00 FS	*- FS
66	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	242.00 FS	*- FS
					2,107.00 FS	*- FS
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
67	2		*FRONT WINDOW GUIDE TRIM STRIP - LH / RH	Not Necessary	470.00 FS	*- FS
68	2		*FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH / RH	Not Necessary	560.00 FS	*448.00 FS
69	1		*FRONT NO. PLATE	Cut	25.00 FS	*25.00 FS
70	1		*SUNDRIES	Bent	1,000.00 FS	*39.12 FS
71	1		*BONNET LOCK CABLE OVER	Necessary	9.00 FS	*- FS
72	1		*UPPER AIR DUCT	Not Necessary	15.00 FS	*- FS
				Not Necessary		
				Total Parts (S\$)		
					36,108.00	15,250.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARTY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO DISMANTLE BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY	New	600.00	600.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	3,250.00
5	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS	New	5,600.00	3,850.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			13,352.00	9,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >