



**ESTIMATE TO REPAIR**

VEHICLE NO. : FBK 1952 P  
 MAKE : YAMAHA  
 MODEL : FZN150  
 YEAR : 2015  
 CHASSIS NO : ME1RG1610F2001186

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 14-Mar-19  
 DATE OF ACCIDENT : 7-Mar-19  
 THIRD PARTY REF : YQ 251 G / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Clutch Lever				\$ 38.00
1 pc	Engine Guard				\$ 2,400.00
1 pc	Fuel Tank Side Cover				\$ 65.00
1 pc	Handle Bar				\$ 68.00
1 pc	Brake Lever				\$ 38.00
1 pc	Side Box Bracket				\$ 850.00
					\$ 3,459.00
	Less 10%				\$ 345.90
					\$ 3,113.10
1 pair	Side Box	S.Nett			\$ 360.00
1 set	Sticker	S.Nett			\$ 250.00
1 pc	Safety Helment	S.Nett			\$ 500.00
	To putty and spray painting				\$ 500.00
	Towing Charges				\$ 50.00
	Labour Charges				\$ 500.00
TG/RA-	<b>Total</b>				<b>\$ 5,273.10</b>

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd