ASS. REC. BY:	REF: (s/Smo/9004936/Bad 362) Special Instruction:
1 W 10 W	GQ ASSIGNMENT (Office) Tung Shing Yiof SMO Date/Time: 19/3/198 10:440
Fstimated Cost:	Bill to:
OD TP/WS/TP	RES / OD RES / EVA / INV / MV / CS
	No: SKH 9SSIU Insured: GBC8700×
at Workshop m/s_	Messrs Y8 motor Tel: 8818 1666
of	Blk 9 # 01-44 8in Minglad Est
Policy No: DI	8 MM TPCVE 000 177 Claim No: CMTD 1 901318
Sum Insured:	Excess:
Make of Veh: (Client's Record)	D.O.A. 11/03/2019
CA / REV / RE	P. / REV 24 HRS H.O.D. Endorsement:
Date/Time: 2-2	Tomo 19/3/19 Person Contacted: Ah airng Vehicle IN OUT
Date/Time Act	tion/Instruction () Estimate
	ty 95510 - MBA / INC 19004490/4 b. 0 A - 11/3/2019
91	BL STUDX -X
0 -	compose mail pending estimate.
1/	
19/9- 3	till not ready.
	V
2.10	(1 cm 8/2, Fool enail & Cafrme (Red. 12400; 49%)

enneth		<u>A</u> :	SSIGNMENT		
From:	Date:		^	4 9-	,
Estimated Cost:			Veh No:	4 9551U Yr Reg	n: 10 1 0
OD INP IWS I TP RES !	OD RES / EVA / INV	/ MV	_ ',,' m.oycle	Bus / Van / Lorry / Taxi /	Prime Mover /
To Inspect Vehicle No:			Truck / Trailer		Wegan
at Workshop m/s		V8 Moto	Make:	esting)	c.c 23
of		00 1010		1	nsured / Std / NI / N
Insured:	-		_ Sp.Reading 27	12466 T/Radio: 1	nsured / Std / NI / N.
Policy No.		7014	Eng/No:		
Claims No.		3517		AHR 20	7025
Sum Insured:	Excess:		Gen. Cond: Good Fair	/ Poor / Burnt	
(Client's Record)	Excess:			med/Leaked/Burnt or	
Make of Veh:				med / Leaked / Burnt or	
			Modi: Nil / S/Rim /	STD ATRIM or	-
(Policy Condition)			Tyre Size: F:	225/5	OFRIT
Pemark: The veh had comm			R:		
repair at the time		N/S O/S	BS / DUN / EXNOVA / G	Y/FS/LIZA/MIC/OHTSU	/ PIR / SULL /
	100000000000000000000000000000000000000		TOYO / YOKO or		xen
Bal. or Market Value:	6011		Front	Rear	1
IDAC Accident Rport:	Consistent? : Y		R/Bal.	mm R/Ba!.	
GIA / PR Seen:	Consistent?: Y		L/Bal.	mm L/Bal.	mm
Est. Repairs:		es or No	D.O.A. 11/3/1	9 0.0.1. /	9/2/10
um Sum; 20	% 3 Val.: Ye	es or No	Survey held at	,	13/19
A REV REP. 24	HRS		5.00	ear I OIS I NIS I UIC I F	
0160		Vehicle: IN / OUT	l R	OLC P	Rooftop or
- F615011	Contacted:		The U/C / Chassis fra	me / Body Structure affect	and due to the
Date / Time Action / Inst	ruction			, on other blief	tied due to comsion.
EHR	1) (0				
0011101	recy				
		- RECEIVE	D 1 - 1 OCT 2019.		
/Time, File Pass to?		-			
La Turial	Prell. Report	, Da	ys Of Repair: 18		
Vime. File Return to?	Final Report	Re	survey No. of Trip:	Survey Fee:	1.60
		_	-	Transportation	490
	9	Add Fee:	: Site Insp (\$)_S - RSSI	
1100mm	55	=			
ad Familia			: Interview (\$). Powers	
ort Format :	1001-		Tech Invs (\$) Pixetos) Others	

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	12 Mar 2019		19 Mar 2019 10:44 Assign					New Assi Cancel Ca	
	Main	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SU	BFOLDER DE	TAILS				[Creat	ed by insurer]		
Insured:	CLP INTE	RNATIONAL PTE	LTD, Co. Reg.	No.: 20010	7294D				
Main Claimant:	OMEGA R	ENTALS PTE LTD	, Co. Reg. No.	20160396	7W				
Vehicle Reg No.:	SKH955	SKH9551U			Date of Loss:	11/03/2	11/03/2019 15:00 - :59		
Claim Type	TP / CM	TP / CMTD1901318			Policy/Cover Note No.:	D18MTPCVE000177 (Comprehensive)			
Vehicle Reg No. (Insured):	GBC8700	×			Policy No. (Claimant):				
					Excess:				
Repairer:	Messrs V	Motor Werkz P	te Ltd (HQ) Blk	9, #01-44	Sin Ming Industri	al Est Sed	tor C, 575630 Sin	Ming - Tel:	
Handling Insurer:		Messrs V8 Motor Werkz Pte Ltd (HQ) Blk 9, #01-44 Sin Ming Industrial Est Sector C, 575630 Sin Ming - Tel: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 [Handled by Hwang Shiang Yi - 6329 5205]							
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 28/	(03/2019]		
Driver/Cust dian (Insured):	0	AN S/O KIRUBEIN							
Adj Asg. Remarks:	PIC: Ah Qi	ang - HP 8818 16	66						

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

CLAIM SUBFOLDER TRACKING

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete Due Date Priority Type Task Group Subject Handler Assigned By Completed On

View All Compose Case Mail

No results.

' > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	3967W	
Vehicle No.:	SKH9551U	
Vehicle to be Exported:	No	
Intended Deregistration Date:	20 Mar 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	ESTIMA HYBRID 2.4X A	
Primary Colour:	Black	
Manufacturing Year:	2008	
Engine No.:	2AZH229638	
Chassis No.:	AHR207025333	
Maximum Power Output:	110.0 kW (147 bhp)	
Open Market Value:	\$49,923.00	
Original Registration Date:	21 Oct 2008	
First Registration Date:	21 Oct 2008	
Transfer Count:	4	
Actual ARF Paid: Intended PARF Rebate Details	\$29,954.00	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	20 Oct 2028	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
PQP Paid:	\$32,279.00	
COE Rebate Amount:	\$30,934.00	
Total Rebate Amount:	\$30,934.00	

The information contained herein is correct as at 20 Mar 2019

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Hwang Shiang Yi

Date:

01 Oct 2019

Preliminary Advice

Insured Vehicle No

: GBC8700X

TP Vehicle No

: SKH9551U

Accident Date

: 11/03/2019

Make

: TOYOTA ESTIMA

Assignment Date

: 19/03/2019

Date of Inspection

: 19/03/2019

Est. Duration of Repair

: 18.00

Inspection At

: MESSRS V8 MOTOR WERKZ PTE LTD (HQ)

BLK 9, #01-44 SIN MING INDUSTRIAL EST SECTOR C

SINGAPORE 575630

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear, front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,110.00
Revised Amount	:S\$	15,884.85
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,884.85
Lump Sum Repair	:S\$	12,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

(x)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



MAVIVA

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

*

Moskeri

Ways of Selling





2.88%P.A Low Interest@Gv inance.2 Years Warranty. 800 Down Monthly From \$988 GV Credit Pte Ltd StarAd



Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted Advanced Search ▼ 20 results/page

67 vehicles

Toyota Estima

Toyota Estima 2.4A X (COE till

Model

Depreciation Price

Reg Date > 10 year(s) Eng Cap

Mileage Veh Type

Available

7

Search Selection

Toyota Estima

Any

\$55,800

Any \$11,460 /yr

old 02-Feb-2009

2.362 cc

MPV

Απν

Available

01/2024)

2.88% P.A Lowest Interest At \$988 Monthly For Toyota Estima, \$0 Admin Fees For All GV Purchase, 2 Years Warranty For Engine And Gearbox With STA Evaluation Graded, Add-Ons Available,

2.88%P.A Low Interest@Gv Finance.2 Years Warranty. \$4800 Down Monthly From \$988

GV Credit Pte Ltd

Posted: 20-Mar-2019 Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

Toyota Estima 2.4A Aeras G (COE till 07/2028)

\$69,000

\$7,360 /vr

31-Jul-2008

2.362 cc

MPV

Available

CHEMINICAL DE

Moonroof Model. Full Servicing Done, New Battery, Tyres Changed In March, Road Tax Just Renewed, Regular Servicing Done, Loan And Trade In Available, Viewing By Appointment Only.

360 VR Cars

Posted: 19-Mar-2019 Tags: 2008 Toyota Estima, 2008 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

Tags: 2007 Toyota Estima, 2007 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used

10-Mar-2007

138,291 km

MPV

Available

Toyota Estima 2.4A Aeras Premium Moonroof (COE till 03/2027)

Toyota Estima 2.4A Aeras

\$62,800

\$55,800

\$7,870 /yr

2.362 cc

Evaluated By Vicom, Free 6 Months Maintenance And 1 Grooming.

Yong Lee Seng Motor

Posted: 18-Mar-2019

\$11,570 /yr

14-Jan-2009

2,362 cc

MPV

Available

PREMIUM AD

(COE till 01/2024) 2.88% P.A Lowest Interest At \$988 Monthly For Toyota Estima, \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox With STA Evaluation Graded. Add-Ons Available.

GV Credit Pte Ltd

Posted: 18-Mar-2019

Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used

Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable, We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Estima 2.4A X Moonroof (COE till 11/2028) \$66,800

\$6,910 /yr

17-Nov-2008

2.362 cc

MPV

Available

Selling A Very Well Maintained 8 Seaters MPV, Regularly Serviced, No Repairs Needed. Consignment Vehicle. Great For Family With Kids. Please Call To Schedule For Viewing. High Trade In Welcome, In Hou...

Tags: 2008 Toyota Estima, 2008 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Posted: 18-Mar-2019

Toyota Estima 2.4A Aeras Premium Moonroof (COE till 11/2027)

\$64,800

\$7,440 /yr

14-Dec-2007

2,362 cc

MPV

Available

PREMIUM AD

2 Owner, Low Mileage, 7 Seaters Mpv, Nice Paint Work And Brand New Leather Seats, Excellent Condition, Power Sliding Door, Keyless Entry/Start eather Seat, Sport Rim, Reverse Camera, Rear Air C... isted: 17-Mar-2019 Tags: 2007 Toyota Estima, 2007 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used

Used Toyota Estima Car & Used Cars & Vehicles Singapore - sgCarMart



All Our Quality Consignment! Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA/VICOM Inspection Welcome! Low Mileage Done At Only 9k Km P.A, Smooth And Powerful Engine. Most Of T...

CarOuotz Singapore

Posted: 16-Mar-2019 Tags: 2004 Toyota Estima, 2004 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota



Toyota Estima 2.4A X (New 10-yr COE)

\$72,800

\$7,270 /vr 24-Nov-2008 2.362 cc

2.362 cc

92,000 km

Available

Get Full Loan, New Paintwork. Full Reconditioned Engine, Transmission And Aircon. Worn Parts Replaced And Repaired. We Provide In House Loans And Other Financial Services To Meet Your Budget, Call Us O ...

Posted: 15-Mar-2019 Tags: 2008 Toyota Estima, 2008 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used



Toyota Estima Hybrid 2.4A G (COE till 04/2028)

\$69,888

\$7,700 /yr

15-Apr-2008

166,000 km

MPV

Available

DIRECT OWNER

Fuel Type: Petrol-Electric

Highest G-Specs 7-seater Estima, Recently Changed New Hybrid Battery, New Touch Screen DVD Player With Bluetooth Pairing With Phone, New Rear Axle, Water Pump, Piping, New Power Steering Assembly, Bra...

Tags: 2008 Toyota Estima, 2008 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Posted: 14-Mar-2019



Toyota Estima 2.4A (COE till

\$27,800

\$10.850 /vr

11-Oct-2006

2.362 cc

MPV

Available

10/2021)

1 Owner! AA Trust Certified Quality Vehicle! Well Maintained By 1 Single Owner Only! Exquisite Silver Exterior Matched With Beige Leather Interior! One Of The Most Comfortable Family MPVs In The Marke...

Tags: 2006 Toyota Estima, 2006 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

AA Trust Automotive

Posted: 14-Mar-2019

\$75,800

\$7,610 /yr

05-Mar-2009

2.362 cc

Available

Toyota Estima 2.4A Aeras (COE till 03/2029)

134,200 km

Fully Face-lifted, New Diamond Design Leather Seats, Extremely Well Maintained, Almost Like New, New Road Tax Till 09/19, Various Loan Packages To Choose From, Please Drop By For Viewing/Test Drive.

SEEMIUM OF

Posted: 13-Mar-2019

Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

For old advertisements, view Expired ads

« Back (1 2 3 4) Next »

20 ▼ results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Estima, Toyota Estima Singapore, used Toyota Estima, used vehicles Singapore or even buy used Toyota Estima Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results,

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies,
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	12/03/2019 17:29
Date Of Accident	11/03/2019 15:00
Exact Location Of Accident	CTE (BEFORE PIE CHANGI EXIT)
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKH9551U
Insured/Policyholder	
Name Of Registered Owner	OMEGA RENTALS PTE LTD
Co Reg No	201603967W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98780679
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ESTIMA HYBRID
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5099801489-01
Cover Note Number	
Driver	

MOHAMAD NAUFAL BIN MOHD YACOB Name of Driver

NRIC No S7908501D Date Of Birth 06/04/1979 Occupation OUTDOOR Date Of Driving Pass 22/12/2005

Driving Experience 13 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98780679

Fax Number Contact Number

EMail Address MOHDNAUFAL79@GMAIL.COM

BLK 526 BEDOK NORTH STREET 3 Address

#02-454

460526

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

4

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TECK GHEE NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 321 ANG MO KIO STREET 31, POSTCODE: 560321,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-4599999 - FAX NO: 64574478

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBC8700X

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

RAJA MOHAN S/O KIRUBEINATHAN

NRIC/Passport Number

S7345763G

Contact Number

85155162

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJR6419Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHEN YIRU ALOYSIUS

NRIC/Passport Number

S8539462B

Contact Number

88089408

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GBC8499C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

LEE KOK HING

NRIC/Passport Number

G7174354W

Contact Number

97687771

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMAD NAUFAL BIN MOHD YACOB

Approximate Age

Injuries Sustain

REFER REPORT

Injured person in which vehicle?

SKH9551U

Were seat belts worn?

YES

Was this injured conveyed to hospital by

NO

ambulance?

Address Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the dains process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrapresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Reciseds Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, admowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - [iii] carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as will as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, [collectively the "Purposes"]
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/(including their lawyers/law limms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be chared / disclosed:

QENT.

28183482

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Omega Rentals PTE LTD Registration No:201803967W

Policyhelder's Signature

Date & Time:

Oriver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Contre Personnel's Signature

Name:

NRSC/FIN No.:

Sketch Plan #2

SKETCH PLAN TOWAR BEADEL PLE CHANG

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was ariving along CTE towards DIE CHANGI
exit Bony (5) R 64192) sloved down as there are
a few cars sloved down in front of me , Two levies
behind my are hit each other and (GBC8700X)
hit my some I am somewall a but to the and and
scratch the car (SIR 64192) in front of me 1
customed a neck point due to this recident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Omega Rentals PTE LTD

Registration No:261803947W Policyholder's Signatule

notes to a kill of according

Date & Time:

Driver's Signature

(if driver is not the policyholder) Date & Time.

Reporting Centre Personnel's Signature

NRIC/FIN No.:

Common Statement



Police Station Of Origin: Teck Ghee NPP 321 Ang Mo Kio Street 31 SINGAPORE 560321 Tel No: 1800-4599999

Report No. 1720190311/2188

REPORT OF A TRAFFIC ACCIDENT

Station Diary No. Vide Report No.: Date/Time Report Made: 63 11/03/2019 18:58 APT BLK 526 BEDOK NORTH STREET 3 #02-454 SINGAPORE 460526 Name of Informant: MOHAMAD NAUFAL BIN MOHD YACOB ID Type / ID No.: Contact No.: Mobile: 98780679 Home/Office NRIC NO / S7908501D Email: Nationality: SINGAPORE CITIZEN Type of Informant: Date of Birth: Age: 39 Sex 06/04/1979 Driver Institution / School Name: Male Language: Race: Javanese **Driving Licence Information:** Occupation: Date of Expiry: FINANCIAL CONSULTANT Class:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time Accident: 11/03/201	Straight Road
Location: Along Road 1 CENTRAL EX Towards PIE Weather	(PRESSWAY	Road Surface		Road Speed Limit:
Clear Traffic Flow:		Traffic Control Not Controlled		Traffic Volume; Moderate
One Way Type of Collis Between Mov	ion: ing Vehicles - Head	d To Rear		Anyone conveyed by ambulance: No

Details of V	chicie Invo	No.Ch	57.5500	Color	Condition	No of Pastern
GBC84990	Lorry				Slightly	0
GBC8700X					Slightly	建筑设施
SJR6419Z	100000000000000000000000000000000000000				Slightly	0
SKH9551U	No. of Lot of Lo				Seriously Damage	0

Common Statement



Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321

Tel No: 1800-4599999



CONTINUATION OF REPORT

ved: No jured: NIL EE KOK HING		的 情况	G7174354W	
for the state of t			A Land Control of the Control	
nandana (Lamu)	1	Contact No.	97687771	
ВС8499С (Lorry)		Class of	Class NIL	
NIL		Driving Licence &	Date of Expiry: NIL	
Maria Company	Control of the Contro	arge NIL	国际公司	
Medical Leave NIL	Degree of	njury NIL	Established State of the State	
Wedical Course			S7345763G	
AJA MOHAN S/O KIRUBEINAT	HAN	ID No.	575457000	
	A STATE OF THE REAL PROPERTY.	Contact No	85155162	
BC8700X (Lorry)	4 1	Contact		
		Class of	Class: NIL	
		Driving	Date of Expiry: NIL	
IL CONTRACTOR OF THE PARTY OF T	Date Disc	AL LINE AND ADDRESS OF THE PARTY OF THE PART		
Medical Leave NIL	Degree o			
HEN YIRU ALOYSIUS		ID No.	S8539462B	
JR6419Z (Car)		Contact N	Vo. 88089408	
		Class of	Class NIL	
		Driving	Date of Expiry: NIL	
		Licence		
			ate	
W AND SOLD SOLD SOLD SOLD SOLD SOLD SOLD SOL	Date Di	scharge N	HEREN AND A CONTRACTOR	
Medical Leave NIL	Degrae	of Injury h	ML I STATE OF THE	
	Medical Leave NIL AJA MOHAN S/O KIRUBEINAT BC8700X (Lorry) IL Medical Leave NIL HEN YIRU ALOYSIUS JR6419Z (Car)	Medical Leave NIL Degree of I AJA MOHAN S/O KIRUBEINATHAN BC8700X (Lorry) IL Medical Leave NIL Degree of I HEN YIRU ALOYSIUS JR6419Z (Car) IIL Date Discontinuous Degree of I Date Discontinuous Degree Degre	Licence & Expiry Date Date Discharge NIL Medical Leave NIL Degree of Injury NIL AJA MOHAN S/O KIRUBEINATHAN ID No. BC8700X (Lorry) Contact No IL Date Discharge NIL Medical Leave NIL Degree of Injury NIL HEN YIRU ALOYSIUS ID No. UR6419Z (Car) Contact No Class of Driving Licence Expiry Date Licence Expiry Date Date Discharge NIL Class of Driving Licence Expiry Date Date Discharge NIL Date Discharge NIL Degree NIL Class of Driving Licence Expiry Date NIL Class of Driving Licence Expiry Date NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Discharge NIL Date Dis	



police Station Of Origin: Teck Ghee NPP 321 Ang Mo Kio Street 31 SINGAPORE 560321 Tel No: 1800-4599999



3 of 4 Report No. 122019031122188

CONTINUATION OF REPORT

COD IDE	
COB ID No.	879085010
Conta	a No. 98780679
Class Drivin Licen	Date of Expiry: NIL ce &
	Class

Brief Details.

On 11/03/2019 at about 1455hrs, I was driving vehicle bearing SKH9551U along CTE towards PIE(Changi) on lane 4. My vehicle had came to a stopped as there was a traffic jam. When I was about to move off, the lorry bearing GBC8700X had rammed onto my vehicle from the rear as such my vehicle flung forward however I managed to swerve my vehicle away from the vehicle bearing SJR6419Z however there was scratches on the left side of his rear bumper who was in front of me due to the accident.

After the accident, all of the drivers came down from our vehicles and we exchanged particulars and the driver of the lorry bearing GBC8700X informed that the lorry behind him bearing GBC8499C rammed onto him as such his vehicle rammed onto mine. Subsequently left the accident scene.

Shortly after, I proceeded to seek medical attention and I was given 5 days of MC from the doctor.

Common Statement



Police Station Of Origin; Teck Ghee NPP 321 Ang Mo Kio Street 31 SINGAPORE 560321 Tel No. 1800-4599999



Report No. 100190011/2186

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report.

Sgt 1 YEE JIA WEI JONATHAN

Signature Of Interpreter: Not applicable

Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436

Authentication Stamp

Signature Of Informant.

Date/Time:

11/03/2019 18:58

Classification Of Case:

SN 085

Beer Land Brown

Singapore Police Force

V8 MOTOR WERKZ PRIVATE LIMITED

9 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644

TEL NO: 91442977

EMAIL: V8MOTORWERKZ@GMAIL.COM

ROC NO.: 201622378N

DATE:10/05/19

MAKE / MODEL: TOYOTA ESTIMA 2.4 **VEHICLE PLATE NUM: SKH9551C**

ESTIMATED COST:

Not Northerial LI Sup & 12, 700h Resurry Afer Pary 18deys

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before after spray painting
To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Description	QTY	Amount
1	FRONT BUMPER 1710.00 A	P 1PCS	\$1830.00 (
2	FRONT BUMPER TOW EYE COVER	2PCS	\$82.00
3	FRONT BUMPER SIDE BRACKET	, , 2PCS	\$110.00
4	FRONT HEADLAMP Mgcm/	an 1PCS	\$1480.00
5	FRONT BUMPER REINFORCEMENT	7 1PCS	\$308.00 ×
6	FRONT REINFORCEMENT BUMPER	1PCS	\$110.00 🔨
7	REAR BUMPER SUPPORT BRACKET	1 2PCS	\$110.00 X
8	REAR BUMPER 1380.	By 1PCS	\$1650.00
9	REAR LOWER BUMPER COVER	1PCS	\$45.00
10	REAR BUMPER TOW EYE COVER	1PCS	\$25.00
11	REAR BUMPER REFLECTOR	n ZPCS	\$70.00
12	REAR BUMPER ASBORBER @161-10 322201	2PCS	\$420.00 (
13	REAR BOOT DAMPER	Puz 2PCS	\$780.00
14	REAR BOOT HINGE	7 2PCS	\$120.00
15	REAR BOOT STOPPER	R 2PCS	\$88 X
16	REAR BOOT LOCK ASSY	Ju 1PCS	\$320.00
17	REAR BOOT LOCK ASSY COVER	Nu 1PCS	\$34.00
18	REAR BOOT STRIKER ASSY	DIT 1PCS	\$40.00

REAR BOOT WEATHERSTRIP / SEAL REAR BOOT GANISH SUB-ASSY REAR WINDOW GANISH LEFT AND RIGHT REAR BOOT GANISH DOOR OUTER REAR WINDOW GANISH CENTRE REAR WINDOW GANISH CENTRE REAR BOOT GANISH BOARD ASSY INTER REAR BOOT GANISH BOARD ASSY INTER REAR BOOT (DOOR) REAR BOOT (DOOR) REAR END PANEL REAR END PANEL REAR END SIDE PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER GLASS REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR REAR COOLING COIL THERMOSTAT SET \$530.00 REAR COOLING COIL THERMOSTAT SET \$520.00 REAR COOLING COIL THERMOSTAT SET \$520.00 REAR COOLING COIL THERMOSTA			(43)	
REAR BOOT GANISH SOFT STATE ST		REAR BOOT WEATHERSTRIP / SEAL Pall	1PCS	\$290.00 John
REAR WINDOW GANISH CETT AND ROTTER REAR BOOT GANISH DOOR OUTER REAR WINDOW GANISH CENTRE REAR BOOT GANISH BOARD ASSY INTER REAR GLASS / MOUDLING REAR BOOT (DOOR) REAR BOOT (DOOR) REAR END PANEL REAR END SIDE PANEL ASSY REAR PANEL QUARTER PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER GLASS REAR QUARTER GLASS REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL COVERING REAR COOLING COIL TEMPERATURE SENSOR PICS \$260.00 \$198		REAR BOOT GANISH SUB-ASSY	1PCS	\$218.00
REAR BOOT GANISH DOOR COTER REAR WINDOW GANISH CENTRE REAR BOOT GANISH BOARD ASSY INTER REAR GLASS / MOUDLING REAR BOOT (DOOR) REAR BOOT (DOOR) REAR END PANEL REAR END PANEL REAR END SIDE PANEL ASSY REAR PANEL QUARTER PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER INNER REAR QUARTER GLASS REAR QUARTER GLASS REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL COVERING REAR COOLING COIL TEMPERATURE SENSOR		REAR WINDOW GANISH LEFT AND RIGHT	, 2PCS	\$323.00
REAR WINDOW GAMEST CERTIFIED REAR BOOT GANISH BOARD ASSY INTER REAR GLASS / MOUDLING REAR BOOT (DOOR) REAR BOOT (DOOR) REAR END PANEL REAR END PANEL REAR END SIDE PANEL ASSY REAR PANEL QUARTER PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER INNER REAR QUARTER GLASS REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR PCS \$348.00 1PCS \$348.00 REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 REAR COOLING COIL TEMPERATURE SENSOR		REAR BOOT GANISH DOOR OUTER	1PCS	\$260.00
REAR BOOT GANISH BOARD ASSY INTER REAR GLASS / MOUDLING REAR BOOT (DOOR) REAR BOOT (DOOR) REAR END PANEL REAR END PANEL REAR END SIDE PANEL ASSY REAR PANEL QUARTER PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER INNER REAR QUARTER GLASS REAR QUARTER GLASS REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR 1PCS \$348.00 ALCO COLUMN AND COLUMN A		REAR WINDOW GANISH CENTRE	1PCS	\$198.00
REAR GLASS / MOUDLING REAR BOOT (DOOR) REAR BOOT (DOOR) REAR END PANEL REAR END PANEL REAR END SIDE PANEL ASSY REAR PANEL QUARTER PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER INNER REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL COVERING REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 A 19CS \$130.00 REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 A 19CS \$130.00 REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 A 19CS \$130.00		TO THE PROPERTY OF THE PROPERT	1PCS	\$735.00
REAR BOOT (BOOK) 7667-760 34 1PCS \$667 REAR END PANEL ASSY By 1PCS \$554.00 REAR PANEL QUARTER PANEL ASSY By RH \$1235.00 REAR PANEL QUARTER OUTER UPPER RH \$670.00 X REAR PANEL QUARTER INNER RH \$320.00 X REAR QUARTER GLASS MAY M RH \$450.00 REAR COOLING COIL 1PCS \$280.00 REAR COOLING COIL COVERING 1SET \$580.00 REAR BLOWER MOTOR 1PCS \$348.00 REAR COOLING COIL TEMPERATURE SENSOR 1PCS \$130.00 X				\$1680.00
REAR END PANEL REAR END SIDE PANEL ASSY REAR PANEL QUARTER PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER INNER REAR QUARTER GLASS REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR PCS \$554.00 \$5554.00 RH \$1235.00 RH \$670.00 RH \$320.00 RH \$450.00 PCS \$280.00 REAR SEAR HEATER COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR PCS \$348.00 REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 REAR SEAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 REAR SEAR COOLING COIL TEMPERATURE SENSOR		REAR BOOT (DOOR) 1669.70 By	1PCS	\$2670.00
REAR PANEL QUARTER PANEL ASSY REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER INNER REAR QUARTER GLASS RH \$450.00 REAR COOLING COIL REAR HEATER COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR REAR \$1235.00 RH \$1235.00 RH \$450.00 RH \$450.00 REAR \$450.00 REAR \$280.00 REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR PCS \$130.00 \$100.00			7 1PCS	\$667
REAR PANEL QUARTER OUTER UPPER REAR PANEL QUARTER INNER REAR QUARTER GLASS REAR COOLING COIL REAR HEATER COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR REAR STORM SERVICE STANDARD SERVICE STANDARD SERVICE STANDARD SERVICE STANDARD SERVICE SENSOR REAR COOLING COIL TEMPERATURE SENSOR REAR STANDARD SERVICE SENSOR REAR STANDARD SERVICE SENSOR REAR PANEL QUARTER OUTER UPPER RH \$450.00 RH \$450.00 REAR STANDARD SERVICE SENSOR RH \$450.00 REAR STANDARD SERVICE SENSOR REAR COOLING COIL TEMPERATURE SENSOR REAR COOLING COIL TEMPERATURE SENSOR REAR STANDARD SERVICE SENSOR REAR STANDARD SERVICE SENSOR REAR COOLING COIL TEMPERATURE SENSOR REAR COOLING COIL TEMPERATURE SENSOR REAR STANDARD SERVICE SENSOR RH \$450.00 REAR STANDARD SERVIC		REAR END SIDE PANEL ASSY	2 _f 1PCS	\$554.00
REAR PANEL QUARTER INNER REAR QUARTER GLASS REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR REAR COOLING COIL TEMPERATURE SENSOR REAR SIZO.00 REAR \$320.00 RH \$320.00 RH \$320.00 RH \$450.00 RH \$450.00 RH \$450.00 RH \$450.00 RH \$450.00 RH \$450.00 REAR COOLING COIL COVERING REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR REAR COOLING COIL TEMPERATURE SENSOR REAR COOLING COIL TEMPERATURE SENSOR		REAR PANEL QUARTER PANEL ASSY	RH	\$1235.00
REAR QUARTER GLASS REAR COOLING COIL REAR HEATER COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR REAR STATE SENSOR REAR \$450.00 \$280.00 \$240.00 \$240.00 \$240.00 \$240.00 \$348.00		REAR PANEL QUARTER OUTER UPPER	n RH	\$670.00
REAR COOLING COIL REAR HEATER COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR REAR COOLING COIL TEMPERATURE SENSOR 1PCS \$280.00 \$280.00		REAR PANEL QUARTER INNER	n RH	\$320.00
REAR COOLING COIL REAR HEATER COIL REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR 1PCS \$280.00 \$240.00 \$240.00 \$348.00 PCS \$348.00 \$190.00		REAR QUARTER GLASS Mey No.	RH	\$450.00
REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR 1SET \$580.00 1PCS \$348.00 1PCS \$130.00		REAR COOLING COIL	1PCS	\$280.00
REAR COOLING COIL COVERING REAR BLOWER MOTOR REAR COOLING COIL TEMPERATURE SENSOR 1SET \$580.00 1PCS \$348.00 1PCS \$130.00		REAR HEATER COIL 7 ACL	M 1PCS	\$240.00
REAR COOLING COIL TEMPERATURE SENSOR 1PCS \$130.00 X			1SET	\$580.00
REAR COOLING COLE TERM ENVIOLED SERVICE TO THE TERM ENVIOLENCE		REAR BLOWER MOTOR	1PCS	\$348.00
1000		REAR COOLING COIL TEMPERATURE SENSOR	1PCS	\$130.00
				\$180.00
VACUUM AND AIR COND GAS JOB \$60.00		VACUUM AND AIR COND GAS	1JOB	\$60.00
REAR BOOT FENDER TAIL LAMP GIS OISCHA 2FCS \$1230.00 L		REAR BOOT FENDER TAIL LAMP	ns 2PCS	\$1230.00
REAR BOOR TAIL LAMP CP4 2PCS \$1100.00			2 2PCS	\$1100.00
REAR CAR PLATE LAMP ASSY 256 2PCS \$70.00 X		REAR CAR PLATE LAMP ASSY 258	2PCS	\$70.00 🗶
TO DISMANTLE/REPLACE/REFIT/WELD/FRONT BUMPER ,REAR 1 \$1800.00	TO DIS		1	\$1800.00 600
PANEL LINER ,HEADLAMP , UNDER CARRIAGE,ETC.				
TO PUTTY AND SPRAY PAINT ON FRONT BUMPER, REAR BUMPER, 1 \$1200.00		Y AND SPRAY PAINT ON FRONT BUMPER, REAR BUMPER,	1	\$1200.00 //0
BOOT, RIGHT SIDE PANEL INNER / OUTER		BOOT, RIGHT SIDE PANEL INNER / OUTER		

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed	Status	
	12 Mar 2019		19 Mar 2019 10:44 Edit Adj Rpt	5\$12,700.00		Report Cancel	for Survey			
-	Main	R	eference		laim Det	ails		Document	s	Show All
CLAIM SU	BFOLDER DE	TAILS					[Created	by insurer]		
Insured:	CLP INTE	RNATIONAL PT	LTD, Co. Reg. No	.: 2001072	94D					
Main Claimant:	OMEGA R	ENTALS PTE LT), Co. Reg. No.: 2	01603967W						
Vehicle Reg No.:	SKH9551U Date of Loss: 11/03/2019 15:00 - :59 [124 Months and 18 Days From LTA Reg Date (Mai					Date (Man Yr)]				
Claim Type:	TP / CM	TD1901318			Policy/Co		D18MTPCV	E000177 (Compre	ehensive)	
Vehicle Reg No. (Insured):	GBC8700	x			Policy No (Claima)					
					Excess:					
Repairer:	Messrs V	8 Motor Werkz F	Pte Ltd (HQ) Blk 9,	#01-44 Sin	Ming Ind	ustrial	Est Sector	C, 575630 Sin Mi	ng - Tel:	
Handling Insurer:	15-7-1 477-1		ore Pte. Ltd. (HQ)							(02 (20 10)
Adjuster:	LKK Auto	Consultants Pto	e Ltd (HQ) - Tel: 62	56-3561	. [Handled	by K	ENNETH KO	ONG] [Final	Rpt due 28	/03/2019]
Driver/Cust dian (Insured):	RAJA MOH	IAN S/O KIRUBEI	NATHAN () , NRIC:	S7345763	G, Tel:	+6585	5155162 Em	ail:		
Adj Asg. Remarks:	PIC: Ah Q	iang – HP 8818 10	566							
ASSOCIAT	ED MAIL RE	CEIVED						Vi	ew All Co	mpose Case Mail
• SOMPO_	SG (21/10/20	19): UPLOAD SU	JRVEY REPORT							
ALL ASSO	CIATED TAS	sks⊟					View All	Search Tasks	Create New Ta	sk Complete
Due Date	e Priority	Type Tas	k Group Subje	ct Hand	iler #	\ssign	ned By	Completed On	Create	d On Done

Claim Documents

*SKH9551U (CMTD1901318) [GBC8700X] TP OMEGA RENTALS PTE LTD

Mar 11 2019 3:00PM [CLP INTERNATIONAL PTE LTD] Messrs V8 Motor Werkz Pte Ltd

Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Prin
1	19/03/19 10:43	Accident Statement From:SC - Reg. No: GBC8700X, Claimant: CLP INTERNATIONAL PTE LTD	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	01/10/19 15:53	Adjuster Immediate Advice	0	Load HTM	
			2	page V	
	tos/Images	LIVE A TO CONTRACT THE LATE (NO.)	3 per	Thumbnail	-
No 1	01/10/19 15:38	LKK Auto Consultants Pte Ltd (HQ) General View	0	Load JPG	V
2	01/10/19 15:38	General View	0	Load JPG	V
3	01/10/19 15:38	General View	0	Load JPG	V
4	01/10/19 15:38	General View	0	Load JPG	V
		General View	0	Load JPG	V
5	01/10/19 15:38	popular and analysis for p	0	Load JPG	V
6	01/10/19 15:38	General View	0	Load JPG	<u>Z</u>
7	01/10/19 15:38	General View	0	10 00000	<u>N</u>
8	01/10/19 15:38	General View		Load JPG	_
9	01/10/19 15:38	General View	0	Load JPG	
10	01/10/19 15:38	General View	0	Load JPG	2
11	01/10/19 15:38	General View	0	Load JPG	V
12	01/10/19 15:38	General View	0	Load JPG	V
13	01/10/19 15:38	General View	0	Load JPG	V
14	01/10/19 15:38	General View	0	Load JPG	V
15	01/10/19 15:38	General View	0	Load JPG	V
16	01/10/19 15:38	General View	0	Load JPG	V
17	01/10/19 15:38	General View	0	Load JPG	V
18	01/10/19 15:38	General View	0	Load JPG	V
19	01/10/19 15:38	General View	0	Load JPG	V
20	01/10/19 15:38	General View	0	Load JPG	V
21	01/10/19 15:38	General View	0	Load JPG	V
22	01/10/19 15:38	General View	6	Load JPG	$\overline{\mathbf{v}}$
23	01/10/19 15:38	General View	0	Load JPG	V
24	01/10/19 15:38	General View	0	Load JPG	V
25	01/10/19 15:38	General View	0	Load JPG	V
26	01/10/19 15:38	General View	0	Load JPG	V
27	01/10/19 15:38	General View	0	Load JPG	V
28	01/10/19 15:38	General View	0	Load JPG	V
29	01/10/19 15:38	General View	0	Load JPG	V
30	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
31	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
32	01/10/19 15:44	Reinspection Photo	0	Load JPG	<u>V</u>
33	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
34	01/10/19 15:44		0	Load JPG	2
		Reinspection Photo	0	Load JPG	2
35	01/10/19 15:44	Reinspection Photo			_
36	01/10/19 15:44	Reinspection Photo	0	Load JPG	Z

SSP	ssment Reports		1 per		☑
-	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Load JPG	
	01/10/19 15:44	Reinspection Photo	0	_	☑
39	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
3570	01/10/19 15:44	Reinspection Photo	0	Load JPG	Ø
11	01/10/19 15:44	Reinspection Photo	0	Load JPG	Ø
12	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
43	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
44	01/10/19 15:44	Reinspection Photo	0	Load JPG	
45	01/10/19 15:44	Reinspection Photo	0	Load JPG	\square
46	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
47	01/10/19 15:44	Reinspection Photo	0	Load JPG	$\overline{\mathbf{A}}$
48	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
49	01/10/19 15:44	Reinspection Photo	6	Load JPG	V
50	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
51	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
52	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
53	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
	01/10/19 15:44	Reinspection Photo	0	Load JPG	\mathbf{V}
55	01/10/19 15:44	Reinspection Photo	6	Load JPG	\mathbf{Z}
-		Reinspection Photo	0	Load JPG	$\overline{\mathbf{v}}$
56	01/10/19 15:44	Reinspection Photo	0	Load JPG	\mathbf{Z}
57	01/10/19 15:44	Reinspection Photo	0	Load JPG	☑
58	01/10/19 15:44	Reinspection Photo	0	Load JPG	V
59	01/10/19 15:44	Reinspection Photo	6	Load JPG	
60	01/10/19 15:44		6	Load JPG	V
61	01/10/19 15:44	Reinspection Photo	6	Load JPG	V
62	01/10/19 15:44	Reinspection Photo			
Dog	umentation		1 pe	r page 🔍	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnai	
1	18/03/19 14:27	Third Party E-filed GIA report(2ND)	€		
2	19/03/19 10:43	Pre-Repair Survey - AGREED LKK	€	Load PDF	
3	08/10/19 11:09	PD LOD W ENCLS DT 04.10.19 FR VISION LAW - SKH9551U PD LOD W ENCLS DT 04.10.19 FR VISION LAW - SKH9551U	€	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19004936/KTD3E2

Date:

22/10/2019

REFERENCE

Handling Insurer: Ltd.

Sompo Insurance Singapore Pte.

Policy No:

D18MTPCVE000177

Claimant

SKH9551U Vehicle No:

Insured Vehicle No:

GBC8700X

Date of Loss:

11/03/2019

Nature of Claim:

TP

Claim No:

CMTD1901318

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKH9551U

Make & Model:

TOYOTA ESTIMA, 2.4 E X Hybrid (A) 21/10/2008 (Man. Year: 2008)

Engine No: Chassis No: 2AZH229638

Reg. Date: Colour:

Metallic Black

Odometer:

AHR207025333 272466 km

Engine Capacity:

2362 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Front Tyre Size: Front Left Side:

225/50Z R17

Rear Tyre Size:

225/50Z R17

Front Right Side:

Nexen 6 mm

Rear Left Side: Rear Right Side:

No

Nexen 6 mm Nexen 6 mm

Nexen 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIM	S	Repairer's	Adjuster's	Difference	Diff %
Parts		22,050.00	13,188.17	8,861.83	40.19
Miscellaneous Item	ns	0.00	0.00	0.00	
Labour		3,060.00	2,760.00	300.00	9.80
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	25,110.00	15,948.17	9,161.83	36.49
	Approved Total (Overridden) (S\$)		12,700.00		
	Nett Amount (S\$)	25,110.00	12,700.00	12,410.00	49.42

INSPECTION

Date of Assignment:

19/03/2019

Date Inspected:

19/03/2019 Inspected At:

Messrs V8 Motor Werkz Pte Ltd (HQ)

Blk 9, #01-44 Sin Ming Industrial Est

Sector C

Singapore 575630

Estimated Period of Repair:

18.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2019)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 E X Hybrid (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:		, no print-code for SKH9551U)
		tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No	. Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,830.00 F	*1,710.00 FL
2	2		*FRONT BUMPER TOW EYE COVER	Dented	82.00 F	*82.00 FL
3	1		*FRONT BUMPER SIDE BRACKET	O/S Distorted	110.00 F	*55.00 FL
4	1		*FRONT HEADLAMP	Mtg Cracked / Cut	1,480.00 F	*1,480.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	308.00 F	*- FL
3	1		*FRONT REINFORCEMENT BUMPER	Repair	110.00 F	*- FL
7	2		*REAR BUMPER SUPPORT BRACKET	Repair	110.00 F	*-FL
8	1		*REAR BUMPER	Bent	1,650.00 F	*1,380.00 FL
9	1		*REAR LOWER BUMPER COVER	Serviceable	45.00 F	*- FL
10	1		*REAR BUMPER TOW EYE COVER	Serviceable	25.00 F	*- FL
11	1		*REAR BUMPER REFLECTOR	O/S Cracked	70.00 F	*35.00 FL
12	2		*REAR BUMPER ABSORBER	Cracked	420.00 F	*322.20 FL
13	2		*REAR BOOT DAMPER	Punctured	780.00 F	*780.00 FL
14	2		*REAR BOOT HINGE	Repair	120.00 F	*- FL
15	2		*REAR BOOT STOPPER	Repair	88.00 F	*-FL
16	1		*REAR BOOT LOCK ASSY	Jammed	320.00 F	*320.00 FL
17	1		*REAR BOOT LOCK ASSY COVER	Dented	34.00 F	*34.00 FL
18	1		*REAR BOOT STRIKER ASSY	Distorted	40.00 F	*40.00 FL
19	1		*REAR BOOT WEATHERSTRIP / SEAL (50%)	Dented / Cut	290.00 FS	*145.00 FS
20	1		*REAR BOOT GARNISH SUB-ASSY	Buckled	218.00 F	*218.00 FL
21	2		*REAR WINDOW GARNISH LEFT AND RIGHT	Distorted	323.00 F	*323.00 FL
22	1		*REAR BOOT GARNISH DOOR OUTER	Cracked	260.00 F	*260.00 FL
23	1		*REAR BOOT GARNISH BOARD ASSY INTER	Buckled	735.00 F	*735.00 FL
24	1		*SET REAR GLASS / MOULDING	Broken	1,680.00 F	*1,680.00 FL
25	1		*REAR BOOT (DOOR)	Bent	2,670.00 F	*1,669.70 FL
26	1		*REAR END PANEL	Bent	667.00 F	*667.00 FL
27	1		*REAR END SIDE PANEL ASSY	Bent	554.00 F	*554.00 FL
28	1		*REAR PANEL QUARTER PANEL ASSY RH	Buckled	1,235.00 F	*1,235.00 FL
29	1		*REAR PANEL QUARTER OUTER UPPER RH	Repair	670.00 F	*-FL
30	1		*REAR PANEL QUARTER INNER RH	Repair	320.00 F	*-FL
31	1		*REAR QUARTER GLASS RH	Mldg Necessary	450.00 F	*450.00 FL
32	1		*REAR COOLING COIL	Housing cracked	280.00 F	*280.00 FL
33	1		*REAR HEATER COIL	Housing cracked	240.00 F	*240.00 FL
34	1		*SET REAR COOLING COIL COVERING	Housing cracked	580.00 F	*580.00 FL
35	1		*REAR BLOWER ASSY	Housing cracked	348.00 F	*348.00 FL
36	1		*REAR COOLING COIL TEMPERATURE SENSOR	Serviceable	130.00 F	*- FL
37	1		*REAR COOLING COIL THERMOSTAT	Serviceable	180.00 F	*- FL
38	1		*REAR BOOT FENDER TAIL LAMP	O/S Cracked	1,230.00 F	*615.00 FL
39	2		*REAR BOOT TAIL LAMP	Cracked	1,100.00 F	*1,100.00 FL
40	2		*REAR CAR PLATE LAMP ASSY	Serviceable	70.00 F	*- FL
41	1		*REAR WINDOW GARNISH CENTRE	Cracked	198.00 F	*198.00 FL
F=Fr	anchise	part. S=Sp	cNett. L=ListItemDisc.	Sub Total (S\$)	22 252 22	47 525 00

17,535.90 Sub Total (S\$) 22,050.00

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
-			- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	4,347.73
		Total Parts (S\$)	22,050.00	13,188.17	
			Report was unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	VACUUM AND AIR COND GAS	New	60.00	60.00
2	TO DISMANTLE / REPLACE / REFIT / WELD / FRONT BUMPER, REAR PANEL LINER, HEADLAMP, UNDER CARRIAGE, ETC	New	1,800.00	1,600.00
3	TO PUTTY AND SPRAY PAINT ON FRONT BUMPER, REAR BUMPER, BOOT, RIGHT SIDE PANEL INNER / OUTER	New	1,200.00	1,100.00
	Gross Lab	our Cost (S\$)	3,060.00	2,760.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >