



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885592
Estimator Telephone Number : 68862623
Accident Reporting Number : 68862672

Date Generated : 28/03/2019

User ID : CatherineLee

Poh Kin

Finalized-HJ

Section A - Accident Details

Registration Number	SMB104U
Case Reference Number	BUS/03/19/5036
Registration Date	29/7/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Luo Xuanming
Type of Accident	Side Swipe
Accident Date and Time	15/3/2019 3:50 PM
Accident Reported Date and Time	16/3/2019 2:13 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100680
Special Instruction to ARC, if any	SMB104U - LEFT FRONT PORTION SLC3447S (TP) - RIGHT PORTION. INSURED WITH AXA
Prepared Date and Time	19/3/2019 10:54 AM
Chassis Number	WEB63442021000234
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$432.00	\$262.00
Total Spare Part Cost	\$111.82	\$111.82
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,073.82	\$638.82
Lump Sum Total	\$0.00	\$650.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	Hwee Jie
ARC / Surveyor Sign Off Date	19/03/2019 7:08 PM	20/03/2019 11:56 AM
Signature		
Remarks		U/S repair. Photo after paint

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/03/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & REPLACE ABOVE ITEMS AND REPAIR FRONT LH PORTION	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$432.00	\$262.00
Total Spray Painting & Panel Beating	\$432.00	\$262.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009700	VE		LAMP,BUNKER,FRONT, LEFT, FOR MB OC 500 LE	1.00	\$155.30	10.00	\$139.77	Replace	Replace
Total					\$155.30		\$139.77		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									