

INS. CASE OWNER:

CC 61 MG 1900

5016 / Uha39

LNR:  
IDAC:

Surveyor:

MAPPUS

DOI:

ASSIGNMENT

19/3/19

Date / Time:

20/3/19

Registered in Merimen:

20/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLQ 7119P

Name of Insured:

DANIELA NIEL MANGAUNT G1 P12

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Excess Sec II :SS

D.O.A:

9/12/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

688872R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Urbw



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 18/05/19 - UK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

04/06/19

- TP ACCEPTED OFFER.

06/06/19

- ALL DOCS IN ORDER.  
- TO CLOSE

DV.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost: L16

S\$ 1,200.00 (3 days) Reduction: 48 %

Confirm by:

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final liability:

% 50 (Assessed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Loss of Rental (LOR):

S\$ 600.00 ( days)

BOTH TURNING

Loss of Use (LOU):

S\$ 200.00 x 5 days

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 7.15

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

Total:

S\$ 807.15

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 807.15

Name 1:

LUB BROTHER AUTO ENGINEERING WORKSHOP

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBB872190309

**Estimate**

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 18-03-19

Address Motor Claims Department

Vehicle No: GBB872R

78 Shenton Way #07-16

Model/Make: Toyota Hiace

AIG Building

Singapore 079120

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>cut/oe</i>	\$ 599.30	
2	Bumper Clips 1 set <i>new</i>	\$ 48.00	
3	Tail Lamp <i>ols sca</i>	\$ 303.10	
4	Tail Lamp Lower Garnish <i>cut</i>	\$ 165.10	
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Remove and refix rear bumper reverse sensor	\$ 80.00	- 50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	- 300
	To putty & spray painting & including touch up paint on accident affect	\$ 500.00	- 300
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 50.00	- X

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 2,295.50

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*Not Adhocal*  
*new*  
*4/5 = 1200*  
*19/3/19*  
*3 day.*

*7-11/5.5*  
*257*  
*836.62*  
*1506.62*



> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1196N

Vehicle Details

Vehicle No.:	GBBB72R
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1KD1813104
Chassis No.:	JTFHT02P500023009
Maximum Power Output:	-
Open Market Value:	\$24,647.00
Original Registration Date:	21 Jul 2008
First Registration Date:	21 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$1,233.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	20 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$16,100.00
COE Rebate Amount:	\$13,970.00
Total Rebate Amount:	\$13,970.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 18 Mar 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CAR NUMBER PLATES FOR SALE!

Find the unique car number plate that represents you!

Click here to start the hunt!

Toyota Hiace

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Net Link Partners Pte Ltd » Toyota Hiace (COE till 07/2023)

Toyota Hiace (COE till 07/2023)

Overview

Financial

Accessories

Similar

Research

Photos

Map

NETLINK

Your Commercial Specialist

Specialized in New & Used Commercial Vehicles, Insurance, Hire Purchase, Scrap/Export

Price

\$29,800

Lifespan

07-Jul-2028

Depreciation

\$6,930 /yr

Reg Date

08-Jul-2008  
(4yrs 3mths 17days COE left)

Mileage

N.A.

Manufactured

2008

Road Tax

N.A.

Transmission

Manual

Dereg Value

\$13,850 as of today (change)

OMV

\$32,461

COE

\$16,100

ARF

\$1,624

Engine Cap

2,982 cc

No. of Owners

4

Curb Weight

1,760 kg

Type of Vehicle

Van

Features

View specs of the Toyota Hiace

Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Net Link Partners Pte Ltd

• dealer's prelist

• 88 vch sold | 104 vch available

Address

71 Woodlands Industrial Park E9 #07-01, #08-08

Search cars nearby this location

Location

Wave9

Office No

67531661

Contact Person (s)

Teo

Peter

Jeremy

Ken

92967266

84898866

83215291

82227114

Car Valuation - Free

Find out the market value of your existing car for free. Get started

Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 18-Mar-2019 | Last Updated on: 18-Mar-2019

[Compare](#)

## Nivitha (LKK Auto)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Tuesday, 19 March 2019 1:58 PM  
**To:** assignments  
**Subject:** FW: Request for 3rd party claims survey GBB872R Claims against SLQ7119P  
**Attachments:** GBB872R190309.pdf; GBB872R Search.pdf

2.44pm @ 19/3/19  
anon @ Susan  
vehicle  
7P/ATG  
Repair image  
on 20/3/19

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Susan Low <liusbro@ymail.com>  
**Sent:** Monday, 18 March 2019 6:45 PM  
**To:** Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** Request for 3rd party claims survey GBB872R Claims against SLQ7119P

Accident on 09/03/2019 Along Junction Of Selegie Road / Sungei Road  
Involving GBB872R and SLQ7119P

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low  
M/s Liu's Brother Auto Engineering Workshop  
No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit  
Singapore 417883  
Tel: 6741 1730  
Fax: 6744 5746

Date of Survey:- \_\_\_\_\_

Name of Authorise Surveyor:- \_\_\_\_\_

Surveyor Email:

---

Remark :-

---

Our Ref: GBB872R190309

Date: 16/04/2019

Your Ref:

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
AIG Building  
Singapore 079120  
**Attn: Motor Claims Department**

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG** Junction Of Selegie Road / Sungei Road  
**INVOLVING** GBB872R **AND** SLQ7119P **ON** 09/03/2019

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle - GBB872R at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my claims on his recommendation for **S\$ 1,200-00** being the repair for 03 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle SLQ7119P when the same was involved in the aforesaid accident with our/my m/vehicle - GBB872R.

We/I whereby you are the insurers of m/vehicle SLQ7119P and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle - GBB872R has suffered loss and damage as follows:

(a) Cost of repairs	S\$	<u>1,200-00</u>
(b) LOU for pre-repair notice <u>02</u> days @ S\$ <u>80-00</u>		<u>160-00</u>
(c) LOU Fee for <u>03</u> days @S\$ S\$ <u>80-00</u>		<u>240-00</u>
(d) GIA / LTA search fee		<u>7-45</u>
(e)		
<b>Total Amount</b>	<b>S\$</b>	<b><u>1,607-45</u></b>

We/I enclose herewith copies of the supporting documents for vehicle no. GBB872R as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices and documents;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle GBB872R  
Messers Goldbell Leasing Pte Ltd  
cc. Liu's Bro Auto Engrg Ws





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

18 MAY 2019

**DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD  
1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531  
ATTN: THE CLAIMS DEPT**

Dear Sir/Madam,

**OUR REF : CC6/AIG19005016/Uha3**

**YOUR REF : SLQ 7119P**

**ACCIDENT INVOLVING SLQ 7119P AND GBB 872R ALONG SELEGIE ROAD ON  
09.03.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of GBB 872R against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle GBB 872R. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## Authorization To Act

### **Attn: Motor Claims Department**

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
AIG Building  
Singapore 079120

I / We, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GBB872R (vehicle no.) hereby authorize Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. GBB872R that was damaged pursuant to the accident which occurred on 09/03/2019 (date) along Junction Of Selegie Road / Sungei Road (location) involving SLQ7119P ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 24th day of July (month) 20 19 (year)

3<sup>rd</sup> Party Claimant:

Workshop:

Signature: \_\_\_\_\_

Name: Goldbell Leasing Pte Ltd

Address: No. 18 Tuas Avenue 10

Singapore 639142

Nric/ROC No: 199001196N

Signature: \_\_\_\_\_

Name: Liu's Brother Auto Engrg Workshop

Address: 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

ROB No: 53291793J



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **LIU'S BROTHER AUTO ENGINEERING WORKSHOP** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$600.00** (Repair Cost), **S\$200.00** (Loss of Rental/Use), **S\$7.45** (Disbursement), for vehicle no. **GBB 872R** that was damaged pursuant to the accident which occurred on **09/03/2019** (date) along **SELEGIE ROAD** (location) involving vehicle no/s **SLQ 7119P**. This is pursuant to the inspection conducted on **19/03/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GOLDBELL LEASING PTE LTD** ("the third party claimant") of vehicle no. **GBB 872R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **GBB 872R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 24th (day) of July (month) **2019** (year)

  
Signed by appointed surveyor

  
Signed by "the workshop" (with chop)  
Liu's Brother Auto Engineering Workshop  
ROB No. 53291793J  
No.1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit  
Singapore 417883

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBB872R190309

**Final Bill**

<b>Customer</b>		<b>Date:</b>	16-04-19
<b>Name:</b>	AIG Asia Pacific Insurance Pte Ltd	<b>Vehicle No:</b>	GBB872R
<b>Address</b>	Motor Claims Department	<b>Model/Make:</b>	Toyota Hiace
	78 Shenton Way #07-16		Manual
	AIG Building Singapore 079120		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Bumper	\$ 599.30	\$ -
2	Bumper Clips 1 set	\$ 48.00	\$ -
3	Tail Lamp	\$ 303.10	\$ -
4	Tail Lamp Lower Garnish	\$ 165.10	\$ -
	To check all wiring & electrical component for proper function	\$ 50.00	\$ -
	Remove and refix rear bumper reverse sensor	\$ 80.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	\$ -
	To putty & spray painting & including touch up paint on accident affect	\$ 500.00	\$ -
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 50.00	\$ -

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 2,295.50

Total amount in Lump Sum Basis for repaired vehicle

\$1,200.00

SDLS: One Thousand Two Hundred Only



M/s Liu's Brother Auto Engrg Wks

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 18 Mar 2019 / 18:36:46

Receipt Date/Time : 18 Mar 2019 / 18:36:46

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-190318-003822

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLQ7119P				
As at 09 Mar 2019/13:05:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLQ7119P Enquiry Fee 20190318183504458689	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
<b>Total Before Rounding</b>		7.00	0.49	7.49
<b>Rounding Difference</b>				0.04
<b>Total Amount Payable</b>				7.45
Paid By				
	xxxxxxxxxxxx4559	Credit Card: Visa/MasterCard		7.45
<b>Total</b>				7.45
<b>Cash Change</b>				0.00
<b>Tendered Amount</b>				7.45
<b>Excess Refundable Amount</b>				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Mar 2019 <a href="#">Edit Reg</a>		19 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	<b>DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.,</b> Co. Reg. No.: 199803778Z								
Main Claimant:	<b>GOLDBELL LEASING PTE LTD,</b> Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	<b>GBB872R</b>	Date of Loss:	09/03/2019 00:00 - :59 <b>[127 Months and 16 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 3937316370SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLQ7119P</b>	Policy No. (Claimant):	D-18090757MFCV						
		Excess:							
Repairer:	<b>Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)</b> Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tan, Bennie-WZ</b> - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 29/03/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBB872R (3937316370SG)

[SLQ7119P]

TP

GOLDBELL LEASING PTE LTD

Mar 9 2019 12:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1		Edit			
Assessment Reports															1 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>	
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print			
1	21/03/19 13:31		Accident Statement From: SC - Reg. No: SLQ7119P, Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.												1		Load HTM			
Photos/Images															3 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
2	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
3	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
4	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
5	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
6	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
7	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
8	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
9	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
10	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
11	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
12	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
13	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
14	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
15	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
16	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
17	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
18	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
19	20/03/19 16:37		General View												1		Load JPG		<input checked="" type="checkbox"/>	
20	20/03/19 16:37		Odometer Reading												1		Load JPG		<input checked="" type="checkbox"/>	
21	20/03/19 16:38		Chassis Number												1		Load JPG		<input checked="" type="checkbox"/>	
Documentation															1 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	20/03/19 15:06		TP GIA REPORT												1		Load PDF			
2	20/03/19 15:06		LTA Search												1		Load PDF			
3	17/04/19 08:42		TP ESTIMATE_MARKED (FINAL)												1		Load PDF			
4	24/06/19 13:13		LETTER TO OI												1		Load PDF			
5	15/08/19 10:13		WORKSHOP INVOICE												1		Load PDF			
6	15/08/19 10:13		AUTHORISATION TO ACT FORM												1		Load PDF			
7	15/08/19 10:13		Release Voucher												1		Load PDF			
8	15/08/19 10:13		LTA SEARCH												1		Load PDF			



Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ7119P (Insd veh)	Model:	TOYOTA HIACE 3.0 D (M)
	GBB872R (TP veh)		
Date of Accident:	09/03/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	2,295.50	
Final Repair Cost	:	\$	600.00	
Loss of Use	:	\$	200.00	5.00 days at \$80.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	7.45	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	807.45	

**Is Third Party Workshop GIA Registered?**    ☐ YES    ☒ NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_ 50 \_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Liu's Brother Auto Engineering Workshop	: \$	807.45
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

15 Aug  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19005016/UHA3Q2

Date: 15/08/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBB872R

**Insured Vehicle No :** SLQ7119P

Date of Loss: 09/03/2019

Nature of Claim: TP

Claim No: 3937316370SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB872R**

Make &amp; Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD1813104

Reg. Date: 21/07/2008 (Man. Year: 2008)

Chassis No: JTFHT02P500023009

Colour: White

Odometer: 406280 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Austone 6 mm

Rear Left Side:

Austone 6 mm

Front Right Side: Austone 6 mm

Rear Right Side:

Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,115.50	836.62	278.88	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	670.00	510.00	43.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,295.50</b>	<b>1,506.62</b>	<b>788.88</b>	<b>34.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,295.50</b>	<b>1,200.00</b>	<b>1,095.50</b>	<b>47.72</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		400.00		
		<b>1,600.00</b>		
<b>Liabie Amount (50.00%) (S\$)</b>		<b>800.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>807.45</b>		

### INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 19/03/2019 Inspected At:

Liu's Brother Auto Engineering Workshop  
(kaki Bukit) (HQ)

Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @

Kaki Bt Singapore 417883, Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked Deformed	599.30 F	*599.30 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
3	1		*REAR TAIL LAMP O/S	Scratched	303.10 F	*303.10 FL
4	1		*REAR TAIL LAMP LOWER GARNISH	Cut	165.10 F	*165.10 FL

F=Franchise part. L=ListItemDisc

<b>Sub Total (\$\$)</b>	<b>1,115.50</b>	<b>1,115.50</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>278.88</b>
<b>Total Parts (\$\$)</b>	<b>1,115.50</b>	<b>836.62</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	80.00	50.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCs	New	500.00	300.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	500.00	300.00
5	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
Gross Labour Cost (\$\$)			1,180.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >