

Registration No. QX 538M

S/N	ITEM DESCRIPTION	PARTS			MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	
1	MATERIALS				
1.1	FRONT CROSS-MEMBER	1	DENTED	\$ 1,350.00	\$ 1,350.00
1.2	REAR CROSS-MEMBER	1	BENT	\$ 480.00	\$ 480.00
1.3	REAR LH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00
1.4	REAR RH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00
1.5	REAR LH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00
1.6	REAR RH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00
1.7	FUEL TANK	1	DENTED	\$ 650.00	\$ 650.00
1.8	EXHAUST PIPE (CENTRE)	1	DENTED	\$ 680.00	\$ 680.00
1.9	EXHAUST PIPE (REAR)	1	DENTED	\$ 450.00	\$ 450.00
1.10	EXHAUST PIPE GASKET	4	NECESSARY	\$ 25.00	\$ 25.00
	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 4,115.00	\$ 4,115.00
1	SCOPE OF REPAIRS				
1.1	FRONT CROSS-MEMBER :				2
	REMOVE & REPLACE FRONT CROSS MEMBER				
1.2	REAR CROSS-MEMBER & ANTI-ROLL BAR ;				4
	REMOVE & REPLACE REAR CROSS MEMBER				
	REMOVE & REPLACE REAR ANTI-ROLL BAR				
1.3	REAR LOWER ARM, STAB LINK :				1
	REMOVE & REPLACE REAR LH LOWER ARM				
	REMOVE & REPLACE REAR LH STAB LINK				
	REMOVE & REPLACE REAR RH LOWER ARM				
	REMOVE & REPLACE REAR RH STAB LINK				
1.4	FUEL TANK :				2
	REMOVE & RE-FILL FUEL IN FUEL TANK				
	REMOVE & REPLACE FUEL TANK				
1.5	EXHAUST PIPE :				1

	REMOVE & REPLACE EXHAUST PIPE					
1.6	4-WHEEL ALIGNMENT TEST					2
1.7	CLEANING & REMOVE OF RUST FOR THE ENTIRE UNDER CARRIAGE					4
1.8	TO APPLY 'TUFF COATING PAINT' FOR THE ENTIRE UNDER CARRIAGE					2
COSTING		TOTAL PARTS COST			\$4,115.00	
		TOTAL MAN-HOUR				18