



TRANS EUROKARS PTE LTD

JSS

ESTIMATE COST OF REPAIRS



QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWER SINGAPORE 048583 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Habibah Binte Hussain Patail ADDRESS : Blk 159 Pasir Ris Street 13 #02-09 Singapore 510159 TEL : 96170806		WIP : 45400 EXCESS : DATE: 7-Mar-19	
VEH NO :	SKZ5288L	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BM44A8G0320948	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	26-Jan-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER X NAI 1		\$ 1,065.10
2	TAPE PROTECTOR, SENSOR X NAI 2		\$ 16.20
3	GROMMET, REAR BUMPER X NAI 4		\$ 10.00
4	GROMMET, REAR BUMPER X NAI 2		\$ 5.60
5	RIVET, REAR BUMPER X NAI 4		\$ 21.60
6	RIVET, REAR BUMPER X NAI 2		\$ 15.20
7	RIVET, REAR BUMPER X NAI 6		\$ 32.40
8	CLIP, REAR BUMPER X NAI 2		\$ 5.40
9	GASKET LHS, TAILLAMP / NEC 1		\$ 20.90
10	GASKET RHS, TAILLAMP / NEC 1		\$ 20.90
11	ROCKER PANEL RHS X NAI 1		\$ 988.60
12	GUARD STONE RHS X / NEC 1		\$ 17.30
13	REAR WHEEL RIM RHS / CUT 1		\$ 1,101.70
14	REAR BEARING RHS X NAI 1		\$ 414.10
15	REAR KNUCKLE RHS X NAI 1		\$ 653.70
16	REAR UPPER ARM RHS X NAI 1		\$ 181.80
17	REAR LOWER ARM RHS X NAI 1		\$ 250.20
18	REAR LATERAL LINK RHS X NAI 1		\$ 115.30
19	REAR TRAILING ARM RHS X NAI 1		\$ 200.90
TOTAL PARTS			\$ 5,136.90
LESS 10%			\$ 513.69
TOTAL PARTS COST			\$ 4,623.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To replace damaged part(s) during resurvey
- Parts of cars are subject to confirmation

Labour Description

- Third party survey is on a "Without Prejudice" basis
- Sign modification is allowed

TO REPLACE REAR BUMPER AND REAR FENDER RH. TO REPAIR REAR DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.

1

MZ-BR-REAR09

945

\$ 2,970.00

Acknowledged by Repairer

Signature:

Date:

2	MZ-SP-SSIDE4	TO RESPRAY REAR BUMPER, REAR FENDER RH AND REAR DOOR RH		\$ 1,890.00	✓
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	NETT	\$ 330.00	X
4		TO SUPPLY 1 PC TYRE.		\$ 350.00	X
5	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.		\$ 945.00	X
6	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING. 80	NETT	\$ 120.00	
7	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00	✓
8	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 945.00	X
9	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00	X
10	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00	X
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00	
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00	
13	MZ-BR-SUNDRI	SUNDRIES. 20	NETT	\$ 100.00	

STAN CLKKJ
 8322 8813
 VINT 07/11/19 5:30pm
 5 days
 P/P
 Ry before spy

TOTAL LABOUR	\$ -	\$ 9,410.00
TOTAL PARTS	\$ -	\$ 4,623.21
TOTAL	\$ -	\$ 14,033.21
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
 CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
 WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
 PRICE AS WELL AS LABOUR CHARGES.

TRANS EUOKARS PTE LTD

 Authorised Signature