Khanchna (LKK Auto)

From: Khanchna (LKK Auto) Thursday, 23 May 2019 5:06 PM Sent: To: Bennie-WZ.Tan@aig.com Cc: Hsiao Tong (LKKAuto); Admin A Subject: SEEK MANDATE - [AIG Ref: 6618340344SG] ACCIDENT INVOLVING SLZ1533T(OI) AND SLG1684R(TP) ON 17/03/2019 Recipient **Delivery** Tracking: Bennie-WZ.Tan@aig.com Hsiao Tong (LKKAuto) Delivered: 23/5/2019 5:06 PM Admin A Meikwan@lkkauto.com Delivered: 23/5/2019 5:06 PM olivialau@lkkauto.com Delivered: 23/5/2019 5:06 PM Delivered: 23/5/2019 5:06 PM shupei@lkkauto.com AIG Ref: 6618340344SG LKK Ref: CC6/AIG19005094/APA3Q2 Dear Bennie, ACCIDENT INVOLVING SLZ1533T(OI) AND SLG1684R(TP) ON 17/03/2019 We refer to the above matter. This is a head to rear collision. Liability is not in our driver's favour. We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected. We seek your approval to offer to Third Party repairer, "XIN HUA WORKSHOP PTE LTD (HQ)" is as follows: -

Revised Amount

Claimed Amount

1. Cost of Repair	\$ 14,658.00	\$ 8,905.00
2. Loss of Rental (8days x \$120.00) (w/GST)	\$ 1,027.20	\$ 749.00 (7days X \$100) (w/GST)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 15,692.65	\$ 9,661.45

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: <u>Khanchna@lkkauto.com</u>| Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

^{**5}days recommendation for repair + 1Sunday + 1PRS = 7days