


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 13:33

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014139 Date : 20/08/2019 Order : SCZ2800Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SCZ2800Y (V 36074) Regn Date: 28/11/2017 Mileage: 28710 WIP No.: 45297
Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF7J2035930 Engine: DAX 015010 Dept: U
You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-500.00	1.00	-500.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER ASSY,FRONT BUMPER SPOILER AND BOTH FRONT WHEEL ARCH COVERS	1500.00	1.00	1,500.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A80A853651J RP5	(A) (SK)GRILLE 25/3/1 Less 020%	1.00	3258.00	2,606.40
X	A80A853718E GRU	(A) (SK)COVER 25/3/19 Less 020%	1.00	576.50	461.20
X	A80A853717E GRU	(A) (SK)COVER 25/3/19 Less 020%	1.00	576.50	461.20
X	A80A807107A GRU	(SK)COVER LH Less 020%	1.00	1090.00	872.00
X	A80A807108A GRU	(SK)COVER RH Less 020%	1.00	1090.00	872.00
X	A80A807531 TB2	007171/(V) (GER) UNDER Less 020%	1.00	431.00	344.80
X	A80A807061A GRU	FR.SPOILER Less 020%	1.00	685.00	548.00
X	A80A805607	(SK)MOUNTING Less 020%	1.00	107.00	85.60
X	A80A853736 2ZZ	(SK)INSCRIPTION 'QUA Less 020%	1.00	86.60	69.28
X	A80A807679D RU6	(A) (GER)GRILL 25/3/1 Less 020%	1.00	518.50	414.80
X	A80A807661 GRU	(A) (GER)CONN PIECE 2 Less 020%	1.00	184.00	147.20

Parts 6,882.48
Labour 0.00
Sublet 2,712.00
Menus 0.00
Lubricant 0.00

Sub-Total 9,094.48

7% GST 636.61

Grand Total 9,731.09



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SCZ 2800 Y

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0316/2019/KK
18 April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

1 total pages

Make & Model : Audi Q5 SPORT 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZFY7J2035930
Vehicle Regn No. : **SCZ 2800 Y**
Vehicle Mileage : 22898 KM
Vehicle Owner : Ms. Lim Lee Lee
Certificate No : 1700079534
Own Damage Excess : \$535.00 (Inclusive 7%GST)
Accident Date : 6/3/2019
Place : Holland Village Area
Repair Cost : \$ 9,731.09
WIP No. : 45297
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

18/4