

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 21 Mar 2019

Preliminary Advice

Vehicle No	: SLW9079B	Accident Date	: 16/03/2019
Make	: AUDI Q2	Policy No.	: 1800023129-01
Assignment Date	: 21/03/2019	Excess	: S\$0.00
Date of Inspection	: 20/03/2019	Est. Duration of Repair	: 18 days
Inspection At	: Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector Singapore 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	69,229.00
Revised Amount	:S\$	34,724.00
Check Items (Estimated)	:S\$	21,641.00
Total	:S\$	56,365.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	145,000.00
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	57,947.00
Salvage Value	:S\$	
Margin for Repair (New for old)	:S\$	87,053.00
Margin for Repair	:S\$	47,053.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. (Based on new for old value)
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :