

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Estimate : TP19-027

Date:

Date : 20/03/2019

Vehicle Num. : SLG6762R

Make/Model : Nissan Sylphy-2016

Chassis/Eng# : MNTBAAB17Z0008851/MRA8359531R

Accident Date : 21/02/2019

Claim No. :

Reference :

Policy No. : 10774954 (10/10/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

NETT ITEMS :				
1.	1	Frt Fender RH <i>Repair</i>		766.10 <i>x</i>
2.	1	Frt Door RH <i>Dented</i>		987.40 <i>-</i>
3.	1	Frt Chrome Trim RH <i>new</i>		215.40 <i>-</i>
4.	1	Frt Door Weatherstrip RH <i>new</i>		158.35 <i>+</i>
5.	1	Frt Door Mechanism Lock RH <i>new</i>		281.57 <i>+</i>
6.	1	Rear Door RH <i>Repair</i>		987.40 <i>+</i>
7.	2	Frt Door Hinge, Top/Lower RH <i>new</i>		130.20 <i>+</i>
8.	1	Frt Door Wing Mirror RH <i>new</i>		328.10 <i>+</i>
9.	1	Frt Door Outer Handle RH <i>new</i>		173.20 <i>+</i>
Nett Total S\$:				4,027.72
10.00% Discount S\$:				402.77
				3,624.95

SPECIAL NETT ITEMS :				
1.	1	Side Rocker Skirt RH <i>Repair</i>		718.80 <i>x</i>
Special Nett Total S\$:				718.80

LABOUR :				
To remove, rearrange electrical wirings, check lighting				50.00 <i>30</i>
To remove, replace & transfer door components.				300.00 <i>80</i>
Transfer glass, gear & components.				
To remove, repair and replaced damaged bodyparts, align bodyworks & where consistent to the accident				1,200.00 <i>400</i>
To putty and respray painting on affected area.				1,000.00 <i>800</i>
Labour Total S\$:				2,550.00

E. & O.E.	Total S\$:	6,893.75
-----------	-------------	----------

for SUCCESS UNITED PTE LTD

total: 2392.52 Admin L
L/S: 1.9K L/S 20/03/19.
OS Pays.