



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INS BHD
100, Beach Road
#19-00, Shaw Tower
Singapore 189702

ESTIMATE :TP19004
Date : :20/03/2019
Ref No : :SJX 1617 U
Policy No.: :
Page :01

RE : VEHICLE NO. SJX 1617 U TOYOTA VIOS

Qty	Description	Unit Price	Amount
1	REAR BUMPER <i>Deep cut</i>		\$466.30
1	REAR BUMPER SIDE RETAINER (FRONT) <i>cut</i>		\$75.20
1	REAR BUMPER SIDE RETAINER (REAR) <i>11</i>		\$76.20 X
1	REAR FENDER LH <i>Body work / 11</i>		\$890.40
1	REAR FENDER INNER TRIM <i>11</i>		\$296.30 X
1	PETOL DOOR <i>2</i>		\$195.50 X
1	PETOL DOOR CABLE <i>11</i>		\$106.40 X
1	REAR WINDSCREEN MOULDING <i>11</i>		\$162.50
1	TAILLAMP LH <i>11</i>		\$362.30 X
SUB TOTAL			\$2,631.10
LESS 25 %			\$657.78
TOTAL (1)			\$1,973.32

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS (SET) <i>11</i>	\$48.00	✓
1	REAR BUMPER REVERSE SENSOR w/unit <i>Daye</i>	\$300.00	200
1	WINDSCREEN SEALANT <i>11</i>	\$80.00	40
1	SPORT RIM <i>11</i>	\$580.00	X
TOTAL (2)		\$1,008.00	

LABOUR

TO REMOVE & REFIX WINDSCREEN	\$200.00	120
TO REMOVE & REFIX CUSHION SEAT	\$180.00	100
TO RUST PROOF AFFECTER AREAS	\$100.00	50
TO REMOVE & REFIX PETOL TANK	\$150.00	60
TO REMOVE & REFIX REVERSE SENSOR	\$100.00	50
TO REMOVE & REFIX RIM	\$80.00	2
TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	\$150.00	60
TO PANEL BEATING	\$1,200.00	800
TO SPRAY PAINTING	\$1,100.00	700

TOTAL SPARE PARTS & LABOUR CHARGES

Let Auto Consult will be responsible for the Repairs of the following:

- To result in **LABOUR CHARGES**
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

\$6,241.32 *3423.60*