


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:42

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85013907	Account: A0006 (T 0)	
		Date : 13/06/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
		Order : SLZ1533T		
		Term : 30		
Regn No: SLZ1533T (V 37347)		Regn Date: 24/04/2018	Mileage: 11286	WIP No.: 46662
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG		Chassis: WAUZZZ8V7JA093481	Engine: CHZ 432053	Dept: U
You have been assisted by :- UB-Kelvin Khoo (138)				

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT.TO REALIGN FRONT LOCK CARRIER TO POSITION.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1750.00	1.00	1,750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET AND LHS FRONT FENDER	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V3807681AA9B9	(V)(Ger)GRILL 27/3/1	Less 020%	1.00	170.50
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1301.00
X	A8V0941773D	HEADLIGHT	Less 020%	1.00	5029.00
X	A8V0821105L	FENDER	Less 020%	1.00	777.50
X	A8V0807550A	FOAM INSER	Less 020%	1.00	172.00
X	A8V4807109E	BEAM	Less 020%	1.00	659.50
X	A8V0807065R GRU	COVER	Less 020%	1.00	1698.00
X	A8V0823029D	HOOD	Less 020%	1.00	2501.00
X	A8V0823126B	EDGING	Less 020%	1.00	24.90
X	A8V3807319	PLATE	Less 020%	1.00	270.00
X	A8V0821135A	SUPPORT	Less 020%	1.00	87.30
X	A8V3807183B	GUIDE	Less 020%	1.00	34.40
X	A8V0821467E	BRACKET	Less 020%	1.00	42.60
X	A8V0821091C	PLATE	Less 020%	1.00	55.30
X	A8V0955101B	CYLINDER	Less 020%	1.00	127.50

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLZ1533T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0360/2019/TF
3 April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SPORTSBACK 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V7JA093481
Vehicle Regn No. : **SLZ1533T**
Vehicle Mileage : 11286 KM
Vehicle Owner : Mr. Godfrey Matthew Edward
Certificate No : 1800043659-01
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 17 March 2019
Place : Ramp *From* Choa Chu Kang To KJE
Repair Cost : \$ *15,198.58*
WIP No. : 46662
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



6/4/19
