

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$600/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 100K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 6 Consistent? : Yes or No

Est. Repairs: 6 days ✓ Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SLZ1533T Yr Regn: 2018 / Apr

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Audi A3 SB cc 999

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 11287 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V7A0S348

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rip / ☐ STD A/Rim or

Tyre Size: F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal: 06 mm

L/Bal: 06 mm

D.O.A. _____ D.O.I. 21/03/19

Survey held at Premium

Des. of Damages: ☒ Front / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Front W/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	ODALG
	SLZ 1533T - CC6/ALG 19005601 / Apr 3 D.O.A. - 17/3/2019
22/03/19	@ 11:23 p.m. received PA to ALG via memo.
22/03/19	@ 11:24 p.m. mandate requested authorise repair to ALG.
	MV:
	PV:
	Nett:

22/03/19 @ 16:29 p.m. mandate approved by Lee Lai's Cheng via memo.

25/03/19 @ 12:07 p.m. revert authorise repair to Nara Computer via email.

14/05/19 Confirmed p/p \$14,804.28 @ 6 days with Adrian. (\$12,327.72 Ret - 46%)

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:
1) Typist	2)	IN	Basic & Add.
3)	4)	OUT	S + RS, SI
5)	6)		Photos
			Others
			TOTAL

Prek Report:

Final Report: \$14,804.28 p/p

Resurvey No. of Trip - 2

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 22 Mar 2019

Preliminary Advice

Vehicle No	: SLZ1533T	Accident Date	: 17/03/2019
Make	: AUDI A3	Policy No.	: 1800043659-01
Assignment Date	: 21/03/2019	Excess	: S\$0.00
Date of Inspection	: 21/03/2019	Est. Duration of Repair	: 6 - 9 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,532.00
Revised Amount	:S\$	17,704.00
Check Items (Estimated)	:S\$	3,731.00
Total	:S\$	21,435.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	54,375.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,625.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 14 May 2019 3:15 PM
To: 'Carrine Leong'; 'Boo seng yak'; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Cc: Adrian Ling (LKKAuto); SUR
Subject: RE: FINAL REVISION - SLZ1533T - OD AIG - SURVEYED 21 MAR 19

Dear Carrine,

As spoken, confirmed final fig \$ 14,804.28 @ 6 days of repairs before excess \$ 600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Monday, 15 April 2019 3:43 PM
To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLZ1533T - OD AIG - SURVEYED 21 MAR 19

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$14,804.28 @ 9 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 25 March 2019 12:07 PM
To: 'NORA'; 'Claims Dept'
Cc: 'Adrian Ling (LKKAuto)'; 'SUR'; 'Admin A'
Subject: RE: SLZ 1533 T - OD DAMAGE CLAIM DOA: 17/03/2019
Attachments: ESTIMATE.pdf

Dear All,

As instructed by our client, please proceed to repair the insured vehicle **SLZ 1533T (Excess \$ 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Kindly take note **IF REPLACE LOCK CARRIER, AFTER REMOVAL PHOTO REQUIRE.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: NORA [mailto:nora.khai@premiumauto.com.sg]
Sent: Monday, 25 March 2019 8:54 AM
To: 'Claims Dept' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>
Subject: RE: SLZ 1533 T - OD DAMAGE CLAIM DOA: 17/03/2019

Dear All,

Kindly advise for OD approval. Take note vehicle is in the premises.

Thank you.

Best Regards,

Norah Khai
Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 22 March 2019 8:56 AM
To: 'Claims Dept'; 'SUR'; 'Admin A'
Cc: 'Adrian Ling (LKKAUTO)'
Subject: RE: SLZ 1533 T - OD DAMAGE CLAIM DOA: 17/03/2019

Dear all,

Kindly note that the mentioned vehicle is in our premises.

Thank You.

Best Regards,
Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Friday, 22 March 2019 8:54 AM
To: 'SUR'; 'Admin A'
Cc: 'Claims Dept'; 'Adrian Ling (LKKAUTO)'
Subject: SLZ 1533 T - OD DAMAGE CLAIM DOA: 17/03/2019

Dear All,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.
The mentioned vehicle did the survey yesterday 21/3/2019 by Adrian.
Kindly advise on approval.

Thank You.

Best Regards,
Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SLZ1533T (6618340344SG)**

OD

Mar 17 2019 9:00PM

[GODFREY MATTHEW EDWARD]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **22/03/2019 16:29 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$16454.00) - SLZ1533T - Claim Handler: Mohd Zawaye, Norsazani

Approved:16454.00:KINDLY RE-SUBMIT FIRST ADVICE INTERIM AMOUNT IN-CORRECT RE-INSPECTION REQUIRE ON ALL SUPPLEMENTARY PARTS AND HIDDEN PART WITH CHECK ITEM. IF REPLACE LOCK CARRIER, AFTER REMOVAL PHOTO REQUIRE.

DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2229F
Vehicle Details	
Vehicle No.:	SLZ1533T
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CHZ432053
Chassis No.:	WAUZZZ8V7JA093481
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,176.00
Original Registration Date:	24 Apr 2018
First Registration Date:	24 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$25,847.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2028
PARF Rebate Amount:	\$19,385.00
Intended COE Rebate Details	
COE Expiry Date:	23 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,510.00
COE Rebate Amount:	\$34,990.00
Total Rebate Amount:	\$54,375.00

The information contained herein is correct as at 22 Mar 2019.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/03/2019 19:38
Date Of Accident	17/03/2019 21:20
Exact Location Of Accident	RAMP FROM CHOA CHU KANG DRIVE TO KJE TOWARDS BKE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLZ1533T
Insured/Policyholder	
Name Of Registered Owner	GODFREY MATTHEW EDWARD
NRIC No	S2772229F
Email Address	MATTGOD1@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96153898
Alternative Phone No	OTHERS-96153898
Vehicle Particulars	
Manufacturer	AUDI
Model	A3 SB 1.0 TF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800043659-01
Cover Note Number	
Driver	
Name of Driver	GODFREY MATTHEW EDWARD
NRIC No	S2772229F
Date Of Birth	03/07/1967
Occupation	INDOOR
Date Of Driving Pass	24/07/1997
Driving Experience	21 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96153898
Fax Number	
Contact Number	OTHERS-96153898
EEmail Address	MATTGOD1@GMAIL.COM

Address	27 JALAN LIMAU NIPIS
Postcode	468280
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

17 MARCH 2019 APPROXIMATELY: 0915 - 0920 PM. WHILE TURNING OFF TO CHOA CHU KANG DRIVE, ON TO THE SLIP RAMP THAT LEADS ONTO KJE, I RAN INTO THE BACK OF THE CHEV ORLANDO OWNED BY MR NG. THE FRONT LEFT OF MY AUDI A3 IMPACTED THE BACK RIGHT OF THE CHEV ORLANDO. THIS DAMAGED THE FRONT OF MY CAR AND THE REAR RIGHT OF THE CHEV. WE STOPPED BOTH CARS MR NG AND MRS NG, SAID THAT THEY WERE NOT INJURED. I APOLOGISED FOR THE ACCIDENT. WE DISCUSSED REQUESTING POLICY BUT AS NO INJURIES AND BOTH CARS MOBILE WE AGREED NOT NECESSARY. WE EXCHANGED IC AND DETAILS. I COMMITTED TO REPORTING TO INSURANCE THE FOLLOWING DAY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG1684R
Vehicle Make/Model/Colour	CHEVROLET ORLANDO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG HONG CHIANG
NRIC/Passport Number	
Contact Number	91086065
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

DAMAGE TO REAR RIGHT BUMPER/FENDER

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: March 18th
2-30 PM


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Tony Fong
NRIC/IN No.: G7401811

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

17th MARCH - APPROXIMATELY 9.15-9.20 PM.

While turning off Choa Chu Kang drive, on to the slip ramp that leads on to KJE, I ran into the back of the Chevy Orlando owned by MR NG.

THE FRONT LEFT OF MY AUDI A3 IMPACTED THE BACK RIGHT OF THE CHEVY ORLANDO. THIS DAMAGED THE FRONT OF MY CAR AND THE REAR RIGHT OF THE CHEVY

WE STOPPED BOTH CARS MR NG AND MRS NG SAID THAT THEY WERE NOT INJURED. I APOLOGISED FOR THE ACCIDENT. WE DISCUSSED REQUESTING POLICY BUT AS NO INJURIES AND BOTH CARS MOBILE WE AGREED NOT NECESSARY. WE EXCHANGED IC AND DETAILS. I COMMITTED TO REPORTING TO INSURANCE THE FOLLOWING DAY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 18 MARCH
2.34 PM

Driver's Signature

(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature

Name: Tony Fong
NRIC/FIN No: 67010107K

Accident Photo



REPUBLIC OF SINGAPORE

License Number **F2503165L**

Holder

GODFREY MATTHEW EDWARD

Birth Date: **03 Jul 1967**

Issue Date: **05 Jan 2015**

Valid Till **04 Jan 2020**

002382511J

NP 428A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S2772229F**

Name

GODFREY MATTHEW EDWARD

Race

CAUCASIAN

Date of birth

03-07-1967

Country/Place of birth

AUSTRALIA

Sex

M

S2772229F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	24 Jul 1997

NP 428A

License No: **F2503165L**

9452794

S2772229F

Nationality

AUSTRALIAN

Date of issue

24-07-2017

Address

**27 JALAN LIMAU NIPIS
SINGAPORE 468280**



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : GODFREY MATTHEW EDWARD
Period of Insurance : 24 Apr 2019 To 23 Apr 2020
Engine No. : CHZ432053
Chassis No. : WAUZZZ8V7JA093481

Vehicle No. : SLZ1533T
Policy No. : 1800043659-01
Endorsement No. :
Issued Date : 17 Mar 2019

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

GODFREY MATTHEW EDWARD - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63862323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part (V) of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

AIGSGMOBILEAPP

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0360/2019/DY
Date : 20-Mar-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Godfrey Matthew Edward
Address : 27 Jalan Limau Nipis
Singapore 468280
Telephone : 96153898
Type of Claim : Own Damage Claims
Policy No. : 1800043659-01
Vehicle No : **SLZ 1533 T**
Model Code : A3 SPORTBACK 1.0 TF
Model / Year : 24/4/2018
Engine No : CHZ 432053
Chassis No : WAUZZZ8V7A093481
Mileage :
Date In : 18-Mar-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Mar-19
Place of Accident : Ramp From Choa Chu Kang

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 1533 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 960.00	? X
3	To dismantle and renew front bumper, LHS front fender, bonnet and LHS headlight. To renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 4,500.00	✓ 1750, without Lock carrier 3000 with Lock carrier
4	To respray front bumper, bonnet and LHS front fender.	\$ 2,500.00	✓ 1650
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,512.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLZ 1533 T**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 1,698.00 ✓	1352.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00 +	
3	FRONT BUMPER GUIDE SECTION - LH <i>Dist</i>	\$ 35.00 ✓	27.52
4	GRILLE - CENTER <i>new</i>	\$ 146.00 +	
5	CLOSING ELEMENT - LOWER CENTER <i>new</i>	\$ 270.00 +	
* 6	CLOSING ELEMENT - LH <i>new Dist.</i>	\$ 270.00 + ✓	216
7	RADIATOR GRILLE <i>Combined</i>	\$ 1,301.00 ✓	1040.20
* 8	END PLATE <i>new Dist.</i>	\$ 174.00 + ✓	138.20
9	AIR GUIDE GRILLE - LH <i>Dist</i>	\$ 171.00 ✓	136.40
10	SIDE REINFORCEMENT <i>Dist.</i>	\$ 660.00 ✓	527.60
11	FOAM FILLER PIECE <i>crushed.</i>	\$ 172.00 ? ✓	137.60
12	FRONT BUMPER COVER <i>new</i>	\$ 111.00 ? X	
13	AIR CONDITIONER STICKER <i>new</i>	\$ 7.00 ✓	5.12
14	SIGN "CAUTION" <i>new</i>	\$ 13.00 ✓	9.76
15	FRONT FENDER - LH <i>Unleaded</i>	\$ 778.00 ✓	622.00
16	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ 65.00 ? X	
17	FRONT FENDER BRACKET - LH <i>Dist</i>	\$ 43.00 ✓	34.63
18	FRONT FENDER BRACE <i>Dist</i>	\$ 88.00 ✓	69.34
* 19	FRONT FENDER CLOSING ELEMENT - LH <i>new Dist.</i>	\$ 56.00 x ✓	44.24
20	WHEEL HOUSING LINER - LH <i>new</i>	\$ 156.00 +	

SUB TOTAL SPARE PARTS: **\$ 6,384.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLZ 1533 T**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	WHEEL HOUSING ELEMENT ATTACHMENT PARTS <i>2nd</i>	S 52.00	+
22	BONNET <i>Dented</i>	S 2,501.00	✓ 2000.30
23	BONNET ATTACHMENT PARTS <i>2nd new</i>	S 149.00	? X
24	LID HINGE - LH <i>2</i>	S 56.00	X
25	LID HINGE - RH <i>1st new</i>	S 56.00	+
26	GAS FILLED STRUT	S 109.00	+
27	FRONT EDGE PROTECTION <i>new</i>	S 25.00	✓ 19.92
28	BONNET CATCH HOOK <i>2</i>	S 81.00	↑
29	BONNET STRIKER - LH <i>1st new</i>	S 100.00	+
30	LID LOCK MICRO-SWITCH	S 184.00	+
31	LED HEADLIGHT - LH <i>cracked</i>	S 5,029.00	✓ 4023.20
32	LIGHT POWER REGULATOR <i>2nd new</i>	S 693.00	+
33	LED HEAT SINK - LH <i>new</i>	S 666.00	+
34	LIGHT CONTROL UNIT <i>new</i>	S 508.00	+
35	HEADLIGHT LIFT CULINDER - LH <i>cracked</i>	S 128.00	✓ 102.00
36	HOSE <i>2nd new</i>	S 61.00	? X
37	WASH WATER RESERVOIR <i>Distorted</i>	S 186.00	? ✓ 148.40
38	WINDSCREEN WASHER PUMP <i>2nd new</i>	S 118.00	? X
39	HEADLIGHT WASHER PUMP <i>2nd new</i>	S 147.00	? X
40	RETAINER SIGNAL HORN - LH <i>Damaged</i>	S 182.00	? ✓ 145.60
SUB SPARE PARTS		\$ 11,031.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLZ 1533 T**

S/N	Parts Description	<u>Damaged Parts & Prices</u>		Remark
		S/Nett		
41	AIR GUIDE - LH <i>Not new</i>	\$	22.00	✓ X
42	AIR GUIDE - UPPER CENTER <i>Not new</i>	\$	11.00	✓ X
43	COOLANT RADIATOR LOCK CARRIER <i>Not new</i>	\$	663.00	✓ X
55	READY-MIX COOLANT <i>Not new</i>	4 \$	84.00	✓ X
45	FRONT NO PLATE <i>new</i>	S/N \$	25.00	✓
46	SUNDRIES <i>new</i>	\$	800.00	✓ 19.20
TOTAL SPARE PARTS		:	\$ 19,020.00	
TOTAL LABOUR CHARGES			\$ 8,512.00	
GRAND TOTAL			\$ 27,532.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lim

Surveyed Date

: 21/03/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 06 Days (Excluding
Lock Carrier)
09 Days (including
Lock Carrier).

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0360/2019/DY
Date : 20-Mar-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

9 days - ok - jb - 15 Apr 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Godfrey Matthew Edward
Address : 27 Jalan Limau Nipis
Singapore 468280
Telephone : 96153898
Type of Claim : Own Damage Claims
Policy No. : 1800043659-01
Vehicle No : **SLZ 1533 T**
Model Code : A3 SPORTBACK 1.0 TF
Model / Year : 24/4/2018
Engine No : CHZ 432053
Chassis No : WAUZZZ8V7A093481
Mileage :
Date In : 18-Mar-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Mar-19
Place of Accident : Ramp From Choa Chu Kang

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 1533 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Presssurise cooling system. To carry out vacuum and regas.	S/N \$ 960.00	
3	To dismantle and renew front bumper, LHS front fender, bonnet and LHS headlight. To renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 4,500.00	\$ 1,750.00
4	To respray front bumper, bonnet and LHS front fender.	\$ 2,500.00	\$ 1,650.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: <u>\$ 8,512.00</u>	<u>\$ 3,952.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLZ 1533 T**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,698.00	\$ 1,358.40
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 35.00	\$ 27.52
4	GRILLE - CENTER	\$ 146.00	
5	CLOSING ELEMENT - LOWER CENTER	\$ 270.00	
6	CLOSING ELEMENT - LH	\$ 270.00	\$ 216.00
7	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
8	END PLATE	\$ 174.00	\$ 138.80
9	AIR GUIDE GRILLE - LH	\$ 171.00	\$ 136.40
10	SIDE REINFORCEMENT	\$ 660.00	\$ 527.60
11	FOAM FILLER PIECE	\$ 172.00	\$ 137.60
12	FRONT BUMPER COVER	\$ 111.00	
13	AIR CONDITIONER STICKER	\$ 7.00	\$ 5.12
14	SIGN "CAUTION"	\$ 13.00	\$ 9.76
15	FRONT FENDER - LH	\$ 778.00	\$ 622.00
16	FRONT FENDER ATTACHMENT PARTS	\$ 65.00	
17	FRONT FENDER BRACKET - LH	\$ 43.00	\$ 34.08
18	FRONT FENDER BRACE	\$ 88.00	\$ 69.84
19	FRONT FENDER CLOSING ELEMENT - LH	\$ 56.00	\$ 44.24
20	WHEEL HOUSING LINER - LH	\$ 156.00	
SUB TOTAL SPARE PARTS		\$ 6,384.00	\$ 4,368.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLZ 1533 T**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 4,368.16
21	WHEEL HOUSING ELEMENT ATTACHMENT PARTS	\$	52.00	
22	BONNET	\$	2,501.00	\$ 2,000.80
23	BONNET ATTACHMENT PARTS	\$	149.00	
24	LID HINGE - LH	\$	56.00	
25	LID HINGE - RH	\$	56.00	
26	GAS FILLED STRUT	\$	109.00	
27	FRONT EDGE PROTECTION	\$	25.00	\$ 19.92
28	BONNET CATCH HOOK	\$	81.00	
29	BONNET STRIKER - LH	\$	100.00	
30	LID LOCK MICRO-SWITCH	\$	184.00	
31	LED HEADLIGHT - LH	\$	5,029.00	\$ 4,023.20
32	LIGHT POWER REGULATOR	\$	693.00	
33	LED HEAT SINK - LH	\$	666.00	
34	LIGHT CONTROL UNIT	\$	508.00	
35	HEADLIGHT LIFT CULINDER - LH	\$	128.00	\$ 102.00
36	HOSE	\$	61.00	
37	WASH WATER RESERVOIR	\$	186.00	\$ 148.40
38	WINDSCREEN WASHER PUMP	\$	118.00	
39	HEADLIGHT WASHER PUMP	\$	147.00	
40	RETAINER SIGNAL HORN - LH	\$	182.00	\$ 145.60
SUB SPARE PARTS		:	\$ 11,031.00	\$ 10,808.08

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLZ 1533 T**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 10,808.08
41	AIR GUIDE - LH		\$ 22.00	
42	AIR GUIDE - UPPER CENTER		\$ 11.00	
43	COOLANT RADIATOR LOCK CARRIER		\$ 663.00	
55	READY-MIX COOLANT	4	\$ 84.00	
45	FRONT NO PLATE	S/N	\$ 25.00	\$ 25.00
46	SUNDRIES		\$ 800.00	\$ 19.20
TOTAL SPARE PARTS			\$ 19,020.00	\$ 10,852.28
TOTAL LABOUR CHARGES			\$ 8,512.00	\$ 3,952.00
GRAND TOTAL			\$ 27,532.00	\$ 14,804.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLZ 1533 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0360/2019/KS

17 June 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLZ 1533 T, Audi A3 SB 1.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLZ 1533 T**, claimant,
Mr. Godfrey Matthew Edward, please find the related document per attached.

1. A copy of the Original invoice no. 85013907 – S\$15,198.58.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLZ 1533 T

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2322
Main Telefax 6841 1163

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:42

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013907 Date: 13/06/2019 Order: SLX1533T Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLX1533T (V 37347)	Regn Date: 24/04/2018	Mileage: 11286	WIP No.: 46662
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG	Chassis: WAU2Z28V7JA093481	Engine: CHZ 432053	Dept: U
You have been assisted by :- UB-Kelvin Khoo (138)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT.TO REALIGN FRONT LOCK CARRIER TO POSITION.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1750.00	1.00	1,750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET AND LHS FRONT FENDER	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ABV3807681AA9B9	(V)(Ger)GRILL 27/3/1	Less 020%	1.00	170.50
X	ABV3853651AA3F2	GRILLE	Less 020%	1.00	1301.00
X	ABV0941773D	HEADLIGHT	Less 020%	1.00	5029.00
X	ABV0821105L	FENDER	Less 020%	1.00	777.50
X	ABV0807550A	FOAM INSER	Less 020%	1.00	172.00
X	ABV4807109E	BEAM	Less 020%	1.00	659.50
X	ABV0807065R GRU	COVER	Less 020%	1.00	1698.00
X	ABV0823029D	HOOD	Less 020%	1.00	2501.00
X	ABV0823126B	EDGING	Less 020%	1.00	24.90
X	ABV3807319	PLATE	Less 020%	1.00	270.00
X	ABV0821135A	SUPPORT	Less 020%	1.00	87.30
X	ABV3807183B	GUIDE	Less 020%	1.00	34.40
X	ABV0821467E	BRACKET	Less 020%	1.00	42.60
X	ABV0821091C	PLATE	Less 020%	1.00	55.30
X	ABV0955101B	CYLINDER	Less 020%	1.00	127.50

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159936
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159936
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 16:42

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013907 Date : 13/06/2019 Order : SL21533T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SL21533T (V 37347) Regn Date: 24/04/2018 Mileage: 11286 WIP No.: 46662

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAU2Z28V7JA093481 Engine: CH2 432053 Dept: U

You have been assisted by :- US-Kelvin Khoo [138]

		Details	Qty	Unit Price	Amount
X	ABK0010520A	PLATE	Less 020%	1.00	12.20
X	ABV0010515A	STICKER	Less 020%	1.00	6.40
X	ABV3853949	PLATE	Less 020%	1.00	173.50
X	ASQ0955453R	WATER RES.	Less 020%	1.00	185.50
X	ABV0951209C	(V) (SK) HORN 27/3/19	Less 020%	1.00	182.00
X	AN 0161857	POP-RIVET	Less 020%	8.00	3.00

Parts 10,827.28
Labour 0.00
Sublet 3,977.00
Menus 0.00
Lubricant 0.00



Sub-Total	14,204.28
7% GST	994.30
Grand Total	15,198.58

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLZ1533T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0360/2019/TF
3 April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SPORTSBACK 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V7JA093481
Vehicle Regn No. : **SLZ1533T**
Vehicle Mileage : 11286 KM
Vehicle Owner : Mr. Godfrey Matthew Edward
Certificate No : 1800043659-01
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 17 March 2019
Place : Ramp *From* Choa Chu Kang To KJE
Repair Cost : \$ 15,198.58
WIP No. : 46662
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


6/4/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2019		21 Mar 2019 16:47 Edit Adj Rpt	\$14,804.28 Edit Estimates	\$14,804.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS Insured: GODFREY MATTHEW EDWARD, ID: S2772229F, Tel: +6596153898, Email: MATTGOD1@GMAIL.COM Vehicle Reg. No.: SLZ1533T Claim Type: OD / 6618340344SG Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911 Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/04/2019] Driver/Custodian: GODFREY MATTHEW EDWARD (S1 / Male), NRIC: S2772229F, Tel: +6596153898 Email: MATTGOD1@GMAIL.COM ASSOCIATED MAIL RECEIVED View All Compose Case Mail - AIG_SG (22/03/2019): Alert - Adj Mandate Approved (\$16454.00) - SLZ1533T - Claim Handler: Mohd Zaway... - AIG_SG (22/03/2019): SLZ1533T / OD / 17/03/2019 / Coverage & Excess update ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SLZ1533T (6618340344SG)
ODMar 17 2019 9:00PM
[GODFREY MATTHEW EDWARD]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer	
Assessment Reports															1 per page			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print	
1	22/03/19 11:23		Adjuster Immediate Advice													Load HTML		
Photos/Images															3 per page			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print	
1	22/03/19 10:49		General View													Load JPG		
2	22/03/19 10:49		Chassis Number													Load JPG		
3	22/03/19 10:49		General View													Load JPG		
4	22/03/19 10:49		General View													Load JPG		
5	22/03/19 10:49		General View													Load JPG		
6	22/03/19 10:49		General View													Load JPG		
7	22/03/19 10:49		General View													Load JPG		
8	22/03/19 10:49		General View													Load JPG		
9	22/03/19 10:49		General View													Load JPG		
10	22/03/19 10:49		General View													Load JPG		
11	22/03/19 10:49		General View													Load JPG		
12	22/03/19 10:49		General View													Load JPG		
13	22/03/19 10:49		General View													Load JPG		
14	22/03/19 10:49		General View													Load JPG		
15	22/03/19 10:49		General View													Load JPG		
16	22/03/19 10:49		General View													Load JPG		
17	22/03/19 10:49		General View													Load JPG		
18	22/03/19 10:49		General View													Load JPG		
19	22/03/19 10:49		General View													Load JPG		
20	22/03/19 10:49		General View													Load JPG		
21	22/03/19 10:49		General View													Load JPG		
22	22/03/19 10:49		General View													Load JPG		
23	22/03/19 10:49		General View													Load JPG		
24	22/03/19 10:49		General View													Load JPG		
25	22/03/19 10:49		General View													Load JPG		
26	22/03/19 10:49		General View													Load JPG		
27	22/03/19 10:49		General View													Load JPG		
28	06/05/19 12:12		Reinspection Photo													Load JPG		
29	06/05/19 12:12		Reinspection Photo													Load JPG		
30	06/05/19 12:12		Reinspection Photo													Load JPG		
31	06/05/19 12:12		Reinspection Photo													Load JPG		
32	06/05/19 12:12		Reinspection Photo													Load JPG		
33	06/05/19 12:12		Reinspection Photo													Load JPG		
34	06/05/19 12:12		Reinspection Photo													Load JPG		
35	06/05/19 12:12		Reinspection Photo													Load JPG		
36	06/05/19 12:12		Reinspection Photo													Load JPG		
37	06/05/19 12:12		Reinspection Photo													Load JPG		
38	06/05/19 12:12		Reinspection Photo													Load JPG		
39	06/05/19 12:12		Reinspection Photo													Load JPG		
40	06/05/19 12:12		Reinspection Photo													Load JPG		

41	06/05/19 12:12	Reinspection Photo		Load JPG	
42	06/05/19 12:12	Reinspection Photo		Load JPG	
Documentation					
				1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/03/19 10:48	DRIVING & CI.pdf		Load PDF	
2	22/03/19 10:48	SLZ 1533T GIA.pdf		Load PDF	
3	22/03/19 10:48	ESTIMATE.pdf		Load PDF	
4	14/05/19 15:12	ESTIMATE MARKED.pdf		Load PDF	
5	24/06/19 10:35	WORKSHOP INVOICE		Load PDF	
6	24/06/19 10:35	DISCHARGE VOUCHER		Load PDF	

Linked Accident Report Documents

				View	Use Viewer
Assessment Reports				1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	18/03/19 20:04	Accident Statement		Load HTM	
Photos/Images					
				3 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	18/03/19 19:57	Accident Photo		Load JPG	
2	18/03/19 19:57	Accident Photo		Load JPG	
3	18/03/19 19:57	Accident Photo		Load JPG	
4	18/03/19 19:57	Accident Photo		Load JPG	
5	18/03/19 19:57	Accident Photo		Load JPG	
6	18/03/19 19:57	Accident Photo		Load JPG	
7	18/03/19 19:57	Accident Photo		Load JPG	
8	18/03/19 19:57	Accident Photo		Load JPG	
9	18/03/19 19:57	Accident Photo		Load JPG	
10	18/03/19 19:57	Accident Photo		Load JPG	
11	18/03/19 19:57	Accident Photo		Load JPG	
12	18/03/19 19:57	Accident Photo		Load JPG	
13	18/03/19 19:57	Accident Photo		Load JPG	
Documentation					
				1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	18/03/19 19:49	Sketch Plan		Load JPG	
2	18/03/19 19:49	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19005160/ASD3N2

Date: 24/06/2019

REFERENCE

Insured/Claimant: GODFREY MATTHEW EDWARD
Date of Loss: 17/03/2019Policy No: 1800043659
Nature of Claim: OD

Claim No: 6618340344SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ1533T	Engine No:	CHZ432053
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8V7JA093481
Reg. Date:	24/04/2018 (Man. Year: 2018)	Odometer:	11287 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,020.00	10,852.28	8,167.72	42.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,512.00	3,952.00	4,560.00	53.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,532.00	14,804.28	12,727.72	46.23
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	26,932.00	14,204.28	12,727.72	47.26
+ GST 7.00/7.00% (S\$)	1,885.24	994.30	890.94	47.26
Nett Amount (S\$)	28,817.24	15,198.58	13,618.66	47.26

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 21/03/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,698.00 FS	*1,358.40 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1	*FRONT BUMPER GUIDE SECTION-LH	Damaged	35.00 FS	*27.52 FS
4	1	*GRILLE-CENTER	Not Necessary	146.00 FS	*- FS
5	1	*CLOSING ELEMENT-LOWER CENTER	Not Necessary	270.00 FS	*- FS
6	1	*CLOSING ELEMENT-LH	Damaged	270.00 FS	*216.00 FS
7	1	*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
8	1	*END PLATE	Bent	174.00 FS	*138.80 FS
9	1	*AIR GUIDE GRILLE-LH	Deformed	171.00 FS	*136.40 FS
10	1	*SIDE REINFORCEMENT	Bent	660.00 FS	*527.60 FS
11	1	*FOAM FILLER PIECE	Cracked	172.00 FS	*137.60 FS
12	1	*FRONT BUMPER COVER	Not Necessary	111.00 FS	*- FS
13	1	*AIR CONDITIONER STICKER	Necessary	7.00 FS	*5.12 FS
14	1	*SIGN CAUTION	Necessary	13.00 FS	*9.76 FS
15	1	*FRONT FENDER-LH	Buckled	778.00 FS	*622.00 FS
16	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
17	1	*FRONT FENDER BRACKET-LH	Bent	43.00 FS	*34.08 FS
18	1	*FRONT FENDER BRACE	Bent	88.00 FS	*69.84 FS
19	1	*FRONT FENDER CLOSING ELEMENT-LH	Damaged	56.00 FS	*44.24 FS
20	1	*WHEEL HOUSING LINER-LH	Not Necessary	156.00 FS	*- FS
21	1	*WHEEL HOUSING ELEMENT ATTACHMENT PARTS	Not Necessary	52.00 FS	*- FS
22	1	*BONNET	Dented	2,501.00 FS	*2,000.80 FS
23	1	*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
24	1	*LID HINGE-LH	Not Necessary	56.00 FS	*- FS
25	1	*LID HINGE-RH	Not Necessary	56.00 FS	*- FS
26	1	*GAS FILLED STRUT	Not Necessary	109.00 FS	*- FS
27	1	*FRONT EDGE PROTECTION	Necessary	25.00 FS	*19.92 FS
28	1	*BONNET CATCH HOOK	Not Necessary	81.00 FS	*- FS
29	1	*BONNET STRIKER-LH	Not Necessary	100.00 FS	*- FS
30	1	*LID LOCK MICRO-SWITCH	Not Necessary	184.00 FS	*- FS
31	1	*LED HEADLIGHT-LH	Cracked	5,029.00 FS	*4,023.20 FS
32	1	*LIGHT POWER REGULATOR	Not Necessary	693.00 FS	*- FS
33	1	*LED HEAT SINK-LH	Not Necessary	666.00 FS	*- FS
34	1	*LIGHT CONTROL UNIT	Not Necessary	508.00 FS	*- FS
35	1	*HEADLIGHT LIFT CYLINDER-LH	Cracked	128.00 FS	*102.00 FS
36	1	*HOSE	Not Necessary	61.00 FS	*- FS
37	1	*WASH WATER RESERVOIR	Distorted	186.00 FS	*148.40 FS
38	1	*WINDSCREEN WASHER PUMP	Not Necessary	118.00 FS	*- FS
39	1	*HEADLIGHT WASHER PUMP	Not Necessary	147.00 FS	*- FS
40	1	*RETAINER SIGNAL HORN-LH	Damaged	182.00 FS	*145.60 FS
41	1	*AIR GUIDE-LH	Not Necessary	22.00 FS	*- FS
42	1	*AIR GUIDE-UPPER CENTER	Not Necessary	11.00 FS	*- FS
43	1	*COOLANT RADIATOR LOCK CARRIER	Not Necessary	663.00 FS	*- FS
44	4	*READY-MIX COOLANT	Not Necessary	84.00 FS	*- FS
45	1	*FRONT NO PLATE	Necessary	25.00 FS	*25.00 FS
46	1	*SUNDRIES	Necessary	800.00 FS	*19.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,020.00 10,852.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCOND CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	960.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER.LHS FRONT FENDER,BONNET AND LHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALLIGN TO POSITION.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,500.00	1,750.00
4	TO RESPRAY FRONT BUMPER,BONNET AND LHS FRONT FENDER	New	2,500.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,512.00	3,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >