



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/05/2019

Survey Details:

Date of loss	20-Mar-19
Date of appointment	21-Mar-19
Date of survey	25-Mar-19
Location of survey	CHEW MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKZ 792E
Make and Model	TOYOTA HARRIER 1986CC
Date of registration	8/1/2016
Excess	
Market Value	\$90,000
Parf Rebate	\$61,500
Nett Loss	\$28,500

Repair details:

Initial Estimate	\$ 23,855.65
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 6,708.99
Check items (estimate)	
Labour	\$ 2,190.00
Total	\$ 8,898.99
Lump Sum(if applicable)	\$ 7,100.00

Number of days for repair	6
---------------------------	---



Remarks:

We have not authorized repairs. HEAD TO REAR

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$	7,597.00
Loss of use	\$	700.00 \$100 x 7 days
LTA search fee	\$	7.45
Proposed Total	\$	8,304.45